



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

PAGE: 1

M/S : RMG RENT-A-CAR PTE LTD
NO.25 HOOT KIAM ROAD
SINGAPORE 249407

TEL : 6235 1311

FAX : 6235 5256

ATTN :

YOUR REF NO : SGZ9458J
CLAIM TYPE : THIRD PARTY
TP INS. CO. : QBE INSURANCE (SINGAPORE) PTE LTD
ACCIDENT DATE : 23/12/2017
TP VEH REG NO : SGZ9458J

ESTIMATE

NO : QUOT201712-0088(00)
DATE : 29/12/2017
POLICY NO : SD17V05636/VPZ/R04
VEH REG NO : SLQ1055D
MAKE/MODEL : TOYOTA HARRIER ELEGANCE
2.0 A
CHASSIS NO : ZSU600087829
ENGINE NO : 3ZRB861051
REG. DATE : 2016

Estimate Repair Cost to Vehicle No : SLQ1055D

Description	Quantity	Unit Price	Amount
		S\$	S\$
LIST PRICE			
1 Front bumper	1	1,500.00	1,500.00 ✓
2 Front bumper reinforcement	1	550.00	550.00 X
3 Front bumper centre lower grille	1	390.00	390.00 ?
4 Front bumper clips	15	5.50	82.50 ✓
5 Front bumper lower spoiler	1	325.00	325.00 X
6 Front grille assy	1	580.00	580.00 ✓
7 Headlamp - RH	1	3,187.00	3,187.00 ?
			6,614.50
		Less 25%	1,653.62
			4,960.88
SPECIAL NET			
8 Front number plate	1	40.00	40.00 ✓
			40.00
LABOUR			
9 To remove and refit front bumper sensor	1	100.00	100.00 X
10 To check and focus wiring system	1	80.00	80.00 200
11 To pabel beat and straighten support panel, front chassis frame, including replacement of parts and align where necessary, to refit and adjust the same	1	850.00	850.00 400
12 To putty and spray paint on affected areas	1	1,000.00	1,000.00
13 To apply rust-proofing on replaced and repaired panels	1	120.00	120.00 X
			2,150.00
TOTAL			S\$ 7,150.88
ADD GST @ 7%			500.56
GRAND TOTAL			S\$ 7,651.44

SINGAPORE DOLLAR SEVEN THOUSAND SIX HUNDRED FIFTY-ONE AND CENTS FORTY-FOUR ONLY

FOR TONG LUCK AUTO PTE LTD

AUTHORISED SIGNATURE