

**TRANS-CAB AUTO SERVICES PTE LTD**

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

**SHB7804X - III****AAD1712-295***Not Authorized  
6/1/2017 @ 56501*

Vehicle No.:  
Chassis No.:  
Vehicle Make:  
Vehicle Model:  
Date of Accident :  
Third Party Insurer :

**SHB7804X - CANDY**  
**KL1LA69RJB098439**  
**CHEVROLET**  
**EPICA 2.0**  
**27.12.2017**  
**III**

**PART****LIST**

|    |   |                                         |    |               |
|----|---|-----------------------------------------|----|---------------|
| 1  | 1 | Front Bumper                            | \$ | CM 1,202.00 ✓ |
| 2  | 1 | Front Bumper Lower Absorber             | \$ | Br 180.00 X   |
| 3  | 1 | Front Bumper Reinforcement              | \$ | Br 356.00 ✓   |
| 4  | 1 | Front Bumper Retainer RH                | \$ | Br 102.00 X   |
| 5  | 1 | Front Bumper Retainer LH                | \$ | Br 102.00 X   |
| 6  | 1 | Front Bumper Lower Grille               | \$ | Br 78.00 X    |
| 7  | 1 | Front Bumper Lower Stiffener            | \$ | R 134.37      |
| 8  | 1 | Front Bumper Bracket LH                 | \$ | R 10.00       |
| 9  | 1 | Front Bumper Bracket RH                 | \$ | R 10.00       |
| 10 | 1 | Bumper Fog Lamp Cover RH                | \$ | Br 32.40      |
| 11 | 1 | Bumper Fog Lamp Cover LH                | \$ | Br 32.40      |
| 12 | 1 | Front Fender RH                         | \$ | R 837.60      |
| 13 | 1 | Front Fender LH                         | \$ | R 837.60      |
| 14 | 1 | Front Fender Liner RH                   | \$ | Br 47.00      |
| 15 | 1 | Fender Insulation RH                    | \$ | Br 39.00      |
| 16 | 1 | Front Fender RR Bracket RH              | \$ | R 7.10        |
| 17 | 1 | Front Fender Inner Wheel House Panel RH | \$ | R 1,437.00    |
| 18 | 1 | Front Fender Liner LH                   | \$ | Br 47.00      |
| 19 | 1 | Fender Insulation LH                    | \$ | Br 39.00      |
| 20 | 1 | Front Fender RR Bracket LH              | \$ | R 7.10        |
| 21 | 1 | Front Fender Inner Wheel House Panel LH | \$ | R 1,437.00    |
| 22 | 1 | Resonator (B/S Fender LH) AIR BOX       | \$ | Br 134.67     |
| 23 | 1 | Resonator Hose                          | \$ | Br 37.00      |
| 24 | 1 | Bonnet                                  | \$ | Br 1,250.00 ✓ |
| 25 | 1 | Bonnet under weatherstrip seal          | \$ | Br 105.00 X   |
| 26 | 1 | Bonnet hinge RH                         | \$ | R 36.00 X     |
| 27 | 1 | Bonnet hinge LH                         | \$ | R 36.00 X     |
| 28 | 1 | Bonnet Moulding                         | \$ | R 161.97 ✓    |
| 29 | 1 | Bonnet Lock                             | \$ | R 60.00 X     |
| 30 | 1 | Bonnet cable                            | \$ | Br 125.00 X   |
| 31 | 1 | Bonnet insulator                        | \$ | Br 400.00 X   |
| 32 | 1 | Centr' logo badge                       | \$ | Br 60.00 ✓    |
| 33 | 1 | Bonnet Gas T/Gate Spring RH             | \$ | Br 286.90 X   |
| 34 | 1 | Bonnet Gas T/Gate Spring LH             | \$ | Br 286.90 X   |
| 35 | 1 | Front Support Panel Assy                | \$ | R 1,222.32 X  |
| 36 | 1 | Front brace panel                       | \$ | Br 134.37 ✓   |

**TRANS-CAB AUTO SERVICES PTE LTD****AAD1712-295**

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

**SHB7804X - III**

|    |   |                                        |    |                             |            |
|----|---|----------------------------------------|----|-----------------------------|------------|
| 37 | 1 | Headlamp RH                            | \$ | <i>S<sub>2</sub></i>        | 816.00 X   |
| 38 | 1 | Headlamp LH                            | \$ | <i>my car</i>               | 816.00 ✓   |
| 39 | 1 | Front Windscreen                       | \$ | <i>S<sub>2</sub></i>        | 1,304.00 X |
| 40 | 1 | Front Windscreen Moulding              | \$ | <i>S<sub>2</sub></i>        | 196.00 X   |
| 41 | 1 | Windscreen Washer Tank - Filler Neck   | \$ | <i>S<sub>2</sub></i>        | 4.80 X     |
| 42 | 1 | Windscreen Washer Tank                 | \$ | <i>S<sub>2</sub></i>        | 62.00 X    |
| 43 | 1 | Windscreen Washer Tank Motor           | \$ | <i>S<sub>2</sub></i>        | 51.00 X    |
| 44 | 1 | TANK, WIPER HOSE                       | \$ | <i>S<sub>2</sub></i>        | 21.00 X    |
| 45 | 1 | Radiator Assembly                      | \$ | <i>1 hour B<sub>2</sub></i> | 618.00 ✓   |
| 46 | 1 | Radiator expansion tank                | \$ | <i>S<sub>2</sub></i>        | 45.00 X    |
| 47 | 1 | Radiator upper hose                    | \$ | <i>S<sub>2</sub></i>        | 30.00 X    |
| 48 | 1 | Radiator lower hose                    | \$ | <i>S<sub>2</sub></i>        | 120.00 X   |
| 49 | 1 | Radiator Grille (Grille A-Rad)         | \$ | <i>C<sub>2</sub></i>        | 367.00 ✓   |
| 50 | 1 | Radiator Grille Top Cover              | \$ | <i>S<sub>2</sub></i>        | 45.02 X    |
| 51 | 1 | Fan Blade(A/C)                         | \$ | <i>C<sub>2</sub></i>        | 536.00 ✓   |
| 52 | 1 | Fan Blade(Radiator)                    | \$ | <i>S<sub>2</sub></i>        | 634.00 X   |
| 53 | 1 | Aircon Condenser                       | \$ | <i>1 hour B<sub>2</sub></i> | 600.00 ✓   |
| 54 | 1 | Aircon compressor - pump               | \$ | <i>S<sub>2</sub></i>        | 1,847.95 X |
| 55 | 1 | Aircon hose - condenser to compressor  | \$ | <i>S<sub>2</sub></i>        | 450.00 X   |
| 56 | 1 | Aircon hose - compressor to evaporator | \$ | <i>S<sub>2</sub></i>        | 624.00 X   |
| 57 | 1 | Aircon hose - condenser to evaporator  | \$ | <i>S<sub>2</sub></i>        | 580.00 X   |
| 58 | 1 | Air Cleaner Assembly (Cleaner A-Air)   | \$ | <i>S<sub>2</sub></i>        | 112.00 X   |
| 59 | 1 | Alternator assembly                    | \$ | <i>S<sub>2</sub></i>        | 1,040.00 X |
| 60 | 1 | Horn Unit (High Tone)                  | \$ | <i>S<sub>2</sub></i>        | 53.46 X    |
| 61 | 1 | <del>Air</del> Intercooler             | \$ | <i>B<sub>2</sub></i>        | 652.00 ✓   |
| 62 | 1 | Air Intercooler Hose (FILTER FUEL)     | \$ | <i>S<sub>2</sub></i>        | 34.67 X    |
| 63 | 1 | Power steering hose                    | \$ | <i>S<sub>2</sub></i>        | 312.11 X   |
| 64 | 1 | Front Fuse Box                         | \$ | <i>S<sub>2</sub></i>        | 715.00 X   |
| 65 | 1 | W/HARNESS-ENG                          | \$ | <i>S<sub>2</sub></i>        | 1,500.00 X |

|       |    |           |
|-------|----|-----------|
| TOTAL | \$ | 25,497.71 |
| 10%   | \$ | 2,549.77  |
|       | \$ | 22,947.94 |

**Specical Nett**

|   |       |                                    |    |                      |              |
|---|-------|------------------------------------|----|----------------------|--------------|
| 1 | 1 Set | Front Bumper Fastener Clip         | \$ | <i>na</i>            | 24.00 ✓      |
| 2 | 1 Set | Radiator Grille Top Cover Clip     | \$ | <i>na</i>            | 10.00 X      |
| 3 | 1 Set | Front licence plate with holder    | \$ | <i>C<sub>2</sub></i> | 192.00 45.00 |
| 4 | 2     | Front windscreen sealant           | \$ | <i>na</i>            | 80.00 X      |
| 5 | 1     | Front windscreen inner sponge seal | \$ | <i>na</i>            | 100.00 X     |
| 6 | 2     | Front ERP Sticker                  | \$ | <i>na</i>            | 40.00 X      |
| 7 | 1 Set | Radiator Coolant                   | \$ | <i>na</i>            | 60.00 20.00  |
| 8 | 1 Set | Radiator Grille clip               | \$ | <i>na</i>            | 35.00 ✓      |
| 9 | 1 Set | Front Fender Liner clip            | \$ | <i>na</i>            | 30.00 X      |

**TRANS-CAB AUTO SERVICES PTE LTD****AAD1712-295**

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

**SHB7804X - III**10 2 Bonnet stopper \$ *R* 15.00 *X*

|                    |           |                  |
|--------------------|-----------|------------------|
| <b>TOTAL</b>       | <b>\$</b> | <b>586.00</b>    |
| <b>TOTAL PARTS</b> | <b>\$</b> | <b>23,533.94</b> |

|                                                                                                                           |    |                           |
|---------------------------------------------------------------------------------------------------------------------------|----|---------------------------|
| To Check Electrical Lighting Concerned.                                                                                   | \$ | 170.00 <i>201</i>         |
| Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same | \$ | 4,050.00 <i>5001</i>      |
| Putty and spray painting of the affected portion.                                                                         | \$ | 4,200.00 <i>6001</i>      |
| Towing Fees.                                                                                                              | \$ | 120.00 <i>501</i>         |
| To Remove And Refit Front W/Screen Glass To Facilitate Bodywork Repair.                                                   | \$ | <i>nn</i> 170.00 <i>X</i> |
| Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.                                           | \$ | <i>nn</i> 380.00 <i>X</i> |
| To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.                           | \$ | <i>nn</i> 380.00 <i>X</i> |
| To remove and renew power steering pump, oil cooler pipe and final checking and testing.                                  | \$ | <i>nn</i> 440.00 <i>X</i> |
| To check ABS brake efficiency, final checking and testing.                                                                | \$ | <i>nn</i> 380.00 <i>X</i> |
| To check steering geometry and computer wheel alignment                                                                   | \$ | <i>nn</i> 220.00 <i>X</i> |
| To replace, refix and top up coolant for radiator                                                                         | \$ | 170.00 <i>501</i>         |
| To dismantle and refit aircon assy and attachment, vacuum and charge-in-gas.                                              | \$ | 380.00 <i>1001</i>        |
| To rust-proofing of the affected areas.                                                                                   | \$ | 170.00 <i>301</i>         |

|                       |           |                  |
|-----------------------|-----------|------------------|
| <b>TOTAL</b>          | <b>\$</b> | <b>11,230.00</b> |
| <b>Over All Total</b> | <b>\$</b> | <b>34,763.94</b> |

**Repair Days**~~15 Days~~*3 days*