

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHC 3347U

DATE 29/12/2017 16:15

MAKE :

MODEL : HYUNDAI SONATA

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Front Bumper Cover ✓			\$ 538.80
	Front Bumper Side Bracket, LH ✓			\$ 14.30
	Front Bumper Clips 10 pcs ✓			\$ 22.00
	Front Fender (LH) ✓			\$ 593.00
	Front Fender Shield (LH) ?			\$ 86.00
	Front Fender Retainer ?			\$ 9.20
	Headlamp (LH) ?			\$ 1,388.00
	Front Wheel Hub Cap (LH) ✓			\$ 145.00
	SUB TOTAL			\$ 2,796.30
	LESS 20%			\$ 559.26
	DISCOUNTED TOTAL			\$ 2,237.04
	Front Fender Advertisement Logo (LH) ✓			\$ 100.00 Nett
	Labour Charge			
	Panel Beating			\$ 400.00 200
	Spray Painting Charge			\$ 400.00 360
	Wiring Charge			\$ 50.00 20?
	Tuff Kote			\$ 50.00 20
	FRT Wheel Alignment			\$ 120.00 60
	TOTAL LABOUR			\$ 1,020.00
	ESTIMATE TOTAL			\$ 3,357.04
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company. LKK Auto Consultants hence notify the Repairer of the following: - To resurvey before/after spray painting - To display damaged part(s) during resurvey - Parts prices are subject to confirmation - Third party survey is on a "Without Prejudice" basis - No illegal modification(s) is allowed. - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: _____ Date: _____				