

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG:200707743D GST REG:200707743D

29-Dec-17

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHB 8609 L

1 pc	Rear bumper ✓	\$ 696.00
1 pc	Rear bumper lower cover ✓	\$ 206.00
1 pc	Rear bumper o/s side bracket @ \$29.00 ✓	\$ 29.00
1 pc	Rear bumper inner sponge ✗	\$ 114.00
1 pc	Rear bumper reinforcement ✓	\$ 607.00
1 pc	Rear bumper o/s stay @ \$53.00 ✓	\$ 53.00
1 pc	Rear bumper o/s reflector @ \$46.00 ✓	\$ 46.00
1 pc	Rear o/s tail lamp @ \$421.00 ✗	\$ 421.00
1 pc	Bootlid o/s reflector @ \$350.00 ✗	\$ 350.00
1 pc	End panel ✗	\$ 250.00
1 pc	Rear o/s fender ✗	\$ 1,205.00
1 pc	Rear windshield moulding ✗	\$ 87.00
		<hr/>
		\$ 4,064.00
		\$ 406.40
		<hr/>
		\$ 3,657.60

S/NETT

1 set	Rear bumper clips ✓	\$ 48.00
1 set	Reverse sensor ✓	\$ 280.00 200
1 pc	Rear bumper top protector ✓	\$ 80.00 50
1 pc	Rear o/s fender sticker ✓	\$ 60.00
1 set	Rear windscreen sealant ✗	\$ 50.00
		<hr/>
	Towing Fee	\$ 50.00 ✓
	Sundry	\$ 50.00 20
	To dismantle / refit rear windscreen to facilitate repairs	\$ 120.00 ✗
	To dismantle / replace reverse sensor to new bumper and reset to the same	\$ 120.00 20
	To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.	\$ 180.00 50
	To labour charge for dismantle and renew the accident damaged parts. To heat/weld, cut the end panel, rear o/s fender. Including knock-out, straighten, repair, reshape and adjust of the same	\$ 1,400.00 800
	To putty and spray painting on rear bumper, end panel, rear o/s fender	\$ 600.00 500
	To apply rustproofing on the repaired and replaced panels.	\$ 250.00 50
		<hr/>
		\$ 6,945.60

LKK A... Less 10%

the Rep...

- To repair...
- To disas...
- Parts pr...
- Third party...
- No... ga...
- Supp... the... is subject to...

Acknowledged by Repairer

Signature: *[Signature]*

Date: *2/1/18*

2/1/18 1025hrs.

3 hrs.

45

After Repair