



HKL LIM
TEAM MOTORSPORT

Blk 1008 #01-24, Bukit Merah Lane 3, Singapore 159722 Tel: 6275 6656, 6275 6566, 62727292 Fax: 6272 9291
Email: support@hklilmotorsport.com.sg Website: www.hklilmotorsport.com.sg

FBE2010H

1. Towing - \$35 ✓
 2. Front wheel rim - \$250 ✗
 3. Front bearing - \$50 *new* ✓
 4. Front wheel shalf - \$40 ?
 5. Front brake disc - \$130 ?
 6. Front fork assy lh - \$290 } *R SN \$130.140*
 7. Front fork assy rh - \$290 }
 8. Front fork under bracket - \$180 ✗
 9. Steering cone bearing - \$90 *new* ✓
 10. Front fender - \$95 *cut* ✓
 11. P plate - \$10 *new* ✓
 12. Head cowling - \$150 *new* ✓
 13. Windscreen - \$90 *cut* ✓
 14. Head light - \$280 *cut* ✓
 15. Lamp stay - \$80 ✗
 16. Front signal rh - \$45 *new* ✓
 17. Handlebar - \$120 ?
 18. Handlebar balancer - \$30 *cut* ✓
 19. Side mirror lh / rh - \$90 *new* ✓
 20. Brake lever - \$25 *cut* ✓
 21. Fuel tank - \$550 *dd* ✓
 22. Fuel tank side cover rh - \$130 *cut* ✓
 23. Brake pedal - \$80 *dd* ✓
 24. Front foot rest - \$55 *cut* ✓
 25. Exhaust pipe - \$480 ✗
 26. Exhaust cover - \$90 *cut* ✓
 27. Side cover rh - \$120 ✗
 28. Tail board rh - \$90 ✗
 29. Top box - \$160 *cut* ✓
 30. Top box rack - \$80 *bt* ✓
 31. Rear signal rh - \$45 *dis* ✓
 32. Rear body alignment - \$450 *250 - photo.*
 33. Labour - \$550 *250.*
- Total - \$ 5250

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Tan Jiah 9745749
- WP'

02/01/18 @ 1700

Lumpsum

Ready after repair.

5 days.

Sum@11km town.