

TRANS-CAB AUTO SERVICES PTE LTD
 NO.2 ANG MO KIO ST63 SINGAPORE 569111
 TEL NO. 6287 6666 FAX NO. 6257 1330
 CO/GST REG NO. 201019626G
SHF779K - AXA

AAD1712-301

Not Authored
Revised By party

Vehicle No.:
 Chassis No.:
 Vehicle Make:
 Vehicle Model:
 Date of Accident :
 Third Party Insurer :

SHF779K - AXA
 VF1ABL15AUC283286
 RENAULT
 LATITUDE
 27.12.2017
AXA

PART

LIST

1	1	BUMPER COVER FRT	\$	<i>Bu</i> 1,259.42 ✓
2	1	BUMPER SPOILER FRT	\$	<i>Sm</i> 181.75 X
3	1	BUMPER FOG LAMP GRILLE LH	\$	<i>Sm</i> 207.22 X
4	1	BUMPER RETAINER FRT LH	\$	<i>D.I</i> 151.41 ✓
5	1	BUMPER RETAINER FRT RH	\$	<i>Sm</i> 151.41 X
6	1	BUMPER SUPPORT FRT LH	\$	<i>Sm</i> 123.88 ✓
7	1	BUMPER SUPPORT FRT RH	\$	<i>Sm</i> 123.88 X
8	1	BUMPER BEAM FRT	\$	<i>R</i> 914.08
9	1	RADAIOR GRILLE	\$	<i>Sm</i> 1,707.78
10	1	RADAIOR GRILLE BADGE 'RENAULT'	\$	<i>Sm</i> 225.36
11	1	RADAIOR GRILLE FRAME	\$	<i>Sm</i> 1,353.75
12	1	FRAME FULL SUPPORT PANEL	\$	<i>R</i> 615.90 } X
13	1	FRAME FULL SUPPORT BRACKET	\$	<i>Sm</i> 89.79
14	1	AIR CLEANER LOWER	\$	<i>Sm</i> 352.64
15	1	AIR CLEANER HOSE	\$	<i>Sm</i> 76.14
16	1	LOWER ARM LH	\$	<i>Sm</i> 685.76
17	1	KUNCKLE ARM LH	\$	<i>Sm</i> 846.98
18	1	ABSORBER FRT LH	\$	<i>Sm</i> 360.54
19	1	BONNET	\$	<i>R</i> 1,941.63
20	1	HEADLAMP LH	\$	1,184.43 ?
21	1	HEADLAMP PANEL FRT LH	\$	<i>R</i> 152.15 X
22	1	FENDER PANEL FRT LH	\$	<i>R</i> 783.83 ✓
23	1	FENDER INSULATOR LH	\$	<i>Sm</i> 130.84 X
24	1	WHEEL HOUSING PANEL FRT LH	\$	<i>R</i> 4,682.09 X
25	1	WHEELARCH FRT LH	\$	<i>Sm</i> 278.84 X
26	1	DOOR MIRROR LH	\$	<i>Sm</i> 1,483.40 X
27	1	DOOR MIRROR GLASS LH	\$	<i>Sm</i> 148.20 X
28	1	DOOR MIRROR BACK COVER LH	\$	<i>Sm</i> 218.46 X
29	1	DOOR PANEL FRT LH	\$	<i>R</i> 2,844.66 X

TOTAL	\$	23,276.23
10%	\$	2,327.62
	\$	20,948.60

TRANS-CAB AUTO SERVICES PTE LTD**AAD1712-301**

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHF779K - AXA**Specical Nett**

1	1SET	FRONT BUMPER CLIP	\$	<i>nn</i> 66.00 ✓
2	1SET	WHEELARCH CLIP LH	\$	<i>nn</i> 66.00 X
3	1	TOW COVER FRT	\$	<i>sn</i> 14.50 X
4	1	CAP HUB LH FRT	\$	<i>nn</i> 35.00 ✓
5	1	RIM LH FRT	\$	<i>sn</i> 385.00 X
6	1	TYRE LH FRT	\$	<i>sn</i> 330.00 X
7	1SET	BUMPER SUPPORT FRT CLIP LH	\$	<i>nn</i> 9.80 X
8	1SET	BUMEPR RETAINER FRT CLIP LH	\$	<i>nn</i> 12.50 X
9	1	DOOR STICKER "Trans-cab"	\$	<i>nn</i> 80.00 X
10	1	DOOR STICKER "Classic"	\$	<i>nn</i> 30.00 X

TOTAL	\$	1,028.80
TOTAL PARTS	\$	21,977.40

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same

\$ 2,800.00 *400*

To Check Electrical Lighting Concerned.

\$ 170.00 *20*

Putty and spray painting of the affected portion.

\$ 3,000.00 *440*

To check steering geometry and computer wheel alignment

\$ 220.00 *60*

Towing Fees

\$ *nn* 120.00 X

To transfer of tire, rim and on wheel balancing.

\$ *nn* 170.00 X

To rust-proofing of the affected areas.

\$ 170.00 *30*

Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.

\$ *nn* 380.00 X

To Transfer Of Fender Fittings, Attachments And Perform Water Seepage Test.

\$ *nn* 170.00 X

TOTAL	\$	7,200.00
Over All Total	\$	29,177.40

(PARTS BY PARTS) Repair Days**10 Days***2 days*