

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

Vehicle Insured : YP 3673H
Accident Date : 21-Dec-2017

Our Ref : 217197 (AXA) / JANICE

ROBERT BOSCH (SOUTH EAST ASIA) PTE LTD
38C JALAN PEMIMPIN
Singapore 577180

No. : 05692

Date : 22-Dec-2017

PAGE : 1

*Not Authorised
11 Pps @ 1700.
Repair After Rain
3 days*

ESTIMATED COST OF REPAIR FOR RENAULT KANGOO 1.6A GBA8860C

- 1 pc O/s sliding door
- 1 pc O/s sliding door inner lock
- 1 pc O/s sliding door outer handle
- 1 pc O/s sliding door glass
- 1 pc O/s sliding door protector

Ry 2,150.00 ✓
Tr 480.00 ✓
CM 280.00 ✓
Shatter 680.00 ✓
Mr 320.00 ✓

3,910.00

Less 10% : 391.00

- 1 pc O/s sliding door glass sealant
- 1 pc O/s door company sticker

Mr 3,519.00 *40sn*
Mr 60.00 *sn*
Mr 200.00 *sn/20sn*

To putty and spray replaced parts

400.00 *280*

To remove, cut-out damaged parts,
panel beating, welding, align,

500.00 *300*

To install sliding door glass

200.00 *120*

Total : S\$ 4,879.00

Singapore Dollars Four Thousand Eight Hundred
and Seventy Nine Only

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: