

INS. CASE OWNER:

CC 3 /ICS1800 0050 / T12639

LKK:

IDAC:

Surveyor:

Taufik

DOI:

B/118

Date / Time:

21/18

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

8KN 1268

Name of Insured:

YAP KIM WEON

Insured Tel No.:

HP:

9247774

Excess Sec II :SS

D.O.A:

12/17/18

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

YAP KIM WEON

Driver Tel No.:

(V/L: YES / NO)

Claim No.:

Policy No.:

Make / Model:

Place of Accident:

MPCAB01034202

BMW

238 PARHON WELB

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No

STW 81287

INSRS:  
WSP:  
Tel:  
Liability:  
RMKS:

Performance

INSRS:  
WSP:  
Tel:  
Liability:  
RMKS:INSRS:  
WSP:  
Tel:  
Liability:  
RMKS:INSRS:  
WSP:  
Tel:  
Liability:  
RMKS:

Date/ Time

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OE:

Email 21/18

After call ltr to OE:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OE:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

Confirm by: TAUFIK

REALIZATION

Date/Time: 26/2/18

Confirm with: CAROLINE

Confirm by: TAUFIK

Repair Cost:

P/T

SS 6,561.75

( 5 days)

Reduction:

29 %

Email

Call

L SETTLEMENT

Date/Time:

Confirm with

Email

Call

Liability:

SS 100

(Agreed / Assessed) BOLA S/N No.:

NIL

If NO or B 28, Ass. Lia:

Repair Cost:

SS 7,021.01

0.0 - IN PARKED TP.

of Rental (LOR):

SS -

( days)

of Use (LOU):

SS 400.00

(500 x 4 days)

of Income (LOI):

SS -

(5 x 4 days)

only ☐ LOU only ☒

LOR + LOU

☐ LOR + LOI☐ [Tick only one]

LTA Search

SS 2.00

al:

SS -

rsement:

SS -

(e.g. Tow/ Independent)

Cost

SS -

SS 7,423.01

Global Sum SS:

1) Claim status: Normal/Reject/Private Settle/MP

2) Report Format:

TP

3) Survey fee:

+ 350

AL PAYMENT

Date/Time:

Confirm with:

Email

Call

Name 1:

SS

Name 1:

Name 2: (Strike if N.A.)

SS

Name 2:

Name 3: (Strike if N.A.)

SS

Name 3:

COPY SENT





Auto  
Consultants  
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: To Be Advised  
Our ref: CC3/ICS18000050/T1eb3

Date: 16.01.2018

The Motor Claims Department  
M/s ECICS LIMITED

Dear Sir/Madam,

**PRELIMINARY ADVICE OF VEHICLE NO.**

**SJW8128Z**

We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 15.01.2018 at the premises of M/s Performance Motors Limited and have the following to report:-

Workshop Estimate Amount	: S\$	8,257.85
Revised Estimate Amount	: S\$	6,756.10
"Check" Items Amount	: S\$	345.75
Market Value	: S\$	-
LTA Reimbursement Value	: S\$	-
Nett Value	: S\$	-

Description of Damage:

The vehicle sustained damages at the  
N/S Portion



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 5 days

Yours faithfully,

MOHD. TAUFIKH  
Licensed Appraiser



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
ECICS LTD		Ref : CC3/ICS18000050/eb3		
7 TEMASEK BOULEVARD #10-01 SUNTEC TOWER ONE SINGAPORE 038987		Date : 02-01-2018		
		Code : ICS		
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SKN 126S	Veh. Inspected	SJW 8128Z	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	02/01/2018	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
<b>4. Description of Damages</b>				
<b>5. General Information</b>				
Accident Date	24/12/2017	Inspection Date		
Survey held at	PERFORMANCE MOTORS LTD 303 ALEXANDRA ROAD SINGAPORE 159941			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

## Performance Motors Limited

A member of the Sime Darby Group

Co. Reg. No. 197401359W GST Reg. No M2-0020081-X



333, Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941

Tel: 63190100 (Sales & Admin)  
63190111 (AfterSales)  
Fax: 64747770

389, Kampong Arang Road  
East Coast Centre  
Singapore 438180

Tel: 63190888 (AfterSales)  
Fax: 63449773

315, Alexandra Road  
Sime Darby Business Centre  
Singapore 159944

Tel: 63190528 (AfterSales)  
63190533/530 (Motorrad)  
Fax: 64786601 (AfterSales)  
64786624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

## ESTIMATE

02 JAN 2018

Estimate No. : b1 45313  
Date Estimated : 28/12/2017  
Prepared By : Gary Poh Chai Hoon

Page No. : 1 of 2

## - ESTIMATE REPAIR FOR -

Tay Bee Leng  
235 Pavilion Circle

SINGAPORE 658250

- ACCOUNT - 40000

Cash Sales - Service  
Singapore

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SJW8128Z	0R99715	23/09/2016	X3 sDrive20	0

## DESCRIPTION

To Replace left rear door, and remove and install front door and attachment include knocking cause by the accident

VALUE

1700 2,550.00

Painting left front door, left rear door.

1868 2,076.00

To transfer lock mechanism from old to new door including conduct checks on new door power window system for proper function. (1 door).

451 531.00

To carry out body cavity preservation.  
(Per panel).

100 118.00

To supply and install rear left window quarter glass solar film.

+ un 425.00

Sundries.

? 80.00

Total Labour 1: 5,780.00

## DESCRIPTION

RR LH DOOR  
CLIP  
CLIP  
IMPACT STRIP DOOR FRT LH (M)  
MOULDING DOOR REAR LH (M)  
OUTER WEATHERSTRIP RR LH DOOR (ALU)  
SIDE WINDOW FIXED GREEN RR LH  
CLIP  
COVER WHEEL ARCH RR LH (M)  
(DG/SL) W/SCREEN SEALANT (COLD 1 HOUR)

QTY	PRIC	VALUE
1	1,387.40	1,387.40
8	12.50	100.00
4	15.10	60.40
1	145.70	145.70
1	151.60	151.60
1	105.35	105.35
1	171.60	171.60
8	1.15	9.20
1	215.05	215.05
1	131.55	131.55

Total Parts : 2,477.85

## Performance Motors Limited

A member of the Sime Darby Group  
Co. Reg. No. 187401339W GST Reg. No M2-0020081-X



303, Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941  
Tel: 63190100 (Sales & Admin)  
63190111 (AfterSales)  
Fax: 64747770

280, Tampong Arang Road  
East Coast Centre  
Singapore 438180  
Tel: 63190888 (AfterSales)  
Fax: 63448773

319, Alexandra Road  
Sime Darby Business Centre  
Singapore 159944  
Tel: 63190528 (AfterSales)  
63190533/330 (Motorrad)  
64796501 (AfterSales)  
64796524 (Motorrad)

GST REG. NO : M2 - 0020081 - X

## E S T I M A T E

Estimate No. : b1 45313  
Date Estimated : 28/12/2017  
Prepared By : Gary Poh Chai Hoon

Page No. : 2 of 2

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SJW8128Z	0R99715	23/09/2016	X3 sDrive20	0

Client No / Ref: 01

Page No. 1 of 1

Estimate No. 13/11/18 01144

Engine No. 9249544

Author of Est. [Signature]

Signature [Signature]

5 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Labour 1	:	5,780.00
Parts	:	2,477.85
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	578.05
Grand Total	:	8,835.90

\*\* THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY \*\*

\*\* PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE \*\*

# Performance Motors Limited

A member of the Sino Dairy Group  
Co. Reg. No. 197401559W, GST Reg. No. M2-0030081-X



## SUPPLEMENTARY

Estimate No. : b1 45313  
Date Estimated : 28/12/2017  
Prepared By : Gary Poh Chai Hoon

Page No. :

REPAIR FOR -  
Tay Bee Leng  
235 Pavilion Circle

- ACCOUNT - 144674  
ECICS Limited  
7 Temasek Boulevard, #10-03 Suntec Tower 1  
Singapore 038987

SINGAPORE 658250

REGN NO	CHASSIS NO	REGN DATE	MODEL	MILEAGE
SJW8128Z	0R99715	23/09/2016	X3 sDrive20	0

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
# To remove and install rear LH door fixed window glass to facilitate repairs	413.00		413.00 ✓
# To conduct checks on all doors and boot lid central locking system for proper function	150.00		150.00 ✓

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# DOOR WEATHERSTRIP REAR *	142.35	1.00		142.35 net ✓
# FRT LH MOULDING ROCKER PANEL (X LINE *	150.00	1.00		150.00 net ✓
# RR LH MOULDING ROCKER PANEL (X LINE *	120.00	1.00		120.00 net ✓

Total Labour :	563.00
Total Parts :	412.35
Total Labour & Parts :	975.35



## FINAL REPORT

Estimate No. : b1 45313  
Date Estimated : 28/12/2017  
Prepared By : Gary Poh Chai Hoon

Page No. :

REPAIR FOR -  
Tay Bee Leng  
235 Pavilion Circle

- ACCOUNT - 144674  
ECICS Limited  
7 Temasek Boulevard, #10-03 Suntec Tower 4  
Singapore 038987

SINGAPORE 658250

REGN NO	CHASSIS NO	REGN DATE	MODEL	MILEAGE	
SJW8128Z	OR99715	23/09/2016	X3 sDrive20	0	
DESCRIPTION			ORIGINAL PRICE	DISC. %	NETT
To replace rear LH door and attachments include making good the front LH door and knocking out dents caused by the accident			1700.00		1,700.00
To spray paint front LH door and rear LH door			1868.00		1,868.00
To transfer lock mechanism from old to new door include conducting checks on new door power window system for proper function (1x)			451.00		451.00
To carry out body cavity preservation, (Per panel).			100.00		100.00
# To remove and install rear LH door fixed window glass to facilitate repairs			413.00		413.00
# To conduct checks on all doors and boot lid central locking system for proper function.			150.00		150.00
Sundries			80.00		80.00

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
RR LH DOOR	1,387.40	1.00		1,387.40
# DOOR WEATHERSTRIP REAR *	142.35	1.00		142.35
# FRT LH MOULDING ROCKER PANEL (X LIN *	150.00	1.00		150.00
# RR LH MOULDING ROCKER PANEL (X LINE *	120.00	1.00		120.00

### # SUPPLEMENTARY ITEMS

Total Labour :	4,762.00
Total Parts :	1,799.75
Total Labour & Parts :	6,561.75
Deduction for Excess :	
Total Repair Costs less Excess:	6,561.75
GST @7%:	459.32
Grand Total :	7,021.07



## Asher Sng (LKKAuto)

---

**From:** Asher Sng (LKKAuto)  
**Sent:** Monday, 8 January 2018 10:30 AM  
**To:** 'YAPKL126@GMAIL.COM'  
**Cc:** 'XIIAOKENN@HOTMAIL.COM'  
**Subject:** ACCIDENT INVOLVING SKN 126S & SJW 8128Z AT / ALONG 238 PAVILION CIRCLE ON 25/12/2017.

Dear YAP KIM LEONG,

[Without Prejudice]

By Email Only

### ACCIDENT INVOLVING SKN 126S & SJW 8128Z AT / ALONG 238 PAVILION CIRCLE ON 25/12/2017.

We refer to the above accident matter.

As spoken, we are the loss adjusters acting on behalf of M/s ECICS Limited, the Motor Insurer of SKN 126S on the reported accident on 25/12/2017.

Our Principal has received a Third Party property damage claim from the owner of SJW 8128Z with regards to the above accident.

We will try our best to negotiate for an amicable settlement on best possible terms with Third Party under the terms and conditions of your motor policy. In this respect, the vehicle's premium/NCD may be affected as a result of the above claim.

In the event that you receive any letters/ court documents regards to the above accident matter, please do not reply or respond, you may forward to us directly for further handling and we will reply on your behalf.

Thank you.

Best Regards,

**Asher Sng** | Case Handler

**LKK Auto Consultants**

phone: 6841-6051 | email: [ashersng@lkkauto.com](mailto:ashersng@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



ECICS Limited  
7 Temasek Boulevard  
#10-03 Suntec Tower One  
Singapore 038987  
Attention: Motor Claims

**"Without Prejudice"**

Your Ref:  
Our Ref:  
Date:  
Subject:

09 March 2018

**ACCIDENT INVOLVING VEHICLES SJWB128Z & SKN126S ON 24.12.2017**

Dear Sirs

We refer to the above matter.

The accident was caused solely by the negligence on the part of your insured. As a result of the said accident, our client has suffered losses which are set out hereunder as follows:-

Cost of repair	: S\$	7021.07
Loss of use	: S\$	400.00 (S\$ 100.00 x 4 days)
GIA search fee	: S\$	2.00
Total	: S\$	7423.07

A copy of each of the following supporting documents is enclosed:

1. Copy of Accident Report
2. Copy of Final Repair bill & GIA search slip
3. Copy of Certificate of Insurance
4. Copy of Identification Card & Driving License
5. Copy of Letter of Authorisation

Please note that you or your insured should send us an acknowledgement of receipt of this letter within fourteen (14) days from the date of this letter, failing which our client will have no alternative but to commence legal proceedings against you without any further notice to you or your insured.

Should you have a counterclaim against our client arising out of the accident, you are also required to send a letter giving full particulars of the counterclaim together with all relevant supporting documents within eight (8) weeks of your receipt of this letter.

For any correspondence, please contact Ms Caroline Tan at 6319-0174 / Fax. 6479-4601 or email to [pml-pbsp@simedarby.com.sg](mailto:pml-pbsp@simedarby.com.sg).

Yours sincerely

**Teng Wai Khan**  
Customer Service Manager, Body & Paint

Performance Motors  
Limited  
1800-Car-BMW  
(1800-2255-359)  
[www.pml.com.sg](http://www.pml.com.sg)

303 Alexandra Road  
Simed Darby  
Performance Centre  
Singapore 159041  
Tel Sales 6319 0100  
Tel AfterSales  
6319 0111  
Fax 6474 7770

315 Alexandra Road  
#01-01  
Simed Darby  
Business Centre  
Singapore 159044  
Tel Sales 6319 0111  
Tel AfterSales  
6319 0537  
Fax 6479 6624

280  
Kampung Arang Rd  
East Coast Centre  
Singapore 438180  
Tel AfterSales  
6319 0888  
Fax 6344 1332

Registered Office  
305 Alexandra Road  
#02-01  
Vantage  
Automotive Centre  
Singapore 159042

Co. Reg. No.  
127401628W

## Performance Motors Limited

A member of the Sime Darby Group  
Co. Reg. No. 197401559W GST Reg. No. K2-0020081-K



303, Alexandra Road  
Sime Darby Performance Centre  
Singapore 119942  
Tel. 63190100 (Sales & Admin)  
63190111 (AfterSales)  
Fax. 64747770

280, Kampong Arang Road  
East Coast Centre  
Singapore 438180  
Tel. 63190888 (AfterSales)  
Fax. 63443773

313, Alexandra Road  
Sime Darby Business Centre  
Singapore 159944  
Tel. 63190528 (AfterSales)  
63190533/530 (Motorrad)  
Fax. 64796621 (AfterSales)  
64796624 (Motorrad)

## SERVICE TAX INVOICE

Repair Order No. : B1 1240765  
Date IN : 29/01/2018  
Cust. Svc. Advisor: Gary Poh Chai Hoon

Page No. : 1 of 2  
Invoice Number : 1939002 / WSB  
Invoice Date : 27/02/2018  
Payment Terms : 30 Days From Invoice  
Invoice By : Sharon Heng

## - CUSTOMER INFORMATION -

Ms Tay Bee Leng  
235 Pavilion Circle

SINGAPORE 658250

## - INVOICE TO - 144674

ECICS Limited  
7 Temasek Boulevard, #10-03 Suntec Tower Or  
Singapore 038987

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SJW8128Z	0R99715	23/09/2016	X3 SDRIVE20	30944

## - - - - LABOUR 1 - - - -

	NETT
To replace rear left door and door weatherstrip, front left rocker panel moulding and rear left rocker panel moulding etc including to make good the front left door and knock out dented area caused by the accident.	1,700.00
To remove and install body parts in order to carry out painting job.	
To respray front left door and rear left door.	1,868.00
To transfer lock mechanism from old to new door including conduct checks on new door power window system for proper function.	451.00
To carry out body cavity preservation.	100.00
To remove and install rear left door fixed window glass to facilitate repair job.	413.00
To conduct checks on all doors and bootlid central locking system for proper function.	150.00
Sundries.	80.00
INS CLAIMS : ACCIDENT REPAIR. DIRECT SETTLEMENT.	0.00
DATE OF ACCIDENT : 24.12.2017. 3RD PARTY CAR : SKN126S.	
YOUR REF NO : NIL.	
VEHICLE WAS SURVEYED BY MR TAUFIKH FROM LKK AUTO CONSULTANTS PTE LTD ON 15.1.2018 AT 11.00 AM.	
AUTHORISED REPAIR BY MS ASHER SNG FROM LKK ON 4.1.2018 VIA E-MAIL.	
PROPOSE LOSS OF USE = \$100X4. THE AMOUNT IS SUBJECTED TO INSURANCE COMPANY CONFIRMATION.	0.00
GIA SEARCH FEE = \$2.00.	0.00
<b>Total Labour 1:</b>	<b>4,762.00</b>

## - - - - PARTS - - - -

	Qty	Retail Price	NETT
RR LH DOOR	1	1,387.40	1,387.40
DOOR WEATHERSTRIP REAR	1	142.35	142.35
FRT LH MOULDING ROCKER PANEL (X LIN	1	150.00	150.00
RR LH MOULDING ROCKER PANEL (X LINE	1	120.00	120.00
<b>Total Parts :</b>			<b>1,799.75</b>

## Performance Motors Limited

A member of the Sime Darby Group

Co. Reg. No. 197401155W GST Reg. No. 02-0020061-X

101, Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941  
Tel. 63190120 (Sales & Admin)  
63190111 (AfterSales)  
Fax. 64747770

280, Kembangan Road  
East Coast Centre  
Singapore 436187  
Tel. 63190888 (AfterSales)  
Fax. 63445773

111, Alexandra Road  
Sime Darby Business Centre  
Singapore 159944  
Tel. 63190528 (AfterSales)  
63190533/533 (Motors)  
Fax. 64796601 (AfterSales)  
64796624 (Motors)



## SERVICE TAX INVOICE

Repair Order No. : B1 1240765	Page No. : 2 of 2
Date IN : 29/01/2018	Invoice Number : 1939002 / WSB
Cust. Svc. Advisor: Gary Poh Chai Hoon	Invoice Date : 27/02/2018
	Payment Terms : 30 Days From Invoice
	Invoice By : Sharon Heng

Labour Charges : 4,682.00	Total Labour & Parts Charges : S\$ 6,561.75
Parts Charges : 1,799.75	Less Insurance Excess : S\$ 0.00
Lubricant/Misc : 80.00	Invoice Total Amount Exclude GST : S\$ 6,561.75
	GST @ 7% : S\$ 459.32
	Invoice Total Amount Include GST : S\$ 7,021.07

Computer generated invoice. No signature is required.

Amount Payable Include GST : S\$ 7,021.07

All amounts are in Singapore Dollars.

Work was carried out subject to the Company's Terms and Conditions of Service.

No complaints will be entertained unless reported within seven (7) days of the date of this invoice.

For credit purchases, interest @1% per month will be debited on overdue amounts.



New Dealer

**Performance Motors Limited**A member of the Sime Darby Group  
Co. Reg. No. 197461558N GST Reg. No. M2-0020081-X301, Alexandra Road  
Sime Darby Performance Centre  
Singapore 159943  
Tel: 63190100 (Sales & Admin)  
63190111 (AfterSales)  
Fax: 64747770287, Kewpong Arang Road  
East Coast Centre  
Singapore 438140  
Tel: 63190888 (AfterSales)  
Fax: 63449773318, Alexandra Road  
Sime Darby Business Centre  
Singapore 159946  
Tel: 63190528 (AfterSales)  
63190532/529 (Motorrad)  
Fax: 64796601 (AfterSales)  
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

**E S T I M A T E**

02 JAN 2017

Estimate No. : b1 45313  
Date Estimated : 28/12/2017  
Prepared By : Gary Poh Chai Hoon

Page No. : 1 of 2

**- ESTIMATE REPAIR FOR -**Tay Bee Leng  
235 Pavilion Circle

SINGAPORE 658250

**- ACCOUNT - 40000**Cash Sales - Service  
Singapore

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SJW8128Z	0R99715	23/09/2016	X3 sDrive20	0

**DESCRIPTION**

To Replace left rear door, and remove and install front door and attachment include knocking cause by the accident

1700 2,550.00

Painting left front door, left rear door.

1868 2,076.00

To transfer lock mechanism from old to new door including conduct checks on new door power window system for proper function. (1 door).

451 531.00

To carry out body cavity preservation.  
(Per panel).

100 118.00

To supply and install rear left window quarter glass solar film.

✓ 425.00

Sundries.

? 80.00

Total Labour 1: 5,780.00

**DESCRIPTION**RR LH DOOR  
CLIP  
CLIP  
IMPACT STRIP DOOR FRT LH (M)  
MOULDING DOOR REAR LH (M)  
OUTER WEATHERSTRIP RR LH DOOR (ALU)  
SIDE WINDOW FIXED GREEN RR LH  
CLIP  
COVER WHEEL ARCH RR LH (M)  
(DG/SL) W/SCREEN SEALANT (COLD 1 HOUR)

QTY	PRIC
1	1,387.40
8	12.50
4	15.10
1	145.70
1	151.60
1	105.35
1	171.60
8	1.15
1	215.05
1	131.55

VALUE
bt 1,387.40
? 100.00
? 60.40
ant 145.70
nt 151.60
? 105.35
nt 171.60
nt 9.20
nt 215.05
nt 131.55

Total Parts : 2,477.85

BMW Dealer

# Performance Motors Limited

A member of the Sime Darby Group  
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X

107, Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941  
Tel. 63190100 (Sales & Admin)  
63190111 (AfterSales)  
Fax. 64761770

289, Tampung Arang Road  
East Coast Centre  
Singapore 438150  
Tel. 63190888 (AfterSales)  
Fax. 63449773

315, Alexandra Road  
Sime Darby Business Centre  
Singapore 159944  
Tel. 63190528 (AfterSales)  
63190533/330 (Motorrad)  
Fax. 64796601 (AfterSales)  
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

## ESTIMATE

Estimate No. : b1 45313  
Date Estimated : 28/12/2017  
Prepared By : Gary Poh Chai Hoon

Page No. : 2 of 2

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SJWB1282	0R99715	23/09/2016	X3 sDrive20	0

Called 05/12/17 / 15/1/18 211am  
Page 1/1  
Customer: 15/1/18 211am  
Engineer: [Signature]  
Engineer's Name: [Signature]  
Engineer's Tel: 92495341  
Approved: YH/Ho  
Authorised (Sig): [Signature]  
Date: 15/1/18  
Signature: [Signature]  
No. of days: 5 days

Labour 1	:	5,780.00
Parts	:	2,477.85
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	578.05
Grand Total	:	8,835.90

\*\* THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONI Y\*\*

**GENERAL  
INSURANCE  
ASSOCIATION**

RECORDS MANAGEMENT CENTRE

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE  
RECORDS MANAGEMENT CENTRE**6 Raffles Quay #18-00, Singapore 048580  
Phone: +65 6224 0010 Fax: +65 6224 0030  
Operating Hours: Monday to Friday 9am to 5pm  
GST Registration No: M400017735

## Third Party Insurer Enquiry

Our Ref No: GR-18-000536  
Date of Request: 02/01/2018

Your Ref No: Online Purchase

Performance Motors Limited  
303 Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941

Dear Sir/Madam,

Enquiry Date: 02/01/2018  
Enquiry By: THEMIS ALLIANCE  
TP Vehicle No: SKN126S  
Accident Date: 24/12/2017**Enquiry Result**

TP Vehicle No.	Insurer	Period of Insurance	Insurer Tel. No.
SKN126S	ECICS Limited	01/08/2017-31/07/2018	63374779 /6303 0178

Thank You.

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

This is a computer generated document and requires no signature.

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE  
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580  
Phone: +65 6224 0010 Fax: +65 6224 0030  
Operating Hours: Monday to Friday 9am to 5pm  
GST Registration No: M400017735

**TAX INVOICE**

Our Ref No: GR-18-000536  
Date of Request: 02/01/2018

Your Ref No: Online Purchase

Performance Motors Limited  
303 Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941

Dear Sir/Madam,

Enquiry Date 02/01/2018  
Enquiry By THEMIS ALLIANCE  
TP Vehicle No. SKN126S  
Accident Date 24/12/2017

DESCRIPTION	AMOUNT (S\$)
TP Insurer Enquiry	1.87
GST Amount	0.13
Total Amount Due (GST Inclusive)	2.00

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

☒ GIRO ☐ Cash ☐ Cheque



# Performance Motors Limited

A member of the Sime Darby Group



## LETTER OF AUTHORISATION

ACCIDENT INVOLVING SDW8128Z & PKN128S ON 24/12/17.


I, Ms Tay Bee Leng owner of Vehicle Registration No. SDW8128Z hereby authorise **Performance Motors Limited** to submit, correspond, negotiate and settle my claim for cost of repair and/or uninsured losses arising from the above accident.

I further authorise **Performance Motors Limited** to execute, sign, seal and deliver all documents whatsoever in relation to this matter and to accept and receive any payment due to me in respect of my claim above.


I hereby declare that all acts and documents done by virtue of this Letter of Authorisation on my behalf shall be good valid and effectual to all intents and purposes whatsoever as if the same had been done or executed by me in person.

I further confirm that the acceptance by **Performance Motors Limited** of the settlement amount in respect of such claim shall constitute the full discharge of my claim in respect of such loss and damage.

Signed by:

4   
Name: TAY BEE LENG (Date) 30/12/17  
NRIC No.: 57305042A

In the presence of:

  
Name: \_\_\_\_\_ (Date) 30/12/17  
NRIC No.: \_\_\_\_\_



Your ref: Please advise  
Our ref: DMPC1700778H

BY FAX: 6479 4601 & POST

22 March 2018

WITHOUT PREJUDICE  
SAVE AS TO COSTS

M/s Performance Motors Limited  
303 Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941

Dear Sirs,

**ACCIDENT INVOLVING SKN 126S & SJW 8128Z ON 25.12.2017**

We refer to the above accident & acknowledged receipt of your enclosures documents dated 9 March 2018.

We are currently investigating & shall revert to you substantively soon either on our decision or an offer for a settlement once we have gathered sufficient information and receiving all the relevant documents to support on your client's claim.

To enable us to proceed further into this matter, kindly let us have the following require documents for our perusal and action:-

- The CCTV video footage/ Colour photographs of damage and the accident scene of all vehicles.
- The Final Police Investigation result, if any.
- Any witness statement available, if any.
- All the receipt of the original payment made.

For all future correspondences pertaining to this case, please quote our claim reference number in order for us to revert to you expeditiously.

Meanwhile, please hold your hands on any intending to escalate the matter, if you have any further queries, please call the undersigned and we will be most happy to assist you.

Yours faithfully,

Lionel Chua  
Operation & Claims  
DID: 6303 0167  
Fax: 6338 9267

## Shu Pei (LKKAUTO)

---

**From:** ECICS Claims <claims@ecics.com.sg>  
**Sent:** Wednesday, 3 January, 2018 10:16 AM  
**To:** Shu Pei (LKKAUTO)  
**Cc:** ECICS Claims; Lionel Chua Kok Keong (ECICS, Claims); Carrie Tan Chi Hui (ECICS, Claims); Janice Goh Siew Geok (ECICS, Claims); Phoebe Jay Xie (ECICS, Claims); Admin A; Asher Sng (LKKAUTO)  
**Subject:** RE: Direct Settlement - Accident Involving SKN126S (OI : ICS - TBA) and SJW8128Z (TP : LKK REF - CC3/ICS18000050/eb3) on 24.12.2017  
**Attachments:** TP GIA REPORT.PDF; TP ESTIMATE.tif; SAS2333035.pdf

Without Prejudice

Our claim no. DMPC1700778H

Dear Shu Pei,

We attached a copy of our insured's GIA report that you have requested for your attention.

Thank you.

Regards,  
Lionel Chua  
DID: +65 6303 0167  
FAX: +65 6338 9267  
**ECICS LIMITED**  
Email: [claims@ecics.com.sg](mailto:claims@ecics.com.sg)

follow us on  facebook   follow us on  twitter   visit our website [ecics.com.sg](http://ecics.com.sg) 

---

**From:** Shu Pei (LKKAUTO) [mailto:shupeil@lkkauto.com]  
**Sent:** Tuesday, 2 January, 2018 6:14 PM  
**To:** ECICS Claims  
**Cc:** Lionel Chua Kok Keong (ECICS, Claims); Carrie Tan Chi Hui (ECICS, Claims); Janice Goh Siew Geok (ECICS, Claims); Phoebe Jay Xie (ECICS, Claims); Admin A; Asher Sng (LKKAUTO)  
**Subject:** Direct Settlement - Accident Involving SKN126S (OI : ICS - TBA) and SJW8128Z (TP : LKK REF - CC3/ICS18000050/eb3) on 24.12.2017

### WITHOUT PREJUDICE

Dear Sir / Madam,

We refer to the above matter.

This is a TP direct settlement case at M/s Performance Motors Limited.

Enclosed for your perusal is:

- TP GIA report
- TP estimated cost of repair

Meanwhile, kindly let us have a copy of your insured's GIA report for our necessary action.

Kindly take note that the case handler in-charge Asher and she can be contacted at DID: 6841 6051.

Thank you.

Best Regards,

**Shu Pei | Admin**

**LKK Auto Consultants Pte Ltd**

Phone: 6366-0055 | email: [shupeil@lkkauto.com](mailto:shupeil@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

<input type="checkbox"/> <small>Reply</small>	<input type="checkbox"/> <small>Reply</small>	<input type="checkbox"/> <small>Reply</small>
---	---	---

This message may contain privileged and confidential information and is only intended for use by the addressee. No representation, warranty, guarantee or undertaking expressed or implied is made by ECICS Limited; as to the fairness, accuracy or completeness of any information, projections or opinions contained in this message. Any unauthorized disclosure, use or dissemination either in whole or in part is prohibited. If you are not the addressee indicated in this message (or responsible for delivery of the message to such person), you may not copy or deliver this message to anyone. In such case, you should destroy this message and kindly notify the sender by reply email. Opinions contained herein are the personal opinions of the sender and do not necessarily represent the views of ECICS Limited.

## Asher Sng (LKKAUTO)

---

**From:** Crystabelle Tan Gek Peng (ECICS, Claims) <Crystabelle\_Tan@ecics.com.sg>  
**Sent:** Friday, 7 December 2018 11:00 AM  
**To:** Asher Sng (LKKAUTO); Shu Pei (LKKAUTO)  
**Cc:** Admin A  
**Subject:** RE: Direct Settlement - Accident Involving SKN126S (OI : ICS - TBA) and SJW8128Z (TP : LKK REF - CC3/ICS18000050/eb3) on 24.12.2017 (Ref : DMPC1700778H/CT)

Dear Asher

TP has forwarded the LOD to us since March'2018 and no settlement at your end.

As this case has been dragging for months, we will liaise with TP directly.

Please submit report survey in order for us to close case.

Best regards,  
Crystabelle Tan  
Claims Division  
DID: +65 6303 0190  
FAX: +65 6338 9267  
Email: [crystabelle\\_tan@ecics.com.sg](mailto:crystabelle_tan@ecics.com.sg)

ECICS Limited  
10 Eunos Road 8, Singapore Post Center #09-04A, Singapore 408600

---

**From:** Asher Sng (LKKAUTO) [mailto:[AsherSng@lkkauto.com](mailto:AsherSng@lkkauto.com)]  
**Sent:** Friday, 7 December, 2018 9:37 AM  
**To:** Crystabelle Tan Gek Peng (ECICS, Claims); Shu Pei (LKKAUTO)  
**Cc:** Admin A  
**Subject:** RE: Direct Settlement - Accident Involving SKN126S (OI : ICS - TBA) and SJW8128Z (TP : LKK REF - CC3/ICS18000050/eb3) on 24.12.2017 (Ref : DMPC1700778H/CT)

Hi Crystabelle,

We refer to the email below.

We are preparing our report to seek approval from your end.

Thank You.

Best Regards,

Asher Sng | Case Handler

LKK Auto Consultants Pte Ltd

phone: 6841-6051 | email: [asher.sng@lkkauto.com](mailto:asher.sng@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

**From:** Crystabelle Tan Gek Peng (ECICS, Claims) <Crystabelle\_Tan@ecics.com.sg>  
**Sent:** Thursday, 6 December 2018 3:40 PM  
**To:** Shu Pei (LKKAuto) <shupeil@lkkauto.com>  
**Cc:** Admin A <admin-a@lkkauto.com>; Asher Sng (LKKAuto) <AsherSng@lkkauto.com>  
**Subject:** RE: Direct Settlement - Accident Involving SKN126S (OI : ICS - TBA) and SJW8128Z (TP : LKK REF - CC3/ICS18000050/eb3) on 24.12.2017 (Ref : DMPC1700778H/CT)

Dear Shu Pei

Please submit survey report.

Best regards,  
Crystabelle Tan  
Claims Division  
DID: +65 6303 0190  
FAX: +65 6338 9267  
Email: [crystabelle\\_tan@ecics.com.sg](mailto:crystabelle_tan@ecics.com.sg)

**ECICS Limited**  
**10 Eunus Road 8, Singapore Post Center #09-04A, Singapore 408600**

---

**From:** Shu Pei (LKKAuto) [<mailto:shupeil@lkkauto.com>]  
**Sent:** Tuesday, 16 January, 2018 6:28 PM  
**To:** ECICS Claims  
**Cc:** Lionel Chua Kok Keong (ECICS, Claims); Carrie Tan Chi Hui (ECICS, Claims); Janice Goh Siew Geok (ECICS, Claims); Phoebe Jay Xie (ECICS, Claims); Admin A; Asher Sng (LKKAuto)  
**Subject:** RE: Direct Settlement - Accident Involving SKN126S (OI : ICS - TBA) and SJW8128Z (TP : LKK REF - CC3/ICS18000050/eb3) on 24.12.2017

**WITHOUT PREJUDICE**

Dear Sir / Madam,

We refer to the above matter.

We had inspected TP vehicle SJW 8128Z at M/s Performance Motors Limited.

Enclosed for your perusal is:

- Estimated cost of repair
- Preliminary advice

Thank you

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: [shupeil@lkkauto.com](mailto:shupeil@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

**From:** ECICS Claims [mailto:claims@ecics.com.sg]

**Sent:** Wednesday, 3 January 2018 10:16 AM

**To:** Shu Pei (LKKAUTO) <shupe@lkkauto.com>

**Cc:** ECICS Claims <claims@ecics.com.sg>; Lionel Chua Kok Keong (ECICS, Claims) <Lionel\_Chua@ecics.com.sg>; Carrie Tan Chi Hui (ECICS, Claims) <Carrie\_Tan@ecics.com.sg>; Janice Goh Siew Geok (ECICS, Claims) <Janice\_Goh@ecics.com.sg>; Phoebe Jay Xie (ECICS, Claims) <PhoebeJay\_Xie@ecics.com.sg>; Admin A <admin-a@lkkauto.com>; Asher Sng (LKKAUTO) <AsherSng@lkkauto.com>

**Subject:** RE: Direct Settlement - Accident Involving SKN126S (OI : ICS - TBA) and SJW8128Z (TP : LKK REF - CC3/ICS18000050/eb3) on 24.12.2017

Without Prejudice

Our claim no. DMPC1700778H

Dear Shu Pei,

We attached a copy of our insured's GIA report that you have requested for your attention.

Thank you.

Regards,

Lionel Chua

DID: +65 6303 0167

FAX: +65 6338 9267

**ECICS LIMITED**

Email: [claims@ecics.com.sg](mailto:claims@ecics.com.sg)

follow us on  
facebook



follow us on  
twitter



visit our website  
[ecics.com.sg](http://ecics.com.sg)



---

**From:** Shu Pei (LKKAUTO) [mailto:shupe@lkkauto.com]

**Sent:** Tuesday, 2 January, 2018 6:14 PM

**To:** ECICS Claims

**Cc:** Lionel Chua Kok Keong (ECICS, Claims); Carrie Tan Chi Hui (ECICS, Claims); Janice Goh Siew Geok (ECICS, Claims); Phoebe Jay Xie (ECICS, Claims); Admin A; Asher Sng (LKKAUTO)

**Subject:** Direct Settlement - Accident Involving SKN126S (OI : ICS - TBA) and SJW8128Z (TP : LKK REF - CC3/ICS18000050/eb3) on 24.12.2017

**WITHOUT PREJUDICE**

Dear Sir / Madam,

We refer to the above matter.

This is a TP direct settlement case at M/s Performance Motors Limited.

Enclosed for your perusal is:

- TP GIA report
- TP estimated cost of repair

Meanwhile, kindly let us have a copy of your insured's GIA report for our necessary action.

Kindly take note that the case handler in-charge Asher and she can be contacted at DID: 6841 6051.

Thank you.

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: [shupeil@lkkauto.com](mailto:shupeil@lkkauto.com) | fax: 6741-4108

Blk S1, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
--------------------------	--------------------------	--------------------------

This message may contain privileged and confidential information and is only intended for use by the addressee. No representation, warranty, guarantee or undertaking expressed or implied is made by ECICS Limited; as to the fairness, accuracy or completeness of any information, projections or opinions contained in this message. Any unauthorized disclosure, use or dissemination either in whole or in part is prohibited. If you are not the addressee indicated in this message (or responsible for delivery of the message to such person), you may not copy or deliver this message to anyone. In such case, you should destroy this message and kindly notify the sender by reply email. Opinions contained herein are the personal opinions of the sender and do not necessarily represent the views of ECICS Limited.



**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

**Affiliated to Federation Internationale Des Experts En Automobile**

ECICS LTD

Ref : CC3/ICS18000050/T1eb3q2

7 TEMASEK BOULEVARD  
#10-01 SUNTEC TOWER ONE  
SINGAPORE 038987

Date : 14-12-2018



Code : ICS

**1. Policy Particulars :- THIRD PARTY CLAIM**

Insured Veh.	SKN 126S	Veh. Inspected	SJW 8128Z
Policy No.	MPC17B00039202	Coverage (\$)	0.00
Claim No.	DMPC1700778H	Excess (\$)	0.00
Assign From		Assign Date	15/01/2018

**2. Vehicle Particulars & Condition**

Make & Model	B.M.W. X3	c.c	1997
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	WBAWY920100R99715	Colour	BLACK
Odometer	30495	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

**3. Conditions of Tyres**

	Size	Make	Balance
R/H Front Tyre	245/50 R18	PIRELLI	6 mm
L/H Front Tyre	245/50 R18	PIRELLI	6 mm
R/H Rear Tyre	245/50 R18	PIRELLI	6 mm
L/H Rear Tyre	245/50 R18	PIRELLI	6 mm

**4. Description of Damages**

THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY. DAMAGES SEE DETAILS.
--

**5. General Information**

Accident Date	25/12/2017	Inspection Date	15/01/2018
Survey held at	PERFORMANCE MOTORS LTD 303 ALEXANDRA ROAD SINGAPORE 159941		

**5a. Remarks**

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

**5b. Estimate Days of Repair**

ESTIMATED NORMAL PERIOD FOR REPAIR:	<b>5 Working Days</b>
-------------------------------------	-----------------------



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJW 8128Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
1	SUNDRIES (SN)	NECESSARY	80.00	80.00
1	RR LH DOOR (SN)	BENT	1,387.40	1,387.40
8	CLIP (SN)	NOT NECESSARY	100.00	-
4	CLIP (SN)	NOT NECESSARY	60.40	-
1	IMPACT STRIP DOOR FRT LH (M) (SN)	NOT NECESSARY	145.70	-
1	MOULDING DOOR REAR LH (M) (SN)	NOT NECESSARY	151.60	-
1	OUTER WEATHERSTRIP RR LH DOOR (ALU) (SN)	NOT NECESSARY	105.35	-
1	SIDE WINDOW FIXED GREEN RR LH (SN)	NOT NECESSARY	171.60	-
8	CLIP (SN)	NOT NECESSARY	9.20	-
1	COVER WHEEL ARCH RR LH (M) (SN)	NOT NECESSARY	215.05	-
1	(DG/SL) W/SCREEN SEALANT (COLD 1 HOUR) (SN)	NOT NECESSARY	131.55	-
1	DOOR WEATHERSTRIP REAR (ADDITIONAL) (SN)	NECESSARY	142.35	142.35
1	FRT LH MOULDING ROCKER PANEL (X LIN) (ADDITIONAL) (SN)	CUT	150.00	150.00
1	RH LH MOULDING ROCKER PANEL (X LINE) (ADDITIONAL) (SN)	CUT	120.00	120.00
			2,970.20	1,879.75
<b>LABOUR</b>				
TO REMOVE AND INSTALL REAR LH DOOR FIXED WINDOW GLASS TO FACILITATE REPAIRS.(ADDITIONAL)			413.00	413.00
TO CONDUCT CHECKS ON ALL DOORS AND BOOT LID CENTRAL LOCKING SYSTEM FOR PROPER FUNCTION. (ADDITIONAL)			150.00	150.00
TO REPLACE LEFT REAR DOOR ,AND REMOVE AND INSTALL FRONT DOOR AND ATTACHMENT INCLUDE KNOCKING CAUSE BY THE ACCIDENT .			2,550.00	1,700.00
PAINTING LEFT FRONT DOOR ,LEFT REAR DOOR .			2,076.00	1,868.00
TO TRANSFER LOCK MECHANISM FROM OLD TO NEW DOOR INCLUDING CONDUCT CHECKS ON NEW DOOR POWER WINDOW SYSTEM FOR PROPER FUNCTION. (1 DOOR).			531.00	451.00
TO CARRY OUT BODY CAVITY PRESERVATION.(PER PANEL).			118.00	100.00

Report Ref No. CC3/ICS18000050/T1eb3q2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO SUPPLY AND INSTALL REAR LEFT WINDOW QUARTER GLASS SOLAR FILM.	NOT NECESSARY	425.00	-
			6,263.00	4,682.00
GRAND TOTAL			9,233.20	6,561.75
RECOMMENDED COST OF REPAIRS				6,561.75

Report Ref No. CC3/ICS18000050/T1eb3q2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.