

22/03/2002

ASS. REC. BY:

REF:

CS MSG18000059 Krbz

Special instruction:

Sub Voucher:

ASSIGNMENT (Office)

From (Person): Pearllyn Kang

of

MSG

Date/Time:

2/1/2018

Estimated Cost:

\$11,911.70

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

STZ 3237 J

Insured:

at Workshop m/s

Lai Huet Meng Kee

Tel:

64538110

of 160 S/M #04-01

Policy No:

27843959 MCX

Claim No:

543536

Sum Insured:

Excess:

3500/-

Make of Veh:

(Client's Record)

D.O.A.

28/12/17

CA **REV** / REP. / REV 24 HRS

3/1/2018

H.O.D. Endorsement:

Date/Time:

2/1

Person Contacted:

Jenny

Vehicle **IN** / OUT

Date/Time

Action/Instruction () Estimate

To check on the tyres and brakes.

3/1/17

Repairer (Jenny) inform they agree to repair at 2/1 \$5,800

3/1/17

Revert to MSIB, seek mandate

4/1/17

Mandate approve inform repairer authorize repair & excess

REF:

MSG CS/MSG18000039/Krb

ASSIGNMENT

From

Date

Estimated Cost:

☒ TP / WS / TP RES / OD RES / EVA / INV / MVTo inspect Vehicle No: 8JZ3237Jat Workshop no: Lai Huat (Meng Kee)

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

3500/-

(Client's Record)

Make of Veh

3/1/2018 Morning

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
NS	OS
<input type="checkbox"/>	<input type="checkbox"/>

Bal. or Market Value:

8776

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

10 days

Res: Yes or No

Lump Sum:

%

3 Val: Yes or No

CA / ☒ REV / REP. / 24 HRS

Vehicle: IN / OUT

Date

Person Contacted:

Van No

STZ 3237J Page 09 ofType: ☒ M. Car / ☐ M. Cycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Prime Mover

Truck / Trailer or

Make:

Honda Civicto 1799

Colour:

M. P. White

A/C Insured / Std / Nil / NA

Sp. Reading

188178

T. Radio Insured / Std / Nil / NA

Eng. No:

C. No.

JHMF016308S 219733Gen. Cond. ☒ Good / ☐ Fair / ☐ Poor / ☐ BurntSteering: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt orBrake: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt orModi: Nil / ☒ S/Rim / ☐ STD A/Rim or

Tyre Size

F:

R:

215/45R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Dayton

Front

Rear

R. Bal.

S

mm

R. Bal.

S

mm

L. Bal.

S

mm

L. Bal.

S

mm

D.O.A.

28/12/17.

D.O.A.

3/1/18

Survey held at:

Des. of Damages: ☒ Frt / ☐ Rear / ☐ O/S / ☐ N/S / ☐ U/C / ☐ Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date Time Action Instruction

4/1/18 Check on the tyres and brakes.
File pass to Catherine5/1/18 According to Jenny, Owner decide scratch the vehicle10/1/18 Submit prelim report

RECEIVED 10 JAN 2018

Date/Time File Passed to:



Prelim. Report

Days Of Repair:

typist



Final Report

Resurvey No. of Trip:

Date/Time File Returned to:

Survey Fee

Transportation

Lump Sum

Fees

Other

Total

Add Fee:



Site Insp \$



Inspection \$



Technical \$



Resurvey \$

Report Format:

OD

Lump Sum J.B.K. \$

30010310




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MSIG INSURANCE (SINGAPORE) PTE LTD		Ref : CS/MSG18000059/Krb		
16 RAFFLES QUAY #24-01 HONG LEONG BLDG SINGAPORE 048581		Date : 02-01-2018		
		Code : MSG		
1. Policy Particulars :- OWN DAMAGE				
Insured Veh.		Veh. Inspected		SJZ 3237J
Policy No. 543536		Coverage (\$)		0.00
Claim No. 27843959MCX		Excess (\$)		0.00
Assign From PEARLLYN KANG		Assign Date		02/01/2018
2. Vehicle Particulars & Condition				
Make & Model		c.c		
Engine No.		Year of Reg.		
Chassis No.		Colour		
Odometer		Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date 28/12/2017		Inspection Date		
Survey held at				
5a. General Remarks				

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	29 Dec 2017 17:05 Sendback Est	02 Jan 2018 11:19 S\$11,911.70	02 Jan 2018 11:42 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS

Insured:	STARHIGH ASIA PACIFIC (PTE. LTD.), Co. Reg. No.: 200618190W, Tel: +6594306892		
Vehicle Reg. No.:	SJZ3237J	Date of Loss:	28/12/2017 23:00 - :59
Claim Type:	OD	Policy/Cover Note No.:	27843959MCX (Comprehensive) Coverage: 01/03/2017 - 28/02/2018
		Excess:	S\$3,500.00
Repairer:	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming) 160 Sin Ming Drive #04-01, Sin Ming AutoCity, 575722 Sin Ming - Tel: 64538110		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Pearlyn Kang Yen Lin - 6594 2588]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 03/01/2018]		
Driver/Custodian:	TANG YU KIANG (DONG YOUQIAN) (33 / Male), NRIC: S8416404F, Tel: +6598765339		
Adj Asg. Remarks:	Car in. Please survey and revert. Do help to check on the tyres and brakes. Thank you.		

ASSOCIATED MAIL RECEIVED

View All

Compose Case Mail

There are no mail for this case.



ALL ASSOCIATED TASKS

View All

Search Tasks

Create New Task

Complete

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Veh la
3/1/18 Morning

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Pearllyn Kang Yen Lin

Date: 03 Jan 2018

Preliminary Advice

Vehicle No	: SJZ3237J	Accident Date	: 28/12/2017
Make	: HONDA CIVIC	Policy No.	: 27843959MCX
Assignment Date	: 02/01/2018	Excess	: S\$3,500.00
Date of Inspection	: 03/01/2018	Est. Duration of Repair	: 10.00
Inspection At	: LAI HUAT (MENG KEE) MOTOR PTE LTD (SIN MING) 160 SIN MING DRIVE #04-01, SIN MING AUTOCITY SINGAPORE 575722		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	11,911.70
Revised Amount	:S\$	10,657.10
Check Items (Estimated)	:S\$	1,184.60
Total	:S\$	11,841.70

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	17,000.00
COE / PARF Rebate	:S\$	11,180.00
Salvage Value	:S\$	
Margin for Repair	:S\$	5,820.00

Remarks

(X) The vehicle is economical/not economical for repair.

Pending repair cost from repairer.

() The above survey was conducted on a 'without prejudice' basis.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Pearlyn Kang Yen Lin

Date: 03 Jan 2018

Preliminary Advice

Vehicle No	: SJZ3237J	Accident Date	: 28/12/2017
Make	: HONDA CIVIC	Policy No.	: 27843959MCX
Assignment Date	: 02/01/2018	Excess	: S\$3,500.00
Date of Inspection	: 03/01/2018	Est. Duration of Repair	: 10.00
Inspection At	: LAI HUAT (MENG KEE) MOTOR PTE LTD (SIN MING) 160 SIN MING DRIVE #04-01, SIN MING AUTOCITY SINGAPORE 575722		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	11,911.70
Revised Amount	:S\$	10,657.10
Check Items (Estimated)	:S\$	1,184.60
Total	:S\$	11,841.70

Lump Sum Repair(Estimated)	:S\$	5,800.00
----------------------------	------	----------

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	17,000.00
COE / PARF Rebate	:S\$	11,180.00
Salvage Value	:S\$	
Margin for Repair	:S\$	5,820.00

Remarks

(X) The vehicle is economical for repair. The repairer agree to repair at Lump Sum not more than \$5,800.00.

Brake in order and tyres is serviceable condition.

() The above survey was conducted on a 'without prejudice' basis.

Print Received Message

This mail is associated with :

SJZ3237J (543536)

OD

Dec 28 2017 11:00PM

[STARHIGH ASIA PACIFIC (PTE. LTD.)]

Lai Huat (Meng Kee) Motor Pte Ltd

From MSIG Insurance (Singapore) Pte. Ltd. (MSIG_SG), sent on 04/01/2018 11:33 AM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$5800.00) - SJZ3237J - Claim Handler: Pearlyn Kang Yen Lin

Approved:5800.00:lumpsum repair including supplementary parts and check items at \$5.8k before \$3.5k excess

Janice Lee (LKKAuto)

From: Jenny Lim <jenny.lim@laihuat.com.sg>
Sent: Friday, January 05, 2018 11:09 AM
To: Janice Lee (LKKAuto)
Subject: RE: SJZ 3237J MSIG OD DOA : 28.12.2017

Hi Janice

This is to inform you that our client's decided to scrap the car.

Please close your file accordingly.

Thank you.

Kind regards.

Jenny Lim
for LAI HUAT (MENG KEE) MOTOR PTE LTD
160 Sin Ming Drive
#04-01, #04-02 & #07-03
Sin Ming Autocity
Singapore 575722
Tel: 64538110
Fax: 64596267

From: Janice Lee (LKKAuto) [mailto:JaniceLee@lkkauto.com]
Sent: Thursday, 4 January, 2018 2:33 PM
To: jenny.lim@laihuat.com.sg
Cc: SUR
Subject: SJZ 3237J MSIG OD DOA : 28.12.2017

Dear Sir,

As instructed by our client, please proceed to repair the insured vehicle **SJZ 3237J (excess \$3,500/-)**. Please note that **repair cost Lump Sum not more than \$5,800 (before excess)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Thank you.

Best Regards,

Janice Lee (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: janicelee@lkkauto.com | fax: 6256-4315

Enquire PARF/COE Rebate for Registered Vehicle

DOA: 28/11/17
(MSIG)

Vehicle Owner Particulars

Owner ID Type: Company
Owner ID: 8190W

Vehicle Details

Vehicle No.: SJZ3237J
Vehicle to be Exported: No
Intended De-registration Date: 02 Jan 2018
Vehicle Make: HONDA
Vehicle Model: CIVIC 1.8L A
Primary Colour: White
Manufacturing Year: 2008
Engine No.: R18A13042465
Chassis No.: JHMF16308S219733
Maximum Power Output: 103.0 kW (138 bhp)
Open Market Value: \$20,479.00
Original Registration Date: 01 Sep 2008
First Registration Date: 01 Sep 2008
Transfer Count: 3
Actual ARF Paid: \$20,479.00

16-18

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 31 Aug 2018
PARF Rebate Amount: \$10,239.00

Intended COE Rebate Details

COE Expiry Date: 31 Aug 2018
COE Category: B - Car (1601cc & above)

COE Period(Years): 10

QP Paid: \$14,235.00

COE Rebate Amount: \$941.00

Total Rebate Amount: \$11,180.00

The information contained herein is correct as at 02 Jan 2018

OK

來發(明記)摩哆有限公司 LAI HUAT (MENG KEE) MOTOR PTE LTD

Sin Ming Autocity
160 Sin Ming Drive #04-01/#04-02/#07-03 Singapore 575722
Tel: 64538110 Fax: 64596267 Email: info@laihuat.com.sg
UEN: 199407592C

INSURER: MSIG Insurance (Singapore) Pte. Ltd. (HQ)

PARTICULARS OF CLAIM

Claim Type:	OD (Own Damage)	Ref. No:	69109
Policy No:	27843959MCX	Date of Loss:	28/12/2017
Vehicle Reg. No.:	SJZ3237J	Driveable?	
Driver Age/Info:	33 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	STARHIGH ASIA PACIFIC (PTE. LTD.)	Contact No:	+6594306892
Driver:	TANG YU KIANG (DONG YOUQIAN)		

Make/Model:	HONDA CIVIC, 1.8 L (A)	Vehicle Reg. Date:	01/09/2008
Vehicle Colour:	White	Chassis No:	JHMF16308S219733
Engine No:	R18A13042465		
Odometer:	0 KM		

Paint Type:
Total Loss? **NO**
Est. Duration of Repair (day) 10 ✓

Fax: 62584315

FM
Not Authorized
11/12/17
Runny After Paint
Ex 835001

Description of Accident/Loss: I WAS DRIVING ALONG BALESTIER ROAD TOWARDS MOULMEIN ROAD. I HAD JUST SWITCHED FROM THE RIGHT MOST LANE TO THE MIDDLE, CHECKED THAT EVERYTHING WAS CLEAR. AS I WAS GOING THROUGH THE YELLOW BOX, I NOTICED THE RED CAR (SLM 8300X) IN FRONT OF ME TURNING FROM THE OPPOSITE DIRECTION INTO THE CTE AND I FLOORED THE BRAKES. I COULD NOT STOP IN TIME AND THE CARS COLLIDED.

Present Location: LAI HUAT (MENG KEE) MOTOR PTE LTD (SIN MING) / VICTOR FAN

COST OF CLAIMS

	Amount
Parts	9,491.70
Miscellaneous Items	0.00
Labour	1,420.00
Paintwork Labour	1,000.00
Towing	0.00
Calculated Gross Total (\$\$)	11,911.70
- Excess (\$\$)	3,500.00
(\$\$)	8,411.70
+ GST 7.00% (\$\$)	588.82

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Nett Amount (S\$) 9,000.52

This claim is handled by: VICTOR FAN

Generated using **Merimen e-Claims Internet Estimation & Adjusting System**

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 02 Jan 2018)
Parts: 143 HONDA CIVIC 1.8 L (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's (Price-denominated Standard List)
Print Code: Lai Huat (Meng Kee) Motor Pte Ltd/SJZ3237J/02/01/2018 11:19
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount	
1	1		*Bonnet	0.00	0.00	B ₁ *290.00 F	✓
2	1		*Bonnet lock	0.00	0.00	B ₁ *55.00 F	✓
3	1		*Bonnet hinge LH	0.00	0.00	B ₁ *35.00 F	✓
4	1		*Bonnet hinge RH	0.00	0.00	B ₁ *35.00 F	✓
5	1		*Bonnet insulator	0.00	0.00	Refman *45.00 F	✓
6	1		*Front fender LH	0.00	0.00	B ₁ *150.00 F	✓
7	1		*Front fender RH	0.00	0.00	B ₁ *150.00 F	✓
8	1		*Front fender inner shield RH	0.00	0.00	T ₁ *48.00 F	✓
9	1		*Front bumper	0.00	0.00	C ₁ M ₁ *180.00 F	✓
10	1		*Front bumper reinforcement	0.00	0.00	B ₁ *140.00 F	✓
11	1		*Front bumper fog lamp LH	0.00	0.00	C ₁ M ₁ *180.00 F	✓
12	1		*Front bumper fog lamp RH	0.00	0.00	M ₁ *180.00 F	✓
13	1		*Front headlamp LH	0.00	0.00	C ₁ M ₁ *250.00 F	✓
14	1		*Front headlamp RH	0.00	0.00	C ₁ M ₁ *250.00 F	✓
15	1		*Radiator grille	0.00	0.00	M ₁ *38.00 F	✓
16	1		*Radiator grille chrome moulding	0.00	0.00	M ₁ *58.00 F	✓
17	1		*Front support panel	0.00	0.00	B ₁ *280.00 F	✓
18	1		*Front support panel top cover	0.00	0.00	M ₁ *32.00 F	✓
19	1		*Air con condenser	0.00	0.00	B ₁ *350.00 F	✓
20	1		*Air con suction pipe	0.00	0.00	B ₁ *115.00 F	✓
21	1		*Air con receiver pipe	0.00	0.00	B ₁ *120.00 F	✓
22	1		*Air con fan cowling	0.00	0.00	B ₁ *60.00 F	✓
23	1		*Air con fan blade	0.00	0.00	*38.00 F	?
24	1		*Air con fan motor	0.00	0.00	*105.00 F	?
25	1		*Radiator	0.00	0.00	*320.00 F	✓
26	1		*Radiator fan cowling	0.00	0.00	*65.00 F	?
27	1		*Radiator fan blade	0.00	0.00	*38.00 F	?
28	1		*Radiator fan motor	0.00	0.00	*180.00 F	?
29	1		*Power steering pipe	0.00	0.00	Ref *70.00 F	✓
30	1		*EGR pipe	0.00	0.00	*80.00 F	?
31	1		*Passenger airbag	0.00	0.00	Ref *680.00 F	✓
32	1		*Driver airbag	0.00	0.00	*1,250.00 F	✓
33	1		*Passenger seat belt	0.00	0.00	T ₁ *580.00 F	✓
34	1		*Driver seat belt	0.00	0.00	T ₁ *580.00 F	✓
35	1		*Airbag control unit	0.00	0.00	M ₁ *850.00 F	✓
36	1		*Front engine mounting LH	0.00	0.00	*95.00 F	?
37	1		*Front engine mounting RH	0.00	0.00	*150.00 F	?
38	1		*Front number plate garnish	0.00	0.00	M ₁ *15.00 F	✓
39	1		*o2 oxygen sensor lower	0.00	0.00	*235.00 F	?
40	1		*Steering coil spring	0.00	0.00	M ₁ *225.00 F	✓
41	1		*Front number plate	0	0.00	M ₁ *35.00 FS	✓

F=Franchise part. S=SpcNett.

Sub Total (\$\$) 8,632.00
 + Margin on L,N Items 10.00% (\$\$) 859.70

Total Parts (\$\$) 9,491.70

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
Paintwork Labour			
1	To spray paint	New	1,000.00 ✓
Labour Items			
2	To remove + renew engine mounting	New	100.00 ✓
3	To remove + renew airbag and safety belt, etc	New	200.00 ✓
4	To remove + renew air con condenser and refill gas	New	120.00 100 ✓
5	To erase fault code	New	50.00 ✓
6	To straighten front body chassis including cutting and welding, to knock dents on front chassis LH & RH and renew of parts	New	950.00 900 ✓
Gross Labour Cost (S\$)			2,420.00

Lai Huat (Meng Kee) Motor Pte Ltd/SJZ3237J/02/01/2018 11:19. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to our quotation
- Third party survey is on a 'no win, no fee' basis
- No illegal modification allowed
- Supplementary labour must be approved and is subject to final approval from insurance Company

Acknowledged by Repairer

Signature:

Date:

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	29/12/2017 11:27
Date Of Accident	28/12/2017 23:45
Exact Location Of Accident	JUNCTION OF BALESTIER ROAD & ENTRANCE INTO CTE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJZ3237J
Insured/Policyholder	
Name Of Registered Owner	STARHIGH ASIA PACIFIC (PTE. LTD.)
Co Reg No	20061890W
Email Address	YOUQIAN@STARHIGH.COM.SG
Mobile Phone No	(LOCAL) +65-98765339
Alternative Phone No	OFFICE-98765339

Vehicle Particulars

Manufacturer	HONDA
Model	CIVIC-1.8 L (A)

Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
--	-------------

Are you claiming under your own insurance policy for repair to your vehicle?	YES
--	-----

If No, Please state action to be taken

Vehicle Category	COMMERCIAL VEHICLE
------------------	--------------------

Insurance Company

Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	A27843959MCX
Cover Note Number	

Driver

Name of Driver	TANG YU KIANG (DONG YOUQIAN)
NRIC No	S8416404F
Date Of Birth	05/06/1984
Occupation	INDOOR
Date Of Driving Pass	24/03/2017
Driving Experience	0 YEAR AND 9 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-98765339
Fax Number	
Contact Number	
EMail Address	YOUQIAN@STARHIGH.COM.SG

Address	BLK 159A RIVERVALE CRESCENT #09-659
Postcode	541159
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - MAJOR/MINOR RD
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	YES
Number of Passengers (Including Driver)	2
Passenger 1	
	NAME: : ALICIA ALI MOOSA
	GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

I was driving along Balestier Road towards Moulmein Road. I had just switched from the right most lane to the middle, checked that everything was clear. As I was going through the yellow box, I noticed the red car (SLM 8300X) in front of me turning from the opposite direction into the CTE and I floored the brakes. I could not stop in time and the cars collided.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLM8300X
Vehicle Make/Model/Colour	TOYOTA / RED
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	CHEAH MEE YIN
NRIC/Passport Number	S7778050E
Contact Number	97459446
Address	
Postcode	
Insurance Company Name	AXA INSURANCE PTE LTD
Nature Of Damage	

No. Of Passenger (Including Driver)

1

Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature

Date & Time: 29 DEC 2017

11:30

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature


Name:

Deborah Lai

NRIC/FIN No.:


S7332811Z

REPUBLIC OF SINGAPORE **DRIVING LICENCE**



TANG YU KIANG
(DONG YOUQIAN)

05 Jun 1984
24 Mar 2017



002669192J

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S8416404F



Name

TANG YU KIANG
(DONG YOUQIAN)

董友乾

Race

CHINESE

Date of birth

05-06-1984

Sex

M

S8416404F

Country/Place of birth

SINGAPORE




YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

EFFECTIVE DATE

Class 3 Motor cars with unladen weight $\leq 3000\text{kg}$ with ≤ 7 passengers, exclusive of driver; and other motor vehicles with unladen weight $\leq 2500\text{kg}$ **24 Mar 2017**

NP 428A



Licence No: S8416404F

5480410



NRIC No. **S8416404F**



Date of issue

05-06-2015

Address

APT BLK 159A RIVERVALE CRESCENT
#09-659
SINGAPORE 541159

MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way, # 21-01, SGX Centre 2, Singapore 068807
Tel +65 6827 7888, Fax +65 6827 7800
Co. Reg. No. 200412212G GST Reg. No. 20-0412212G

Certificate of Insurance

ROAD TRANSPORT ACT 1987 (MALAYSIA)
THE MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1959 (FEDERATION OF MALAYSIA)
THE MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CAP. 189 OF THE REVISED EDITION)
(REPUBLIC OF SINGAPORE)
THE MOTOR VEHICLES (THIRD-PARTY RISK AND COMPENSATION) RULES, 1996 EDITION (REPUBLIC OF SINGAPORE)
OR ANY AMENDMENT, ACT OR ACTS PASSED IN SUBSTITUTION THEREOF.

Form M.X.4
Company Ownership

MOTORMAX-COMMERCIAL
Comprehensive

Certificate No. A 27843959 MCX

Excess : SGD500
Windscreen Excess : SGD100

1. Index Mark and Registration Number of Vehicle
SJZ3237J

2. Name of Policyholder
Starhigh Asia Pacific (Pte. Ltd.)

3. Effective Date of the Commencement of Insurance for the purposes of the Act
01/03/2017

4. Date of Expiry of Insurance
28/02/2018

5. Persons or Classes of Persons entitled to drive*

Any other person provided he is driving on the Policyholder's order or with the Policyholder's permission.

* Provided that the person driving is permitted in accordance with the licensing or other laws or laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

6. Limitations as to use*

Use only for social domestic and pleasure purposes and for the Policyholder's business.
The Policy does not cover use for hire or reward racing pace-making reliability trial speed-testing the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with the Motor Trade.

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

**PLEASE NOTE ALL CLAIMS RELATED REPAIR MUST BE CARRIED OUT AT ANY MSIG
AUTHORISED WORKSHOP LISTED IN THE ATTACHED.**

This Certificate is not transferable to a new owner of the vehicle. If for any reason the Policy is terminated during its currency, the Certificate must be returned to the Insurer within 7 days of the termination or if the Certificate has been lost or destroyed, a Statutory Declaration to that effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189).

I/WE HEREBY CERTIFY that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia) or any Amendment, Act or Acts passed in substitution thereof.

MSIG Insurance (Singapore) Pte. Ltd.
Approved Insurers


for Chief Executive Officer

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Company

Owner ID: 8190W

Vehicle Details

Vehicle No.: SJZ3237J

Vehicle to be Exported: No

Intended De-registration Date: 29 Dec 2017

Vehicle Make: HONDA

Vehicle Model: CIVIC 1.8L A

Primary Colour: White

Manufacturing Year: 2008

Engine No.: R18A13042465

Chassis No.: JHMF16308S219733

Maximum Power Output: 103.0 kW (138 bhp)

Open Market Value: \$20,479.00

Original Registration Date: 01 Sep 2008

First Registration Date: 01 Sep 2008

Transfer Count: 3

Actual ARF Paid: \$20,479.00

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 31 Aug 2018

PARF Rebate Amount: \$10,239.00

Intended COE Rebate Details

COE Expiry Date: 31 Aug 2018

COE Category: B - Car (1601cc & above)

COE Period(Years): 10

QP Paid: \$14,235.00

COE Rebate Amount: \$956.00

Total Rebate Amount: \$11,195.00

The information contained herein is correct as at 29 Dec 2017

OK

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	29 Dec 2017 Sendback Est	02 Jan 2018 11:19 S\$11,911.70	02 Jan 2018 11:42 Edit Adj Rpt	S\$10,657.10 Edit Estimates	S\$10,657.10 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
-------------	------------------	----------------------	------------------	-----------------

CLAIM SUBFOLDER DETAILS

Insured:	STARHIGH ASIA PACIFIC (PTE. LTD.), Co. Reg. No.: 200618190W, Tel: +6594306892		
Vehicle Reg. No.:	SJZ3237J	Date of Loss:	28/12/2017 23:00 - :59
Claim Type:	OD / 543536	Policy/Cover Note No.:	27843959MCX (Comprehensive) Coverage: 01/03/2017 - 28/02/2018
		Excess:	S\$3,500.00
Repairer:	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming) 160 Sin Ming Drive #04-01, Sin Ming AutoCity, 575722 Sin Ming - Tel: 64538110		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Pearllyn Kang Yen Lin - 6594 2588]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 01/02/2018]		
Driver/Custodian:	TANG YU KIANG (DONG YOUQIAN) (33 / Male), NRIC: S8416404F, Tel: +6598765339		
Adj Asg. Remarks:	Car in. Please survey and revert. Do help to check on the tyres and brakes. Thank you.		

ASSOCIATED MAIL RECEIVED
[View All](#)
[Compose Case Mail](#)


































- MSIG_SG (04/01/2018): Alert - Adj Mandate Approved (S\$5800.00) - SJZ3237J - Claim Handler: Pearllyn Ka...

ALL ASSOCIATED TASKS
[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

SJZ3237J (543536)
OD
Dec 28 2017 11:00PM
[STARHIGH ASIA PACIFIC (PTE. LTD.)]
Lai Huat (Meng Kee) Motor Pte Ltd

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)	Thumbnail	Print
1	29/12/17 16:08	Accident Statement	 Load HTM	
2	02/01/18 11:19	Repairer Estimates	 Load HTM	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	03/01/18 15:55	Adjuster Immediate Advice	 Load HTM	
2	03/01/18 17:23	Adjuster Immediate Advice	 Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)	Thumbnail	Print
1	30/12/17 10:11	Front View Right	 Load JPG	<input checked="" type="checkbox"/>
2	30/12/17 10:11	Front View	 Load JPG	<input checked="" type="checkbox"/>
3	30/12/17 10:11	Front View Left	 Load JPG	<input checked="" type="checkbox"/>
4	30/12/17 10:11	Front View	 Load JPG	<input checked="" type="checkbox"/>
5	30/12/17 10:11	Chassis Number	 Load JPG	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	10/01/18 15:24	General View	 Load JPG	<input checked="" type="checkbox"/>
2	10/01/18 15:24	General View	 Load JPG	<input checked="" type="checkbox"/>
3	10/01/18 15:24	General View	 Load JPG	<input checked="" type="checkbox"/>
4	10/01/18 15:24	General View	 Load JPG	<input checked="" type="checkbox"/>
5	10/01/18 15:24	General View	 Load JPG	<input checked="" type="checkbox"/>
6	10/01/18 15:24	General View	 Load JPG	<input checked="" type="checkbox"/>
7	10/01/18 15:24	General View	 Load JPG	<input checked="" type="checkbox"/>
8	10/01/18 15:24	General View	 Load JPG	<input checked="" type="checkbox"/>
9	10/01/18 15:24	General View	 Load JPG	<input checked="" type="checkbox"/>
10	10/01/18 15:24	General View	 Load JPG	<input checked="" type="checkbox"/>
11	10/01/18 15:24	General View	 Load JPG	<input checked="" type="checkbox"/>
12	10/01/18 15:24	General View	 Load JPG	<input checked="" type="checkbox"/>
13	10/01/18 15:24	General View	 Load JPG	<input checked="" type="checkbox"/>
14	10/01/18 15:24	General View	 Load JPG	<input checked="" type="checkbox"/>
15	10/01/18 15:24	General View	 Load JPG	<input checked="" type="checkbox"/>
16	10/01/18 15:24	General View	 Load JPG	<input checked="" type="checkbox"/>
17	10/01/18 15:24	General View	 Load JPG	<input checked="" type="checkbox"/>
18	10/01/18 15:24	General View	 Load JPG	<input checked="" type="checkbox"/>
19	10/01/18 15:24	General View	 Load JPG	<input checked="" type="checkbox"/>
20	10/01/18 15:24	General View	 Load JPG	<input checked="" type="checkbox"/>
21	10/01/18 15:24	General View	 Load JPG	<input checked="" type="checkbox"/>
22	10/01/18 15:24	General View	 Load JPG	<input checked="" type="checkbox"/>
23	10/01/18 15:24	General View	 Load JPG	<input checked="" type="checkbox"/>
24	10/01/18 15:24	General View	 Load JPG	<input checked="" type="checkbox"/>

25	10/01/18 15:24	General View	1	Load JPG	<input checked="" type="checkbox"/>
26	10/01/18 15:24	General View	1	Load JPG	<input checked="" type="checkbox"/>
27	10/01/18 15:24	General View	1	Load JPG	<input checked="" type="checkbox"/>
28	10/01/18 15:24	General View	1	Load JPG	<input checked="" type="checkbox"/>
29	10/01/18 15:24	General View	1	Load JPG	<input checked="" type="checkbox"/>
30	10/01/18 15:24	General View	1	Load JPG	<input checked="" type="checkbox"/>
31	10/01/18 15:24	General View	1	Load JPG	<input checked="" type="checkbox"/>
32	10/01/18 15:24	General View	1	Load JPG	<input checked="" type="checkbox"/>
33	10/01/18 15:24	General View	1	Load JPG	<input checked="" type="checkbox"/>
34	10/01/18 15:24	General View	1	Load JPG	<input checked="" type="checkbox"/>
35	10/01/18 15:25	General View	1	Load JPG	<input checked="" type="checkbox"/>
Documentation					
			1 per page	<input checked="" type="checkbox"/>	
No	Finalized On	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)	Thumbnail	Print	
1	30/12/17 11:07	E-filed GIA report	1	Load PDF	
2	30/12/17 11:07	Drivers NRIC + Driving License	1	Load PDF	
3	30/12/17 11:07	Certificate of Insurance	1	Load PDF	
4	30/12/17 11:07	Enquire PARF / COE Rebate for Registered Vehicle	1	Load PDF	
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print	
1	02/01/18 10:44	TP GIA Report	1	Load PDF	
2	02/01/18 10:44	Enquire Transfer Fee	1	Load PDF	
3	02/01/18 10:44	Enquire Rebate	1	Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print	
1	03/01/18 17:25	SJZ 3237J ESTIMATE	1	Load PDF	
2	10/01/18 15:08	EMAIL FROM REPAIRER: OWNER DECIDE TO SCRATCH THE VEHICLE	1	Load PDF	

Linked Accident Report Documents

			View	View in Browser	
Assessment Reports			1 per page	<input checked="" type="checkbox"/>	
No	Finalized On	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)	Thumbnail	Print	
1	29/12/17 16:08	Accident Statement	1	Load HTM	
Photos/Images					
			3 per page	<input checked="" type="checkbox"/>	
No	Finalized On	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)	Thumbnail	Print	
1	29/12/17 16:08	Accident Photo	1	Load JPG	<input checked="" type="checkbox"/>
2	29/12/17 16:08	Accident Photo	1	Load JPG	<input checked="" type="checkbox"/>
3	29/12/17 16:08	Accident Photo	1	Load JPG	<input checked="" type="checkbox"/>
4	29/12/17 16:08	Accident Photo	1	Load JPG	<input checked="" type="checkbox"/>
5	29/12/17 16:08	Chassis Number	1	Load JPG	<input checked="" type="checkbox"/>
Documentation					
			1 per page	<input checked="" type="checkbox"/>	
No	Finalized On	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)	Thumbnail	Print	
1	29/12/17 16:07	Sketch Plan	1	Load TIF	
2	29/12/17 16:07	Insurance Certificate	1	Load TIF	
3	29/12/17 16:07	Driver NRIC and Driving Licence	1	Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Repairer ☐ Handling Insurer
Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way, #21-01 SGX Centre 2
Singapore 068807

Our File No: CS/MSG18000059/KRBE2

Date: 15/01/2018

REFERENCE

Insured/Claimant: STARHIGH ASIA PACIFIC (PTE. LTD.)
Date of Loss: 28/12/2017

Policy No: 27843959MCX

Nature of Claim: OD Claim No: 543536

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJZ3237J**
Make & Model: HONDA CIVIC, 1.8 L (A) Engine No: R18A13042465
Reg. Date: 01/09/2008 (Man. Year: 2008) Chassis No: JHMFD16308S219733
Colour: Metallic Pearl White Odometer: 188178 km
Engine Capacity: 1799 cc
Market Value/New Car Price: S\$17,000.00
Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 215/45 R17 Rear Tyre Size: 215/45 R17
Front Left Side: Dayton 8 mm Rear Left Side: Dayton 8 mm
Front Right Side: Dayton 8 mm Rear Right Side: Dayton 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,491.70	8,407.10	1,084.60	11.43
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,420.00	1,250.00	170.00	11.97
Paintwork Labour	1,000.00	1,000.00	0.00	0.00
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	11,911.70	10,657.10	1,254.60	10.53
- Excess (\$\$)	3,500.00	3,500.00	0.00	0.00
(\$\$)	8,411.70	7,157.10	1,254.60	14.91
+ GST 7.00/7.00% (\$\$)	588.82	501.00	87.82	14.91
Nett Amount (\$\$)	9,000.52	7,658.10	1,342.42	14.91

INSPECTION

Date of Assignment: 02/01/2018 Present Location: Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)
Date Inspected: 03/01/2018 Inspected At: 160 Sin Ming Drive #04-01, Sin Ming AutoCity Singapore 575722
Estimated Period of Repair: 10.0 days

Adjuster: KENNETH KONG

Manager: Janice Lee Si Hua

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

(REPAIR COST NOT CONCLUDE)

(EXCLUDE CHECK ITEMS S\$1,184.60 NETT)

REPAIR DETAILS

Reference

Part Source: MRM-SG **Version:** 1.0 (Last Synchronised: 15 Jan 2018)

Parts: 143 **HONDA CIVIC 1.8 L (A) (Catalogue:Merimen Singapore 1.0)**

Labour: Repairer's **(Price-denominated Standard List)**

Print Code: (Unsubmitted, no print-code for SJZ3237J)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*Bonnet	Bent	290.00 F	*290.00 F
2	1		*Bonnet lock	Bent	55.00 F	*55.00 F
3	1		*Bonnet hinge LH	Distorted	35.00 F	*35.00 F
4	1		*Bonnet hinge RH	Bent	35.00 F	*35.00 F
5	1		*Bonnet insulator	Deformed	45.00 F	*45.00 F
6	1		*Front fender LH	Buckled	150.00 F	*150.00 F
7	1		*Front fender RH	Buckled	150.00 F	*150.00 F
8	1		*Front fender inner shield RH	Torn	48.00 F	*48.00 F
9	1		*Front bumper	Cracked	180.00 F	*180.00 F
10	1		*Front bumper reinforcement	Bent	140.00 F	*140.00 F
11	1		*Front bumper fog lamp LH	Cracked	180.00 F	*180.00 F
12	1		*Front bumper fog lamp RH	Missing	180.00 F	*180.00 F
13	1		*Front headlamp LH	Cracked	250.00 F	*250.00 F
14	1		*Front headlamp RH	Cracked	250.00 F	*250.00 F
15	1		*Radiator grille	Missing	38.00 F	*38.00 F
16	1		*Radiator grille chrome moulding	Missing	58.00 F	*58.00 F
17	1		*Front support panel	Bent	280.00 F	*280.00 F
18	1		*Front support panel top cover	Missing	32.00 F	*32.00 F
19	1		*Air con condenser	Bent	350.00 F	*350.00 F
20	1		*Air con suction pipe	Dented	115.00 F	*115.00 F
21	1		*Air con receiver pipe	Dented	120.00 F	*120.00 F
22	1		*Air con fan cowling	Distorted	60.00 F	*60.00 F
23	1		*Air con fan blade	* Check	38.00 F	*- F
24	1		*Air con fan motor	* Check	105.00 F	*- F
25	1		*Radiator	Housing Broken	320.00 F	*320.00 F
26	1		*Radiator fan cowling	* Check	65.00 F	*- F
27	1		*Radiator fan blade	* Check	38.00 F	*- F
28	1		*Radiator fan motor	* Check	180.00 F	*- F
29	1		*Power steering pipe	Dented	70.00 F	*70.00 F
30	1		*EGR pipe	* Check	80.00 F	*- F
31	1		*Passenger airbag	Burst	680.00 F	*680.00 F
32	1		*Driver airbag	Burst	1,250.00 F	*1,250.00 F
33	1		*Passenger seat belt	Jammed	580.00 F	*580.00 F
34	1		*Driver seat belt	Jammed	580.00 F	*580.00 F
35	1		*Airbag control unit	Necessary	850.00 F	*850.00 F
36	1		*Front engine mounting LH	* Check	95.00 F	*- F
37	1		*Front engine mounting RH	* Check	150.00 F	*- F
38	1		*Front number plate garnish	Missing	15.00 F	*15.00 F
39	1		*o2 oxygen sensor lower	* Check	235.00 F	*- F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
40	1		*Steering coil spring	Necessary	225.00 F	*225.00 F
41	1		*Front number plate	Missing	35.00 FS	*35.00 FS
					<hr/>	
Sub Total (S\$)					8,632.00	7,646.00
+ Margin on L,N Items 10.00/10.00% (S\$)					859.70	761.10
					<hr/>	
Total Parts (S\$)					9,491.70	8,407.10
					<hr/>	

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Paintwork Labour</u>				
1	To spray paint	New	1,000.00	1,000.00
<u>Labour Items</u>				
2	To remove + renew engine mounting (* Check)	New	100.00	0.00
3	To remove + renew airbag and safety belt, etc	New	200.00	200.00
4	To remove + renew air con condenser and refill gas	New	120.00	100.00
5	To erase fault code	New	50.00	50.00
6	To straighten front body chassis including cutting and welding, to knock dents on front chassis LH & RH and renew of parts	New	950.00	900.00
Gross Labour Cost (S\$)			2,420.00	2,250.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >