

ASS. REC. BY:

REF:

CS/MSA18000060/THber

Special Instruction:

Surveyor:

ASSIGNMENT (Office)From (Person): Jasmine Lok

of

MSIGDate/Time: 2/1/2018Estimated Cost: \$22,806.20

Bill to:

OD / ~~TP~~ DWS / TP RES / OD RES / EVA / INV / MV / CSTo Inspect Vehicle No: SLT 3560KInsured: STG 654Hat Workshop m/s Kah MotorTel: 90721769 Sin Haiof 255 Alexandra RdPolicy No: PJ7105154DMV

Claim No:

SH2H18

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 22/12/173/1/2018**CA / REV / REP. / REV 24 HRS**

H.O.D. Endorsement:

Date/Time: 2/1

Person Contacted:

Sin HaiVehicle **IN** / OUT

Date/Time	Action/Instruction () Estimate
	<u>SLT 3560K - X</u>
	<u>STG 654H - X</u>
	<u>Part by Part \$19,539.28 (Red: 4499.39 : 18%)</u>


Taufik

REF.

MSG

ASSIGNMENT

From: _____ Date: 3/1
Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
To inspect Vehicle No: SLJ 3560 K
at Workshop in: Kah Motor
of: 255 Alexandra Rd
Insured: _____
Policy No: _____
Claims No: _____
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____



(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: \$98K.
IDAC Accident Report: _____ Consistent?: Yes or No
GIA / FR Seen: _____ Consistent?: Yes or No
Est. Repairs: _____ days Res: Yes or No
Lum Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Sin Hai

Veh No: SLJ 3560 K Page: 20/6 Acc.
Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover
Truck / Trailer or
Make: Honda HRV do: 1496
Colour: white A/C: _____ Insured / Std / Nil / NA
So. Reading: 16786 T. Radio: Insured / Std / Nil / NA
Eng No: _____
C No: JHMR4/8/06X 201217
Gen. Cond: Good / Fair / Poor / Burnt
Steering: Inorder / Jammed / Leaked / Burnt or
Brake: Inorder / Jammed / Leaked / Burnt or
Modif: Nil / S/Rim / STD A/Rim or
Tyre Size: F: 215/60R16
R: 215/60R16
BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or
Front: _____ Rear: _____
R.Bal: 6 mm L.Bal: 6 mm
L.Bal: 6 mm L.Bal: 6 mm
D.O.A. 22/12/17 D.O.I. 03/01/18 @ 1/55
Survey held at: Kah Motor Alexandra
Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
The U/C / Chassis frame / Body Structure affected due to collision.

Date Time Action / Instruction 58297.

21/5/2018

RECEIVED 21 MAY 2018

Date Time File Pass to: ☐ Preli. Report

21/5 Typist ☒ Final Report

Date Time File Return to:

Days Of Repair: 14

Resurvey No. of Trip: _____

Survey Fee

Transportation

___ S - P. ___ S

Photo

Other

Add Fee: ☐ Site Insp. ___ S

☐ Interview ___ S

☐ Tech. Insp. ___ S

☐ Test & Rep. ___ S

Report Format: TP

Lump Sum / 19,539.28

300

10

310



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MSIG INSURANCE (SINGAPORE) PTE LTD		Ref : CS/MSG18000060/T1tb		
16 RAFFLES QUAY #24-01 HONG LEONG BLDG SINGAPORE 048581		Date : 02-01-2018		
		Code : MSG		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SJG 654H	Veh. Inspected	SLJ 3560K	
Policy No.	P27105154DMV	Coverage (\$)	0.00	
Claim No.	542418	Excess (\$)	0.00	
Assign From	JASMINE LOK	Assign Date	02/01/2018	
2. Vehicle Particulars & Condition				
Make & Model	c.c		0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.	Colour			
Odometer	Steering			
Brakes	Modification			
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	22/12/2017	Inspection Date	03/01/2018	
Survey held at	KAH MOTOR CO SDN BERHAD NO. 255 ALEXANDRA ROAD SINGAPORE 159937			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	23 Dec 2017		02 Jan 2018 15:00 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS		[Created by insurer]
Insured:	CHEUNG KIAN HOCK, ID: S1567555A, Tel: +6594563126, Email: CHEUNGKH17@GMAIL.COM	
Main Claimant:	KEE CHONG CHING, ID: S2550166G	
Vehicle Reg. No.:	SLJ3560K	Date of Loss: 22/12/2017 08:00 - :59
Claim Type:	TP / 542418	Policy/Cover Note No.: P27105154DMV (Comprehensive) Coverage: 19/06/2017 - 18/06/2018
Vehicle Reg. No. (Insured):	SJG654H	Policy No. (Claimant):
		Excess:
Repairer:	Kah Motor Co Sdn Bhd (ALEXANDRA) 255 ALEXANDRA ROAD, - Alexandra - Tel:	
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Jasmine Lok Kheng Kwei - 6594 2550]	
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 03/01/2018]	
Driver/Custodian (Insured):	CHEUNG KIAN HOCK (55 / Male), NRIC: S1567555A, Tel: +6594563126	
Adj Asg. Remarks:	ON WP	

ASSOCIATED MAIL RECEIVED	View All	Compose Case Mail
There are no mail for this case.		

ALL ASSOCIATED TASKS											View All	Search Tasks	Create New Task	Complete
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?					
No results.														

Veh In.

2/1/18

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Jasmine Lok Kheng Kwei

Date: 06 Jan 2018

Preliminary Advice

Insured Vehicle No	: SJG654H	Accident Date	: 22/12/2017
TP Vehicle No	: SLJ3560K	Assignment Date	: 02/01/2018
Make	: HONDA HR-V	Est. Duration of Repair	: 14.00
Date of Inspection	: 03/01/2018		
Inspection At	: KAH MOTOR CO SDN BHD (ALEXANDRA) 255 ALEXANDRA ROAD SINGAPORE -		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	23,462.86
Revised Amount	:S\$	18,692.15
Check Items (Estimated)	:S\$	1,100.46
Total	:S\$	19,792.61
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is economical/not economical for repair.
- (x) The above survey was conducted on a 'without prejudice' basis.

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 0166G

Vehicle Details

Vehicle No.: SLJ3560K
Vehicle to be Exported: No
Intended De-registration Date: 04 Jan 2018
Vehicle Make: HONDA
Vehicle Model: HRV 1.5 DX CVT
Primary Colour: White
Manufacturing Year: 2016
Engine No.: L15B4531218
Chassis No.: JHMRU1810GX201217
Maximum Power Output: 96.0 kW (128 bhp)
Open Market Value: \$21,466.00
Original Registration Date: 07 Dec 2016
First Registration Date: 07 Dec 2016
Transfer Count: 0
Actual ARF Paid: \$17,053.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 06 Dec 2026
PARF Rebate Amount: \$12,789.00

Intended COE Rebate Details

COE Expiry Date: 06 Dec 2026
COE Category: A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years): 10

QP Paid: \$50,991.00

• COE Rebate Amount: \$45,494.00

Total Rebate Amount: \$58,283.00

The information contained herein is correct as at 04 Jan 2018

OK

SGCARMART.COM[New Cars](#)[Used Cars](#)[Sell My Car](#)[Directory](#)[Products](#)[Articles](#)

ANNOUNCING BENEFIT AUTO

as sgCarMart Premium Dealer for the 4th Consecutive Year



Post an Advertisement

Sell it yourself! Advertise it at just

\$58 until it's SOLD![Post an Ad](#)[Advertiser Login](#)[Ways of Selling](#)

New 5 Year Coe Renewal 2008 Toyota Wish 1.8A




\$2800 Downpayment Monthly
From \$688 Onwards. Lowest
3.68%P.A@GV Cars Financing.
GV Credit Pte Ltd

[Browse by Category](#)[Sort by Date](#)

5 vehicles

honda hrv

Advanced Search

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage
Search Selection	honda hrv		Any	Any	2016	Any	Any
	Honda HR-V 1.5A LX		\$99,800	\$10,220 /yr	13-Oct-2016	1,496 cc	25,500
Immaculate Condition, Upgraded 17" Sports Rims, Maintained By Kah Motor, 5 Years Warranty, 3 Years Free Service, Nano C							
Posted: 02-Jan-2018 Tags: 2016 Honda HR-V, 2016 Honda HRV, Honda HR-V, Honda HRV, Honda, HR-V, HRV, Used Honda							
	Honda HR-V 1.5A LX		\$99,800	\$10,030 /yr	13-Dec-2016	1,496 cc	29,000
Up To 90% Loan Available For As Good As New Signature Honda HR-V! Beautiful Blue Unit Against Black Leather Interior! Ka							
Warranty Valid Till Dec 2021! Completely Stock With No Mods ...							
Euro Performance Asia Pte Ltd							
Posted: 31-Dec-2017 Tags: 2016 Honda HR-V, 2016 Honda HRV, Honda HR-V, Honda HRV, Honda, HR-V, HRV, Used Honda							
	Honda HR-V 1.5A LX		\$94,800	\$9,880 /yr	24-Aug-2016	1,496 cc	-
Car Serviced & Under Warranty By Agent. Up To 90% Loan! Flexible Repayment With In House Financing. Our Vehicle Inspe							
For Highest Quality. Owning A Car Is So Much Easier With ...							
Universe Motoring							
Posted: 30-Dec-2017 Tags: 2016 Honda HR-V, 2016 Honda HRV, Honda HR-V, Honda HRV, Honda, HR-V, HRV, Used Honda							
	Honda HR-V 1.5A LX (OPC)		\$83,000	\$8,480 /yr	06-Sep-2016	1,496 cc	3,600
As Good As New! Superb Low Mileage. Immaculate Conditon, Accident Free! Kah Motor Unit. Still Under Agent Warranty. Roa							
Reliable And Low Fuel Consumption SUV. Buy With A Peace Of...							
Euro Performance Asia Pte Ltd							
Posted: 29-Dec-2017 Tags: 2016 Honda HR-V, 2016 Honda HRV, Honda HR-V, Honda HRV, Honda, HR-V, HRV, Used Honda							

[Car Buying](#)[Car Selling](#)[Car Aftermarket](#)[Car Ownership](#)[On The Move](#)[Lifestyle](#)
[Buy Tyre](#)
[Latest Sp](#)
[Compare](#)

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	22/12/2017 19:57
Date Of Accident	22/12/2017 08:10
Exact Location Of Accident	PUNGGOL EAST
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLJ3560K
Insured/Policyholder	
Name Of Registered Owner	KEE CHONG CHING
NRIC No	S2550166G
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-91000582
Alternative Phone No	OFFICE-91000582

Vehicle Particulars

Manufacturer	HONDA
Model	HR-V-1.5 (A)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company	LIBERTY INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO

Policy Number

Cover Note Number

Driver

Name of Driver	KEE CHONG CHING
NRIC No	S2550166G
Date Of Birth	04/02/1964
Occupation	INDOOR
Date Of Driving Pass	11/07/1997
Driving Experience	20 YEARS AND 5 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-91000582
Fax Number	
Contact Number	OFFICE-91000582
EEmail Address	NOEMAIL

Address SINGAPORE
Postcode
Was driver an employee of the Insured's Company NO
If No, Relationship of the Driver with the Insured OWNER
Vehicle Registration Number of Driver's Own Vehicle -
-
-
Insurance Company of Driver's Own Vehicle -
-
-

General Information of the Accident

Type Of Accident CHAIN COLLISION
Weather Conditions CLEAR
Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
Number of vehicles involved in the accident 3
Was any body injured in the Accident? NO
Was any injured conveyed to hospital by ambulance? NO
Was any other material or property damaged? YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? NO
If Yes, Please state which Police Station
Was notice of intended Prosecution given? NO
If Yes, against whom?

Circumstances of Accident

REFER TO ATTACH

Attachment(s)

Are accident photos available for attachment? YES
Was there any video captured by Car Camera? NO
Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SJG654H
Vehicle Make/Model/Colour
Details Of Properties
Vehicle Category PRIVATE CAR
Name of Driver
NRIC/Passport Number
Contact Number
Address
Postcode
Insurance Company Name MSIG INSURANCE (SINGAPORE) PTE. LTD.
Nature Of Damage
No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number GBB5596E
Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

COMMERCIAL VEHICLE

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Sketch Plan


Vehicle No _____

SKETCH PLAN

ANNEX D

IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)
I understand, acknowledge, agree and consent that:
(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"); the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
(ii) investigating the accident and/or my claims;
(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
(collectively the "Purposes")
(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.


Policyholder's Signature / Date & Time


Driver's Signature (If driver is not the policyholder) / Date & Time


Witnessed by Reporting Centre Personnel

Sketch Plan



1. State confirmed to Annex C

Vehicle No _____

Annex E


Describe Circumstances of the Accident

I was traveling along Punggol East Road. The front vehicle C
slow down and stop and I follow to slow down and stop
too. Vehicle B couldn't brake in time and hit onto
the rear of my vehicle A and the impact pushes
my vehicle A to move forward and hit onto vehicle C.
It is a 3 car vehicle chain collision.

You had been advised by the workshop that in the event that you wish to claim against your own policy (OD claim), there is a fourteen (14) days clause whereby the claim must be made within the stipulated timeframe from the day of occurrence.

Declaration

We declare the foregoing particulars are true in every respect.



Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time



Witnessed by Reporting Centre Personnel

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer	: MSIG INSURANCE (SINGAPORE) PTE	Document No.	: SQT17005197	Page	1
	16 RAFFLES QUAY	Date	: 22. Dec 2017		
	HONG LEONG BUILDING	Customer No.	: WZM003		
	SINGAPORE 048581	Svc Advisor	:		
Registration No	: SLJ3560K	Engine No	: L15B4531218		
Chassis No	: JHMRU1810GX201217	Date Time	: 22. Dec 2017 7:58:55 PM		
Model	: HRV DX-SIN CVT YM 2016	Surveyor Name	:		
Owner's Name	: KEE CHONG CHING	Survey Date	:		
Ins Policy No.	:	Authorisation Date	:		
Date of Accident	: 22/12/2017				

Item	Description	Qty	Unit Price	Disc %	Amount	GST Amt	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO:)						
	OWNER:KEE CHONG CHING						
	OWNER INSURER:LIBERTY INSURANCE						
	ACC DATE:22/12/2017						
	SURVEYED BY:						
	DATE:						
	REF NO:						
	TP INSURER:MSIG INSURANCE (SINGAPORE) PTE LTD						
	TP VEH:SJG654H						
71126-T7B-Z01 ✓	SET,FR.GRILLE ASSY	1	265.50 <i>crn</i>	25	199.12	13.94	213.06
71122-T7A-901 ✓	MOLDINGFR.GRILLE UPPER	1	186.10 <i>cut</i>	25	139.57	9.77	149.34
71123-T7A-901 ✓	MOLDINGFR.GRILLE	1	42.80 <i>Xna</i>	25	32.10 <i>X</i>	2.25 ✓	34.35
75700-TA0-A00 ✓	EMBLEMFR.	1	25.90 <i>rec</i>	25	19.42	1.36	20.78
90301-ST0-003 ✓	NUTPUSH 3MM	2	1.90 <i>rel</i>	25	2.85	0.20	3.05
04711-T7A-N00ZZ ✓	FACEFR.BUMPER	1	466.20 <i>del</i>	25	349.65	24.48	374.13
91505-TM8-003 ✓	CLIPBUMPER	18	2.00 <i>ni</i>	25	27.00	1.89	28.89
71102-T7B-000	FACE FR. BUMPER LOWER	1	344.20 <i>? del</i>	25	258.15 <i>X</i>	18.07 <i>X</i>	276.22
71103-T7A-000	GRILLEFR.BUMPER	1	77.50 <i>Xnn</i>	25	58.12	4.07	62.19
71190-T7A-000 ✓	BEAML.FR.BUMPER UPPER	1	23.90 <i>ht</i>	25	17.92 ✓	1.25	19.17
71130-T7A-000ZZ ✓	BEAM COMPFR.BUMPER	1	236.60 <i>.ht</i>	25	177.45 ✓	12.42	189.87
33150-T7S-E11 ✓	HEAD LIGHT ASSY,L.	1	1479.70 <i>crn</i>	25	1109.77	77.68	1187.45
71106-T7A-000	GARNISHL.FR.FOG LIGHT	1	21.10 <i>Xnn</i>	25	15.82	1.11	16.93
33950-SLE-J51	LIGHT ASSYL.FR.FOGLIGHT	1	235.00 <i>Xnn</i>	25	176.25	12.34	188.59
33966-T7A-J00	BRACKETL.FOG LIGHT	1	49.00 <i>Xnn</i>	25	36.75	2.57	39.32
71193-T7A-000 ✓	SPACERR.FR.BUMPER SIDE	1	10.40 <i>rel</i>	25	7.80	0.55	8.35
71198-T7A-000 ✓	SPACERL.FR.BUMPER SIDE	1	10.40 <i>rel</i>	25	7.80	0.55	8.35
RS-TMP3040L ✓	VPC 4PCS REAR SENSORS	1	320.00 <i>nn</i>		320.00	22.40	342.40
33502-T7A-J01	LAMP UNITR.	1	428.70 <i>Xnn</i>	25	321.52	22.51	344.03
33552-T7A-J01	LAMP UNITL.	1	428.70 <i>Xnn</i>	25	321.52	22.51	344.03
34150-T7A-J01	LIGHT ASSY,R.LID	1	264.60 <i>Xnn</i>	25	198.45	13.89	212.34

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : MSIG INSURANCE (SINGAPORE) PTE
16 RAFFLES QUAY
HONG LEONG BUILDING
SINGAPORE 048581

Registration No : SLJ3560K

Chassis No : JHMRU1810GX201217

Model : HRV DX-SIN CVT YM 2016

Owner's Name : KEE CHONG CHING

Ins Policy No. :

Date of Accident : 22/12/2017

Document No. : SQT17005197 Page 2

Date : 22. Dec 2017

Customer No. : WZM003

Svc Advisor :

Engine No : L15B4531218

Date | Time : 22. Dec 2017 7:58:55 PM

Surveyor Name :

Survey Date :

Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	GST Amt	Amount incld GST
34155-T7A-J01	LIGHT ASSYL.LID	1	264.60	25	198.45	13.89	212.34
68100-T7A-J20ZZ ✓	TAILGATE COMP ✓	1	838.90	25	629.17	44.04	673.21 ✓
74440-T7A-003 ✓	WEATHERSTRIPTAILGATE	1	96.80	25	72.60	5.08	77.68 ✓
74800-T7A-J02 ✓	LOCK ASSYTAILGATE	1	76.60	25	57.45	4.02	61.47 ✓
84431-T7A-J01ZA	LINING ASSYTAILGATE	1	133.40	25	100.05	7.00	107.05 X
75722-T7W-A01 ✓	EMBLEMRR.	1	12.90	25	9.67	0.68	10.35 ✓
75725-T8N-T00 ✓	EMBLEM,RR. I-VTEC	1	14.10	25	10.57	0.74	11.31 ✓
33505-T7A-J01	REFLECTOR ASSYR.RR.	1	151.80	25	113.85	7.97	121.82 X
33555-T7A-J01 ✓	REFLECTOR ASSYL.RR.	1	151.80	25	113.85	7.97	121.82 ✓
04717-T7A-000ZZ	FACER.RR.BUMPER CORNER	1	92.30	25	69.22	4.85	74.07 X
04718-T7A-000ZZ	FACEL.RR.BUMPER CORNER	1	92.30	25	69.22	4.85	74.07 X
71593-T7A-000 ✓	SPACERR.RR.BUMPER SIDE	1	11.50	25	8.62	0.60	9.22 ✓
71598-T7A-000 ✓	SPACERL.RR.BUMPER SIDE	1	11.50	25	8.62	0.60	9.22 ✓
91505-TM8-003 ✓	CLIPBUMPER	8	2.00	25	12.00	0.84	12.84 ✓
66100-T7A-300ZZ ✓	PANEL COMPRR.	1	365.70	25	274.27	19.20	293.47 ✓
84640-T7A-J01ZA	LINING ASSYRR.PANEL	1	43.00	25	32.25	2.26	34.51 X
04655-T7A-310ZZ	PANEL SETRR.FLOOR	1	662.20	25	496.65	34.77	531.42 ✓
72841-SH3-315 ✓	OILSHEET	3	39.90	25	89.77	6.28	96.05 ✓
73214-T7J-H01 ✓	RUBBER CR.WINDSHIELD DAMPER	1	19.30	25	14.47	1.01	15.48 ✓
73226-SZW-000 ✓	DAMPERSTD 5X5	1	8.30	25	6.22	0.44	6.66 ✓
73254-T7J-H01 ✓	RUBBER CL.WINDSHIELD DAMPER	1	19.30	25	14.47	1.01	15.48 ✓
76711-T6A-003 ✓	CAPPIVOT	1	4.70	25	3.52	0.25	3.77 ✓
91501-S70-003 ✓	FASTENER BW/SHIELD	4	3.20	25	9.60	0.67	10.27 ✓
91502-S70-003 ✓	FASTENER B	2	4.90	25	7.35	0.51	7.86 ✓
91536-SS0-J01 ✓	FASTENER AW/SHIELD	2	3.50	25	5.25	0.37	5.62 ✓
BO-WS-SEALANT ✓	WINDSCREEN SEALANT (N)	2	60.00		120.00	8.40	128.40 ✓
60100-T7A-000ZZ ✓	HOOD COMPENGINE	1	785.20	25	588.90	41.22	630.12 ✓
72841-SH3-315	OILSHEET X	3	39.90	25	89.77	6.28	96.05
Sum Item					7022.86	491.61	7,514.47
BOSUN	SUNDRIES	1	100.00		100.00	7.00	107.00

Printed on 3/1/2018 12:06:28 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s)

24038.67

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : MSIG INSURANCE (SINGAPORE) PTE
16 RAFFLES QUAY
HONG LEONG BUILDING
SINGAPORE 048581

Registration No : SLJ3560K

Chassis No : JHMRU1810GX201217

Model : HRV DX-SIN CVT YM 2016

Owner's Name : KEE CHONG CHING

Ins Policy No. :

Date of Accident : 22/12/2017

Document No. : SQT17005197 Page 3

Date : 22. Dec 2017

Customer No. : WZM003

Svc Advisor :

Engine No : L15B4531218

Date | Time : 22. Dec 2017 7:58:55 PM

Surveyor Name :

Survey Date :

Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	GST Amt	Amount incld GST
BA02R	REMOVE & RENEW REVERSE SENSORS-4 PCS (N)	1	180.00 ✓		180.00	12.60	192.60
BOJSE	SEALANT FOR REAR END PANEL	1	80.00 ✓		80.00	5.60	85.60
BOJSE	SEALANT FOR REAR FLOOR PANEL	1	80.00 ✓		80.00	5.60	85.60
BOJSE	SEALANT FOR TAILGATE	1	80.00 ✓		80.00	5.60	85.60
BML02I	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER	1	150.00 ✓		150.00	10.50	160.50
BMF00D	RREMOVE & INSTALL FUEL TANK FUEL PIPES.(N)	1	560.00 ✓		560.00	39.20	599.20
BMI02D	REMOVE & INSTALL SPEAKER BOARD RR SEATS TRUNK	1	560.00 ✓		560.00	39.20	599.20
BKTG02R	REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST &	1	560.00 ✓		560.00	39.20	599.20
BG02D	REMOVE & INSTALL RR. WINDSCREEN.(N)	1	560.00 ✓		560.00	39.20	599.20
BODAMKIT	WINDSCREEN DAM KIT.	1	100.00 80.		100.00	7.00	107.00
BKRP02M	CUT OFF & RENEW RR PANEL. 560	1	4500.00 3920.		4500.00	315.00	4815.00
BP06R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (6P) 450.	1	3000.00 2700.		3000.00	210.00	3210.00
BKOT00R	REMOVE & RENEW RR FLOOR INSULATOR.(N)	1	450.00 ✓		450.00	31.50	481.50
BKBU01R	REMOVE, RE-FIX AND ALIGN REAR VIEW CAMERA	1	380.00 ✓		380.00	26.60	406.60
BP00R	APPLY BODY UNDERSIDE COATING (N).	1	450.00 ✓		450.00	31.50	481.50
BML01I	INSPECT FR LIGHTING MECHANISMS & FOCUS	1	150.00 ✓		150.00	10.50	160.50
BKBU01R	REMOVE & RENEW FR BUMPER AND ALL DAMAGED PARTS	1	2500.00 1680.		2500.00	175.00	2675.00
BP03R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (3P)	1	2000.00 1350.		2000.00	140.00	2140.00
Sum Labor					16440.00	1,150.80	17,590.80

Survey By : Tan Jiah 97495719

Date & Time : 03/01/18 01:55

Excess : WP

Status : 14 days

Signature : [Signature]

Total Amount : 23,462.86 1,642.41 25,105.27

Total (Inclusive of GST) : 25,105.27

Printed on 3/1/2018 12:06:28 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s)

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:



SERVICE PRE-INVOICE

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer: WZM003 / MSIG INSURANCE
Chassis No: JHMRU1810GX201217
License No: SLJ3560K
Mileage: 10260
Engine No: L15B4531218

Document No: SVO18000509
Printed By: SHNG
Order Date: 3. January 2018
Order Time: 12:49:15 PM
Service Advisor: NG SIN HAI

ITEM	DESCRIPTION	QTY	UNIT	DISC %	AMOUNT	GST Amt	Amount Incl GST
	TP DIRECT SETTLEMENT (J/NO:) OWNER:KEE CHONG CHING OWNER INSURER:LIBERTY INSURANCE ACC DATE:22/12/2017 SURVEYED BY:TAUFIKH DATE:03/01/2018 REF NO: TP INSURER:MSIG INSURANCE (SINGAPORE) PTE LTD TP VEH:SJG654H ADDITIONAL PART						
35070	- CUSHIONHOOD 74827-SLE-003	1	5.90	25	4.42	0.31	4.73 ✓ (A)
	SUM EXCESS:				4.42	0.31	4.73
71126-T7B-Z01	SET,FR.GRILLE ASSY	1	265.50	25	199.12	13.94	213.06
71122-T7A-901	MOLDINGFR.GRILLE UPPER	1	186.10	25	139.57	9.77	149.34
71123-T7A-901	MOLDINGFR.GRILLE	1	42.80	25	32.10	2.25	34.35
75700-TA0-A00	EMBLEMFR. ✓	1	25.90	25	19.42	1.36	20.78
90301-ST0-003	NUTPUSH 3MM	2	1.90	25	2.85	0.20	3.05
04711-T7A-N00ZZ	FACEFR.BUMPER	1	466.20	25	349.65	24.48	374.13
91505-TM8-003	CLIPBUMPER	18	2.00	25	27.00	1.89	28.89
71190-T7A-000	BEAML.FR.BUMPER UPPER	1	23.90	25	17.92	1.25	19.17
71130-T7A-000ZZ	BEAM COMPFR.BUMPER	1	236.60	25	177.45	12.42	189.87
33150-T7S-E11	HEAD LIGHT ASSY,L	1	1,479.70	25	1,109.77	77.68	1,187.45
71193-T7A-000	SPACERR.FR.BUMPER SIDE	1	10.40	25	7.80	0.55	8.35
71198-T7A-000	SPACERL.FR.BUMPER SIDE	1	10.40	25	7.80	0.55	8.35
NMRS-4P-TM3040L ✓	4PCS ACT RR.SENSOR	1	320.00		320.00	22.40	342.40
68100-T8P-U10ZZ	TAILGATE COMP	1	838.90	25	629.17	44.04	673.21
74440-T7A-003	WEATHERSTRIPTAILGATE	1	96.80	25	72.60	5.08	77.68
74800-T7A-J02	LOCK ASSYTAILGATE	1	76.60	25	57.45	4.02	61.47
75722-T7W-A01	EMBLEMRR.	1	12.90	25	9.67	0.68	10.35
75725-T8N-T00	EMBLEM,RR. I-VTEC	1	14.10	25	10.57	0.74	11.31
33555-T7A-J01	REFLECTOR ASSYL.RR.	1	151.80	25	113.85	7.97	121.82
71593-T7A-000	SPACERR.RR.BUMPER SIDE	1	11.50	25	8.62	0.60	9.22
71598-T7A-000	SPACERL.RR.BUMPER SIDE	1	11.50	25	8.62	0.60	9.22
91505-TM8-003	CLIPBUMPER	8	2.00	25	12.00	0.84	12.84
66100-T7A-300ZZ	PANEL COMPRR.	1	365.70	25	274.27	19.20	293.47
04655-T7A-310ZZ	PANEL SETRR.FLOOR	1	662.20	25	496.65	34.77	531.42
72841-SH3-315	OILSHEET	3	39.90	25	89.77	6.28	96.05
73215-T7A-003	RUBBER CR.WINDHSIELD DAM	1	19.30	25	14.47	1.01	15.48
73226-SZW-000	DAMPERSTD 5X5	1	8.30	25	6.22	0.44	6.66
73265-T7A-003	RUBBER,L.WINDSHIELD DAM	1	19.30	25	14.47	1.01	15.48
76711-T6A-003	CAPPIVOT	1	4.70	25	3.52	0.25	3.77
91501-S70-003	FASTENER BW/SHIELD	4	3.20	25	9.60	0.67	10.27
91502-S70-003	FASTENER B	2	4.90	25	7.35	0.51	7.86
91536-SS0-J01	FASTENER AW/SHIELD	2	3.50	25	5.25	0.37	5.62
BO-WS-SEALANT	WINDSCREEN SEALANT (N)	2	60.00		120.00	8.40	128.40
60100-T7A-000ZZ	HOOD COMPENGINE	1	785.20	25	588.90	41.22	630.12
19043-PNB-A00	LABELCOOLANT INFORMATION	1	4.90	25	3.67	0.26	3.93 (A)
80050-TG7-000	LABLE AIR CON	1	0.80	25	0.60	0.04	0.64 A
74940-TZ5-A01	BUZZER ASSYSMART	1	59.30	25	44.47	3.11	47.58 A



SERVICE PRE-INVOICE

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer: WZM003 / MSIG INSURANCE
Chassis No: JHMRU1810GX201217
License No: SLJ3560K
Mileage: 10260
Engine No: L15B4531218

Document No: SVO18000509
Printed By: SHNG
Order Date: 3. January 2018
Order Time: 12:49:15 PM
Service Advisor: NG SIN HAI

71150-T7A-000	BEAMR.FR.GRILLE SIDE UPPER	1	38.70	25	29.02	2.03	31.05
71140-T7A-000	BEAMR.FR.BUMPER UPPER	1	23.90	25	17.92	1.25	19.17
04716-T7A-900ZZ	FACE,RR.BUMPER	1	463.70	25	347.77	24.34	372.11
74646-T7A-010	COVERRR.FLOOR UN	1	118.30	25	88.72	6.21	94.93
80525-T2F-A01	SENSOR ASSYAMBIENT	1	42.60	25	31.95	2.24	34.19
91555-T7A-J01	CLIPAMBIENT SENSOR	1	4.30	25	3.22	0.23	3.45
90661-SC7-003	GROMMET SCREW	2	2.30	25	3.45	0.24	3.69
93903-45320	SCREWTAPPING 5X16	2	0.40	25	0.60	0.04	0.64
		SUM PARTS:		5,534.86	387.43	5,922.29	
BOSUN	0701	1	30.00		30.00	2.10	32.10
SUNDRIES							
BA02R	0669	1	180.00		180.00	12.60	192.60
REMOVE & RENEW REVERSE SENSORS-4 PCS (N)							
BOJSE	1374	1	80.00		80.00	5.60	85.60
SEALANT FOR REAR END PANEL							
BOJSE	1374	1	80.00		80.00	5.60	85.60
SEALANT FOR REAR FLOOR PANEL							
BOJSE	1374	1	80.00		80.00	5.60	85.60
SEALANT FOR TAILGATE							
BML02I	0669	1	150.00		150.00	10.50	160.50
INSPECT RR LIGHTING MECHANISMS. PERFORM WATER TEST.(N)							
BMF00D	1757	1	560.00		560.00	39.20	599.20
RREMOVE & INSTALL FUEL TANK FUEL PIPES.(N)							
BMI02D	1757	1	560.00		560.00	39.20	599.20
REMOVE & INSTALL SPEAKER BOARD RR SEATS TRUNK LININGS GARNISHES & ETC.(N)							
BKTG02R	0669	1	560.00		560.00	39.20	599.20
REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST & ALIGN TAILGATE.(N)							
BG02D	1757	1	560.00		560.00	39.20	599.20
REMOVE & INSTALL RR. WINDSCREEN. (N)							
BODAMKIT	0701	1	80.00		80.00	5.60	85.60
WINDSCREEN DAM KIT.							
BKRP02M	0669	1	3,920.00		3,920.00	274.40	4,194.40
CLUT OFF & RENEW RR PANEL. RR FLOOR PAN & RENEW DAMAGE PARTS.							
BP06R	1610	1	2,700.00		2,700.00	189.00	2,889.00
SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (6P) REAR PORTION							
BKOT00R	0669	1	450.00		450.00	31.50	481.50
REMOVE & RENEW RR FLOOR INSULATOR.(N)							
BKBU01R	1757	1	380.00		380.00	26.60	406.60
REMOVE, RE-FIX AND ALIGN REAR VIEW CAMERA							



SERVICE PRE-INVOICE

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer: WZM003 / MSIG INSURANCE
Chassis No: JHMRU1810GX201217
License No: SLJ3560K
Mileage: 10260
Engine No: L15B4531218

Document No: SVO18000509
Printed By: SHNG
Order Date: 3. January 2018
Order Time: 12:49:15 PM
Service Advisor: NG SIN HAI

BP00R	1374	1	450.00	450.00	31.50	481.50
	APPLY BODY UNDERSIDE COATING (N).					
BML01I	0669	1	150.00	150.00	10.50	160.50
	INSPECT FR LIGHTING MECHANISMS & FOCUS HEADLIGHTS.(N)					
BKBU01R	0669	1	1,680.00	1,680.00	117.60	1,797.60
	REMOVE & RENEW FR BUMPER AND ALL DAMAGED PARTS					
BP03R	1610	1	1,350.00	1,350.00	94.50	1,444.50
	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS.(3P) FRONT PORTION					

SUM LABOUR: 14,000.00 980.00 14,980.00

TOTAL SGD 19,539.28 1,367.74 20,907.02

Total Payable (SGD) 20,907.02

GST Amount is calculated from individual line(s)

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer	: MSIG INSURANCE (SINGAPORE) PTE	Document No.	: SQT18000280	Page	1
	16 RAFFLES QUAY	Date	: 18. Jan 2018		
	HONG LEONG BUILDING	Customer No.	: WZM003		
	SINGAPORE 048581	Svc Advisor	:		
Registration No	: SLJ3560K	Engine No	: L15B4531218		
Chassis No	: JHMRU1810GX201217	Date Time	: 18. Jan 2018 7:34:30 PM		
Model	: HRV DX-SIN CVT YM 2016	Surveyor Name	:		
Owner's Name	: KEE CHONG CHING	Survey Date	:		
Ins Policy No.	:	Authorisation Date	:		
Date of Accident	:				

Item	Description	Qty	Unit Price	Disc %	Amount	GST Amt	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO:)						
	OWNER:						
	OWNER INSURER:						
	ACC DATE:						
	SURVEYED BY:						
	DATE:						
	REF NO:						
	TP INSURER:						
	TP VEH:						
	SUPPLEMENTARY						
74827-SLE-003	CUSHIONHOOD	1	5.90	25	4.42	0.31	4.73
19043-PNB-A00	LABELCOOLANT INFORMATION	1	4.90	25	3.67	0.26	3.93
80050-TG7-000	LABLE AIR CON	1	0.80	25	0.60	0.04	0.64
74940-TZ5-A01	BUZZER ASSYSMART	1	59.30	25	44.47	3.11	47.58
71150-T7A-000	BEAMR.FR.GRILLE SIDE UPPER	1	38.70	25	29.02	2.03	31.05
71140-T7A-000	BEAMR.FR.BUMPER UPPER	1	23.90	25	17.92	1.25	19.17
04715-T7A-900ZZ	FACE,RR.BUMPER	1	463.70	25	347.77	24.34	372.11
74646-T7A-010	COVERRR.FLOOR UN	1	118.30	25	88.72	6.21	94.93
80525-T2F-A01	SENSOR ASSYAMBIENT	1	42.60	25	31.95	2.24	34.19
91555-T7A-J01	CLIPAMBIENT SENSOR	1	4.30	25	3.22	0.23	3.45
90661-SC7-003	GROMMET SCREW	2	2.30	25	3.45	0.24	3.69
93903-45320	SCREWTAPPING 5X16	2	0.40	25	0.60	0.04	0.64
Sum Item					575.81	40.30	616.11

Survey By

Date & Time

Excess

Status

Signature

Total Amount 575.81 40.30 616.11

Total (Inclusive of GST) 616.11

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	23 Dec 2017		02 Jan 2018 15:00 Edit Adj Rpt	S\$19,539.28 Edit Estimates	S\$19,539.28 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured: CHEUNG KIAN HOCK , ID: S1567555A, Tel: +6594563126, Email: CHEUNGKH17@GMAIL.COM									
Main Claimant: KEE CHONG CHING , ID: S2550166G									
Vehicle Reg. No.: SLJ3560K		Date of Loss: 22/12/2017 08:00 - :59 [12 Months and 15 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / 542418		Policy/Cover Note No.: P27105154DMV (Comprehensive) Coverage: 19/06/2017 - 18/06/2018							
Vehicle Reg. No. (Insured): SJG654H		Policy No. (Claimant):							
		Excess:							
Repairer: Kah Motor Co Sdn Bhd (ALEXANDRA) 255 ALEXANDRA ROAD, - Alexandra - Tel:									
Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Jasmine Lok Kheng Kwei - 6594 2550]									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 01/02/2018]									
Driver/Custodian (Insured): CHEUNG KIAN HOCK (55 / Male), NRIC: S1567555A, Tel: +6594563126									
Adj Asg. Remarks: ON WP									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SLJ3560K (542418)**

[SJG654H]

TP

KEE CHONG CHING

Dec 22 2017 8:00AM

[CHEUNG KIAN HOCK]

Kah Motor Co Sdn Bhd

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Assessment Reports			1 per page	☒
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	27/12/17 16:56	Accident Statement From: SC - Reg. No: SJG654H, Claimant: CHEUNG KIAN HOCK	 Load HTM	☐
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	06/01/18 13:03	Adjuster Immediate Advice	 Load HTM	☐
Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	21/05/18 13:40	General View	 Load JPG	☒
2	21/05/18 13:40	General View	 Load JPG	☒
3	21/05/18 13:40	General View	 Load JPG	☒
4	21/05/18 13:40	General View	 Load JPG	☒
5	21/05/18 13:40	General View	 Load JPG	☒
6	21/05/18 13:40	General View	 Load JPG	☒
7	21/05/18 13:40	General View	 Load JPG	☒
8	21/05/18 13:40	General View	 Load JPG	☒
9	21/05/18 13:40	General View	 Load JPG	☒
10	21/05/18 13:40	General View	 Load JPG	☒
11	21/05/18 13:40	General View	 Load JPG	☒
12	21/05/18 13:40	General View	 Load JPG	☒
13	21/05/18 13:40	General View	 Load JPG	☒
14	21/05/18 13:40	General View	 Load JPG	☒
15	21/05/18 13:40	General View	 Load JPG	☒
16	21/05/18 13:40	General View	 Load JPG	☒
17	21/05/18 13:40	General View	 Load JPG	☒
18	21/05/18 13:40	General View	 Load JPG	☒
19	21/05/18 13:40	General View	 Load JPG	☒
20	21/05/18 13:40	General View	 Load JPG	☒
21	21/05/18 13:40	General View	 Load JPG	☒
22	21/05/18 13:40	General View	 Load JPG	☒
23	21/05/18 13:40	General View	 Load JPG	☒
24	21/05/18 13:40	General View	 Load JPG	☒
25	21/05/18 13:40	General View	 Load JPG	☒
26	21/05/18 13:40	General View	 Load JPG	☒
27	21/05/18 13:40	General View	 Load JPG	☒
28	21/05/18 13:40	General View	 Load JPG	☒
29	21/05/18 13:40	General View	 Load JPG	☒
30	21/05/18 13:40	General View	 Load JPG	☒
31	21/05/18 13:40	General View	 Load JPG	☒
32	21/05/18 13:40	General View	Load JPG	☐

Assessment Reports			1 per page	☒
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
				☒
33	21/05/18 13:40	General View	 Load JPG	☒
34	21/05/18 13:40	General View	 Load JPG	☒
35	21/05/18 13:40	General View	 Load JPG	☒
36	21/05/18 13:40	General View	 Load JPG	☒
37	21/05/18 13:40	General View	 Load JPG	☒
38	21/05/18 13:40	General View	 Load JPG	☒
39	21/05/18 13:40	General View	 Load JPG	☒
40	21/05/18 13:40	General View	 Load JPG	☒
41	21/05/18 13:40	General View	 Load JPG	☒
42	21/05/18 13:40	General View	 Load JPG	☒
43	21/05/18 13:40	General View	 Load JPG	☒
44	21/05/18 13:40	General View	 Load JPG	☒
45	21/05/18 13:40	General View	 Load JPG	☒
46	21/05/18 13:40	General View	 Load JPG	☒
47	21/05/18 13:40	General View	 Load JPG	☒
48	21/05/18 13:40	General View	 Load JPG	☒
49	21/05/18 13:40	General View	 Load JPG	☒
50	21/05/18 13:40	General View	 Load JPG	☒
51	21/05/18 13:40	General View	 Load JPG	☒
52	21/05/18 13:40	General View	 Load JPG	☒
53	21/05/18 13:40	General View	 Load JPG	☒
54	21/05/18 13:40	General View	 Load JPG	☒
55	21/05/18 13:40	General View	 Load JPG	☒
56	21/05/18 13:40	General View	 Load JPG	☒
57	21/05/18 13:40	General View	 Load JPG	☒
58	21/05/18 13:40	General View	 Load JPG	☒
59	21/05/18 13:40	General View	 Load JPG	☒
60	21/05/18 13:40	General View	 Load JPG	☒
61	21/05/18 13:40	General View	 Load JPG	☒
62	21/05/18 13:40	General View	 Load JPG	☒
63	21/05/18 13:40	General View	 Load JPG	☒
64	21/05/18 13:40	General View	 Load JPG	☒
65	21/05/18 13:40	General View	 Load JPG	☒
66	21/05/18 13:40	General View	 Load JPG	☒
67	21/05/18 13:40	General View	 Load JPG	☒
68	21/05/18 13:40	General View	 Load JPG	☒
69	21/05/18 13:40	General View	 Load JPG	☒
70	21/05/18 13:40	General View	 Load JPG	☒
71	21/05/18 13:40	General View	 Load JPG	☒
72	21/05/18 13:40	General View	 Load JPG	☒
73	21/05/18 13:40	General View	 Load JPG	☒
74	21/05/18 13:40	General View	 Load JPG	☒
75	21/05/18 13:40	General View	 Load JPG	☒
76	21/05/18 13:40	General View	 Load JPG	☒
77	21/05/18 13:40	General View	 Load JPG	☒
78	21/05/18 13:40	General View	 Load JPG	☒
79	21/05/18 13:40	General View	 Load JPG	☒
80	21/05/18 13:40	General View	 Load JPG	☒
81	21/05/18 13:40	General View	 Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail Print
82	21/05/18 13:40	General View		Load JPG ☒
83	21/05/18 13:40	General View		Load JPG ☒
84	21/05/18 13:40	General View		Load JPG ☒
85	21/05/18 13:40	General View		Load JPG ☒
86	21/05/18 13:40	General View		Load JPG ☒
87	21/05/18 13:40	General View		Load JPG ☒
88	21/05/18 13:40	General View		Load JPG ☒
89	21/05/18 13:40	General View		Load JPG ☒
90	21/05/18 13:40	General View		Load JPG ☒
91	21/05/18 13:40	General View		Load JPG ☒
92	21/05/18 13:40	General View		Load JPG ☒
93	21/05/18 13:40	General View		Load JPG ☒
94	21/05/18 13:40	Reinspection Photo		Load JPG ☒
95	21/05/18 13:40	Reinspection Photo		Load JPG ☒
96	21/05/18 13:40	Reinspection Photo		Load JPG ☒
97	21/05/18 13:40	Reinspection Photo		Load JPG ☒
98	21/05/18 13:40	Reinspection Photo		Load JPG ☒
99	21/05/18 13:40	Reinspection Photo		Load JPG ☒
100	21/05/18 13:40	Reinspection Photo		Load JPG ☒
101	21/05/18 13:40	Reinspection Photo		Load JPG ☒
102	21/05/18 13:40	Reinspection Photo		Load JPG ☒
103	21/05/18 13:40	Reinspection Photo		Load JPG ☒
104	21/05/18 13:40	Reinspection Photo		Load JPG ☒
105	21/05/18 13:40	Reinspection Photo		Load JPG ☒
106	21/05/18 13:40	Reinspection Photo		Load JPG ☒
107	21/05/18 13:40	Reinspection Photo		Load JPG ☒
108	21/05/18 13:40	Reinspection Photo		Load JPG ☒
109	21/05/18 13:40	Reinspection Photo		Load JPG ☒
110	21/05/18 13:40	Reinspection Photo		Load JPG ☒
111	21/05/18 13:40	Reinspection Photo		Load JPG ☒
112	21/05/18 13:40	Reinspection Photo		Load JPG ☒
113	21/05/18 13:40	Reinspection Photo		Load JPG ☒
Documentation			1 per page	☒
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail Print
1	27/12/17 16:58	E-FILE REPORT (SLJ3560K)		Load PDF
2	27/12/17 17:06	KAH MOTOR - CHECKING ON LIABILITY		Load PDF
3	28/12/17 09:15	TP EST BILL		Load PDF
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
1	21/05/18 15:36	Supplementary		Load PDF

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			

Show Remarks To: ☐ Handling Insurer
Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co. Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18000060/T1TB2

Date: 21/05/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. Policy No: P27105154DMV
Claimant Vehicle No : SLJ3560K **Insured Vehicle No :** SJG654H
 Date of Loss: 22/12/2017 Nature of Claim: TP Claim No: 542418

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLJ3560K**
 Make & Model: HONDA HR-V, 1.5 (A) Engine No: L15B4531218
 Reg. Date: 07/12/2016 (Man. Year: 2016) Chassis No: JHMRU1810GX201217
 Colour: White Odometer: 16786 km
 Engine Capacity: 1496 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 215/60 R16 Rear Tyre Size: 215/60 R16
 Front Left Side: Dunlop 6 mm Rear Left Side: Dunlop 6 mm
 Front Right Side: Dunlop 6 mm Rear Right Side: Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,698.67	5,569.28	2,129.39	27.66
Miscellaneous Items	0.00	0.00	0.00	
Labour	16,340.00	13,970.00	2,370.00	14.50
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	24,038.67	19,539.28	4,499.39	18.72
+ GST 7.00/7.00% (S\$)	1,682.71	1,367.75	314.96	18.72
Nett Amount (S\$)	25,721.38	20,907.03	4,814.35	18.72

INSPECTION

Date of Assignment: 02/01/2018
 Date Inspected: 03/01/2018 Inspected At: Kah Motor Co Sdn Bhd (ALEXANDRA)
 NO. 255 ALEXANDRA ROAD
 SINGAPORE 159937
 Estimated Period of Repair: 14.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 21 May 2018)
Parts: M1-SUV HONDA HR-V 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's (Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SLJ3560K)
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SET,FR.GRILLE ASSY	Cracked	199.12 FS	*199.12 FS
2	1		*MOLDINGFR.GRILLE UPPER	Cut	139.57 FS	*139.57 FS
3	1		*MOLDINGFR.GRILLE	Necessary	32.10 FS	*32.10 FS
4	1		*EMBLEMFR	Necessary	19.42 FS	*19.42 FS
5	1		*NUTPUSH 3MM (2 PCS)	Necessary	2.85 FS	*2.85 FS
6	1		*FACEFR.BUMPER	Deformed	349.65 FS	*349.65 FS
7	18		*CLIPBUMPER	Necessary	27.00 FS	*27.00 FS
8	1		*FACE FR.BUMPER LOWER	Not Necessary	258.15 FS	*- FS
9	1		*GRILLEFR.BUMPER	Not Necessary	58.12 FS	*- FS
10	1		*BEAML.FR.BUMPER UPPER	Bent	17.92 FS	*17.92 FS
11	1		*BEAM COMPFR.BUMPER	Bent	177.45 FS	*177.45 FS
12	1		*HEAD LIGHT ASSY, L	Cracked	1,109.77 FS	*1,109.77 FS
13	1		*GARNISHL.FR.FOG LIGHT	Not Necessary	15.82 FS	*- FS
14	1		*LIGHT ASSYL.FR.FOGLIGHT	Not Necessary	176.25 FS	*- FS
15	1		*BRACKET.FOG LILGHT	Not Necessary	36.75 FS	*- FS
16	1		*SPACERR.FR.BUMPER SIDE	Necessary	7.80 FS	*7.80 FS
17	1		*SPACERL.FR.BUMPER SIDE	Necessary	7.80 FS	*7.80 FS
18	1		*VPC 4PCS REAR SENSORS	Not Working	320.00 FS	*320.00 FS
19	1		*LAMP UNITR	Not Necessary	321.52 FS	*- FS
20	1		*LAMP UNITL	Not Necessary	321.52 FS	*- FS
21	1		*LIGHT ASSY,R.LID	Not Necessary	198.45 FS	*- FS
22	1		*LIGHT ASSYL.LID	Not Necessary	198.45 FS	*- FS
23	1		*TAILGATE COMP	Bent	629.17 FS	*629.17 FS
24	1		*WEATHERSTRIPTAILGATE	Twisted	72.60 FS	*72.60 FS
25	1		*LOCK ASSYTAILGATE	Bent	57.45 FS	*57.45 FS
26	1		*LINING ASSYTAILGATE	Not Necessary	100.05 FS	*- FS
27	1		*EMBLEMRR	Necessary	9.67 FS	*9.67 FS
28	1		*EMBLEM. RR.I-VTEC	Necessary	10.57 FS	*10.57 FS
29	1		*REFLECTOR ASSYR.RR	Not Necessary	113.85 FS	*- FS
30	1		*REFLECTOR ASSYL.RR	Necessary	113.85 FS	*113.85 FS
31	1		*FACER.RR.BUMPER CORNER	Repair	69.22 FS	*- FS
32	1		*FACEL.RR.BUMPER CORNER	Repair	69.22 FS	*- FS
33	1		*SPACERR.RR.BUMPER SIDE	Necessary	8.62 FS	*8.62 FS
34	1		*SPACERL.RR.BUMPER SIDE	Necessary	8.62 FS	*8.62 FS
35	8		*CLIPBUMPER	Necessary	12.00 FS	*12.00 FS
36	1		*PANEL COMPRR.	Bent	274.27 FS	*274.27 FS
37	1		*LINING ASSYRR.PANEL	Not Necessary	32.25 FS	*- FS
38	1		*PANEL SETRR.FLOOR	Buckled	496.65 FS	*496.65 FS
39	1			Necessary	89.77 FS	*89.77 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
			*OILSHEET (3PCS)			
40	1		*RUBBER CR.WINDSHIELD DAMPER	Necessary	14.47 FS	*14.47 FS
41	1		*DAMPESTD 5X5	Necessary	6.22 FS	*6.22 FS
42	1		*RUBBER CL.WINDSHIELD DAMPER	Necessary	14.47 FS	*14.47 FS
43	1		*CAPPIVOT	Necessary	3.52 FS	*3.52 FS
44	4		*FASTENER BW/SHIELD	Necessary	9.60 FS	*9.60 FS
45	1		*FASTENER B (2PCS)	Necessary	7.35 FS	*7.35 FS
46	1		*FASTENER AW/SHIELD (2PCS)	Necessary	5.25 FS	*5.25 FS
47	2		*WINDSCREEN SEALANT	Necessary	120.00 FS	*120.00 FS
48	1		*HOOD COMPENGINE	Bent	588.90 FS	*588.90 FS
49	3		*OILSHEET	Not Necessary	89.77 FS	*- FS
50	1		*SUNDRIES	Necessary	100.00 FS	*30.00 FS
51	1		*CUSHION HOOD	Necessary	4.42 FS	*4.42 FS
52	1		*LABELCOOLANT INFORMATION	Necessary	3.67 FS	*3.67 FS
53	1		*LABLE AIR CON	Necessary	0.60 FS	*0.60 FS
54	1		*BUZZER ASSYSMART	Cracked	44.47 FS	*44.47 FS
55	1		*BEAMR.FR.GRILLE SIDE UPPER	Bent	29.02 FS	*29.02 FS
56	1		*BEAMR.FR.BUMPER UPPER	Bent	17.92 FS	*17.92 FS
57	1		*FACE,RR.BUMPER	Deformed	347.77 FS	*347.77 FS
58	1		*COVERRR.FLOOR UN	Deformed	88.72 FS	*88.72 FS
59	1		*SENSOR ASSYAMBIENT	Distorted	31.95 FS	*31.95 FS
60	1		*CLIPAMBIENT SENSOR	Necessary	3.22 FS	*3.22 FS
61	1		*GROMMET SCREW (2PCS)	Necessary	3.45 FS	*3.45 FS
62	2		*SCREWTAPPING 5X16	Necessary	0.60 FS	*0.60 FS
F=Franchise part. S=SpcNett.						
Total Parts (S\$)					7,698.67	5,569.28

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REMOVE & RENEW REVERSE SENSORS	New	180.00	180.00
2	SEALANT FOR REAR END PANEL	New	80.00	80.00
3	SEALANT FOR REAR FLOOR PANEL	New	80.00	80.00
4	SEALANT FOR TAILGATE	New	80.00	80.00
5	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER	New	150.00	150.00
6	REMOVE & INSTALL FUEL TANK FUEL PIPES	New	560.00	560.00
7	REMOVE & INSTALL SPEAKER BOARD RR SEATS TRUNK	New	560.00	560.00
8	REMOVE & TRANSFER ITEMS TO NEW TAILGATE ADJUST &	New	560.00	560.00
9	REMOVE & INSTALL RR. WINDSCREEN	New	560.00	560.00
10	WINDSCREEN DAM KIT	New	100.00	80.00
11	CUT OFF & RENEW RR PANEL	New	4,500.00	3,920.00
12	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS (6P)	New	3,000.00	2,700.00
13	REMOVE & RENEW RR FLOOR INSULATOR	New	450.00	450.00
14	REMOVE, RE-FIX AND ALIGN REAR VIEW CAMERA	New	380.00	380.00
15	APPLY BODY UNDERSIDE COATING	New	450.00	450.00
16	INSPECT FR LIGHTING MECHANISMS & FOCUS	New	150.00	150.00
17	REMOVE & RENEW FR BUMPER AND ALL DAMAGED PARTS	New	2,500.00	1,680.00
18	SPRAY PAINTING ON REPAIRED AND REPLACED AREAS (3P)	New	2,000.00	1,350.00
Gross Labour Cost (\$\$)			16,340.00	13,970.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >