

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : MSIG INSURANCE (SINGAPORE) PTE
16 RAFFLES QUAY
HONG LEONG BUILDING
SINGAPORE 048581
Registration No : SLJ3560K
Chassis No : JHMRU1810GX201217
Model : HRV DX-SIN CVT YM 2016
Owner's Name : KEE CHONG CHING
Ins Policy No. :
Date of Accident :

Document No. : SQT18000280 Page 1
Date : 18. Jan 2018
Customer No. : WZM003
Svc Advisor :
Engine No : L15B4531218
Date | Time : 18. Jan 2018 7:34:30 PM
Surveyor Name :
Survey Date :
Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	GST Amt	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO:) OWNER: OWNER INSURER: ACC DATE: SURVEYED BY: DATE: REF NO: TP INSURER: TP VEH: SUPPLEMENTARY						
74827-SLE-003	CUSHIONHOOD	1	5.90	25	4.42	0.31	4.73
19043-PNB-A00	LABELCOOLANT INFORMATION	1	4.90	25	3.67	0.26	3.93
80050-TG7-000	LABLE AIR CON	1	0.80	25	0.60	0.04	0.64
74940-TZ5-A01	BUZZER ASSYSMART	1	59.30	25	44.47	3.11	47.58
71150-T7A-000	BEAMR.FR.GRILLE SIDE UPPER	1	38.70	25	29.02	2.03	31.05
71140-T7A-000	BEAMR.FR.BUMPER UPPER	1	23.90	25	17.92	1.25	19.17
04715-T7A-900ZZ	FACE,RR.BUMPER	1	463.70	25	347.77	24.34	372.11
74646-T7A-010	COVERRR.FLOOR UN	1	118.30	25	88.72	6.21	94.93
80525-T2F-A01	SENSOR ASSYAMBIENT	1	42.60	25	31.95	2.24	34.19
91555-T7A-J01	CLIPAMBIENT SENSOR	1	4.30	25	3.22	0.23	3.45
90661-SC7-003	GROMMET SCREW	2	2.30	25	3.45	0.24	3.69
93903-45320	SCREWTAPPING 5X16	2	0.40	25	0.60	0.04	0.64
Sum Item					575.81	40.30	616.11

Survey By

Date & Time

Excess

Status

Signature

Total Amount 575.81 40.30 616.11

Total (Inclusive of GST) 616.11