

ASS. REC. BY:

REF:

C8/EG118000083/Kgb 02

Special Instruction:

Surveyor:

ASSIGNMENT (Office)

From (Person):

Yue Pei Li

of

EG1

Date/Time:

2/1/2018

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

STK 2846L

Insured:

XD 77688

at Workshop m/s

Accord Auto

Tel:

9740 0999 Jersey

of 10 ANIC #03-11

Policy No:

Claim No:

XD 77688 / SE / pl

Sum Insured:

Excess:

Make of Veh:

D.O.A.

28/12/2017

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

Person Contacted:

Vehicle IN OUT

Date/Time

Action/Instruction () Estimate

STK 2846L - X

XD 77688 - X.

04/1/18 @ 4.21pm revised to Pei Li by email.

15/5 11 Sep @ 1300 email (Paid \$1530.53, 54%)

ASSIGNMENT

From _____ Date 3/1
Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MY
To Inspect Vehicle No: STK 28461
at Workshop m/s Accord Auto.
of 10 AMC #03-11
Insured _____
Policy No. _____
Claims No. _____
Sum Insured _____ Excess _____
(Client's Record)
Make of Veh. _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

NS	OIS

Ball. or Market Value: 877K

IDAC Accident Rpt.: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 03 days Res.: Yes or No

Lum Sum: 20 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Vch No: STK 2846L Yr Regn: 10 08
 Type: Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: Toy Axi CC 1496
 Colour: Dark Grey A.C. Insured / Std / NI / NA
 Sp. Reading: 195732 T. Radio: Insured / Std / NI / NA
 Eng/No: _____
 Cr/No: NBE141 6087467
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Mod: Nil / 2Rim / STD A/Rim or
 Tyre Size: F: R195/65R15
 R: _____
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or Agenda

<u>Front</u>	<u>Rear</u>
R/Bal. <u>4</u> mm	R/Bal. <u>7</u> mm
L/Bal. <u>4</u> mm	L/Bal. <u>7</u> mm
D.O.A. <u>28/12/17</u>	D.O.A. <u>31/1/18</u>

 Survey held at ✓
 Des. of Damages: Frt Rear / O/S / N/S / U/C / Rooftop or
 The U/C / Chassis frame / Body Structure affected due to collision

Date / Time	Action / Instruction
-------------	----------------------

4/1 rate pass to Costumer

RECEIVED 10 MAY 2010

Date/Time: File Pass to? ☐ : Preli. Report
: *1/15/94* ☐ : Final Report
Date/Time: File Return to?

Days Of Repair: _____
Resurvey No. of Trip: _____

Survey Fee
Transportation

Add Fee:	<input type="checkbox"/>	Site Insp	\$
	<input type="checkbox"/>	Interview	\$
	<input type="checkbox"/>	Tech. Insp	\$
	<input type="checkbox"/>	Weekend	\$

Report Format : TP
Lump Sum / IEP : 1300

250




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
ERGO INSURANCE PTE LTD		Ref : CS/EGI18000083/Kqb		
5 TEMASEK BOULEVARD #04-01 SUNTEC TOWER FIVE SINGAPORE 038985		Date : 03-01-2018		
		Code : EGI		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	XD 7768S	Veh. Inspected	SJK 2846L	
Policy No.		Coverage (\$)	0.00	
Claim No.	XD 7768S/SE/pl	Excess (\$)	0.00	
Assign From	YEE PEI LI	Assign Date	03/01/2018	
2. Vehicle Particulars & Condition				
Make & Model	c.c			
Engine No.	Year of Reg.			
Chassis No.	Colour			
Odometer	Steering			
Brakes	Modification			
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	28/12/2017	Inspection Date		
Survey held at				
5a. Remarks				



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: XD7768S/SE/pl

Date: 27th December 2017

Our Ref: CS/EGI18000083/Kqb

Without Prejudice

The Motor Claims Department
ERGO Insurance Pte Ltd

Attn: Pei Li

Dear Sirs/Mdm

PRELIMINARY ADVICE OF VEHICLE NO. SJK 2846L


We thank you for the instruction on 02/01/2018.

Please be informed that we had conducted the inspection of the abovementioned vehicle on 03/01/2018 at the premises of M/s ACCORD AUTO and have the following to report:-

Workshop Estimate Amount	: S\$ <u>2,830.53</u>
Revised Estimate Amount	: S\$ <u>1,256.97</u>
"Check" Items Amount	: S\$ <u>1,191.94</u>
Market Value	: S\$ <u>-</u>
Salvage Value	: S\$ <u>-</u>
Nett Value	: S\$ <u>-</u>

Description of Damage:

The vehicle sustained damages at the front portion.



Comments/ Present Status:

Damages consistent.

Days of repair: 3 days.

We have NOT authorise repair.

Yours faithfully

KENNETH KONG
Licensed Appraiser

Catherine Chong (LKK Auto)

From: Survey Report (ERGO Insurance Pte. Ltd.) <Survey.Report@ergo.com.sg>
Sent: Tuesday, 2 January, 2018 10:48 AM
To: 'admin-d@lkkauto.com'
Subject: OI : XD7768S / TP : SJK2846L/LKK / DOA : 28/12/2017
Attachments: XD7768S - SAS.pdf; SJK2846L - SAS.pdf; SJK2846L - PRS FORM.pdf

Dear Catherine,

In compliance with "State Courts Practice Directions Amendment No.1 of 2016" in regards to the Pre Repair Survey, both TP repairer and ERGO Insurance Pte Ltd have agreed on your company **LKK AUTO CONSULTANTS PTE LTD** to be the "Single Joint Expert".

Please assist to conduct this survey from **ACCORD AUTO SERVICES PTE LTD**.

ADDRESS : 10 ANG MO KIO IND. PARK 2A
#03-11 ANG MO KIO AUTO POINT
SINGAPORE 568047

PERSON TO CONTACT : JESSY SOE @ 9740 0999 / 6481 9517

ERGO OFFICER-IN-CHARGE : STEVE LIM

Note: To survey on without prejudice basis. Obtain estimate and advise the consistency of damages to third party vehicle that you are require to conduct a re-survey before vehicle is returned to claimant. They are to contact your office directly. Please do keep us in the loop.

Please fill up the necessary on ERGO PRS Form from workshop and return to us together on your update of the survey status via Survey.Report@ergo.com.sg.

Attached are insured and TP's SAS (note: reports not to be released to any Third Party).

Kindly acknowledge receipt of this email.

Thank you

Yee Pei Li

Claims Assistant (Motor)
ERGO Insurance Pte. Ltd.
5 Temasek Boulevard
#04-01 Suntec Tower Five
Singapore 038985
Tel.: 65 6829 9199 DID: 65 6829 9194
Website: www.ergo.com.sg

ERGO is one of the major insurance groups in Germany and Europe. Worldwide, ERGO is represented in more than 30 countries and concentrates on Europe and Asia. ERGO is part of Munich Re (Group), one of the world's leading risk carriers.

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Thursday, 4 January, 2018 4:21 PM
To: 'Survey Report (ERGO Insurance Pte. Ltd.)'; Admin-D (LKKAUTO)
Cc: SUR
Subject: RE: OI : XD7768S / TP : SJK2846L/LKK / DOA : 28/12/2017
Attachments: CSEGI18000083Kqb.pdf

Dear Pei Li,

Enclosed herewith preliminary advice of SJK 2846L.

Wishes you a Happy New Year 2018

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Survey Report (ERGO Insurance Pte. Ltd.) [<mailto:Survey.Report@ergo.com.sg>]
Sent: Tuesday, 2 January, 2018 10:48 AM
To: Admin-D (LKKAUTO) <admin-d@lkkauto.com>
Subject: OI : XD7768S / TP : SJK2846L/LKK / DOA : 28/12/2017

Dear Catherine,

In compliance with "State Courts Practice Directions Amendment No.1 of 2016" in regards to the Pre Repair Survey, both TP repairer and ERGO Insurance Pte Ltd have agreed on your company **LKK AUTO CONSULTANTS PTE LTD** to be the "Single Joint Expert".

Please assist to conduct this survey from **ACCORD AUTO SERVICES PTE LTD**.

ADDRESS : 10 ANG MO KIO IND. PARK 2A
#03-11 ANG MO KIO AUTO POINT
SINGAPORE 568047

PERSON TO CONTACT : JESSY SOE @ 9740 0999 / 6481 9517

ERGO OFFICER-IN-CHARGE : STEVE LIM

Note: To survey on without prejudice basis. Obtain estimate and advise the consistency of damages to third party vehicle that you are require to conduct a re-survey before vehicle is returned to claimant. They are to contact your office directly. Please do keep us in the loop.

Please fill up the necessary on ERGO PRS Form from workshop and return to us together on your update of the survey status via Survey.Report@ergo.com.sg.

Attached are insured and TP's SAS (note: reports not to be released to any Third Party).

ERGO

Date: 02.01.2018
Our Reference: XD 7768S/SE/pl
Your Reference: SJK 2846L

Sent via Fax

or

Email

claims@mycarworkshop.com.sg

To: **ACCORD AUTO SERVICES PTE LTD**

Pre-Repair Survey (PRS) Acknowledgement

Vehicle For Inspection: SJK 2846L
Insured's Vehicle: XD 7768S
Date Of Accident: 28.12.2017


We acknowledge receipt of your request for PRS on: 29.12.2017

In compliance with "State Courts Practice Directions Amendment No.1 of 2016", do select an assessor from the list below and indicate your selection in the box marked *.

* LKK

AIS	Automobile Inspection Services Pte Ltd	LBS	L.B.S Auto Consultants Pte Ltd
FTA	FormTeam Consultancy Pte Ltd	LKK	LKK Auto Consultants Pte Ltd
IAS	Infiniti Appraisal Service	PS	Priority Services
JPk	JP Knights Pte Ltd	VAC	Vicom Ltd

- ☒ Your request for inspection does not have your client's cost of repair estimate, kindly forward a copy.
- ☐ Your request for inspection does not have your client's complete GIA report, kindly forward a copy.
- ☐ We acknowledge your interest for direct settlement, we will assess & revert soon upon receipt of estimate.
- ☐ Our Insured's driver has not reported the accident to us to date.
- ☒ Others: **OFFICER-IN-CHARGE - STEVE**

Prepared by:		Pei Li	6829 9194	claims@ergo.com.sg
Signature:				FAX : 6829 9247

Assessor use only:

Assignment Date: _____
Assignment Time: _____

Remarks:

Workshop use only:

Assessor attended workshop on:

Date: _____
Time: _____
Inspector: _____

☐ Vehicle not available at the appointed date and time.

Kindly acknowledge our Assessor presence for the above job.

Workshop Acknowledgement & Stamp.

Note: Our Inspection is on a without admission to liability basis.

Enquire Transfer Fee

Vehicle Details	
Vehicle No. :	SJK2846L
Vehicle Type :	Z10 - Private Hire (Chauffeur) Motor Car
Vehicle Attachment 1 :	No Attachment
Vehicle Scheme :	Normal
Vehicle Make :	TOYOTA
Vehicle Model :	COROLLA AXIO 1.5X A
Chassis No. :	NZE1416087467
Propellant :	Petrol
Engine No. :	1NZD104906
Engine Capacity :	1496 cc
Maximum Power Output :	81.0 kW (108 bhp)
Maximum Laden Weight :	1405 kg
Unladen Weight :	1130 kg
Year Of Manufacture :	2008
Original Registration Date :	14 Oct 2008
Lifespan Expiry Date :	-
COE Category :	A - Car (1600cc & below)
Quota Premium :	\$13,801.00
COE Expiry Date :	13 Oct 2018
Road Tax Expiry Date :	13 Apr 2018
PARF Eligibility Expiry Date :	13 Oct 2018
Inspection Due Date :	13 Oct 2019

ACCORD AUTO SERVICES PTE LTD

10 Ang Mo Kio Industrial Park 2A

#03-11 AMK Autopoint Singapore 568047

Tel: 6481 9518 / 6481 9517 Fax: 6481 9516 email: claims@mycarworkshop.com.sg

Not Authorised

ESTIMATE

ERGO Insurance Pte. Ltd.

5 Temasek Boulevard

#04-01 Suntec Tower Five

Singapore 038985

Attn: Motor Claims Department

61 Day @ 1300L
Repair After Rain
3 days

Date : 29/12/2017
Vehicle No : SJK2846L
Veh Make/Model : Toyota Corolla Axio 1.5x A
YOM : 2008
Chassis No : NZE1416087467
Date of Accident : 28/12/2017

No	Qty	Description	Amount \$
List Items:-			
1	1	Bonnet	\$ 678.90
2	2	Bonnet hinge	\$ 140.62
3	1	Bonnet lock	\$ 142.31
4	1	Bonnet seal	\$ 92.60
5	2	Bonnet stopper	\$ 37.52
6	1	Wiper garnish - LH	\$ 495.70
7	1	Wiper garnish - RH	\$ 455.80
8	1	Wiper side garnish - LH	\$ 70.16
9	1	Wiper side garnish - RH	\$ 70.16
10	1	Wiper garnish seal	\$ 59.14
11	1	Front grille	\$ 397.80
Total - List Item			\$ 2,640.71
Less 20%			\$ 528.14
Total			\$ 1,980.53
Labour Charges:-			
1		Spray painting on all affected area.	\$ 350.00
2		Labour remove/refix accident damages parts to knock, jack, cut weld and realign accident affected area.	\$ 400.00
3		To apply anti rust treatment.	\$ 100.00
Total - L/C			\$ 850.00
Sub-Total			
7% GST			\$ 138.64
Total			\$ 3,028.67

LKK Auto Consultants hence notify the Repairer of the following:

- to resurvey before spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- Repair and material cost(s) is allowed

Sub-Total \$ 2,830.53

7% GST \$ 198.14

Total \$ 3,028.67

Acknowledged by Repairer

Signature:


Date:

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
ERGO INSURANCE PTE LTD		Ref : CS/EGI18000083/Kqbn2	
5 TEMASEK BOULEVARD #04-01 SUNTEC TOWER FIVE SINGAPORE 038985		Date : 18-05-2018	
		Code : EGI	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	XD 7768S	Veh. Inspected	SJK 2846L
Policy No.		Coverage (\$)	0.00
Claim No.	XD 7768S/SE/pl	Excess (\$)	0.00
Assign From	YEE PEI LI	Assign Date	02/01/2018
2. Vehicle Particulars & Condition			
Make & Model	TOYOTA AXIO (A)	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2008
Chassis No.	NZE1416087467	Colour	METALLIC GREY
Odometer	195732	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	195/65 R15	DUNLOP	4 mm
L/H Front Tyre	195/65 R15	DUNLOP	4 mm
R/H Rear Tyre	195/65 R15	AGENDA	7 mm
L/H Rear Tyre	195/65 R15	AGENDA	7 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	28/12/2017	Inspection Date	03/01/2018
Survey held at	ACCORD AUTO SERVICES PTE LTD 10 ANG MO KIO INDUSTRIAL PARK 2A AMK AUTO POINT #03-11 SINGAPORE 568047		
5a. Remarks			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJK 2846L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	BONNET	BENT	678.90	678.90
2	BONNET HINGE	DISTORTED	140.62	140.62
1	BONNET LOCK	DISTORTED	142.31	142.31
1	BONNET SEAL	SERVICEABLE	92.60	-
2	BONNET STOPPER	SERVICEABLE	37.52	-
1	WIPER GARNISH-LH	SERVICEABLE	495.70	-
1	WIPER GARNISH-RH	DENTED / CRACKED	455.80	455.80
1	WIPER SIDE GARNISH-LH	SERVICEABLE	70.16	-
1	WIPER SIDE GARNISH-RH	SERVICEABLE	70.16	-
1	WIPER GARNISH SEAL	SERVICEABLE	59.14	-
1	FRONT GRILLE	SERVICEABLE	397.80	-
	LESS 25% DISCOUNT		-660.18	-354.41
			1,980.53	1,063.22
LABOUR				
	SPRAY PAINTING ON ALL AFFECTED AREA.		350.00	320.00
	LABOUR REMOVE/REFIX ACCIDENT DAMAGES PARTS TO KNOCK,JACK,CUT,WELD AND REALIGN ACCIDENT AFFECTED AREA.		400.00	250.00
	TO APPLY ANTI RUST TREATMENT.		100.00	30.00
			850.00	600.00
GRAND TOTAL			2,830.53	1,663.22
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				1,300.00

Report Ref No. CS/EGI18000083/Kqbn2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.