

Surveyor:

ASSIGNMENT (Office)

From (Person): Catherine Thia of MSIG Date/Time: 2/1/2018

Estimated Cost: \_\_\_\_\_ Bill to: \_\_\_\_\_

**OD / ~~TP~~ / WS / TP RES / OD RES / EVA / INV / MV / CS**

To Inspect Vehicle No: GBC 8536D Insured: GBA 2206G

at Workshop m/s Liu's Brother Tel: 67441730

of BK1 Kaki Bukit Ave 6 #01-01

Policy No: MSD/VCT/17-002325 Claim No: MSC/V/17-001972

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

Make of Veh: \_\_\_\_\_ D.O.A. 19/12/2017

(Client's Record)

CA / REV / REP. / REV 24 HRS H.O.D. Endorsement: \_\_\_\_\_

Date/Time: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle ☒ IN ☐ OUT

Date/Time	Action/Instruction ( ) Estimate
	<u>GBC 8536D - N</u>
	<u>GBA 2206G - V</u>
<u>04/01/18@</u>	<u>11:40am Informed Catherine Thia, we are pending estimate from repairer</u>

Signature: *W. C. C. U. S.*

REF:

MS16/

# ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV  
 To inspect Vehicle No: *GBC 8536D*  
 at Workshop m/s: *1. U'S B D*  
 of: \_\_\_\_\_  
 Insured: *GSA 22066*  
 Policy No. \_\_\_\_\_  
 Claims No. \_\_\_\_\_  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \_\_\_\_\_  
 IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No  
 GIA / PR Seen: *2* Consistent? : Yes or No  
 Est. Repairs: *6* days Res.: Yes or No  
 Lum Sum: *20* % 3 Val.: Yes or No  
 CA / REV / REP. / 24 HRS  
 Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

Veh No: *GBC 8536D* Yr Regn: *12 13*  
 Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
 Truck / Trailer or *nm /*  
 Make: *Toyota hiace* cc: *2982*  
 Colour: *blue* A.O. Insured / Std / NI / NA  
 Sp. Reading: *128840* T. Radio: Insured / Std / NI / NA  
 Eng. No: \_\_\_\_\_  
 C/No: *JTFHT029.00124144*  
 Gen. Cond: *Good* / Fair / Poor / Burnt  
 Steering: *In order* / Jammed / Leaked / Burnt or  
 Brake: *In order* / Jammed / Leaked / Burnt or  
 Mod: *Nil* / S/Rim / STD A/Rim or  
 Tyre Size: F: *195 R15*  
 R: \_\_\_\_\_  
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
 TOYO / YOKO or *Firenze*  
 Front *6* Rear *6*  
 R/Bal. *6* mm R/Bal. *6* mm  
 L/Bal. *6* mm L/Bal. *6* mm  
 D.O.A. *19/12/17* D.O.I. *3/1/18*  
 Survey held at \_\_\_\_\_  
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or  
*Rear*  
 The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time: *25/1/18* Action/ Instruction: *2/5 4530 conf. read with Susan (Red 8 4753.70, 51%)*

*Amant*  
*25/1/2018*

RECEIVED 25/1/2018

Date/Time: File Pass to? ☐ : Preli. Report  
*16/1/18* ☐ : Final Report  
 Date/Time: File Return to? \_\_\_\_\_

Days Of Repair: *6*  
 Resurvey No. of Trip: *1*

Add Fee: ☐ : Site Insp. IS  
☐ : Interview IS  
☐ : Tech. Ins IS  
☐ : Weekend IS

Report Format: *mer-7p*  
 Lump Sum / I.B. IS: *4550*

Survey Fee  
 Transportation  
 \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_

200
10
210




# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MSIG INSURANCE (SINGAPORE) PTE LTD		Ref : CS/MSG18000086/Uqb	
16 RAFFLES QUAY #24-01 HONG LEONG BLDG SINGAPORE 048581		Date : 03-01-2018	
Code : MSG			
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>			
Insured Veh.	GBA 2206G	Veh. Inspected	GBC 8536D
Policy No.	MSD/VCT/17-002325	Coverage (\$)	0.00
Claim No.	MSC/V/17-001972	Excess (\$)	0.00
Assign From	CATHERINE THIA	Assign Date	03/01/2018
<b>2. Vehicle Particulars &amp; Condition</b>			
Make & Model	c.c		
Engine No.	Year of Reg.		
Chassis No.	Colour		
Odometer	Steering		
Brakes	Modification		
General			
<b>3. Conditions of Tyres</b>			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
<b>4. Description of Damages on</b>			
<b>5. General Information</b>			
Accident Date	19/12/2017	Inspection Date	
Survey held at			
<b>5a. General Remarks</b>			



## ...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	19 Dec 2017		02 Jan 2018 17:37 Assign				<b>New Assignment</b> Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:

KST AUTO RENTAL PTE LTD, Co. Reg. No.: 200806860W

Main Claimant:

STVE PTE LTD, Co. Reg. No.: 198703585C

Vehicle Reg. No.:

GBC8536D

Date of Loss:

19/12/2017 10:00 - :59

Claim Type:

TP / MSC/V/17-001972

Policy/Cover Note No.:

MSD/VCT/17-002325 (Third Party Only)  
Coverage: 06/10/2017 - 05/10/2018

Vehicle Reg. No. (Insured):

GBA2206G

Policy No. (Claimant):

Excess:

Repairer:

Lius Brother Auto Workshop (HQ) Liu's Brother Auto Workshop, Blk 1 Kaki Bt Ave 6 #01-01 Auto Bay @ Kaki Bt Singapore 417883, 417883 Kaki Bukit - Tel: 67411730

Handling Insurer:

MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Catherine Thia Shi Yi - 6594 2545]

Adjuster:

LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 03/01/2018]

Driver/Custodian (Insured):

PERUMAL BALAJI (), NRIC: G7047213P, Tel: +6590504276

Adj Asg. Remarks:

please appoint Mr Marcus Chua to survey. Thank You.

ASSOCIATED MAIL RECEIVED

View All

Compose Case Mail

There are no mail for this case.

ALL ASSOCIATED TASKS

View All

Search Tasks

Create New Task

Complete

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	19/12/2017 21:24
Date Of Accident	19/12/2017 10:40
Exact Location Of Accident	ALONG SLE TOWARDS BKE BEFORE MANDAI RD EXIT
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	GBC8536D
<b>Insured/Policyholder</b>	
Name Of Registered Owner	STVE PTE LTD
Co Reg No	198703585C
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-64942897

### Vehicle Particulars

Manufacturer	TOYOTA
Model	HIACE MANUAL
Exact Purpose for which vehicle was being used at time of accident	COMMERCIAL
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE

### Insurance Company

Name of Insurance Company	FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	YES
Policy Number	D-17087422MFCV
Cover Note Number	N.A

### Driver

Name of Driver	MAJID BIN TAIB
NRIC No	S0196959E
Date Of Birth	20/06/1952
Occupation	OUTDOOR
Date Of Driving Pass	20/04/1979
Driving Experience	38 YEARS AND 7 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96247012
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	NIL
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	
	NAME: : BUANG BIN ANOOR
	GENDER: : MALE

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

I was driving along SLE towards BKE in the middle lane. in front of me was a motorcycle which was wobbling due to his jacket being stuck on his chain. Therefore I slowed down to avoid collision. However, after a few seconds, i felt an impact from the back. Vehicle GBA2206G had collided onto the rear portion of my vehicle. Followed by another car which collided onto GBA2206G. I did not manage to obtain his particulars. No injuries were involved.

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBA2206G
Vehicle Make/Model/Colour	TOYOTA / DYNA 150
Details Of Properties	NIL
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	NIL
NRIC/Passport Number	G7047213P
Contact Number	90504276
Address	
Postcode	
Insurance Company Name	

Nature Of Damage

No. Of Passenger (Including Driver)

1



— 12 —

**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This form must be completed by the policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance coverage or its benefits to be denied.
4. The subject and accuracy of this form for insurance companies is not an admission of policy liability on the part of insurance companies.
5. Any false statements made will be referred to the Police for investigation.
6. The report will be furnished by the members of the Oak Products Management Centre established by the General Insurance Association of Singapore (GIAS) for archiving and that copies of this report will be made available at discretion by interested parties.
7. By the submission of this report to the insurers, you hereby consent to the archiving of this report at the Centre and to copies of the report being made available at discretion.
8. Form made available pursuant to the Personal Data Protection Act (PDPA).

10) processing, handling and/or dealing with any claims, including the settlement of the claims and any necessary investigations relating to the claims.

## THE CURE

37. Investigating the accident and its causes.  
38. Carrying out similar testing with my instructions or responding to any enquiries by the  
39. Submitting the evidence concerning the making of correspondence, statements, invoices, reports or notices to me, which would involve  
40. Submitting the evidence concerning the making of correspondence, statements, invoices, reports or notices to me, which would involve

by disseminating my claims involving the mailing of correspondence, statements, answers, reports or  
disclosure of certain personal facts about me to bring about delivery of the same as well as on the external cover of envelopes, mass  
postage, and/or

(or complying with applicable law in storing, processing, handling and/or dealing with my claims (including the "Purposes")

(c) as a claimant who has incurred expenses involved in this accident and the Insurers' representative firms may be permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

**Ammar Hamdan bin**

## Introduction

**Postmaster's Signature / Date & Time**

Officer's Signature (If Officer is not the policyholder) / Date &amp; Time

Released by Reporting Centre  
Personnel

<p>             1st Row: BUE              2nd Row: before              3rd Row: Mandar              4th Row: 6/11           </p>		<p>             A: ABCB666D              B: GB922066              C: no details           </p>
--	--	--

ACCIDENT STATEMENT (2000 characters)

I was driving along SLE towards BKE in the middle lane. in front of me was a motorcycle which was wobbling due to his jacket being stuck on his chain. Therefore I slowed down to avoid collision. However, after a few seconds, i felt an impact from the back. Vehicle GBA2206G had collided onto the rear portion of my vehicle. Followed by another car which collided onto GBA2206G. I did not manage to obtain his particulars. No injuries were involved.

Tax Voucher No.:

DECLARATION

I/We declare that the above particulars & information provided above are true in every aspect

VERIFIED BY AJAX MARS REPORTING OFFICER -  
AMMAR HAMIZAN

MARS Officer



Registered Owner or Driver's Signature

Job Complete Date/Time

Date/Time:

## Enquire PARF/COE Rebate for Registered Vehicle

### Vehicle Owner Particulars

Owner ID Type:	Company
Owner ID:	3585C

### Vehicle Details

Vehicle No.:	GBC8536D
Vehicle to be Exported:	No
Intended De-registration Date:	02 Jan 2018
Vehicle Make:	TOYOTA
Vehicle Model:	HIACE MANUAL
Primary Colour:	Blue
Manufacturing Year:	2013
Engine No.:	1KD2330399
Chassis No.:	JTFHT02P100124144
Maximum Power Output:	-
Open Market Value:	\$25,820.00
Original Registration Date:	27 Dec 2013
First Registration Date:	27 Dec 2013
Transfer Count:	0
Actual ARF Paid:	\$1,291.00

### Intended PARF Rebate Details

PARF Eligibility:	No
PARF Eligibility Expiry Date:	-

PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 26 Dec 2023

COE Category: C - Goods Vehicle & Bus

COE Period(Years): 10

QP Paid: \$48,001.00

COE Rebate Amount: \$28,710.00

**Total Rebate Amount: \$28,710.00**

The information contained herein is correct as at 02 Jan 2018

OK

PARF Rebate Amount: \$0.00

**Intended COE Rebate Details**

COE Expiry Date: 26 Dec 2023

COE Category: C - Goods Vehicle & Bus

COE Period(Years): 10

QP Paid: \$48,001.00

COE Rebate Amount: \$28,710.00

**Total Rebate Amount: \$28,710.00**

The information contained herein is correct as at 02 Jan 2018

OK

**Subject:** MSIG Auto-Reply  
**From:** noreply@sg.msig-asia.com (noreply@sg.msig-asia.com)  
**To:** liusbro@ymail.com;  
**Date:** Tuesday, 2 January 2018, 15:18

Thank you for your email.

We will review your claim and our Claims Officer may contact you for more details, if required.

This is a system-generated acknowledgement. Please do not reply to this email address.

Regards  
Claims Services Department  
MSIG Insurance (Singapore) Pte Ltd  
Claims Hotline: +65 6827 7660 | E-mail: [claims@sg.msig-asia.com](mailto:claims@sg.msig-asia.com)

#### CONFIDENTIALITY NOTICE

This e-mail (including any attachments) may contain information that is privileged or confidential. The sending of this e-mail to any person other than the intended recipient is not a waiver of the privilege or confidentiality that attaches to it. If you are not the intended recipient, please notify the sender immediately, delete the email and do not copy, distribute or disclose its contents.



RECORDS MANAGEMENT CENTRE

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE  
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580  
Phone: +65 6224 0010 Fax: +65 6224 0030  
Operating Hours: Monday to Friday 9am to 5pm  
GST Registration No: M400017735

**Third Party Insurer Enquiry**

Our Ref No: GR-18-000465

Date of Request: 02/01/2018

Your Ref No: Online Purchase

LIU'S BROTHER AUTO WORKSHOP  
1 Kaki Bukit Ave 6 #01-01  
Auto Bay@Kaki Bukit  
Singapore 417883

Dear Sir/Madam,

Enquiry Date 02/01/2018  
Enquiry By Susan Low  
TP Vehicle No. GBA2206G  
Accident Date 19/12/2017

**Enquiry Result**

TP Vehicle No.	Insurer	Period of Insurance	Insurer Tel. No.
GBA2206G	MSIG Insurance (Singapore) Pte. Ltd.	06/10/2017-05/10/2018	+65 6827 7888

Thank You.

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

This is a computer generated document and requires no signature.

**Shiau Chan (LKKAuto)**

---

**From:** Do-Not-Reply <do-not-reply@merimen.com>  
**Sent:** Thursday, 4 January, 2018 11:40 AM  
**To:** catherine\_thia@sg.msig-asia.com  
**Cc:** SUR  
**Subject:** VEHICLE GBC 8536D (YOUR REF: MSC/V/17-001972)

This mail is associated with :  
**\*GBC8536D (MSC/V/17-001972)**  
**[GBA2206G]**  
TP  
STVE PTE LTD  
Dec 19 2017 10:00AM  
[KST AUTO RENTAL PTE LTD]  
Lius Brother Auto Workshop

Dear Catherine,

Please be informed that we have inspected the vehicle GBC 8536D on 03/01/2018.

We are pending for estimate from repairer.

Thanks & Regards,

Shiau Chan (Ms)  
LKK Auto Consultants Pte Ltd  
Tel: 6256 3561  
Fax: 6256 4315

[ This mail is sent from a mailer account - do not reply to this email address ]

Sent by : SHIAU CHAN (LKK Auto Consultants Pte Ltd)





RECORDS MANAGEMENT CENTRE

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE  
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580  
Phone: +65 6224 0010 Fax: +65 6224 0030  
Operating Hours: Monday to Friday 9am to 5pm  
GST Registration No: M400017735

**Third Party Insurer Enquiry**

Our Ref No: GR-18-000465

Date of Request: 02/01/2018

Your Ref No: Online Purchase

LIU'S BROTHER AUTO WORKSHOP  
1 Kaki Bukit Ave 6 #01-01  
Auto Bay@Kaki Bukit  
Singapore 417883

Dear Sir/Madam,

Enquiry Date 02/01/2018  
Enquiry By Susan Low  
TP Vehicle No. GBA2206G  
Accident Date 19/12/2017

**Enquiry Result**

TP Vehicle No.	Insurer	Period of Insurance	Insurer Tel. No.
GBA2206G	MSIG Insurance (Singapore) Pte. Ltd.	06/10/2017-05/10/2018	+65 6827 7888

Thank You.

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

This is a computer generated document and requires no signature.



# LIU'S BROTHER AUTO ENGINEERING WORKSHOP

No. 1 Kaki Bukit Avenue 5 #01-01 Auto Bay @ Kaki Bukit Singapore 417883

ROB No: 53291793J, Tel: 6744 1730 / 731, Fax: 6744 5746, Email: liubro@ymail.com

Invoice/Ref No: GBC8536D171219

## Estimate

### Customer

Name: MSIG Insurance (Singapore) Pte Ltd

Date: 02-01-18

Address: Motor Claims Department

Vehicle No: GBC8536D

4 Shenton Way #21-01

Model/Make: Toyota Hiace

SGX Centre 2

Singapore 068807

Manual

Item No.	Descriptions Of Parts	Original Quotation / Estimation	Revised Quotation / Cost Of Repair
1	Rear Tailgate <i>B. 6500</i>	\$ 1,850.00	
2	Tailgate Lock <i>400/3m</i>	\$ 359.00	
3	Tailgate Rubber <i>1m</i>	\$ 387.90	
4	Tailgate "Toyota" Emblem <i>new</i>	\$ 32.50	
5	Tailgate "Hiace" Emblem <i>new</i>	\$ 52.50	
6	Tailgate "Toyota Logo" Motif <i>new 66.50</i>	\$ 70.50	
7	Tailgate "70 KM/H" Sticker <i>new</i>	\$ 12.00	
8	Tailgate "8 Pax" Sticker <i>new</i>	\$ 12.00	
9	Tail Lamp 02 pcs (@ \$354.00) <i>one</i>	\$ 708.00	
10	Tailgate Windscreen Moulding <i>new 128.10</i>	\$ 219.00	
11	Tailgate Windscreen Sealant <i>new</i>	\$ 45.00	
12	Bumper <i>new</i>	\$ 416.00	
13	Bumper Clips 06 pcs (@ \$5.00) <i>11</i>	\$ 30.00	
14	Bumper Side Bracket 02 pcs (@ \$202.00) <i>sent 66.50 x 2</i>	\$ 404.00	
15	Bumper Reverse Sensor <i>shorted</i>	\$ 220.00	
16	End Panel Inner <i>new</i>	\$ 936.20	
17	End Panel Outer <i>B. 6500</i>	\$ 566.10	
18	Corner Panel Garnish 02 pcs (@ \$75.00) <i>0/500</i>	\$ 150.00	
19	Corner Panel Garnish Bracket 02 pcs (@ \$31.50) <i>11</i>	\$ 63.00	
20	"Company Advertisement" Sticker <i>new (25%)</i>	\$ 300.00	
	Remove and <del>refix</del> rear Bumper <del>distance</del> sensor	\$ 90.00	
	Remove and refix rear tailgate components & wiper mechanism	\$ 80.00	
	To check all wiring & electrical component for proper function	\$ 80.00	
	Labor for Panel Beating, Cut, Weld, Straighten & Replacing Parts Etc	\$ 1,200.00	
	To putty & spray painting & including touch up paint on accident affected area	\$ 800.00	
	To apply Rust Proofing, reseal tuff-coating treatment on accident area	\$ 100.00	
	Remove & reinstall Windscreen Glass to facilitate repairs	\$ 120.00	

Total Parts & Labour of estimate for damaged vehicle

\$ 9,303.70

Total amount in Lump Sum Basis for repaired vehicle

SDLS:

Tel: 6594 7060

Fax: 6338 1504



M/s Liu's Brother Auto Engrg Wks

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Not Authorized  
1/5 \$4550/  
6 day  
whipht. after apn  
31/1/18

P-4819-6

252

3614.7

5714.7

4671

### ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	19 Dec 2017		02 Jan 2018 17:37 <a href="#">Edit Adj Rpt</a>	<b>S\$4,550.00</b> <a href="#">Edit Estimates</a>	<b>S\$4,550.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS				[Created by insurer]
Insured:	KST AUTO RENTAL PTE LTD, Co. Reg. No.: 200806860W			
Main Claimant:	STVE PTE LTD, Co. Reg. No.: 198703585C			
Vehicle Reg. No.:	GBC8536D	Date of Loss:	19/12/2017 10:00 - :59	
Claim Type:	TP / MSC/V/17-001972	Policy/Cover Note No.:	MSD/VCT/17-002325 (Third Party Only) Coverage: 06/10/2017 - 05/10/2018	
Vehicle Reg. No. (Insured):	GBA2206G	Policy No. (Claimant):		
		Excess:		
Repairer:	Lius Brother Auto Workshop (HQ) Liu's Brother Auto Workshop, Blk 1 Kaki Bt Ave 6 #01-01 Auto Bay @ Kaki Bt Singapore 417883, 417883 Kaki Bukit - Tel: 67411730			
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Catherine Thia Shi Yi - 6594 2545]			
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Imm.Advice due 03/01/2018]			
Driver/Custodian (Insured):	PERUMAL BALAJI (), NRIC: G7047213P, Tel: +6590504276			
Adj Asg. Remarks:	please appoint Mr Marcus Chua to survey. Thank You.			

ASSOCIATED MAIL RECEIVED	<a href="#">View All</a>	<a href="#">Compose Case Mail</a>
There are no mail for this case.		

ALL ASSOCIATED TASKS										<a href="#">View All</a>	<a href="#">Search Tasks</a>	<a href="#">Create New Task</a>	<a href="#">Complete</a>
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?				
No results.													

## Claim Documents

\*GBC8536D (MSC/V/17-001972)

[GBA2206G]

































TP

STVE PTE LTD

Dec 19 2017 10:00AM

[KST AUTO RENTAL PTE LTD]

Lius Brother Auto Workshop

<a href="#">Upload Documents</a>		<a href="#">Upload Photos</a>	<a href="#">Compose New Letter</a>	<b>View</b> <a href="#">View in Browser</a>	
<b>Assessment Reports</b>				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	02/01/18 16:31	<b>Accident Statement</b> From: SC - Reg. No: GBA2206G, Claimant: KST AUTO RENTAL PTE LTD		Load HTM	
<b>Photos/Images</b>				3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	03/01/18 13:31	<b>Odometer Reading</b>		Load JPG	<input checked="" type="checkbox"/>
2	03/01/18 13:31	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
3	03/01/18 13:31	<b>Chassis Number</b>		Load JPG	<input checked="" type="checkbox"/>
4	03/01/18 13:31	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
5	03/01/18 13:31	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
6	03/01/18 13:31	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
7	03/01/18 13:31	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
8	03/01/18 13:31	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
9	03/01/18 13:31	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
10	03/01/18 13:31	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
11	03/01/18 13:31	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
12	03/01/18 13:31	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
13	03/01/18 13:31	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
14	03/01/18 13:31	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
15	03/01/18 13:31	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
16	03/01/18 13:31	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
17	03/01/18 13:31	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
18	03/01/18 13:31	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
19	03/01/18 13:31	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
20	03/01/18 13:31	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
21	03/01/18 13:31	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
22	03/01/18 13:31	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
23	03/01/18 13:31	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
24	03/01/18 13:31	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
25	03/01/18 13:31	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
26	03/01/18 13:31	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
27	03/01/18 13:31	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
28	03/01/18 13:31	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
29	03/01/18 13:31	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
30	03/01/18 13:31	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
31	03/01/18 13:31	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>

32	03/01/18 13:31	General View	1	Load JPG	<input checked="" type="checkbox"/>
33	08/01/18 08:09	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
34	08/01/18 08:09	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
35	08/01/18 08:09	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
36	08/01/18 08:09	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
37	08/01/18 08:09	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
38	08/01/18 08:09	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
39	08/01/18 08:09	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
40	08/01/18 08:09	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
41	08/01/18 08:09	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
42	08/01/18 08:09	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
43	08/01/18 08:09	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
44	08/01/18 08:09	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
45	08/01/18 08:09	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
46	08/01/18 08:09	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
47	08/01/18 08:09	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
48	08/01/18 08:09	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
49	08/01/18 08:09	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
50	08/01/18 08:09	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
51	08/01/18 08:09	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
52	08/01/18 08:09	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
53	08/01/18 08:09	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
54	08/01/18 08:09	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
55	08/01/18 08:09	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
56	08/01/18 08:09	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
57	08/01/18 08:09	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
58	08/01/18 08:09	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
59	08/01/18 08:09	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
60	08/01/18 08:09	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
61	08/01/18 08:09	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
62	08/01/18 08:09	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
63	08/01/18 08:09	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
64	08/01/18 08:09	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
65	08/01/18 08:09	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
66	08/01/18 08:09	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
67	08/01/18 08:09	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
68	21/01/18 10:35	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
69	21/01/18 10:35	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
70	21/01/18 10:35	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
71	21/01/18 10:35	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
<b>Documentation</b>				1 per page <input type="checkbox"/>	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	02/01/18 16:31	<b>GBC8536D E-FILE REPORT</b> From:SC - Reg. No: GBA2206G, Claimant: KST AUTO RENTAL PTE LTD	1	Load PDF	
2	02/01/18 16:31	<b>TP request for PRI</b> From:SC - Reg. No: GBA2206G, Claimant: KST AUTO RENTAL PTE LTD	1	Load PDF	
3	02/01/18 16:33	<b>TP agreed on SJE</b>	1	Load PDF	

## Documents Checklist

**DOCUMENTS CHECKLIST**

Reset

Save

Print

There are no document checklists configured.

**Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)****Show Remarks To:** ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

# LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18000086/UQBE2

Date: 29/01/2018

### REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: MSD/VCT/17-002325

Claimant Vehicle No: GBC8536D

Insured Vehicle No: GBA2206G

Date of Loss: 19/12/2017

Nature of Claim: TP

Claim No: MSC/V/17-001972

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: GBC8536D

Make &amp; Model: TOYOTA HIACE, 2.0 (M)

Engine No: 1KD2330399

Reg. Date: 27/12/2013 (Man. Year: 2013)

Chassis No: JTFHT02P100124144

Colour: Blue

Odometer: 128840 km

Engine Capacity: 2982 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): Market Value/New Car Price

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 195 R15

Rear Tyre Size: 195 R15

Front Left Side: Firenza 6 mm

Rear Left Side: Firenza 6 mm

Front Right Side: Firenza 6 mm

Rear Right Side: Firenza 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,833.70	3,914.70	2,919.00	42.71
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,470.00	1,800.00	670.00	27.13
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$\$)</b>	<b>9,303.70</b>	<b>5,714.70</b>	<b>3,589.00</b>	<b>38.58</b>
<b>Approved Total (Overridden) (\$\$)</b>		<b>4,550.00</b>		
<b>Nett Amount (\$\$)</b>	<b>9,303.70</b>	<b>4,550.00</b>	<b>4,753.70</b>	<b>51.09</b>

### INSPECTION

Date of Assignment: 02/01/2018

Date Inspected: 03/01/2018 Inspected At:

Liu's Brother Auto Workshop,  
Blk 1 Kaki Bt Ave 6 #01-01 Auto Bay @  
Kaki Bt  
Singapore 417883

Estimated Period of Repair: 6.0 days

**Adjuster:** MARCUS CHUA

**Manager:** SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*



## REPAIR DETAILS

### Reference

**Part Source:** (Last Synchronised: 29 Jan 2018)  
**Parts:** N/A TOYOTA HIACE 2.0 (M) (Model not available in database)  
**Labour:** Repairer's (Price-denominated Standard List)  
**Print Code:** (Unsubmitted, no print-code for GBC8536D)  
**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page  
**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAILGATE	Badly Dented	1,850.00 F	*1,850.00 FL
2	1		*REAR TAILGATE LOCK	Twisted / Jammed	359.00 F	*359.00 FL
3	1		*REAR TAILGATE RUBBER	Twisted	387.90 F	*387.90 FL
4	1		*REAR TAILGATE TOYOTA EMBLEM	Necessary	32.50 F	*32.50 FL
5	1		*REAR TAILGATE HIACE EMBLEM	Necessary	52.50 F	*52.50 FL
6	1		*REAR TAILGATE TOYOTA LOGO MOTIF	Necessary	70.50 F	*66.50 FL
7	1		*REAR TAILGATE 70KM/H STICKER	Necessary	12.00 FS	*10.00 FS
8	1		*REAR TAILGATE 8 PAX STICKER	Necessary	12.00 FS	*10.00 FS
9	2		*REAR TAIL LAMP	Cracked	708.00 F	*708.00 FL
10	1		*REAR TAILGATE WINDSCREEN MOULDING	Necessary	219.00 F	*128.10 FL
11	1		*REAR TAILGATE WINDSCREEN SEALANT	Necessary	45.00 F	*45.00 FL
12	1		*REAR BUMPER	Dented	416.00 F	*416.00 FL
13	6		*REAR BUMPER CLIPS	Not Necessary	30.00 F	*- FL
14	2		*REAR BUMPER SIDE BRACKET	Bent	404.00 F	*133.00 FL
15	1		*REAR BUMPER REVERSE SENSOR	Shorted	220.00 FS	*200.00 FS
16	1		*REAR END PANEL INNER	Repair	936.20 F	*- FL
17	1		*REAR END PANEL OUTER	Badly Dented	566.10 F	*566.10 FL
18	1		*REAR CORNER PANEL GARNISH	O/S Dented	150.00 F	*75.00 FL
19	2		*REAR CORNER PANEL GARNISH BRACKET	Not Necessary	63.00 F	*- FL
20	1		*REAR COMPANY ADVERTISEMENT STICKER	Necessary	300.00 FS	*80.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>6,833.70</b>	<b>5,119.60</b>
<b>- List Item Discount on L Items 0.00/25.00% (\$\$)</b>	<b>0.00</b>	<b>1,204.90</b>
<b>Total Parts (\$\$)</b>	<b>6,833.70</b>	<b>3,914.70</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	REMOVE AND REPLACING REAR BUMPER SENSOR	New	90.00	50.00
2	REMOVE AND REFIX REAR TAILGATE COMPONENTS & WIPER MECHANISM	New	80.00	60.00
3	TO CHECK ALL WIRING & ELECTRICAL COMPONENT FOR PROPER FUNCTION	New	80.00	30.00
4	LABOR FOR PANEL BEATING, CUT, WELD, STRAIGHTEN & REPLACING PARTS ETCS	New	1,200.00	800.00
5	TO PUTTY & SPRAY PAINTING & INCLUDING TOUCH UP PAINT ON ACCIDENT AFFECTED AREA	New	800.00	680.00
6	TO APPLY RUST PROOFING, RESEAL TUFF-COATING TREATMENT ON ACCIDENT AREA	New	100.00	60.00
7	REMOVE & REINSTALL WINDSCREEN GLASS TO FACILITATE REPAIRS	New	120.00	120.00
Gross Labour Cost (S\$)			2,470.00	1,800.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >