C/No :	
Action/Instruction:	
1.File 2.Submit Photo? YES / NO	
3.Indicate Res. Date On Photo Page? YES / NO	Message:
If No, due to a) No authorisation b) Days of repair	
others:	

CS TP1800 0089 UVD

dmin (): Case handler to make sure all Inform	mation created	by the assign	gnment tea	am are A
	Assign Form	Y-Date	N-Date	Y-Date	N-Date
C	Reference No.	~			
C	Customer Code				
N	Assign From				
c	Assign Date	~			
C	Veh No (Inspected)	~			
c	Veh No (Insured)				
	D.O.A	~			
С		2101			
С	Policy No				
С	Claim No		-		
С	Insurance Authorisation (CA /REV/REP)				
С	Report Type	~			1.
C	Weekend Charges		-	10-10-11-1	
N	Survey held at/Repairer	~			1
C	Excess				
Survey	40.0 90.0	the surveryor c	ompleted a	II required	informa
	nment Form	V		103550000000	
С	Vehicle No	~			V ===
С	Regn Month/Year	\ \ \			
N	Vehicle Type	-			
N	Make & Model	-	-		1
C	Engine Capacity. (C.C)	-	-	-	1
N	Colour				+
С	Odometer. (Sp.Reading)	V	-	-	+
C	Chassis No	~			-
N	General Condition	~		-	-
N	Steering				+
N	Brake	~			+
N	Modification (Modi)	~			-
C	Tyre Size	~			-
	Tyre Make	~			
N	Tyre Balance	~			
C	Date of Inspection	~			
C	Survey held	~			
N	Des.of Damages	~			
N					
(2) Syst	tem - (Views/Merimen)		T		
С	Damaged Vehicle Photographs Uploaded				
	rkshop Estimate/Assignment Form	T v	_		T
N	ALL Parts condition		1	1	
С	Market Value for OD cases			1	
C	Estimate Repair Cost for PRI (RSI, TMI, MSIG)	_	-	1	
С	Days of repair		-	1	
С	Finalised Amount		-	1	
C	Re-inspection Cases to Finalize within 5 Days				
(4) Sys	tem - (Views/Merimen)				
C	Resurvey photo Uploaded			-	

Check By: VERON 5 1/18

Case Handler Date



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

		Ref: CS/TP18000089/Uvb
FOR	TUNA MOTOR *	Ref : CS/TP18000089/Uvb
40 U 4552	IPPER EAST COAST ROADSING 212	APORE Date: 03-01-2018 Code: TP167
1.	Poli	cy Particulars :- THIRD PARTY CLAIM
	Insured Veh.	Veh. Inspected SFL 325D
	Policy No.	Coverage (\$) 0.00
	Claim No.	Excess (\$) 0.00
	Assign From	Assign Date 02/01/2018
2.		Vehicle Particulars & Condition
	Make & Model	c.c 0
	Engine No. HIDDEN	Year of Reg.
	Chassis No.	Colour
	Odometer -	Steering
	Brakes	Modification
	General	
3.		Conditions of Tyres
	Size	Make Balance
	R/H Front Tyre	mm
	L/H Front Tyre	mm
	R/H Rear Tyre	mm
	L/H Rear Tyre	mm
4.		Description of Damages
5.		General Information
	Accident Date	Inspection Date 02/01/2018
	Survey held at FORTUNA MC	DTOR
		ST COAST ROAD 455212
5a.	A)THE INSPECTION WAS COND	Remarks

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Singapore NRIC	
Owner ID:	1989A	
Vehicle Details		
Vehicle No.:	SFL325D	
Vehicle to be Exported:	No	
Intended De-registration Date:	03 Jan 2018	
Vehicle Make:	ТОУОТА	
Vehicle Model:	VIOS 1.5E M	
Primary Colour:	Silver	
Manufacturing Year:	2004	
Engine No.:	1NZX164469	
Chassis No.:	MR053HY4204082841	
Maximum Power Output:	80.0 kW (107 bhp)	
Open Market Value:	\$11,405,00	
Original Registration Date:	22 Jul 2004	
First Registration Date:	22 Jul 2004	
Transfer Count:	0	
Actual ARF Paid:	\$12,546.00	
Intended PARF Rebate De		
PARF Eligibility:	Forfeited	
PARF Eligibility Expiry Date:	Y. N	
PARF Rebate Amount:	\$0.00	
Intended COE Rebate Det		
COE Expiry Date:	21 Jul 2019	
COE Category:	A - Car (1600cc & below)	
COE Period(Years):	5	
PQP Paid:	\$33,293.00	
COE Rebate Amount:	\$10,310.00	
otal Rebate Amount: Message	\$10,310.00	
	E for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE	

The information contained herein is correct as at 03 Jan 2018



SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- Please report correctly the details of the accident to speed up the claims process.
- This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy ability
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

Any false reporting may be referred to the Police for investigation.

- This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singepore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7. By the todgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT	STAT	тым	HI V
ACCIDENT			

27/12/2017 15:51 Date Of Report

27/12/2017 13:30 Date Of Accident

JUNC OF UPPER EAST COAST RD & BEDOK SOUTH AVE 1 Exact Location Of Accident

SINGAPORE Country/State of Loss

DETAILS OF OWN VEHICLE

SFL325D Vehicle Registration Number

Insured/Policyholder

TANG TZE SOONG Name Of Registered Owner

S0151989A NRIC No.

NOEMAIL Email Address

(LOCAL) +65-96105668 Mobile Phone No OTHERS-96105668 Alternative Phone No.

Vehicle Particulars

TOYOTA Manufacturer VIOS 1.5E M Model

Exact Purpose for which vehicle was being used at PRIVATE USE

for repair to your vehicle?

Are you claiming under your own insurance policy NO

THIRD PARTY If No. Please state action to be taken PRIVATE CAR Vehicle Category

Insurance Company

NTUC INCOME INSURANCE CO-OPERATIVE LTD Name of Insurance Company

THIRD PARTY FIRE AND/OR THEFT Type Of Coverage

NO Fleet Policy

5015096433-11 Policy Number

Cover Note Number

Driver

TANG TZE SOONG Name of Driver

S0151989A NRIC No 10/12/1947 Date Of Birth INDOOR Occupation 07/05/1966 Date Of Driving Pass

51 YEARS AND 7 MONTHS Driving Experience

MALE Gender

(LOCAL) +65-96105668 Mobile Number

Fax Number

OTHERS-96105668 Contact Number

NOEMAIL EMail Address

Address

14 BAYSHORE ROAD

Postcode

469966

Was driver an employee of the Insured's Company NO If No, Relationship of the Driver with the Insured

Vehicle Registration Number of Driver's Own

OWNER

Vehicle

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident

COLLISION - HEAD TO REAR

Weather Conditions

CLEAR

Road Surface

DRY

Other Information

Was any foreign vehicle involved in this accident?

NO

Number of vehicles involved in the accident

Was any body injured in the Accident?

NO

Was any injured conveyed to hospital by

ambulance?

YES

Was any other material or property damaged? I have been approached by unknown person(s)

NO

soliciting/offering accident claims assistance. Number of Passengers (Including Driver)

Passenger 1

NAME:

TANG LING LING

GENDER:

FEMALE

Passenger 2

NAME:

SENG BOON HUANG

GENDER:

: FEMALE

Passenger 3

NAME:

: SENG PUI HUANG

GENDER:

: FEMALE

Details of Police Action

Was the accident reported to the police?

NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given?

NO

If Yes, against whom?

Circumstances of Accident

PLS REFER TO THE ATTACHED STATEMENT.

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

NO

Was there any audio recorded?

NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

SJF4214Z

Vehicle Make/Model/Colour

Details Of Properties

PRIVATE CAR

Vehicle Category

Name of Driver

TIMOTHY CHEONG HSIA WEN

NRIC/Passport Number

S8990240A

Contact Number

98243524

Address
Postcode
Insurance Company Name
Nature Of Damage

No. Of Passenger (Including Driver)

SKETCH PLAN

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- The report will be forwarded by the insurers of the GIA Records Management Centre established by the General insurance
 Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by
 interested parties.
- By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature

Date & Time:

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

edok	EST ESTO A - SM 75 F I
April East	Coast Road B = SJF 4214
	- ZA JBI
	LECP

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I h	as wa	rling at	Jundian cad and	of live	1
The	car a	+ itu		MIL	hack.
The	dati u	was S	DF 4214 Dec 20 Opm.	2.1	

		۱ΤI	

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature Date & Time: 27 Dec 2017

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No ::

Not Albaral Mala 1/5 \$ 3800 Siden.

FURTUNA MOTOR

SFL 325D

BOOTLD Bert/suc	\$495.10
BOOTLID HINGES @48.50	\$97.00 ×
BOOTLID WEATHERSTRIP TWI	\$121.10
BOOTLID INNER LOCK TWI	\$65.10
BOOTLID OUTER HANDLE AM	\$99.10 📈
BOOTLID REAR LOGO ~~	\$42.00
BOOTLID VIOS EMBLEM M	\$31.50
BOOTLID 1.5 EMBLEM NEC	\$38.50
BOOTLID VVTI EMBLEM MC	\$39.90
BOOTLID E EMBLEM M	\$30.94
TAILLAMPS @\$320.10	\$640.20
TAILLAMP HOUSING PANELS @\$126.80 /	\$253.60 🗶
REAR BUMPER 20/DE	\$360.95
REAR BUPMER SIDE RETAINERS @\$25.50	\$51.00
1 SET REAR BUMPER CLIPS ALL	\$50.00
REAR END PANEL 1500	\$719.70
REAR END PANEL TOP GARNISH TOLO	\$65.90
REAR FLOOR PANEL /	\$612.90 💢
REAR FLOOR PANEL TOP BOARD TOCA	\$145.50
(200)	\$3,959.99
War	\$3,959.99
S.NETT	21
1 SET REAR BUMPER REVERSE SENSOR	\$280.00 200
1 SET REAR END PANEL SEALANT	\$50.00

	Mark 1997	7200.00	and (1) 1
1 SET REAR END PANEL :	SEALANT M	\$50.00	-
RAER LICENCE PLATE	MY	\$30.00	X
TO CHECK WIRING		\$80.00	30

TO DISMANTLE & REPLACE REVERSE SENSOR \$80.00 TO TRANSFER BOOTLID MECHANISM \$100.00 60 \$120.00 Bo \$100.00 60 TO DISMANTLE & REFIX SEAT CUSHION UOHOLSTERY TO SPRAY RUST PROOFING \$1,080.00 280 LABOUR FOR PANEL BEATING ETCS \$1,200.00 7/80 TO PUTTY & SPRAY PAINTING TOTAL

LKK Auto Consultants hence notify

- . To no invey betweenter spray painting
- * Capies demanded parties) during resurvey
- . Tierts prices are subject to confirmation.
- . Third party survey is on a "Without Prejudice" basis
- . No illegal modification(s) is allowed
- . Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

	Affiliated to Federation Intern	ationale Des Experts En Auton	nobile	
FORTUNA MOTOR	***	Ref : CS/TP18000089/Uvbn2		
40 UPPER EAST COAST ROADSINGAPORE 455212		Date : 09-01-2018		
ON BEHALF OF TAN		Code: TP167		
1.	Policy Particula	ars :- THIRD PARTY CLAI		
Insured Veh.		Veh. Inspected	SFL 325D	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	02/01/2018	
2.		articulars & Condition		
Make & Model		c.c	1497	
Engine No.	HIDDEN	Year of Reg.	2004	
Chassis No.	MR053HY4204082841	Colour	SILVER	
Odometer	130161	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3.	Con	ditions of Tyres		
	Size	Make	Balance	
R/H Front Tyre	175/65 R14	YOKOHAMA	6 mm	
L/H Front Tyre	175/65 R14	YOKOHAMA	6 mm	
R/H Rear Tyre	175/65 R14	YOKOHAMA	6 mm	
L/H Rear Tyre	175/65 R14	YOKOHAMA	6 mm	
4.	Descri	ption of Damages		
THE VEHICLE S	USTAINED DAMAGES AT THE DETAILS.	REAR PORTION.		
5.	Gen	eral Information		
Accident Date	27/12/2017	Inspection Date	02/01/2018	
Survey held at	FORTUNA MOTOR			
	40 UPPER EAST COAST RO SINGAPORE 455212	DAD		
5a.		Remarks		
	TION WAS CONDUCTED ON A" NCE TO YOUR INSTRUCTIONS			
5b.	Estima	ate Days of Repair	AND AND AND AND ASSESSED.	

ESTIMATED NORMAL PERIOD FOR REPAIR:

5 Working Days



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SFL 325D

ty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			1000
1	BOOTLID	BENT / BUCKLED	495.10	495.10
2	BOOTLID HINGES @\$48.50	TO REPAIR SEE LABOUR	97.00	***************************************
1	BOOTLID WEATHERSTRIP	TWISTED	121.10	121.10
1	BOOTLID INNER LOCK	TWISTED	65.10	65.10
1	BOOTLID OUTER HANDLE	NOT NECESSARY	99.10	
1	BOOTLID REAR LOGO	NECESSARY	42.00	42.00
1	BOOTLID VIOS EMBLEM	NECESSARY	31.50	31.50
1	BOOTLID 1.5 EMBLEM	NECESSARY	38.50	38.50
1	BOOTLID VVTI EMBLEM	NECESSARY	39.90	39.90
1	BOOTLID E EMBLEM	NECESSARY	30.94	30.94
2	TAILLAMPS @\$320.10	CRACKED	640.20	640.20
2	TAILLAMP HOUSING PANELS @\$126.80	TO REPAIR SEE LABOUR	253.60	
1	REAR BUMPER	DENTED / DEFORMED	360.95	360.9
2	REAR BUMPER SIDE RETAINERS @\$25.50	BENT	51.00	51.00
1	SET REAR BUMPER CLIPS	NECESSARY	50.00	50.00
1	REAR END PANEL	BADLY DENTED	719.70	719.70
1	REAR END PANEL TOP GARNISH	TORN	65.90	65.9
1	REAR FLOOR PANEL	TO REPAIR SEE LABOUR	612.90	
1	REAR FLOOR PANEL TOP BOARD	TORN	145.50	145.50
	LESS 25% DISCOUNT	10000000000	-	-724.35
			3,959.99	2,173.04
	SPECIAL NETT ITEMS			
1	SET REAR BUMPER REVERSE SENSOR (SN)	SHORTED	280.00	200.00
1	SET REAR END PANEL SEALANT (SN)	NECESSARY	50.00	50.00
1	REAR LICENCE PLATE (SN)	NOT NECESSARY	30.00	0.000010000
			360.00	250.00
	LABOUR			
3	TO CHECK WIRING.		80.00	30.00
	TO DISMANTLE & REPLACE REVERSE SENSOR.		80.00	50.00
	TO TRANSFER BOOTLID MECHANISM.		100.00	60.00

Report Ref No. CS/TP18000089/Uvbn2



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO DISMANTLE & REFIX SEAT CUSHION UPHOLSTERY.		120.00	80.00
	TO SPRAY RUST PROOFING.		100.00	60.00
	LABOUR FOR PANEL BEATING ETCS.INCLUSIVE OF THE REPAIR OF BOOTLID HINGES, TAILLAMP HOUSING PANELS AND REAR FLOOR PANEL.		1,080.00	880.00
	TO PUTTY & SPRAY PAINTING.		1,200.00	1,180.00
			2,760.00	2,340.00
	GRAND TOTAL		7,079.99	4,763.04

RECOMMENDED COST OF LUMP SUM REPAIRS	3,800.00
(TO ITS PRE-ACCIDENT CONDITION)	

Report Ref No. CS/TP18000089/Uvbn2

CHUA KANG SENG

Licensed Appraiser