

ASS. REC. BY:

REF:

CS/MCG18000094/Kyb 02

Special 1:

02

Surveyor:

ASSIGNMENT (Office)

From (Person): Irene Tan of MCG Date: 3/1/2018

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: 8HB 7549H Insured: SKN 66728

at Workshop m/s Trans-Cab. Tel:

of No. 2 AMK St. 63.

Policy No: 28955935QMX Claim No: 542842

Sum Insured: Excess:

Make of Veh: D.O.B. 27/12/2017
(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O. Endorsement:

Date/Time: Person Contacted: Vehicle: OUT

| Date/Time | Action/Instruction () Estimate |
|-----------|---------------------------------|
| | 8HB 7549H - X |
| | SKN 66728 - X |
| 4/1/18 | Send preli revised by merimen |

ASS. REC. BY:

REF:

MSG

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

01 days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

S14B 754914

Yr Regn:

03, 12

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Chevrolet Epica

C.C.

1991

Colour

White/Red

A/C:

Insured / Std / NI / NA

Sp. Reading

381083

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

KL11A69RTBB 091670

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

195/65R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Giti

Front

Rear

R/Bal.

9

mm

R/Bal.

9

mm

L/Bal.

9

mm

L/Bal.

8

mm

D.O.A.

27/12/17

D.O.I.

3/1/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

Rear o/s

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

4/1

File passed to Customer

7

2000 (Red 15,366.85, 9810)

RECEIVED 03 JAN 2018

Date/Time, File Pass to?



: Prel. Report



: Final Report

1)

Date/Time, File Return to?

2)

4/1 - typist

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S - RS - SI

Photos

Others

TOTAL

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech Invs (\$



: Weekend (\$

Report Format:

merimen

Lump Sum / I.B.I: (\$

200/-

300

10

310

Survey Department Check List (Case Handler)

Reference No.: CS/MSG/1800094 Kvb

Policy Type: OD / TP / TP RES / TL / EVA

Case Handler

Typist

Admin (): Case handler to make sure all Information created by the assignment team are ACCURATE.

(1) Office Assign Form

| | | Y-Date | N-Date | Y-Date | N-Date |
|---|---------------------------------------|--------|--------|--------|--------|
| C | Reference No. | ✓ | | | |
| C | Customer Code | | | | |
| N | Assign From | | | | |
| C | Assign Date | ✓ | | | |
| C | Veh No (Inspected) | ✓ | | | |
| C | Veh No (Insured) | ✓ | | | |
| C | D.O.A | ✓ | | | |
| C | Policy No | ✓ | | | |
| C | Claim No | ✓ | | | |
| C | Insurance Authorisation (CA /REV/REP) | | | | |
| C | Report Type | ✓ | | | |
| C | Weekend Charges | | | | |
| N | Survey held at/Repairer | ✓ | | | |
| C | Excess | | | | |

Surveyor (

): Case handler to make sure the surveyor completed all required information.

(1) Assignment Form

| | | | | | |
|---|------------------------|---|--|--|--|
| C | Vehicle No | ✓ | | | |
| C | Regn Month/Year | ✓ | | | |
| N | Vehicle Type | ✓ | | | |
| N | Make & Model | ✓ | | | |
| C | Engine Capacity. (C.C) | ✓ | | | |
| N | Colour | ✓ | | | |
| C | Odometer. (Sp.Reading) | ✓ | | | |
| C | Chassis No | ✓ | | | |
| N | General Condition | ✓ | | | |
| N | Steering | ✓ | | | |
| N | Brake | ✓ | | | |
| N | Modification (Modi) | ✓ | | | |
| C | Tyre Size | ✓ | | | |
| N | Tyre Make | ✓ | | | |
| C | Tyre Balance | ✓ | | | |
| C | Date of Inspection | ✓ | | | |
| N | Survey held | ✓ | | | |
| N | Des.of Damages | ✓ | | | |

(2) System - (Views/Merimen)

| | | | | | |
|---|--------------------------------------|---|--|--|--|
| C | Damaged Vehicle Photographs Uploaded | ✓ | | | |
|---|--------------------------------------|---|--|--|--|

(3) Workshop Estimate/Assignment Form

| | | | | | |
|---|---|---|--|--|--|
| N | ALL Parts condition | ✓ | | | |
| C | Market Value for OD cases | | | | |
| C | Estimate Repair Cost for PRI (RSI, TMI, MSIG) | ✓ | | | |
| C | Days of repair | | | | |
| C | Finalised Amount | | | | |
| C | Re-inspection Cases to Finalize within 5 Days | | | | |

(4) System - (Views/Merimen)

| | | | | | |
|---|-------------------------|--|--|--|--|
| C | Resurvey photo Uploaded | | | | |
|---|-------------------------|--|--|--|--|

Check By: VERON 4/1/18
Case Handler Date

*C: Critical *N: Non-Critical

21/05/2014

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MSG INSURANCE (SINGAPORE) PTE LTD

Ref : CS/MSG18000094/Kvb

16 RAFFLES QUAY

#24-01 HONG LEONG BLDG SINGAPORE 048581

Date : 03-01-2018



Code : MSG

1. Policy Particulars :- THIRD PARTY CLAIM

| | | | |
|--------------|-------------|----------------|------------|
| Insured Veh. | SKN 6672S | Veh. Inspected | SHB 7549H |
| Policy No. | 28955935QMX | Coverage (\$) | 0.00 |
| Claim No. | 542842 | Excess (\$) | 0.00 |
| Assign From | IRENE TAN | Assign Date | 03/01/2018 |

2. Vehicle Particulars & Condition

| | | | |
|--------------|--------|--------------|---|
| Make & Model | | c.c | 0 |
| Engine No. | HIDDEN | Year of Reg. | |
| Chassis No. | | Colour | |
| Odometer | - | Steering | |
| Brakes | | Modification | |
| General | | | |

3. Conditions of Tyres

| | Size | Make | Balance |
|----------------|------|------|---------|
| R/H Front Tyre | | | mm |
| L/H Front Tyre | | | mm |
| R/H Rear Tyre | | | mm |
| L/H Rear Tyre | | | mm |

4. Description of Damages

| | |
|--|--|
| | |
|--|--|

5. General Information

| | | | |
|----------------|--|-----------------|------------|
| Accident Date | 27/12/2017 | Inspection Date | 03/01/2018 |
| Survey held at | TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111 | | |

5a. Remarks

| | |
|--|--|
| | |
|--|--|

...CLAIM SUBFOLDER...(New Assignment)

| CLAIM SUBFOLDER TRACKING | | | | | | | |
|--------------------------|-------------|---------------|--|---------|---------------|------------|--|
| Case | Notified | Est Submitted | Adj Assigned | Adj Rpt | Adj Submitted | Ins Auth'd | Status |
| Main | 27 Dec 2017 | | 03 Jan 2018 09:49 Assign | | | | New Assignment Cancel Case |

| Main | Reference | Claim Details | Documents | Show All | | | | | |
|---|-----------|---|------------|----------|---------|-------------|--------------|------------|-------|
| CLAIM SUBFOLDER DETAILS [Created by insurer] | | | | | | | | | |
| Insured: | | CHU JYH JENG, ID: S84759573 | | | | | | | |
| Main Claimant: | | TRANS-CAB SERVICES PTE LTD, Co. Reg. No.: 200303878K | | | | | | | |
| Vehicle Reg. No.: | | SHB7549H | | | | | | | |
| Claim Type: | | TP / 542842 | | | | | | | |
| Vehicle Reg. No. (Insured): | | SKN6672S | | | | | | | |
| Repairer: | | Trans-cab Services Pte Ltd- Ang Mo Kio (HQ) No. 2 Ang Mo Kio Street 63, 569111 Ang Mo Kio - Tel: | | | | | | | |
| Handling Insurer: | | MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Irene Tan Gek Ing - 6594 2541] | | | | | | | |
| Adjuster: | | LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 04/01/2018] | | | | | | | |
| Adj Asg. Remarks: | | OI DISPUTE NO DAMAGE TO REAR PORTION OF TAXI. | | | | | | | |
| ASSOCIATED MAIL RECEIVED View All Compose Case Mail | | | | | | | | | |
| There are no mail for this case. | | | | | | | | | |
| ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete | | | | | | | | | |
| Due Date | Priority | Type | Task Group | Subject | Handler | Assigned By | Completed On | Created On | Done? |
| No results. | | | | | | | | | |

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Irene Tan Gek Ing

Date: 04 Jan 2018

Preliminary Advice

| | | | |
|--------------------|---|-------------------------|--------------|
| Insured Vehicle No | : SKN6672S | Accident Date | : 27/12/2017 |
| TP Vehicle No | : SHB7549H | Assignment Date | : 03/01/2018 |
| Make | : CHEVROLET EPICA | Est. Duration of Repair | : 1.00 |
| Date of Inspection | : 03/01/2018 | | |
| Inspection At | : TRANS-CAB SERVICES PTE LTD- ANG MO KIO (HQ) NO. 2 ANG MO KIO STREET 63 SINGAPORE 569111 | | |

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear o/s portion and parts claimed are consistent to the accident.

| | | |
|-----------------------------|------|-----------|
| Repairer's Estimate (Gross) | :S\$ | 15,566.85 |
| Revised Amount | :S\$ | 200.00 |
| Check Items (Estimated) | :S\$ | 0.00 |
| Total | :S\$ | 200.00 |

| | | |
|-----------------|------|--|
| Lump Sum Repair | :S\$ | |
|-----------------|------|--|

Total Loss Consideration

| | | |
|--------------------|------|--|
| New for Old Value | :S\$ | |
| Pre-Accident Value | :S\$ | |
| COE / PARF Rebate | :S\$ | |
| Salvage Value | :S\$ | |
| Margin for Repair | :S\$ | |

Remarks

- () The vehicle is economical/not economical for repair.
- (X) The above survey was conducted on a 'without prejudice' basis.

Enquire PARF/COE Rebate for Registered Vehicle

| | |
|--------------------------------|---|
| Vehicle Owner Particulars | |
| Owner ID Type: | Company |
| Owner ID: | 3878K |
| Vehicle Details | |
| Vehicle No.: | SHB7549H |
| Vehicle to be Exported: | Yes |
| Intended De-registration Date: | 28 Dec 2017 |
| Vehicle Make: | CHEVROLET |
| Vehicle Model: | EPICA 2.0DSL AT ABS D/AB 2WD 4DR TURBO |
| Primary Colour: | Red |
| Manufacturing Year: | 2011 |
| Engine No.: | Z20S1454440K |
| Chassis No.: | KL1LA69RJBB091670 |
| Maximum Power Output: | 110.0 kW (147 bhp) |
| Open Market Value: | \$14,361.00 |
| Original Registration Date: | 30 Mar 2012 |
| First Registration Date: | 30 Mar 2012 |
| Transfer Count: | 0 |
| Actual ARF Paid: | \$14,361.00 |
| Intended PARF Rebate Details | |
| PARF Eligibility: | Yes |
| PARF Eligibility Expiry Date: | 29 Mar 2020 |
| PARF Rebate Amount: | \$10,052.00 |
| Intended COE Rebate Details | |

| | |
|---|--------------------------|
| COE Expiry Date: | 29 Mar 2020 |
| COE Category: | A - Car (1600cc & below) |
| COE Period(Years): | 8 |
| PQP Paid: | \$40,962.00 |
| COE Rebate Amount: | \$11,534.00 |
| Total Rebate Amount: | \$21,586.00 |
| Message | |
| Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier. | |

The information contained herein is correct as at 28 Dec 2017

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

| | |
|----------------------------|-------------------------------|
| Date Of Report | 27/12/2017 16:58 |
| Date Of Accident | 27/12/2017 08:50 |
| Exact Location Of Accident | BISHAN MRT STATION TAXI STAND |
| Country/State of Loss | SINGAPORE |

DETAILS OF OWN VEHICLE

| | |
|-----------------------------|----------------------------|
| Vehicle Registration Number | SHB7549H |
| Insured/Policyholder | |
| Name Of Registered Owner | TRANS-CAB SERVICES PTE LTD |
| Co Reg No | 200303878K |
| Email Address | CLAIMS@TRANSCAB.COM.SG |
| Mobile Phone No | |
| Alternative Phone No | OFFICE-62876666 |

Vehicle Particulars

| | |
|--|--|
| Manufacturer | CHEVROLET |
| Model | EPICA-2.0 2.0DSL AT ABS D/AB 2WD 4DR TUR (A) |
| Exact Purpose for which vehicle was being used at time of accident | HIRE AND REWARD |
| Are you claiming under your own insurance policy for repair to your vehicle? | NO |
| If No, Please state action to be taken | THIRD PARTY |
| Vehicle Category | TAXI |

Insurance Company

| | |
|---------------------------|-----------------------|
| Name of Insurance Company | AXA INSURANCE PTE LTD |
| Type Of Coverage | THIRD PARTY |
| Fleet Policy | YES |
| Policy Number | VPX/P1680520 |
| Cover Note Number | |

Driver

| | |
|----------------------|-----------------------|
| Name of Driver | WANG HUI-LIH |
| NRIC No | S2220654J |
| Date Of Birth | 08/01/1962 |
| Occupation | OUTDOOR |
| Date Of Driving Pass | 22/12/1999 |
| Driving Experience | 18 YEARS AND 0 MONTHS |
| Gender | MALE |
| Mobile Number | (LOCAL) +65-90089658 |
| Fax Number | |
| Contact Number | |
| E Mail Address | NOEMAIL |

SKETCH PLAN


IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**


I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:



Driver's Signature
(If driver is not the policyholder)
Date & Time:



Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

TRANS-CAB AUTO SERVICES PTE LTD
 NO.2 ANG MO KIO ST63 SINGAPORE 569111
 TEL NO. 6287 6666 FAX NO. 6257 1330
 CO/GST REG NO. 201019626G
SHB7549H - MSIG

AAD1712-292

Not Authored
CSG &

Vehicle No.:
 Chassis No.:
 Vehicle Make:
 Vehicle Model:
 Date of Accident :
 Third Party Insurer :

SHB7549H - JHOW
 KL1LA69RJB091670
 CHEVROLET
 EPICA 2.0
 27.12.2017
MSIG

| PART | | LIST | |
|------|---|-------------------------------------|---------------|
| 1 | 1 | Rear Bumper | \$ R 1,202.00 |
| 2 | 1 | Rear Bumper Beam | \$ R 239.94 |
| 3 | 1 | Rear Bumper Centre Absorber | \$ R 260.00 |
| 4 | 1 | Rear Bumper Side Retainer RH | \$ R 68.76 |
| 5 | 1 | Rear Bumper Side Retainer LH | \$ R 68.76 |
| 6 | 1 | Rear Bumper Reflectors RH | \$ R 119.74 |
| 7 | 1 | Rear Bumper Tow Hook Cover | \$ R 93.00 |
| 8 | 1 | Bootlid | \$ R 973.00 |
| 9 | 1 | Bootlid Weatherstrip | \$ R 344.28 |
| 10 | 1 | Bootlid Lock - Top | \$ R 466.56 |
| 11 | 1 | Bootlid 'CHEVROLET' Badge | \$ R 120.62 |
| 12 | 1 | Bootlid Logo | \$ R 138.84 |
| 13 | 1 | Bootlid 'EPICA LT' Badge | \$ R 119.84 |
| 14 | 1 | Bootlid Reflector Centre | \$ R 217.97 |
| 15 | 1 | Bootlid Reflector RH | \$ R 128.40 |
| 16 | 1 | Rear Tail Lamp RH | \$ R 479.30 |
| 17 | 1 | Rear Tail Lamp Panel RH | \$ R 359.00 |
| 18 | 1 | Rear Exhaust Box (Muffler A-EXH,RR) | \$ R 1,110.00 |
| 19 | 1 | Rear Fender RH | \$ R 1,145.00 |
| 20 | 1 | Rear Fender Inner Trim RH | \$ R 418.44 |

| | | |
|--------------|----|-----------------|
| TOTAL | \$ | 8,073.45 |
| 10% | \$ | 807.35 |
| | \$ | 7,266.11 |

Special Nett

| | | |
|---|------------------------------------|---------------|
| 1 | 1Set Licence Plate With Holder | \$ R 60.00 X |
| 2 | 1Set Bootlid inner trim board Clip | \$ R 40.00 X |
| 3 | 1Set Rear Bumper Parking Sensor | \$ R 300.00 X |

TRANS-CAB AUTO SERVICES PTE LTD**AAD1712-292**

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHB7549H - MSIG

| | | | | | |
|----|--------------------------------------|----|-----------|--------|---|
| 4 | 1Set Rear Bumper Fastener Clip | \$ | <i>nn</i> | 44.00 | } |
| 5 | 1Set Rear Fender Inner Trim Clip RH | \$ | <i>nn</i> | 30.00 | |
| 6 | 1Set Rear Bumper End Dust Cover Clip | \$ | <i>nn</i> | 30.00 | |
| 7 | 1 Rear Boot Sticker 'Trans-cab' | \$ | <i>nn</i> | 30.00 | |
| 8 | 1 Rear Boot Sticker '6555-3333' | \$ | <i>nn</i> | 30.00 | |
| 9 | 1 Rear Exhaust Mounting | \$ | <i>sh</i> | 10.00 | |
| 10 | 2 Rear Windscreen Sealant | \$ | <i>nn</i> | 80.00 | |
| 11 | 1 Rear Windscreen Inner Sponge Seal | \$ | <i>nn</i> | 100.00 | |
| 12 | 1 Spare Tyre | \$ | <i>sh</i> | 180.00 | |
| 13 | 1 Spare Wheel Rim | \$ | <i>sh</i> | 126.74 | |

| | | |
|--------------------|-----------|-----------------|
| TOTAL | \$ | 1,060.74 |
| TOTAL PARTS | \$ | 8,326.85 |

Panel Beating, Knocking And Straightening The
Necessary Portion, Remove And Renewal Of
Parts, Adjust And Realign The Same

\$ *sh* 2,700.00 X

To Check Electrical Lighting Concerned.

\$ *nn* 170.00 X

To Rust-Proofing Of The Affected Areas.

\$ *nn* 170.00 X

Putty And Spray Painting Of The Affected
Portion.

\$ 2,800.00 *200d*

To reinstall rear bumper parking sensor.

\$ *nn* 170.00 X

To Remove And Refit Rear W/Screen Glass To
Facilitate Bodywork Repair.

\$ *nn* 170.00 X

To transfer of boot fittings and conduct water
seepage test.

\$ *nn* 170.00 X

To transfer of Fender fittings, attachments and
perform water seepage test.

\$ *nn* 170.00 X

To remove and refit interior fittings, trimmings,
garnish, fittings and other, to enable repair.

\$ *nn* 380.00 X

TRANS-CAB AUTO SERVICES PTE LTD**AAD1712-292**

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHB7549H - MSIGTowing fees \$ *120.00* XTo check steering geometry and computer
wheel alignment \$ *220.00* X

| | | |
|--------------|----|------------------|
| | \$ | 7,240.00 |
| TOTAL | \$ | 15,566.85 |

Repair Days*10 Days*
1 day

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18000094/KVBN2

Date: 08/01/2018

REFERENCE

| | | | |
|-----------------------|--------------------------------------|----------------------|-------------|
| Handling Insurer: | MSIG Insurance (Singapore) Pte. Ltd. | Policy No: | 28955935QMX |
| Claimant Vehicle No : | SHB7549H | Insured Vehicle No : | SKN6672S |
| Date of Loss: | 27/12/2017 | Nature of Claim: | TP |
| | | Claim No: | 542842 |

DESCRIPTION & IDENTIFICATION OF VEHICLE

| | | | |
|-----------------------------|---|-------------|-------------------|
| Reg No: | SHB7549H | Engine No: | Z20S1454440K |
| Make & Model: | CHEVROLET EPICA, 2.0 2.0DSL AT ABS D/AB 2WD 4DR TUR (A) | Chassis No: | KL1LA69RJBB091670 |
| Reg. Date: | 30/03/2012 (Man. Year: 2011) | Odometer: | 381083 km |
| Colour: | Red/White | | |
| Engine Capacity: | 1991 cc | | |
| Market Value/New Car Price: | N/A | | |
| Sum Insured (S\$): | Market Value/New Car Price | | |

CONDITION OF VEHICLE AT THE TIME OF SURVEY

| | | | | |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition: | Steering (Serviceable): | Yes | Footbrake (Serviceable): | Yes |
| Handbrake (Serviceable): | Yes | Engine Modification: | No | Pre-accident Condition: |

CONDITION OF TYRES

| | | | |
|-------------------|-----------|------------------|-----------|
| Front Tyre Size: | 195/65R15 | Rear Tyre Size: | 195/65R15 |
| Front Left Side: | Giti 9 mm | Rear Left Side: | Giti 9 mm |
| Front Right Side: | Giti 9 mm | Rear Right Side: | Giti 9 mm |

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|-------------------------------|------------------|---------------|------------------|--------------|
| Parts | 8,326.84 | 0.00 | 8,326.84 | 100.00 |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 7,240.00 | 200.00 | 7,040.00 | 97.24 |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Gross Total (S\$) | 15,566.84 | 200.00 | 15,366.84 | 98.72 |
| + GST 7.00/7.00% (S\$) | 1,089.68 | 14.00 | 1,075.68 | 98.72 |
| Nett Amount (S\$) | 16,656.52 | 214.00 | 16,442.52 | 98.72 |

INSPECTION

| | | |
|-----------------------------|--------------------------|---|
| Date of Assignment: | 03/01/2018 | |
| Date Inspected: | 03/01/2018 Inspected At: | Trans-cab Services Pte Ltd- Ang Mo Kio (HQ) No. 2 Ang Mo Kio Street 63 Singapore 569111 |
| Estimated Period of Repair: | 1.0 days | |

Adjuster: KENNETH KONG

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

| | | |
|----------------------|--|--|
| Part Source: | MRM-SG | Version: 1.0 (Last Synchronised: 08 Jan 2018) |
| Parts: | 143 | CHEVROLET EPICA 2.0 2.0DSL AT ABS D/AB 2WD 4DR TUR (A) (Catalogue:Merimen Singapore 1.0) |
| Labour: | Repairer's | (Price-denominated Standard List) |
| Print Code: | (Unsubmitted, no print-code for SHB7549H) | |
| Validity: | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page | |
| Further Info: | Items/values not in reference catalogue are prefixed with an asterisk *. | |

Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|-----|-----|----------|--------------------------------------|---------------|-------------|--------|
| 1 | 1 | | *REAR BUMPER | Repair | 1,202.00 FL | *- FL |
| 2 | 1 | | *REAR BUMPER BEAM | Repair | 239.94 FL | *- FL |
| 3 | 1 | | *REAR BUMPER CENTRE ABSORBER | Serviceable | 260.00 FL | *- FL |
| 4 | 1 | | *REAR BUMPER SIDE RETAINER RH | Serviceable | 68.76 FL | *- FL |
| 5 | 1 | | *REAR BUMPER SIDE RETAINER LH | Serviceable | 68.76 FL | *- FL |
| 6 | 1 | | *REAR BUMPER REFLECTORS RH | Serviceable | 119.74 FL | *- FL |
| 7 | 1 | | *REAR BUMPER TOW HOOK COVER | Serviceable | 93.00 FL | *- FL |
| 8 | 1 | | *BOOTLID | Repair | 973.00 FL | *- FL |
| 9 | 1 | | *BOOTLID WEATHERSTRIP | Serviceable | 344.28 FL | *- FL |
| 10 | 1 | | *BOOTLID LOCK-TOP | Repair | 466.56 FL | *- FL |
| 11 | 1 | | *BOOTLID CHEVROLET BADGE | Not Necessary | 120.62 FL | *- FL |
| 12 | 1 | | *BOOTLID LOGO | Not Necessary | 138.84 FL | *- FL |
| 13 | 1 | | *BOOTLID EPICA LT BADGE | Not Necessary | 119.84 FL | *- FL |
| 14 | 1 | | *BOOTLID REFLECTOR CENTRE | Serviceable | 217.97 FL | *- FL |
| 15 | 1 | | *BOOTLID REFLECTOR RH | Serviceable | 128.40 FL | *- FL |
| 16 | 1 | | *REAR TAIL LAMP RH | Serviceable | 479.30 FL | *- FL |
| 17 | 1 | | *REAR TAIL LAMP PANEL RH | Repair | 359.00 FL | *- FL |
| 18 | 1 | | *REAR EXHAUST BOX (MUFFLER A-EXH,RR) | Repair | 1,110.00 FL | *- FL |
| 19 | 1 | | *REAR FENDER RH | Repair | 1,145.00 FL | *- FL |
| 20 | 1 | | *REAR FENDER INNER TRIM RH | Serviceable | 418.44 FL | *- FL |
| 21 | 1 | | *SET LICENCE PLATE WITH HOLDER | Serviceable | 60.00 FS | *- FS |
| 22 | 1 | | *SET BOOTLID INNER TRIM BOARD CLIP | Not Necessary | 40.00 FS | *- FS |
| 23 | 1 | | *SET REAR BUMPER PARKING SENSOR | Serviceable | 300.00 FS | *- FS |
| 24 | 1 | | *SET REAR BUMPER FASTENER CLIP | Not Necessary | 44.00 FS | *- FS |
| 25 | 1 | | *SET REAR FENDER INNER TRIM CLIP RH | Not Necessary | 30.00 FS | *- FS |
| 26 | 1 | | *SET REAR BUMPER END DUST COVER CLIP | Not Necessary | 30.00 FS | *- FS |
| 27 | 1 | | *REAR BOOT STICKER TRANS-CAB | Not Necessary | 30.00 FS | *- FS |
| 28 | 1 | | *REAR BOOT STICKER 6555-3333 | Not Necessary | 30.00 FS | *- FS |
| 29 | 1 | | *REAR EXHAUST MOUNTING | Serviceable | 10.00 FS | *- FS |
| 30 | 2 | | *REAR WINDSCREEN SEALANT | Not Necessary | 80.00 FS | *- FS |
| 31 | 1 | | *REAR WINDSCREEN INNER SPONGE SEAL | Not Necessary | 100.00 FS | *- FS |
| 32 | 1 | | *SPARE TYRE | Serviceable | 180.00 FS | *- FS |
| 33 | 1 | | *SPARE WHEEL RIM | Serviceable | 126.74 FS | *- FS |

F=Franchise part. S=SpcNett. L=ListItemDisc.

| | | |
|--|-----------------|-------------|
| Sub Total (\$\$) | 9,134.19 | 0.00 |
| - List Item Discount on L Items 10.00/10.00% (\$\$) | 807.35 | 0.00 |
| Total Parts (\$\$) | 8,326.84 | 0.00 |

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|-------------------------|--|----------|------------|--------|
| Labour Items | | | | |
| 1 | PANEL BEATING,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS,ADJUST AND REALIGN THE SAME | New | 2,700.00 | - |
| 2 | TO CHECK ELECTRICAL LIGHTING CONCERNED | New | 170.00 | - |
| 3 | TO RUST-PROOFING OF THE AFFECTED AREAS | New | 170.00 | - |
| 4 | PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION | New | 2,800.00 | 200.00 |
| 5 | TO REINSTALL REAR BUMPER PARKING SENSOR | New | 170.00 | - |
| 6 | TO REMOVE AND REFIT REAR W/SCREEN GLASS TO FACILITATE BODYWORK REPAIR | New | 170.00 | - |
| 7 | TO TRANSFER OF BOOT FITTINGS AND CONDUCT WATER SEEPAGE TEST | New | 170.00 | - |
| 8 | TO TRANSFER OF FENDER FITTINGS,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST | New | 170.00 | - |
| 9 | TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH,FITTINGS AND OTHER,TO ENABLE REPAIR | New | 380.00 | - |
| 10 | TOWING FEES | New | 120.00 | - |
| 11 | TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT | New | 220.00 | - |
| Gross Labour Cost (S\$) | | | 7,240.00 | 200.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >