

REF:

CC3 / MSG18000099 / Altbnz

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s _____
 of _____
 Insured: **FBC 1203K**
 Policy No: **MSD / VMT / 17-364650-CA**
 Claims No: **MCC / V / 18-000016**
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.

N/S	O/S

Bel. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: **SKZ 2601K** Yr Regn: **2016 Jan.**
 Type: M/Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____
 Make: **Toyota Altis** o/c **1598**
 Colour: **White** A/C: Insured / Std / NI / NA
 Sp. Reading: **31138** T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: **MROS3REit 104546090**
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Mod: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: **205/55R16**
 R: **205/55R16**
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or _____
 Front _____ Rear _____
 R/Bal. **06** mm R/Bal. **06** mm
 L/Bal. **06** mm L/Bal. **06** mm
 D.O.A. _____ D.O.I. **02/01/18**
 Survey held at: **Fastech**
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

TP MS16
SKZ 2601K - X
FBC 1203K - X

lump sum \$4,600/- (Red: 11, 109.36', 70%)

26/3/2018

RECEIVED 26 MAR 2018

Date/Time, File Pass to?



Preli. Report

26/3 Typist
 Date/Time, File Return to?



Final Report

2)

Days Of Repair: **6**Resurvey No. of Trip: **1**

Survey Fee:

Transportation:

3 - RS - SI

Photos

Others

Add Fee:



Site Insp \$



Interview \$



Tech. Insp \$



Weekend \$

Report Format:

Lump Sum / I.B.I: \$ **4,600/-**

TOTAL

300

10

310



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MSIG INSURANCE (SINGAPORE) PTE LTD		Ref : CC3/MSG18000099/Atb		
16 RAFFLES QUAY #24-01 HONG LEONG BLDG SINGAPORE 048581		Date : 03-01-2018		
		Code : MSG		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	FBC 1203K	Veh. Inspected	SKZ 2601K	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	02/01/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	01/01/2018	Inspection Date	02/01/2018	
Survey held at	FASTECH AUTO PTE LTD 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

Denise Tay (LKKAuto)

From: Denise Tay (LKKAuto)
Sent: Thursday, 4 January, 2018 3:37 PM
To: 'Katherine Wong'; Nabilah Rasol
Cc: SUR; Christopher Chionh; Accounts (LKKAuto); KKLau
Subject: DIRECT SURVEY INSPECTION ON WORKSHOP - FASTECH AUTO PTE LTD, DOA: 01/01/2018, SKZ 2601K (TP VEHICLE), FBC 1203K (OI VEHICLE)
Attachments: SKZ 2601K GIA.pdf

Dear Katherine and Nabilah,

Please be informed that we had inspected the vehicle SKZ 2601K at M/s: FASTECH AUTO PTE LTD, 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883 on 28/12/2017.

Enclosed herewith a copy of TP's GIA report. The estimated cost of repair will forward to you shortly.

Meanwhile, kindly provide us the claim reference number for our necessary action.

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	2089G
Vehicle Details	
Vehicle No.:	SKZ2601K
Vehicle to be Exported:	No
Intended De-registration Date:	02 Jan 2018
Vehicle Make:	TOYOTA
Vehicle Model:	TOYOTA COROLLA ALTIS 1.6L CVT
Primary Colour:	White
Manufacturing Year:	2015
Engine No.:	1ZRX554580
Chassis No.:	MR053REH104546090
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$19,589.00
Original Registration Date:	15 Jan 2016
First Registration Date:	15 Jan 2016
Transfer Count:	0
Actual ARF Paid:	\$19,589.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	14 Jan 2026
PARF Rebate Amount:	\$14,691.00
Intended COE Rebate Details	
COE Expiry Date:	14 Jan 2026
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$45,002.00
COE Rebate Amount:	\$36,146.00
Total Rebate Amount:	\$50,837.00

The information contained herein is correct as at 02 Jan 2018

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	02/01/2018 11:12
Date Of Accident	01/01/2018 01:55
Exact Location Of Accident	BKE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKZ2601K
Insured/Policyholder	
Name Of Registered Owner	TAY SOH LIAN
NRIC No	S1172089G
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-96908995
Alternative Phone No	OTHERS-96908995

Vehicle Particulars

Manufacturer	TOYOTA
Model	COROLLA ALTIS-1.6 L CVT (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	2100447852-01000
Cover Note Number	

Driver

Name of Driver	KEVIN NEO JIA HUI
NRIC No	S9242462F
Date Of Birth	09/11/1992
Occupation	INDOOR
Date Of Driving Pass	27/05/2015
Driving Experience	2 YEARS AND 7 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-87520053
Fax Number	
Contact Number	
Email Address	KEVIN.NEO.JH@GMAIL.COM

Address	BLK 22 TEBAN GARDENS ROAD # 21-139 SINGAPORE
Postcode	600022
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	RELATIVE
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	3
Passenger 1	NAME: : JOUYEE LEE GENDER: : FEMALE
Passenger 2	NAME: : HENRY GENDER: : MALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO ATTACH STATEMENT RECORDED BY JIA MIN - PROGRESSIVE AUTOMOTIVE PTE LTD TEL 67415336

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	FBC1203K
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	MOTORCYCLE
Name of Driver	MUHAMMAD SAIFUL ADLY BIN MASDUKI
NRIC/Passport Number	S9523145D
Contact Number	
Address	
Postcode	

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:



21/1/18 11.15am

Driver's Signature
(If driver is not the policyholder)
Date & Time:



Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



Jia Min

Sketch Plan #2

SKETCH PLAN

	<p>Vehicle No</p> <p>A - SK22801K</p> <p>B - FBC203K</p> <p>Legend</p> <div style="display: flex; justify-content: space-around;"> <div style="text-align: center;"> Vehicle </div> <div style="text-align: center;"> Bike </div> </div>
--	---

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was driving along BKE

I was driving ^{straight} along BKE toward wetlands, I slowed down ~~at~~

then the motorbike bang me from behind

- 1) Janyee Lee (women)
- 2) Henry (men)

DECLARATION

I/We declare the foregoing particulars are true in every respect.
 Please be advised that your insurer may have a 14 day clause whereby the claim against own policy must be made within the stipulated timeframe from the date of occurrence. Kindly check your policy for more details.

Policyholder's Signature

Date & Time:

21/11/11 11:15am

GIARMC SketchPlanForm_V3

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

John Min

FASTECH AUTO PTE LTD

page 1/2

1 Kaki Bukit Ave 6 #01-48 Autobay

Singapore 417883

Tel No: 67452063 / 67467158 Fax No: 67458520

Tax Reg No : 20-0006262-D

Estimate : 20066

Date : 02.01.2018

Vehicle Num : ~~8FZ~~ 2601K

Make/Model : TOYOTA ALTIS

Chassis/Engine no :

Accident Date : 01.01.2018

Claim No : 0118-20066

Reference :

Policy No :

TP MS16.

Denise.

MROS3REH 104546080

Qty	Particular	Amount S\$
<u>List Item :</u>		
1 pc	Rear bootlid <i>Dented.</i>	\$ 1,025.20 <i>788.50</i>
2 pc	Rear boot hinga @85.70 <i>new</i>	\$ 171.40 <i>x</i>
1 pc	Rear boot lock <i>Dented</i>	\$ 389.50 <i>281.50</i>
1 pc	Rear boot catch <i>new</i>	\$ 52.50 <i>x</i>
1 pc	Rear boot rubber <i>new</i>	\$ 265.60 <i>x</i>
1 pc	Rear bootlid emblem COROLLA <i>new</i>	\$ 44.90 <i>✓</i>
1 pc	Rear bootlid emblem ALTIS	\$ 51.50 <i>✓</i>
1 pc	Rear boot centre moulding <i>new</i>	\$ 395.50 <i>214.50</i>
1 pc	Rear boot centre emblem <i>new</i>	\$ 48.50 <i>✓</i>
2 pc	Rear boot reflector lamp @391.50 <i>all cracked</i>	\$ 783.00 <i>286 x</i>
1 pc	Rear boot inner board <i>new</i>	\$ 581.50 <i>x</i>
2 pc	Rear boor number plate lamp @82.20 <i>new</i>	\$ 164.40 <i>x</i>
2 pc	Rear taillamp @562.70 <i>RH cracked</i>	\$ 1,125.40 <i>390.50</i>
2 pc	Rear taillamp panel @124.80 <i>RHS</i>	\$ 221.20 <i>x</i>
2 pc	Rear taillamp lower bracket @47.90 <i>new</i>	\$ 95.80 <i>x</i>
1 pc	Rear end panel <i>Dented</i>	\$ 845.20 <i>595</i>
1 pc	Rear end panel top garnish <i>deformed</i>	\$ 291.60 <i>✓</i>
1 pc	Rear spare tyre panel <i>new</i>	\$ 1,230.20 <i>x</i>
1 pc	Rear spare tyre top cover board <i>new</i>	\$ 351.20 <i>x</i>
1 pc	Rear bumper <i>Deformed</i>	\$ 968.50 <i>589.80</i>
2 pc	Rear bumper side retainer short @103.90 <i>new</i>	\$ 207.80 <i>x</i>
2 pc	Rear bumper side retainer long @85.70 <i>new</i>	\$ 171.40 <i>✓</i>
2 pc	Rear bumper reflector @85.70 <i>RH cracked</i>	\$ 171.40 <i>85.70</i>
1 pc	Rear bumper reinforcement with sponge <i>Bent</i>	\$ 596.50 <i>395</i>
2 pc	Rear fender inner garnish @489.40 <i>new</i>	\$ 978.80 <i>x</i>
1 pc	Antenna key <i>Dented</i>	\$ 395.20 <i>157</i>
1 pc	Rear exhaust silencer <i>Bent</i>	\$ 925.20 <i>✓</i>
2 pc	Rear exhaust rubber @73.90 <i>new</i>	\$ 147.80 <i>x</i>
List Item Total :		\$ 12,696.70
Discount 20 %		\$ 2,539.34
		\$ 10,157.36

5327

3995.25

FASTECH AUTO PTE LTD

page 2/2

1 Kaki Bukit Ave 6 #01-48 Autobay

Singapore 417883

Tel No: 67452063 / 67467158 Fax No: 67458520

Tax Reg No : 20-0006262-D

Estimate : 20066

Date : 02.01.2018

Vehicle Num : SJZ 2601K

Make/Model : TOYOTA ALTIS

Chassis/Engine no :

Accident Date : 01.01.2018

Claim No : 0118-20066

Reference :

Policy No :

Qty	Particular	Amount S\$
		B/F \$ 10,157.36
<u>Special Nett Item :</u>		
1 pc	Rear number plate <i>new</i>	\$ 45.00 4
10 pc	Rear boot inner baord clips @12.90 <i>new</i>	\$ 129.00 4
1 pc	Rear end panel top garnish clips @12.90 <i>new</i>	\$ 51.60 ¹⁵
1 pc	Rear end panel sealant <i>new</i>	\$ 80.00 ⁶⁰
12 pc	Rear fender inner garnish @12.90 <i>new</i>	\$ 154.80 4
1 pc	Rear spare tyre top insulator <i>new</i>	\$ 250.00 4
4 pc	Rear taillamp clip @12.90 <i>new</i>	\$ 51.60 ¹⁰
1 pc	Rear reverse camera <i>new</i>	\$ 650.00 4
1 set	Rear reverse sensor <i>new</i>	\$ 550.00 ²⁰⁰
Special Nett Total :		\$ 1,962.00

Labour Charge :

To check wiring	\$ 120.00 ³⁰
Tuff kote	\$ 150.00 ⁴⁰
Remove and replace reverse sensor	\$ 160.00 ⁵⁰
Remove and replace exhaust pipe	\$ 160.00 ⁸⁰
To spray paint affected portion	\$ 1,500.00 ⁷⁰⁰
To remove and replace spare part and panel beating	\$ 1,500.00 ⁶⁰⁰
Labour Charge Total :	\$ 3,590.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:

FASTECH AUTO PTE LTD

Total Amount : \$ 15,709.36

total 5880.25
4.6k 06 days

4.6/10

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/MSG18000099/ATBN2

Date: 27/03/2018

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	MSD/VMT/17-364650-CA
Claimant Vehicle No :	SKZ2601K	Insured Vehicle No :	FBC1203K
Date of Loss:	02/01/2018	Nature of Claim:	TP
		Claim No:	MSC/V/18-000016

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKZ2601K	Engine No:	1ZRX554580
Make & Model:	TOYOTA COROLLA ALTIS, 1.6 L CVT (A)	Chassis No:	MR053REH104546090
Reg. Date:	15/01/2016 (Man. Year: 2015)	Odometer:	31138 km
Colour:	White		
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55R16	Rear Tyre Size:	205/55R16
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	12,119.36	4,280.25	7,839.11	64.68
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,590.00	1,500.00	2,090.00	58.22
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	15,709.36	5,780.25	9,929.11	63.21
Approved Total (Overridden) (\$\$)		4,600.00		
(\$\$)	15,709.36	4,600.00	11,109.36	70.72
+ GST 7.00/7.00% (\$\$)	1,099.66	322.00	777.66	70.72
Nett Amount (\$\$)	16,809.02	4,922.00	11,887.02	70.72

INSPECTION

Date of Assignment:	05/01/2018	
Date Inspected:	02/01/2018 Inspected At:	Fastech Auto Pte Ltd (HQ) 1 Kaki Bukit Ave 6, #01-46/48/50 Autobay Singapore 417883

Estimated Period of Repair: 6.0 days

Adjuster: ADRIAN LING

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our

knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 27 Mar 2018)
Parts: 143	TOYOTA COROLLA ALTIS 1.6 L CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SKZ2601K)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*REAR BOOTLID	Dented	1,025.20 FL	*798.50 FL
2	2	*REAR BOOT HINGA	Not Necessary	171.40 FL	*- FL
3	1	*REAR BOOT LOCK	Damaged	389.50 FL	*281.50 FL
4	1	*REAR BOOT CATCH	Not Necessary	52.50 FL	*- FL
5	1	*REAR BOOT RUBBER	Not Necessary	265.60 FL	*- FL
6	1	*REAR BOOTLID EMBLEM COROLLA	Necessary	44.90 FL	*44.90 FL
7	1	*REAR BOOTLID EMBLEM ALTIS	Necessary	51.50 FL	*51.50 FL
8	1	*REAR BOOT CENTRE MOULDING	Cut	395.50 FL	*214.50 FL
9	1	*REAR BOOT CENTRE EMBLEM	Necessary	48.50 FL	*48.50 FL
10	1	*REAR BOOT REFLECTOR LAMP	N/s Cracked	783.00 FL	*286.40 FL
11	1	*REAR BOOT INNER BOARD	Not Necessary	581.50 FL	*- FL
12	2	*REAR BOOT NUMBER PLATE LAMP	Not Necessary	164.40 FL	*- FL
13	1	*REAR TAILLAMP	O/s Cracked	1,125.40 FL	*390.50 FL
14	2	*REAR TAILLAMP PANEL	Repair	221.20 FL	*- FL
15	2	*REAR TAILLAMP LOWER BRACKET	Not Necessary	95.80 FL	*- FL
16	1	*REAR END PANEL	Dented	845.20 FL	*595.00 FL
17	1	*REAR END PANEL TOP GARNISH	Deformed	291.60 FL	*291.60 FL
18	1	*REAR SPARE TYRE PANEL	Not Necessary	1,230.20 FL	*- FL
19	1	*REAR SPARE TYRE TOP COVER BOARD	Not Necessary	351.20 FL	*- FL
20	1	*REAR BUMPER	Deformed	968.50 FL	*589.80 FL
21	2	*REAR BUMPER SIDE RETAINER SHORT	Not Necessary	207.80 FL	*- FL
22	2	*REAR BUMPER SIDE RETAINER LONG	Necessary	171.40 FL	*171.40 FL
23	1	*REAR BUMPER REFLECTOR	O/s Cracked	171.40 FL	*85.70 FL
24	1	*REAR BUMPER REINFORCEMENT WITH SPONGE	Bent	596.50 FL	*395.00 FL
25	2	*REAR FENDER INNER GARNISH	Not Necessary	978.80 FL	*- FL
26	1	*ANTENNA KEY	Damaged	395.20 FL	*157.00 FL
27	1	*REAR EXHAUST SILENCER	Bent	925.20 FL	*925.20 FL
28	2	*REAR EXHAUST RUBBER	Not Necessary	147.80 FL	*- FL
29	1	*REAR NUMBER PLATE	Not Necessary	45.00 FS	*- FS
30	10	*REAR BOOT INNER BOARD CLIPS	Not Necessary	129.00 FS	*- FS
31	1	*REAR END PANEL TOP GARNISH CLIPS	Necessary	51.60 FS	*15.00 FS
32	1	*REAR END PANEL SEALANT	Necessary	80.00 FS	*60.00 FS
33	12	*REAR FENDER INNER GARNISH	Not Necessary	154.80 FS	*- FS
34	1	*REAR SPARE TYRE TOP INSULATOR	Not Necessary	250.00 FS	*- FS
35	4	*REAR TAILLAMP CLIP	Necessary	51.60 FS	*10.00 FS
36	1	*REAR REVERSE CAMERA	Not Necessary	650.00 FS	*- FS
37	1	*SET REAR REVERSE SENSOR	Damaged	550.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) **14,658.70** **5,612.00**
 - List Item Discount on L Items 20.00/25.00% (\$\$) **2,539.34** **1,331.75**

Total Parts (\$\$) 12,119.36 4,280.25

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING	New	120.00	30.00
2	TUFF KOTE	New	150.00	40.00
3	REMOVE AND REPLACE REVERSE SENSOR	New	160.00	50.00
4	REMOVE AND REPLACE EXHAUST PIPE	New	160.00	80.00
5	TO SPRAY PAINT AFFECTED PORTION	New	1,500.00	700.00
6	TO REMOVE AND REPLACE SPARE PART AND PANEL BEATING	New	1,500.00	600.00
Gross Labour Cost (\$\$)			3,590.00	1,500.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >