

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG:200707743D GST REG:200707743D

2-Jan-18

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHB 8906 D

1 pc	Rear bumper	\$	696.00
1 pc	Rear bumper o/s side bracket ?	\$	29.00
1 pc	Rear o/s wheel cover	\$	116.00
		\$	841.00
	Less 10%	\$	84.10
		\$	756.90

S/NETT

1 set	Rear bumper clips	\$	48.00
1 pc	Rear o/s fender sticker	\$	60.00
1 pc	Rear bumper top protector	\$	80.00
			50
	Sundry	\$	50.00 20
	To check for wheel alignment	\$	80.00 X
	To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.	\$	180.00 X
	To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the rear bumper, rear o/s fender	\$	650.00 400
	To putty and spray painting on rear bumper, o/s rear fender	\$	400.00 260
	To apply rustproofing on the repaired and replaced panels.	\$	250.00 X
		\$	2,554.90

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT
INCLUDE ANY UNFORESEEN DAMAGES.

Kalvin 10/1/18
2/1/18 1545hr
3 days
4/5
After Repair photo