

CITY CAB PTE LTD
REPAIR ESTIMATE*

VEHICLE NO : SHB 2950P

MAKE :

MODEL : HYUNDAI i40

DATE 2/1/2018 11:35

LKK/kalvin *U/Ban*
Lee *QBE*

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Rear Bumper <i>X Repair</i>			\$ 603.60
	Rear Bumper Reinforcement ?			\$ 504.35
	Rear Bumper Reinforcement Bracket (LH/RH) ?		\$ 180.00	\$ 360.00
	Rear Bumper Side Bracket ?			\$ 49.00
	Rear Bumper Clips <i>X</i>			\$ 22.00
	Rear Bumper Sponge ?			\$ 143.40
	Rear Bumper Under Cover <i>X</i>			\$ 225.00
	SUB TOTAL			\$ 1,907.35
	LESS 20% <i>25%</i>			\$ 381.47
	DISCOUNTED TOTAL			\$ 1,525.88
	Rear Bumper Reverse Sensor <i>X</i>			\$ 135.70 Nett
	Rear Bumper Advertisement Logo <i>X</i>			\$ 50.00 Nett
	Rear Bumper Rubber Mat <i>—</i>			\$ 50.00 Nett
	Rear Fender Advertisement Logo (LH/RH) <i>X</i>		\$ 100.00	\$ 200.00 Nett
				\$ 435.70
	Labour Charge			\$ 100.00
	Panel Beating			\$ 200.00 <i>100</i>
	Spray Painting Charge			\$ 200.00 <i>180</i>
	Wiring Charge			\$ 50.00 <i>X</i>
	R/Refix Reverse Sensor			\$ 120.00 <i>X</i>
	TOTAL LABOUR			\$ 920.00
	ESTIMATE TOTAL			\$ 2,881.58
<i>Kelvin (LKK)</i> <i>2/1/18 1420 hrs</i> <i>2 Days</i> <i>4/5</i> <i>After-Repair photo</i> LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: Date:				
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				