

Poh Kin (LKKAUTO)

From: Joel Goh <joel.goh@eqinsurance.com.sg>
Sent: Wednesday, 30 May 2018 4:54 PM
To: Poh Kin (LKKAUTO)
Cc: Hsiao Tong (LKKAUTO); Vic (LKKAUTO)
Subject: RE: <SEEK MANDATE> - Accident Involving GBA9631R (OI : EQI - DM17HO02908-JG) AND SDK8589K (TP : LKK REF - CC6/EQI18000115/Wpb3) on 20.12.2017

Categories: clear

Dear Poh Kin

Please proceed to resolve this matter up to \$15,588.94.

Best Regards,

Joel Goh
Executive | Claims



EQ Insurance Company Limited

5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110
did 65 6500 6772 | tel 65 6223 9433 ext 772 | fax 65 6223 4190
www.eqinsurance.com.sg



Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify the sender.

From: Poh Kin (LKKAUTO) [mailto:pohkin@lkkauto.com]

Sent: Wednesday, May 30, 2018 4:07 PM

To: Joel Goh

Cc: Hsiao Tong (LKKAUTO); Vic (LKKAUTO); Elaine Cheong

Subject: FW: <SEEK MANDATE> - Accident Involving GBA9631R (OI : EQI - DM17/2908-EC) AND SDK8589K (TP : LKK REF - CC6/EQI18000115/Wpb3) on 20.12.2017

Importance: High

RESEND, attached documents.

Your ref : **DM17/2908-EC**

Our ref : CC6/EQI18000115/Wpb3s2

Dear Joel,

ROAD TRAFFIC ACCIDENT INVOLVING GBA 9631R (OI) & SDK 8589K (TP) ON 20/12/2017

We refer to the above matter.

It is a head-to-rear collision. Liability is down against our insured driver. Letter to notify TP claim and NCD issue was sent to OI via E-mail on 8th March 2018.

In view of the above, our Insured is liable to the damages sustained by the TP vehicles.

We seek your approval to offer Third Party repairer "**1st Autoworks Pte Ltd**" at **\$ 15,588.94(all-in)**.

The summary is as follows: -

	Amount Claimed	Amount Revised
1. Cost of Repair (w/GST)	\$21,369.80	\$14,732.94 (\$13,769.10 + 7%GST)
2. Loss of Rental (8days x \$120)	\$ 1,027.20	\$ 856.00 (8 days x \$100) + 7% GST
Total	\$21,221.13	\$15,588.94

****07 days recommendation for repair.**

Enclosed here with all the relevant documents for your perusal.

For your approval please.

Best Regards,

Poh Kin, Chong | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-2132 | email: pohkin@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto
Consultants
Pte Ltd

Save the Earth. Print only when necessary.

This e-mail contain confidential and privileged material, and are for the sole use of the intended recipient. Use or distribution by an unintended recipient is prohibited, and may be a violation of law. If you believe that you received this e-mail in error, please do not read this e-mail or any attached items. Please delete the e-mail and all attachments, including any copies thereof, and inform the sender that you have deleted the e-mail, all attachments and any copies thereof. Thank you.

From: Hsiao Tong (LKKAuto)

Sent: Monday, 28 May 2018 2:07 PM

To: Poh Kin (LKKAuto) <pohkin@lkkauto.com>

Subject: RE: Direct Settlement - Accident Involving GBA9631R (OI : EQI - DM17/2908-EC) AND SDK8589K (TP : LKK REF - CC6/EQI18000115/Wpb3) on 20.12.2017

FIRST AUTOWORKS

Letter of Demand



To: EQ INSURANCE COMPANY LIMITED

Re: Accident involving my vehicle no. SVK 8589K and vehicle no. G8A 9631R on 20/12/17 at 11.50 HRS PM/AM along SIXTH AVE TURNING TO DUNGEAN RD

- 1) I/We, the owner of vehicle no. SVK 8589K hereby appoint 1ST AUTO WORKS PTE LTD ("the workshop") to act for me/us to recover damages sustained in the above accident from the third party driver and/or insurers. Claims are as follows:

Vehicle Repair cost / Excess	\$ 14732.94
Vehicle Rental Fee for <u>8</u> days @	
\$ <u>120</u> per day	\$ 1027.20
Loss of use/rental for _____ days @	
\$ _____ per day	\$
Loss of income for _____ days @	
\$ _____ per day	\$
Police search fee/police report fee/LTA search fees	\$
Others	\$
Total:	\$ 15760.14

Signature of vehicle owner



Name - CHEONG SIAN CHONG

Address: BLK 31 MARINE CRESENT

#10-137 (S) 440031

Tel: 91472999

Witnessed by:

Ramon

Hsiao Tong (LKKAuto)

From: Hsiao Tong (LKKAuto)
Sent: Thursday, 8 March 2018 9:56 AM
To: 'KATHERINE@HHHSURVEYORS.COM.SG'
Subject: ACCIDENT INVOLVING GBA 9631R AND SDK 8589K ON 20/12/2017

08 MARCH 2018

Our Ref: CC6/EQI18000115/Wpb3

M/S HOW HUAI HOON SURVEYORS

Dear Sir/Madam,

ACCIDENT INVOLVING GBA 9631R AND SDK 8589K ON 20/12/2017

We refer to the above subject matter. We write to inform you that we are the loss adjuster appointed by your motor insurer, EQ Insurance Company Ltd to deal with the third party claim against your policy.

We have received a claim from SDK 8589K against your insurance policy.

Based on the accident report and accident scenario, liability is down against us. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 10 days from the date of this letter.

Please note that your No-Claim Discount (NCD) (if any) will be affected and reduced by 30% (20% for commercial vehicles) upon next renewal due to this Third Party claim. However, if your policy has a NCD protector feature, it will be deemed utilized for this claim and your NCD will be protected.

Please call us if you have further queries.

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

C.C: EQ INSURANCE COMPANY LIMITED
(Motor Claims Dept)

Authorization To Act

I, CHONG SIAH CHON ("the third party claimant") of
BLK 31 MARINE CRESCENT #18-137 (S) 440031 (address), owner
of SDK 8589K (vehicle no.) hereby authorize
1ST AUTOWORKS PTE LTD
("the workshop") to act for me with respect to my claim for repair
costs and/or rental and/or loss of use ("claim") for my vehicle
no. SDK 8589K that was damaged pursuant to the accident which
occurred on 20/12/2017 (date) along SIXTH AVE TURNING
TO DENKIN ROAD (location) involving
vehicle no/s G3A 9631 R
("the accident").

I further authorize the workshop to settle my above mentioned claim in a manner that they deem fit and the workshop is further authorized to receive payment further to settlement of my claim with payment cheque/s being made in favour of the workshop.

I further acknowledge that any settlement the workshop may reach on my behalf is on a without prejudice and without admission of liability basis insofar as the driver/owner/insurers of the other vehicle/s is concerned.

Dated this 21 day of 12 (month) 20 17 (year)



Signed by "the third party claimant"



Signed by "the workshop"

FIRST AUTOWORKS

1st Autoworks Pte Ltd

23 Kaki Bukit Ave 4, #04-01 (South Wing) Singapore 415933 Tel: 68441985 Fax: 68445185

TAX INVOICE

EQ Insurance Company Limited
5 Maxwell Road
#17-00 Tower Block, MND Complex,
Singapore 069110

GST Ref. No: M2-0111811-5

Vehicle No: SDK 8589K
Chassis No : W0L0AHM75A2023251
Engine No: Z18XER20NV3779

Invoice No: CGI-ASC-18IR00440C

Invoice Date: 4/4/2018
AMOUNT SGD

DESCRIPTION

Parts

No.	Qty.	Description	Price (SGD)
1	1	REAR BUMPER	2,300.00
2	1	REAR TOW LUG FLAP WITH STRAP	90.00
3	1	REAR BUMPER GUIDE RH	80.00
4	1	REAR BUMPER GUIDE LH	80.00
5	1	REAR BUMPER GUIDE LOWER PANEL, RH	55.00
6	1	REAR BUMPER GUIDE LOWER PANEL, CENTRE	75.00
7	1	REAR BUMPER GUIDE LOWER PANEL, LH	55.00
8	1	REAR BUMPER CHIP SET	45.00
9	1	BUMPER GUIDE RAIL RIVET SET	30.00
10	1	MOULDING, REAR BUMPER PANEL, RH, PRIMED	167.00
11	1	MOULDING, REAR BUMPER PANEL, LH, PRIMED	167.00
12	1	COVER, REAR END PANEL, ANTHRACITE	314.00
13	1	PANEL, REAR LOWER	634.00
14	1	PLATE, REINFORCEMENT CRASH LIMITER	746.00
15	1	TAIL GATE OUTER PANEL	2,606.00
16	1	TAIL GATE HANDLE WITH STYLING STRIP DULL SILVER	650.00
17	1	TAIL GATE LATCH	350.00
18	1	TAIL GATE STRIKER	76.00
19	1	REAR WINDSCREEN MOULDING	150.00
20	1	OPEL EMBLEM	79.00
21	1	RH TAILLAMP	950.00

Total: 9699.00
Less 10%: 969.90
Parts Total : 8729.10

Labour

No.	Description	Price (SGD)
1	To dismantle / renew the accident damaged portion, to panel beating, reshape, straighten, orientate and align repair	2,600.00
2	Carry out spray painting on accident affected area. (Rear Bootlid, Rear bumper, Rear end panel, Rear spare tyre panel)	1,950.00
3	To disconnect wire harness of electrical component to facilitate repairs, reconnect and check electrical function after repair	40.00

1st Autoworks Pte Ltd


23 Kaki Bukit Ave 4, #04-01 (South Wing) Next to Vicom Building, Singapore 415933 Tel : 6844 1985 Fax : 6844 5185

<u>4</u>	Transfer of parts from old bootlid to new bootlid	80.00
<u>5</u>	Remove and replace reverse sensor (Labour)	60.00
Labour Total :		4730.00

<u>Other</u>		<u>Price (SGD)</u>
<u>No.</u>	<u>Other Description</u>	
1	REVERSE SENSOR SET	200.00
2	SEALANT W/SCREEN	60.00
3	NUMBER PLATE WITH BRACKET	50.00
Other Total :		310.00

Total :	13769.10
GST (7%)	963.84
Grand Total:	14732.94

Yours Faithfully,



 Ronnie Tan
 Service Advisor
 Tel: 68441985 Fax:68445185

E & O E

- ALL CHEQUE PAYMENTS SHOULD BE CROSSED AND MADE PAYABLE TO "I ST AUTOWORKS PTE LTD".
 - PLEASE INDICATE THE INVOICE NO. ON THE REVERSE SIDE.



AlpineCarRental

TAX INVOICE

GST Reg no.: M2-0094320-1
Co. Reg no.: 199003483E

CHONG SIAH CHONG
BLK 31 MARINE CRESCENT
#18-137
SINGAPORE 440031

INVOICE NO **REN-18IR02968R**

22-Feb-18

DATE :

DESCRIPTION		AMOUNT
SKN 8076A		
CAR NO. :		
RENTAL PERIOD:	29/1/2018 - 6/2/2018	
* RENTAL DAILY	\$120.00 * 8 DAYS	\$960.00
* GST 7%		\$67.20
E. & O. E.		
TOTAL:		\$1,027.20

ALPINE CAR RENTAL PTE LTD

- ALL CHEQUE PAYMENTS SHOULD BE CROSSED AND MADE PAYABLE TO 'ALPINE CAR RENTAL PTE LTD'.
- PLEASE INDICATE THE INVOICE NO. ON THE REVERSE SIDE.
- PAYMENT IS DUE ON THE TERMS STATED HEREIN. INTEREST WILL BE CHARGED AT THE RATE OF 12% PER ANNUM UNTIL FULL PAYMENT OF THE OUTSTANDING SUM.

This Invoice is computer generated.
No signature is required.



Alpine Car Rental

Check Out / Check In List

CAR NO: SKN 80767 MAKE/MODEL: 2011 ALFA AT/MT**1. ITEMS FITTED / PLACED INSIDE THE CAR**



<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

2. ITEMS FITTED / PLACED INSIDE THE BOOT

<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

3. ITEMS FITTED ON THE EXTERIOR

<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

REMARKS: Mileage: 56223 Petrol: (1/8), (1/4), (3/8), (1/2), (5/8), (3/4), (7/8), FULLMinor Scratches & DentsCHECKED OUT BY: Ramile CHECKED IN BY: RamileDATE/TIME: 29/1/2018 PM/AM DATE/TIME: 6/2/2018 PM/AM

HIRER'S SIGNATURE

HIRER'S SIGNATURE