



Admin LKK-AIG
新福德車廠私人有限公司

NEW HOCK TECK MOTOR PTE. LTD.

1 Kaki Bukit Ave 6, Blk C #01-43 Autobay@Kaki Bukit, Singapore 417883

Email: admin@nhtmotor.com Website: www.nhtmotor.com

Tel: 6747 9241 Fax: 6741 7276

UEN: 201718370K

MARJUNI BIN SUKI

03/01/2018

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

TPA16.

Thin Thin

Accident date: 31/12/2017

Estimated repair cost for vehicle no: SJX5153P TOYOTA ALTIS 1.6 A '05

S/n	Qty	Items	U/price	Amount
1	1	Front Bumper <i>detached</i>		\$378.65 ✓
2	8	Front Bumper Clip <i>m</i>	\$6.50	\$52.00 30
3	1	Front Bumper Lower Spoiler (Nett) <i>Repairs</i>		\$680.00 X
4	1	Front L/H Bumper Side Retainer <i>slit</i>		\$83.90 25.40
5	1	Front L/H Bumper Fog Lamp <i>cracked</i>		\$374.10 184.20
6	1	Front L/H Head Lamp <i>cracked</i>		\$378.85 ✓
7	1	Front L/H Fender <i>Repairs</i>		\$346.20 X
8	1	Front L/H Rim <i>lit</i>		\$650.00 400.00
9	1	Front L/H Tyre <i>not m</i>		\$350.00 X
10	1	Front L/H Lower Arm <i>m</i>		\$581.90 +
11	1	Front L/H Knuckle Arm <i>but</i>		\$561.10 380.10
12	1	Front L/H Knuckle Arm Bearing <i>m</i>		\$191.60 ✓
13	1	Front L/H Shock Absorber <i>m</i>		\$381.90 X
14	1	Front L/H Drive Shaft <i>2 m</i>		\$1,712.40 +
15	1	Front Steering Rack <i>1 m</i>		\$1,822.90 +

1568.80

Subtotal :- \$8,545.50

1176.60

S.W: 400

Labour charges

To remove & refit front lower spoiler		\$380.00 X
To remove & refit front L/H undercarriage		\$380.00 220
To remove & refit front drive shaft & steering rack		\$450.00 X
To check wheel alignment		\$150.00 80
To check wiring		\$100.00 30
Tuff kote	1330	\$150.00 X
Panel beating		\$800.00 400
Spray painting		\$800.00 600

Subtotal :- \$3,210.00

Total:- \$11,755.50

total 2906.60
+/- 2.3K
040mp.
2.3K

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: