

TPA16.
Lani

SLG 1002J.
Kia Cerato K3.

KNAFX411MHS634197

Rear Bumper	Delivered	698	—
Rear Bumper Clips	m	30	—
Rear Bumper Side Holder x 02	m	49.9 x 2 = 99.80	—
Rear Bumper Reinforcement	Bent	360	—
Rear Bumper Reinforcement Bracket ^{8 stay} x 02	Dented	105 x 2 = 210	—
Rear Bumper Reinforcement Bracket x 05	2 pieces Bent	18 x 5 = 90	36
Rear Bumper Lower Garnish	Delivered	473.70	✓
Rear Bumper Lower Garnish Reflector x 02	RH Bent	65 x 2 = 130	65
Reverse Sensor	Bent	250 (SN) - 200 (SN)	—
Rear End Panel	Dented	315	—
Rear End Panel Top Garnish	Delivered	256 66	—
Rear End Panel Sealant	m	60 (SN)	—
Tail Lamp x 02	Cracked	394 x 2 = 788	—
Bootlid	Buckled	863	—
Bootlid Lock	Target	113	—
Bootlid Weatherstripe	Cut	102	—
Bootlid Reflector x 02	xtm	342 x 2 = 684	x
Kia Logo	3 x m	57	—
Cerato Wordmark		48	—

SLG 1002J.

Forle Wording

K3 Wording.

Cycle and Carriage Logo

Spore Tyre Panel Top Cover.

Rear Exhaust Pipe

Rear Exhaust Mounting

Rear Fender Inner Trim x 02

Rear Fender Inner Trim Clips

5124.6

4612.14

36.70 -

39.40 -

38 -

159 x.

686 -

45 x

278x2 = 556 x

60 x.

Panel Bending

Spray Painting.

Wiring

To undersend

To remove reverse sensor

To remove upholstery.

To transfer bottle fittings

To remove Exhaust Pipe

~~1200~~ 800

~~1200~~ 800

~~50~~ 30

~~150~~ 40

~~100~~ 50

~~150~~ 60

~~150~~ 60

~~150~~ 80

1520.

total: 6742.14

h/s: 5.4K 07 Days

Acknowledged by Repairer

Signature:

Date: