

INS. CASE OWNER:

Kay Goy

CC 6 / LCR1800 0121, Aja322

LKK:

IDAC:

Payor:

AOPAN

DOI:

ASSIGNMENT

2/1/18

Date / Time:

2/1/18

Registered in Merimen:

3/1/18

Pre-assign / CCU / FTE



Insured Vehicle No.:

SLO 2565K

Name of Insured:

LORF P/L

Insured Tel No.:

HP:

Excess Sec II :SS

D.O.A:

31/12/2017

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Mohd Fazlie Bin Smp'tee

Driver Tel No.:

(V/L: YES / NO)

Claim No.:

037655230556

Policy No.:

0966998066

Make / Model:

7. SIEN7A

Place of Accident:

CTE C > CITY

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability: %

Final ? Yes / No

SLO 2565K

SJP 8861B

CLA 4912E

SLN 2291Y



INSRS:

WSP:

Tel:

Liability:

RMKS:

m



INSRS:

WSP:

Tel:

Liability:

RMKS:

Putu



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date / Time

10/1
JoySJP 8861B - X
SLO 2565K - XOI LAST VEH. TO CONFIRM IF
A VEH, OI MUST AMEND REPORT

1-3-18

LOD IN - FOR MANDATE

RECEIVED 01 MAR 2018

Step Typist: kindly assist to upload TP
GIA report. total 5 pages. (views
main)

RECEIVED 03 MAR 2018

STAGE	DATE / PIC
Non-Reporting ltr (1st):	
Non-Reporting ltr (2nd):	
Non-Reporting ltr (Final):	
Notification ltr (if non-pickup):	
Call OI:	JOY 10-1-18
After call ltr to OI:	
Documentation Check List:	Handler Typist
Notification ltr (if non-pickup)	☒ ☐
After call ltr to OI:	☒ ☐
Authorisation To Act:	☒ ☐
Release Voucher:	☒ ☐
Final Repair Bill:	☒ ☐
Car Rental Invoice:	☒ ☐
Towing Invoice:	☒ ☐
LTA / GIA:	☒ ☐
Medical Bill:	☒ ☐
PIR:	☒ ☐
Mandate/Reject Instruction:	☒ ☐
LOD	☒ ☐
Payment Breakdown Form:	☐ ☐
Post-Repair Photos:	☐ ☐
Others:	☐ ☐

PRELIMINARY ADVICE	Date/Time:	Sent By:
FINALIZATION	Date/Time:	Confirm with:
Repair Cost:	SS	(days) Reduction: %
FINAL SETTLEMENT	Date/Time: 3-4-18	Confirm with: JASON
Final Liability:	% 100	(Agreed / Assessed) BOLA S/N No.: 28
Repair Cost:	SS 27,820.xx	
Loss of Rental (LOR):	SS	(days)
Loss of Use (LOU):	SS 2,000	(\$100 x 20 days)
Loss of Income (LOI):	SS	(\$ x days)
LOR only ☐ LOU only ☐	☒ LOR + LOU ☐ LOR + LOI ☐	[Tick only one]
GIA/LTA Search	SS 7.45	
Medical:	SS	
Disbursement:	SS	(e.g. Tow/ Independent)
Legal Cost	SS	
Total:	SS 29,827.45	Global Sum SS: 29,800.xx
FINAL PAYMENT	Date/Time:	Confirm with:
Payee 1:	SS 29,800.xx	Name 1: KIM HWEE AUTO PTE LTD
Payee 2: (Strike if N.A.)	SS	Name 2: X
Payee 3: (Strike if N.A.)	SS	Name 3: X

Symptoms

28/02/11
2011 Feb

Veh No: STP8861B Yr Regn: 2011 Fee: 100

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Bmw 523i cc: 2492

Colour: Blue A/C: Insured / Std / NI / NA

Sp. Reading: 104234 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WBAFP320XOC.86408

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 275/35R19

R: 275/35R19

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

BS/DUN/EXNOVA/GY/FS/LIZA/MIC/OHTSU/PIR/SUMI/
TOYO/YOKO or

Front

R/Bal. 06 mm

L/Bal. 06 mm

D.O.A. _____

Survey held at Fustech

Des. of Damages ☒ Fr ☒ Rear ☐ O/S ☐ N/S ☐ U/C ☐ Rooftop or

Rear

R/Bal. 06 mm

L/Bal. 06 mm

D.O.I. 02/01/18

The U/C / Chassis frame / Body Structure affected due to collision.

TP Alg.

L/S \$26,000/-

mv: 70 K
 PV: 43.7 K
 Nett: 26.3 K

$$\times R(\$48,559.61 / .65\%)$$

$$R(53,778.78 / 67\%)$$

☐ : Prelim. Report
☐ : Final Report

Resurvey No. of Trip:

Transportation:

2

☐ Site Insp. (\$

Interview (\$

Tech. Invs (\$)

Weber and (e)

100-100-100

1. [Index](#)

Lump Sum / I.B.I.: (\$



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AIG ASIA PACIFIC INSURANCE PTE LTD			Ref : CC6/LCR18000121/Aja3	
78 SHENTON WAY #08-16 CHARTIS BUILDINGS SINGAPORE 079120			Date : 03-01-2018	
			Code : LCR	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SLD 2565K	Veh. Inspected	SJP 8861B	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	03/01/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	31/12/2017	Inspection Date	02/01/2018	
Survey held at	FASTECH AUTO PTE LTD 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

KIM CHWEE AUTO PTE LTD

1 Kaki Bukit Avenue 6, #01-46/48/50, Autobay, Singapore 417883

H/P: 9487 7074 Tel: 6741 7244, 6746 5405 Fax: 6745 8520, 6746 5786

Vehicle No.: SJP8861B

Vehicle Made & Model: BMW 520i

QTY	List Items:	Amount \$
1	Rear boot lid <i>Distorted</i>	1,862.53 ✓
1	Rear boot BMW logo <i>new</i>	68.85 ✓
2	Rear boot BMW logo clips @ 4.50 <i>m</i>	9.00 ✓
2	Rear boot lamps - L/R @ 341.60 <i>each</i>	683.20 ✓
2	Rear boot licence lamps @ 82.55 <i>new</i>	165.10 x
1	Rear boot opening switch <i>2nd</i>	180.93 ✓
1	Rear boot inner lock <i>Turned</i>	280.95 ✓
1	Rear boot inner lock actuator motor <i>2nd</i>	581.90 ✓
1	Rear boot lock striker <i>Best</i>	68.55 ✓
1	Rear boot inner trim <i>Deformed</i>	291.63 ✓
10	Rear boot inner trim clips @ 5.50 <i>m</i>	55.00 ✓
2	Rear boot inner pull switch <i>new</i>	130.63 x
2	Rear boot hinges - L/R @ 155 <i>Best</i>	310.00 ✓
2	Rear boot stoppers @ 18.60 <i>m</i>	37.20 ✓
1	Rear boot w/strip <i>cut</i>	261.95 ✓
1	Rear bumper - M. Kit <i>Distorted</i>	1,865.50 ✓
1	Rear bumper tow cover <i>Distorted</i>	48.85 ✓
2	Rear bumper reflectors - L/R @ 115 <i>each</i>	230.00 ✓
1	Rear bumper top guide <i>each</i>	181.90 ✓
1	Rear bumper CTR guide <i>each</i>	160.55 ✓
1	Rear bumper lower guide <i>each</i>	126.50 ✓
2	Rear bumper side guides - L/R @ 135 <i>3 per</i>	270.00 ✓
2	Rear bumper side brackets - L/R @ 115	230.00 ✓
1	Rear bumper reinforcement <i>Best</i>	761.90 ✓
4	Rear bumper PDC sensors @ 313.75 <i>2 pieces damaged</i>	1,255.00 - 627.50
1	Rear bumper PDC sensor wire <i>snapped</i>	431.60 ✓
1	Rear bumper PDC sensor control unit <i>2nd</i>	861.90 ✓
1	Rear end panel <i>Distorted</i>	1,018.93 - 850
1	Rear end panel inner member <i>Distorted</i>	1,055.60 - 420
1	Rear end panel garnish <i>each</i>	180.93 ✓
1	Rear exhaust silencer assy <i>Best</i>	3,631.51 - 1850
3	Rear exhaust mountings @ 48.60 <i>turn</i>	97.20 ✓

Vehicle No.: SJP8861BVehicle Made & Model: BMW 520i

2	Rear	exhaust insulators @ 120.60	crushed	251.20 ✓
1	Rear	floor board	deformed	415.20 ✓
1	Rear	floor mat	ton	465.50 ✓
1	Rear	floor compartment panel	Distorted	1,955.60 ✓
2	Rear	floor sponge trays - L/R @ 131.50	ton	263.00 ✓
2	Rear	fenders - L/R @ 1965.50	Rpr	3,931.00 ✓
2	Rear	fender rail panels @ 181.30	green	362.60 ✓
2	Rear	fender rail pannel garnish @ 89.95		179.90 ✓
2	Rear	fender inner trims - L/R @ 580.93	crushed	1,161.86 ✓
2	Rear	fender innr shields - L/R @ 180.92	new	361.84 ✓
2	Rear	taillamps - L/R @ 641.55	crushed	1,283.10 ✓
2	Rear	taillamp panels - L/R @ 155.60	dented	311.20 ✓
2	Rear	taillamp covers - L/R @ 68.55	at	137.10 ✓
1	Battery	bracket	Bent	110.50 ✓
1	Battery	cable electrical fuse box	new	861.55 ✓
1	Front	bonnet	Buckled	2,155.30 ✓
1	Front	bonnet safety lock	new	130.40 ✓
1	Front	bonnet insulator	new	281.63 ✓
6	Front	bonnet insulator clips @ 5.50	new	82.50 ✓
2	Front	bonnet hinges @ 110.60	green	221.20 ✓
2	Front	bonnet dampers - L/R @ 180.20		360.40 ✓
2	Front	bonner locks @ 155.20	changed	310.40 ✓
2	Front	bonnet lock strickers @ 58.80	new	117.60 ✓
2	Front	bonnet lock cables @ 81.55	new	163.10 ✓
1	Front	bumper	Distorted	1,865.50 ✓
1	Front	bumper BMW logo	new	68.85 ✓
2	Front	bumper BMW logo clips @ 4.50	new	9.00 ✓
1	Front	bumper CTR lower grille	delcd	155.30 ✓
2	Front	bumper side grille - L/R @ 89.95	green	179.90 ✓
2	Front	bumper fog lamps - L/R @ 281.43		582.86 ✓
1	Front	bumper top seal	crushed	120.62 ✓
1	Front	bumper tow cover		48.85 ✓
2	Front	bumper spray nozzle covers @ 85	changed	170.00 ✓
1	Front	bumper inner sponge	crushed	130.65 ✓
1	Front	bumper reinforcement	Bent	788.95 ✓
2	Front	bumper reinforcement stays @ 185	Bent	370.00 ✓
2	Front	bumper side grips @ 45	new	90.00 ✓

Vehicle No.: SJP8861BVehicle Made & Model: BMW 520i

1	Front bumper lower beam	bat	195.00	✓
4	Front bumper PDC sensors @	313.75 2 pieces damaged	1,255.00	627.50
1	Front bumper PDC sensor wire	new	289.63	+
2	Front fenders - L/R @	1180.35	2,360.70	+
2	Front fender inner shields - L/R @	141.63 new	283.26	+
2	Front headlamps - L/R @	2551.60 cracked	5,103.20	✓
2	Front headlamp HID control units @	865.50 3 new	1,731.00	+
2	Front headlamp HID bulb - L/R @	481.95	963.90	+
2	Front headlamp top garnishs @	89.95 3 new	179.90	+
2	Front headlamp brackets - L/R @	185.50	371.00	+
2	Front headlamp spray nozzle pen @	189.50	379.00	+
1	Front brace panel	bat	215.50	✓
1	Front support panel	cracked	435.00	✓
1	Front support top garnish	cracked	180.93	✓
10	Front support top garnish clips @	5.50	55.00	✓
1	Front support panel air duct - CTR	3 new	341.55	+
2	Front side lower air ducts - L/R @	120.65	241.30	+
2	Front support brackets @	95.50 bat	181.00	✓
1	Air cleaner intake duct	3 new	187.45	+
1	Air cleaner box assy		865.00	+
1	Air con condenser	Dented	891.65	✓
1	Air con condenser air vent	new	241.50	+
1	Air con discharge pipe		381.90	+
1	Air con suction pipe		361.50	+
1	Air con liquid pipe		241.60	+
1	Radiator assy	Dented	1,150.60	✓
1	Radiator top cooler hose		141.60	+
2	Radiator top stoppers @	18.20	36.40	+
2	Radiator module carriers - L/R @	89.50	179.00	+
1	Radiator bottom cooler hose		130.65	+
1	Radiator top hose connector		142.50	+
1	Radiator heat exchange		448.50	+
1	Radiator temperature sensor		114.55	+
1	Radiator expansion tank		131.85	+
1	Radiator expansion tank pipe		68.20	+
1	Radiator auxiliary fan assy		1,485.50	+
1	Thermostat housing		191.60	+

Vehicle No.: SJP8861B

Vehicle Made & Model: BMW 520i

1	Thermostat housing hose	110.30	✓
1	Trans oil cooler	581.60	✓
1	Trans oil cooler hose - inlet	155.90	✓
1	Trans oil cooler hose - outlet	181.60	✓
1	Power steering cooler pipe	331.45	✓
2	safety belt buckles - L/R @ 281.90	573.80	✓
2	Front seat headrests - L/R @ 580.60	1,161.20	✓
2	Engine mountings - L/R @ 241.55	483.10	✓
1	Engine undercover	180.93	✓

Sub-total	63,762.75
Less 5%	3,188.14
Total List	60,574.61

36593.78

34764.09

Vehicle No.: SJP8861B

Vehicle Made & Model: BMW 520i

Special Nett Items:

1	Rear	boot top spoiler	<i>x6 m</i>	850.00	<i>x</i>
1	Battery	<i>500d</i>		800.00	<i>330</i>
1 set	Rear	floor panel sound insulator	<i>new</i>	150.00	<i>x</i>
1 set	Rear	floor panel sealant gum	<i>new</i>	120.00	<i>60</i>
1 set	Rear	end panel sealant gum	<i>new</i>	120.00	<i>60</i>
1 set	Rear	windscreen sealant	<i>new</i>	120.00	<i>x</i>
1 set	Front	no. plate with holder	<i>new</i>	150.00	<i>70</i>
1 set	Front	grille assy	<i>new</i>	800.00	<i>600</i>
1	Front	bumper spoiler	<i>new</i>	1,500.00	<i>850</i>
1 bot	Air con oil	<i>3m</i>		60.00	<i>40</i>
1 bot	Radiator coolant			65.00	<i>40</i>
1 set	Front	bumper clip	<i>new</i>	60.00	<i>30</i>
Total Special Nett				4,795.00	

2100

Labour Charges:

Towing charges	200.00	<i>150</i>
To remove, refix R/interior trims to assist repair	180.00	<i>100</i>
To reinstall fuel tank to assist repair	200.00	<i>x</i>
To respray undercoating	250.00	<i>100</i>
To check front/rear electrical wiring	150.00	<i>60</i>
To remove, refix rear exhaust systems	180.00	<i>100</i>
To remove, refix A/C condenser & refill A/C gas	180.00	<i>120</i>
To diagnos, erase fault memory after repair	450.00	<i>180</i>
To remove, refix engine parts	300.00	<i>x</i>
To respray painting & etc	2,600.00	<i>1800</i>
Panel beating, cut, weld, remove & replacing above parts	4,500.00	<i>2200</i>
Total Labour	9,190.00	

A810

total: 41674.09
h/s: 2612 - 18 Days

LKK Auto Consultants hence notify the Repairer of the following:

- To respray before after repair
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Date:

ESTIMATE PARTS AND LABOUR GRAND TOTAL \$ 74,559.61

...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	03 Jan 2018 Edit Reg		02 Jan 2018 00:00 Edit Adj Rpt	S\$26,000.00 Edit Estimates	S\$26,000.00 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by adjuster]

Insured:	LCRF PTE LTD, Co. Reg. No.: 201624597K		
Main Claimant:	LIM POH CHEOW, ID: S1395433Z		
Vehicle Reg. No.:	SJP8861B	Date of Loss:	31/12/2017 21:00 - :59 [82 Months and 3 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 0376552305SG	Policy/Cover Note No.:	0999995066 (Comprehensive)
Vehicle Reg. No. (Insured):	SLD2565K	Policy No. (Claimant):	GA236483/1
		Excess:	
Repairer:	Fastech Auto Pte Ltd (HQ) 1 Kaki Bukit Ave 6, #01-46/48/50 Autobay, 417883 Kaki Bukit - Tel: 67465405		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Khoo, Kay-Eng - 6419 1026] Kay-Eng.Khoo@aig.com		
Claimant's Insurer:	AXA Insurance Pte Ltd (HQ) - Tel: 6338 7288		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 12/01/2018]		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

- AIG_SG_EXPRESS (26/03/2018): Alert - Adj Mandate Approved (S\$30027.45) - SJP8861B - Claim Handler: Khoo, Kay-...
- AIG_SG (04/01/2018): Confirmation of vehicle number
- AIG_SG (04/01/2018): NO TP GIA REPORT

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SJP8861B (0376552305SG)**
[SLD2565K]

TP

LIM POH CHEOW
Dec 31 2017 9:00PM
[LCRF PTE LTD]
Fastech Auto Pte Ltd

Upload Documents	Upload Photos	Compose New Letter	Upload Video	Upload Audio	View View in Browser ▼
------------------	---------------	--------------------	--------------	--------------	-------------------------------

Letters/Correspondences				1 per page ▼	☒
No	Finalized On			Thumbnail	Print
1	(Draft)	LKK Auto Consultants Pte Ltd (HQ)			
		Third Party Express Settlement – Payment Breakdown		Edit	

Assessment Reports				1 per page ▼	☒
No	Finalized On			Thumbnail	Print
1	09/01/18 11:33	AIG Asia Pacific Insurance Pte. Ltd. (SG)			
		Accident Statement From:OD - Reg. No: SLD2565K, Claimant: LCRF PTE LTD		Load HTM	

Photos/Images				3 per page ▼	☒
No	Relabel/Reorder			Thumbnail	Print
		LKK Auto Consultants Pte Ltd (HQ)			
1	29/01/18 09:35	General View		Load JPG	☒
2	29/01/18 09:35	General View		Load JPG	☒
3	29/01/18 09:35	Chassis Number		Load JPG	☒
4	29/01/18 09:35	General View		Load JPG	☒
5	29/01/18 09:35	General View		Load JPG	☒
6	29/01/18 09:35	General View		Load JPG	☒
7	29/01/18 09:35	General View		Load JPG	☒
8	29/01/18 09:35	General View		Load JPG	☒
9	29/01/18 09:35	General View		Load JPG	☒
10	29/01/18 09:35	General View		Load JPG	☒
11	29/01/18 09:35	General View		Load JPG	☒
12	29/01/18 09:35	General View		Load JPG	☒
13	29/01/18 09:35	General View		Load JPG	☒
14	29/01/18 09:35	General View		Load JPG	☒
15	29/01/18 09:35	General View		Load JPG	☒
16	29/01/18 09:35	General View		Load JPG	☒
17	29/01/18 09:35	General View		Load JPG	☒
18	29/01/18 09:35	General View		Load JPG	☒
19	29/01/18 09:35	General View		Load JPG	☒
20	29/01/18 09:35	General View		Load JPG	☒
21	29/01/18 09:35	General View		Load JPG	☒
22	29/01/18 09:35	General View		Load JPG	☒
23	29/01/18 09:35	General View		Load JPG	☒
24	29/01/18 09:35	General View		Load JPG	☒
25	29/01/18 09:35	General View		Load JPG	☒
26	29/01/18 09:35	General View		Load JPG	☒
27	29/01/18 09:35	General View		Load JPG	☒
28	29/01/18 09:35	General View		Load JPG	☒

Letters/Correspondences			1 per page ▼	✓
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
29	29/01/18 09:35	General View	 Load JPG	✓
30	29/01/18 09:35	General View	 Load JPG	✓
31	29/01/18 09:35	General View	 Load JPG	✓
32	29/01/18 09:35	General View	 Load JPG	✓
33	29/01/18 09:35	General View	 Load JPG	✓
34	29/01/18 09:35	General View	 Load JPG	✓
35	29/01/18 09:35	General View	 Load JPG	✓
36	29/01/18 09:35	General View	 Load JPG	✓
37	29/01/18 09:35	General View	 Load JPG	✓
38	29/01/18 09:35	General View	 Load JPG	✓
39	29/01/18 09:35	General View	 Load JPG	✓
40	29/01/18 09:35	General View	 Load JPG	✓
41	29/01/18 09:35	General View	 Load JPG	✓
42	29/01/18 09:35	General View	 Load JPG	✓
43	29/01/18 09:35	General View	 Load JPG	✓
44	29/01/18 09:35	General View	 Load JPG	✓
45	29/01/18 09:35	General View	 Load JPG	✓
46	29/01/18 09:35	General View	 Load JPG	✓
47	29/01/18 09:35	General View	 Load JPG	✓
48	29/01/18 09:35	General View	 Load JPG	✓
49	29/01/18 09:35	General View	 Load JPG	✓
50	29/01/18 09:35	General View	 Load JPG	✓
51	29/01/18 09:35	General View	 Load JPG	✓
52	29/01/18 09:35	General View	 Load JPG	✓
53	29/01/18 09:35	General View	 Load JPG	✓
54	29/01/18 09:35	General View	 Load JPG	✓
55	29/01/18 09:35	General View	 Load JPG	✓
56	29/01/18 09:35	General View	 Load JPG	✓
57	29/01/18 09:35	General View	 Load JPG	✓
58	29/01/18 09:35	General View	 Load JPG	✓
59	29/01/18 09:35	General View	 Load JPG	✓
60	29/01/18 09:35	General View	 Load JPG	✓
61	29/01/18 09:35	General View	 Load JPG	✓
62	29/01/18 09:35	General View	 Load JPG	✓
63	29/01/18 09:35	General View	 Load JPG	✓
64	29/01/18 09:35	General View	 Load JPG	✓
65	29/01/18 09:35	General View	 Load JPG	✓
66	29/01/18 09:36	General View	 Load JPG	✓
67	29/01/18 09:36	General View	 Load JPG	✓
68	29/01/18 09:36	General View	 Load JPG	✓
69	29/01/18 09:36	General View	 Load JPG	✓
70	29/01/18 09:36	General View	 Load JPG	✓
71	29/01/18 09:36	General View	 Load JPG	✓
72	29/01/18 09:36	General View	 Load JPG	✓
73	29/01/18 09:36	General View	 Load JPG	✓
74	29/01/18 09:36	General View	 Load JPG	✓
75	29/01/18 09:36	General View	 Load JPG	✓
76	29/01/18 09:36	General View	Load JPG	✓

Letters/Correspondences			1 per page	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
77	29/01/18 09:36	General View	 Load JPG	☒
78	29/01/18 09:36	General View	 Load JPG	☒
79	29/01/18 09:36	Reinspection Photo	 Load JPG	☒
80	29/01/18 09:36	Reinspection Photo	 Load JPG	☒
81	29/01/18 09:36	Reinspection Photo	 Load JPG	☒
82	29/01/18 09:36	Reinspection Photo	 Load JPG	☒
83	29/01/18 09:36	Reinspection Photo	 Load JPG	☒
84	29/01/18 09:36	Reinspection Photo	 Load JPG	☒
85	29/01/18 09:36	Reinspection Photo	 Load JPG	☒
86	29/01/18 09:36	Reinspection Photo	 Load JPG	☒
87	29/01/18 09:36	Reinspection Photo	 Load JPG	☒
88	29/01/18 09:36	Reinspection Photo	 Load JPG	☒
89	29/01/18 09:36	Reinspection Photo	 Load JPG	☒
90	29/01/18 09:36	Reinspection Photo	 Load JPG	☒
91	29/01/18 09:36	Reinspection Photo	 Load JPG	☒
92	29/01/18 09:36	Reinspection Photo	 Load JPG	☒
93	29/01/18 09:36	Reinspection Photo	 Load JPG	☒
94	29/01/18 09:36	Reinspection Photo	 Load JPG	☒
95	29/01/18 09:36	Reinspection Photo	 Load JPG	☒
96	29/01/18 09:36	Reinspection Photo	 Load JPG	☒
97	29/01/18 09:36	Reinspection Photo	 Load JPG	☒
98	29/01/18 09:36	Reinspection Photo	 Load JPG	☒
99	29/01/18 09:36	Reinspection Photo	 Load JPG	☒
100	29/01/18 09:36	Reinspection Photo	 Load JPG	☒
101	29/01/18 09:36	Reinspection Photo	 Load JPG	☒
102	29/01/18 09:36	Reinspection Photo	 Load JPG	☒
103	29/01/18 09:36	Reinspection Photo	 Load JPG	☒
104	29/01/18 09:36	Reinspection Photo	 Load JPG	☒
105	29/01/18 09:36	Reinspection Photo	 Load JPG	☒
106	29/01/18 09:36	Reinspection Photo	 Load JPG	☒
107	29/01/18 09:36	Reinspection Photo	 Load JPG	☒
108	29/01/18 09:36	Reinspection Photo	 Load JPG	☒
109	29/01/18 09:36	Reinspection Photo	 Load JPG	☒
110	29/01/18 09:36	Reinspection Photo	 Load JPG	☒
111	29/01/18 09:36	Reinspection Photo	 Load JPG	☒
112	29/01/18 09:36	Reinspection Photo	 Load JPG	☒
113	29/01/18 09:36	Reinspection Photo	 Load JPG	☒
114	29/01/18 09:36	Reinspection Photo	 Load JPG	☒
115	29/01/18 09:36	Reinspection Photo	 Load JPG	☒
116	29/01/18 09:36	Reinspection Photo	 Load JPG	☒
117	29/01/18 09:36	Reinspection Photo	 Load JPG	☒
118	29/01/18 09:36	Reinspection Photo	 Load JPG	☒
119	29/01/18 09:36	Reinspection Photo	 Load JPG	☒
120	29/01/18 09:36	Reinspection Photo	 Load JPG	☒
121	29/01/18 09:36	Reinspection Photo	 Load JPG	☒
122	29/01/18 09:36	Reinspection Photo	 Load JPG	☒
123	29/01/18 09:36	Reinspection Photo	 Load JPG	☒
124	29/01/18 09:36	Reinspection Photo	Load JPG	☒

Letters/Correspondences			1 per page	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
125	29/01/18 09:36	Reinspection Photo	 Load JPG	☒
126	29/01/18 09:36	Reinspection Photo	 Load JPG	☒
127	29/01/18 09:36	Reinspection Photo	 Load JPG	☒
128	29/01/18 09:36	Reinspection Photo	 Load JPG	☒
129	29/01/18 09:36	Reinspection Photo	 Load JPG	☒
130	29/01/18 09:36	Reinspection Photo	 Load JPG	☒
131	29/01/18 09:36	Reinspection Photo	 Load JPG	☒
132	29/01/18 09:36	Reinspection Photo	 Load JPG	☒
133	29/01/18 09:36	Reinspection Photo	 Load JPG	☒
134	29/01/18 09:36	Reinspection Photo	 Load JPG	☒
135	29/01/18 09:36	Reinspection Photo	 Load JPG	☒
136	29/01/18 09:36	Reinspection Photo	 Load JPG	☒
137	29/01/18 09:36	Reinspection Photo	 Load JPG	☒
138	29/01/18 09:36	Reinspection Photo	 Load JPG	☒
139	29/01/18 09:36	Reinspection Photo	 Load JPG	☒
140	29/01/18 09:36	Reinspection Photo	 Load JPG	☒
141	29/01/18 09:36	Reinspection Photo	 Load JPG	☒
142	29/01/18 09:36	Reinspection Photo	 Load JPG	☒
143	29/01/18 09:36	Reinspection Photo	 Load JPG	☒
144	29/01/18 09:36	Reinspection Photo	 Load JPG	☒
145	29/01/18 09:36	Reinspection Photo	 Load JPG	☒
146	29/01/18 09:36	Reinspection Photo	 Load JPG	☒
147	29/01/18 09:36	Reinspection Photo	 Load JPG	☒
148	29/01/18 09:36	Reinspection Photo	 Load JPG	☒
149	29/01/18 09:36	Reinspection Photo	 Load JPG	☒
150	29/01/18 09:36	Reinspection Photo	 Load JPG	☒
151	29/01/18 09:36	Reinspection Photo	 Load JPG	☒
152	29/01/18 09:36	Reinspection Photo	 Load JPG	☒
153	29/01/18 09:36	Reinspection Photo	 Load JPG	☒
154	29/01/18 09:36	Reinspection Photo	 Load JPG	☒
155	29/01/18 09:36	Reinspection Photo	 Load JPG	☒
156	29/01/18 09:36	Reinspection Photo	 Load JPG	☒
157	29/01/18 09:36	Reinspection Photo	 Load JPG	☒
158	29/01/18 09:36	Reinspection Photo	 Load JPG	☒
159	29/01/18 09:36	Reinspection Photo	 Load JPG	☒
160	29/01/18 09:36	Reinspection Photo	 Load JPG	☒
161	29/01/18 09:36	Reinspection Photo	 Load JPG	☒
162	29/01/18 09:36	Reinspection Photo	 Load JPG	☒
163	29/01/18 09:36	Reinspection Photo	 Load JPG	☒
164	29/01/18 09:36	Reinspection Photo	 Load JPG	☒
165	29/01/18 09:36	Reinspection Photo	 Load JPG	☒
166	29/01/18 09:36	Reinspection Photo	 Load JPG	☒
167	29/01/18 09:36	Reinspection Photo	 Load JPG	☒
168	29/01/18 09:36	Reinspection Photo	 Load JPG	☒
169	29/01/18 09:36	Reinspection Photo	 Load JPG	☒
170	29/01/18 09:36	Reinspection Photo	 Load JPG	☒
171	29/01/18 09:36	Reinspection Photo	 Load JPG	☒
172	29/01/18 09:36	Reinspection Photo	Load JPG	☒

Letters/Correspondences			1 per page ▼	✓
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
173	29/01/18 09:36	Reinspection Photo	 Load JPG	✓
174	29/01/18 09:36	Reinspection Photo	 Load JPG	✓
175	29/01/18 09:36	Reinspection Photo	 Load JPG	✓
176	29/01/18 09:36	Reinspection Photo	 Load JPG	✓
177	29/01/18 09:36	Reinspection Photo	 Load JPG	✓
178	29/01/18 09:36	Reinspection Photo	 Load JPG	✓
179	29/01/18 09:36	Reinspection Photo	 Load JPG	✓
180	29/01/18 09:36	Reinspection Photo	 Load JPG	✓
181	29/01/18 09:36	Reinspection Photo	 Load JPG	✓
182	29/01/18 09:36	Reinspection Photo	 Load JPG	✓
183	29/01/18 09:36	Reinspection Photo	 Load JPG	✓
184	29/01/18 09:36	Reinspection Photo	 Load JPG	✓
185	29/01/18 09:36	Reinspection Photo	 Load JPG	✓
186	29/01/18 09:36	Reinspection Photo	 Load JPG	✓
187	29/01/18 09:36	Reinspection Photo	 Load JPG	✓
188	29/01/18 09:36	Reinspection Photo	 Load JPG	✓
189	29/01/18 09:36	Reinspection Photo	 Load JPG	✓
190	29/01/18 09:36	Reinspection Photo	 Load JPG	✓
191	29/01/18 09:36	Reinspection Photo	 Load JPG	✓
192	29/01/18 09:36	Reinspection Photo	 Load JPG	✓
193	29/01/18 09:36	Reinspection Photo	 Load JPG	✓
194	29/01/18 09:36	Reinspection Photo	 Load JPG	✓
195	29/01/18 09:36	Reinspection Photo	 Load JPG	✓
196	29/01/18 09:36	Reinspection Photo	 Load JPG	✓
197	29/01/18 09:36	Reinspection Photo	 Load JPG	✓
198	29/01/18 09:36	Reinspection Photo	 Load JPG	✓
199	29/01/18 09:36	Reinspection Photo	 Load JPG	✓
200	29/01/18 09:36	Reinspection Photo	 Load JPG	✓
201	29/01/18 09:36	Reinspection Photo	 Load JPG	✓
202	29/01/18 09:36	Reinspection Photo	 Load JPG	✓
203	29/01/18 09:36	Reinspection Photo	 Load JPG	✓
204	29/01/18 09:36	Reinspection Photo	 Load JPG	✓
205	29/01/18 09:36	Reinspection Photo	 Load JPG	✓
206	29/01/18 09:36	Reinspection Photo	 Load JPG	✓
207	29/01/18 09:36	Reinspection Photo	 Load JPG	✓
208	29/01/18 09:36	Reinspection Photo	 Load JPG	✓
209	29/01/18 09:37	Reinspection Photo	 Load JPG	✓
210	29/01/18 09:37	Reinspection Photo	 Load JPG	✓
211	29/01/18 09:37	Reinspection Photo	 Load JPG	✓
212	29/01/18 09:37	Reinspection Photo	 Load JPG	✓
213	29/01/18 09:37	Reinspection Photo	 Load JPG	✓
214	29/01/18 09:37	Reinspection Photo	 Load JPG	✓
215	29/01/18 09:37	Reinspection Photo	 Load JPG	✓
216	29/01/18 09:37	Reinspection Photo	 Load JPG	✓
217	29/01/18 09:37	Reinspection Photo	 Load JPG	✓
218	29/01/18 09:37	Reinspection Photo	 Load JPG	✓
219	29/01/18 09:37	Reinspection Photo	 Load JPG	✓
220	29/01/18 09:37	Reinspection Photo	Load JPG	✓

Letters/Correspondences			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
221	29/01/18 09:37	Reinspection Photo	 Load JPG	☒
222	29/01/18 09:37	Reinspection Photo	 Load JPG	☒
223	29/01/18 09:37	Reinspection Photo	 Load JPG	☒
224	29/01/18 09:37	Reinspection Photo	 Load JPG	☒
225	29/01/18 09:37	Reinspection Photo	 Load JPG	☒
226	29/01/18 09:37	Reinspection Photo	 Load JPG	☒
227	29/01/18 09:37	Reinspection Photo	 Load JPG	☒
228	29/01/18 09:37	Reinspection Photo	 Load JPG	☒
229	29/01/18 09:37	Reinspection Photo	 Load JPG	☒
230	29/01/18 09:37	Reinspection Photo	 Load JPG	☒
231	29/01/18 09:37	Reinspection Photo	 Load JPG	☒
232	29/01/18 09:37	Reinspection Photo	 Load JPG	☒
233	29/01/18 09:37	Reinspection Photo	 Load JPG	☒
234	29/01/18 09:37	Reinspection Photo	 Load JPG	☒
235	29/01/18 09:37	Reinspection Photo	 Load JPG	☒
236	29/01/18 09:37	Reinspection Photo	 Load JPG	☒
237	29/01/18 09:37	Reinspection Photo	 Load JPG	☒
238	29/01/18 09:37	Reinspection Photo	 Load JPG	☒
239	29/01/18 09:37	Reinspection Photo	 Load JPG	☒
240	29/01/18 09:37	Reinspection Photo	 Load JPG	☒
241	29/01/18 09:37	Reinspection Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	05/01/18 10:42	TP GIA REPORT	 Load PDF	
2	06/03/18 17:22	LTA SEARCH	 Load PDF	
3	17/03/18 13:56	LETTER TO LCRF	 Load PDF	
4	04/04/18 09:32	AUTHORISATION TO ACT	 Load PDF	
5	04/04/18 09:32	RELEASE VOUCHER	 Load PDF	
6	04/04/18 09:32	WORKSHOP INVOICE	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST		Reset	Save	Print
There are no document checklists configured.				
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)				
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.				

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SLD2565K (Insd veh)	Model:	BMW 523i 2.5 AT ABS D/AB 2WD
	SJP8861B (TP veh)		4DR GAS/D NAV (A)
Date of Accident:	31/12/2017		

Global Sum Settlement	:	☒ Yes	☐ No	
Repair Estimate	:	\$		79,778.78
Final Repair Cost	:	\$		29,800.00
Loss of Use	:	\$		20.00 days at \$100.00 per day
Rental (if any)	:	\$		days
LTA / GIA Search Fee	:	\$		
Others:	:	\$		
	:	\$		
Final Settlement Sum (GLOBAL SUM)	:	\$		29,800.00
Is Third Party Workshop GIA Registered? ☐ YES ☒ NO (Kindly indicate below)				
A) For Non GIA Registered Workshop:		Agreed Liability _____ 100 _____ (%)		
B) For GIA Registered Workshop:		BOLA Applicable: Yes/ No BOLA Scenario No: _____		
BOLA Liability: _____ (%)		Assessed Liability (*): _____ 100 _____ (%)		
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.				
Remarks _____				

Payment Instruction: Payee's Breakdown			
1)	Kim Chwee Auto Pte Ltd	:	\$ 29,800.00
2)		:	\$
3)		:	\$
4)		:	\$

NUR SHAQILAH BTE ABDOL WAHAB

04 Apr
2018

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.

(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/LCR18000121/AJA3S2
Date: 04/04/2018

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 0999995066
Claimant Vehicle No: SJP8861B Insured Vehicle No: SLD2565K
Date of Loss: 31/12/2017 Nature of Claim: TP Claim No: 0376552305SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SJP8861B
Make & Model: BMW 523i, 2.5 AT ABS D/AB 2WD 4DR GAS/D NAV (A) Engine No: 11037692N52B25AF
Reg. Date: 28/02/2011 (Man. Year: 2011) Chassis No: WBAFP320X0C864408
Colour: Blue Odometer: 104234 km
Engine Capacity: 2497 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 275/35R19 Rear Tyre Size: 275/35R19
Front Left Side: Pirelli 6 mm Rear Left Side: Pirelli 6 mm
Front Right Side: Pirelli 6 mm Rear Right Side: Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	65,369.61	36,864.09	28,505.52	43.61
Miscellaneous Items	0.00	0.00	0.00	
Labour	9,190.00	4,810.00	4,380.00	47.66
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	74,559.61	41,674.09	32,885.52	44.11
Approved Total (Overridden) (S\$)		26,000.00		
(S\$)	74,559.61	26,000.00	48,559.61	65.13
+ GST 7.00/7.00% (S\$)	5,219.17	1,820.00	3,399.17	65.13
Nett Amount (S\$)	79,778.78	27,820.00	51,958.78	65.13
+ Loss of Use (20.0 x S\$100.00/day) (S\$)		2,000.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		29,827.45		
Global Sum Settlement (S\$)		29,800.00		

INSPECTION

Date of Assignment: 02/01/2018
Date Inspected: 02/01/2018 Inspected At:
Estimated Period of Repair: 18.0 days

1 KAKI BUKIT AVENUE 6
#01-46/48/50 AUTOBAY
SINGAPORE 417883

Repairer: KIM CHWEE AUTO PTE LTD

Adjuster: ADRIAN LING**Manager:** Joy Irene Bascao

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT LID	Distorted	1,862.53 FL	*1,862.53 FL
2	1		*REAR BOOT BMW LOGO	Necessary	68.85 FL	*68.85 FL
3	2		*REAR BOOT BMW LOGO CLIPS	Necessary	9.00 FL	*9.00 FL
4	2		*REAR BOOT LAMPS - L/R	Cracked	683.20 FL	*683.20 FL
5	2		*REAR BOOT LICENCE LAMPS	Not Necessary	165.10 FL	*- FL
6	1		*REAR BOOT OPENING SWITCH	Damaged	180.93 FL	*180.93 FL
7	1		*REAR BOOT INNER LOCK	Jammed	280.95 FL	*280.95 FL
8	1		*REAR BOOT INNER LOCK ACTUATOR MOTOR	Damaged	581.90 FL	*581.90 FL
9	1		*REAR BOOT LOCK STRIKER	Bent	68.55 FL	*68.55 FL
10	1		*REAR BOOT INNER TRIM	Deformed	291.63 FL	*291.63 FL
11	10		*REAR BOOT INNER TRIM CLIPS	Necessary	55.00 FL	*55.00 FL
12	2		*REAR BOOT INNER PULL SWITCH	Not Necessary	130.63 FL	*- FL
13	2		*REAR BOOT HINGES - L/R	Bent	310.00 FL	*310.00 FL
14	2		*REAR BOOT STOPPERS	Necessary	37.20 FL	*37.20 FL
15	1		*REAR BOOT W/STRIP	Cut	261.95 FL	*261.95 FL
16	1		*REAR BUMPER - M. KIT	Distorted	1,865.50 FL	*1,865.50 FL
17	1		*REAR BUMPER TOW COVER	Distorted	48.85 FL	*48.85 FL
18	2		*REAR BUMPER REFLECTORS - L/R	Cracked	230.00 FL	*230.00 FL
19	1		*REAR BUMPER TOP GUIDE	Cracked	181.90 FL	*181.90 FL
20	1		*REAR BUMPER CTR GUIDE	Cracked	160.55 FL	*160.55 FL
21	1		*REAR BUMPER LOWER GUIDE	Not Necessary	126.50 FL	*- FL
22	2		*REAR BUMPER SIDE GUIDES - L/R	Necessary	270.00 FL	*270.00 FL
23	2		*REAR BUMPER SIDE BRACKETS	Necessary	230.00 FL	*230.00 FL
24	1		*REAR BUMPER REINFORCEMENT	Bent	761.90 FL	*761.90 FL
25	1		*REAR BUMPER PDC SENSORS	Damaged 2pcs Only	1,255.00 FL	*627.50 FL
		4pcs				
26	1		*REAR BUMPER PDC SENSOR WIRE	Snapped	431.60 FL	*431.60 FL
27	1		*REAR BUMPER PDC SENSOR CONTROL UNIT	Damaged	861.90 FL	*861.90 FL
28	1		*REAR END PANEL	Distorted	1,018.93 FL	*850.00 FL
29	1		*REAR END PANEL INNER MEMBER	Distorted	1,055.60 FL	*420.00 FL
30	1		*REAR END PANEL GARNISH	Cracked	180.93 FL	*180.93 FL
31	1		*REAR EXHAUST SILENCER ASSY	Bent	3,631.51 FL	*1,850.00 FL
32	3		*REAR EXHAUST MOUNTINGS	Torn	97.20 FL	*97.20 FL
33	2		*REAR EXHAUST INSULATORS	Crumpled	251.20 FL	*241.20 FL
34	1		*REAR FLOOR BOARD	Deformed	415.20 FL	*415.20 FL
35	1		*REAR FLOOR MAT	Torn	465.50 FL	*465.50 FL
36	1		*REAR FLOOR COMPARTMENT PANEL	Distorted	1,955.60 FL	*1,955.60 FL
37	2		*REAR FLOOR SPONGE TRAYS - L/R	Torn	263.00 FL	*263.00 FL
38	2		*REAR FENDERS - L/R	Repair	3,931.00 FL	*- FL
39	2		*REAR FENDER RAIL PANELS	Not Necessary	362.60 FL	*- FL
40	2		*REAR FENDER RAIL PANEL GARNISH	Not Necessary	179.90 FL	*- FL
41	2		*REAR FENDER INNER TRIMS - L/R	Crumpled	1,161.86 FL	*1,161.86 FL
42	2		*REAR FENDER INNER SHIELDS - L/R	Not Necessary	361.84 FL	*- FL
43	2		*REAR TAILLAMPS - L/R	Cracked	1,283.10 FL	*1,283.10 FL
44	2		*REAR TAILLAMP PANELS - L/R	Dented	311.20 FL	*311.20 FL
45	2		*REAR TAILLAMP COVERS - L/R	Cut	137.10 FL	*137.10 FL
46	1		*BATTERY BRACKET	Bent	110.50 FL	*110.50 FL
47	1		*BATTERY CABLE ELECTRICAL FUSE BOX	Not Necessary	861.55 FL	*- FL
48	1		*FRONT BONNET	Buckled	2,155.30 FL	*2,155.30 FL
49	1		*FRONT BONNET SAFETY LOCK	Not Necessary	130.40 FL	*- FL
50	1		*FRONT BONNET INSULATOR	Not Necessary	281.63 FL	*- FL
51	6		*FRONT BONNET INSULATOR CLIPS	Not Necessary	82.50 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
52	2		*FRONT BONNET HINGES	Not Necessary	221.20 FL	*- FL
53	2		*FRONT BONNET DAMPERS - L/R	Not Necessary	360.40 FL	*- FL
54	2		*FRONT BONNET LOCKS	Damaged	310.40 FL	*310.40 FL
55	2		*FRONT BONNET LOCK STRIKERS	Not Necessary	117.60 FL	*- FL
56	2		*FRONT BONNET LOCK CABLES	Not Necessary	163.10 FL	*- FL
57	1		*FRONT BUMPER	Distorted	1,865.50 FL	*1,865.50 FL
58	1		*FRONT BUMPER BMW LOGO	Necessary	68.85 FL	*68.85 FL
59	2		*FRONT BUMPER BMW LOGO CLIPS	Necessary	9.00 FL	*9.00 FL
60	1		*FRONT BUMPER CTR LOWER GRILLE	Deformed	155.30 FL	*155.30 FL
61	2		*FRONT BUMPER SIDE GRILLE - L/R	Not Necessary	179.90 FL	*- FL
62	2		*FRONT BUMPER FOG LAMPS - L/R	Not Necessary	582.86 FL	*- FL
63	1		*FRONT BUMPER TOP SEAL	Distorted	120.62 FL	*120.62 FL
64	1		*FRONT BUMPER TOW COVER	Distorted	48.85 FL	*48.85 FL
65	2		*FRONT BUMPER SPRAY NOZZLE COVERS	Damaged	170.00 FL	*170.00 FL
66	1		*FRONT BUMPER INNER SPONGE	Cracked	130.65 FL	*130.65 FL
67	1		*FRONT BUMPER REINFORCEMENT	Bent	788.95 FL	*788.95 FL
68	2		*FRONT BUMPER REINFORCEMENT STAYS	Bent	370.00 FL	*370.00 FL
69	2		*FRONT BUMPER SIDE GRIPS	Necessary	90.00 FL	*90.00 FL
70	1		*FRONT BUMPER LOWER BEAM	Bent	195.00 FL	*195.00 FL
71	1		*FRONT BUMPER PDC SENSORS	Damaged 2pcs Only	1,255.00 FL	*627.50 FL
72	1		4pcs *FRONT BUMPER PDC SENSOR WIRE	Not Necessary	289.63 FL	*- FL
73	2		*FRONT FENDERS - L/R	Repair	2,360.70 FL	*- FL
74	2		*FRONT FENDER INNER SHIELDS - L/R	Not Necessary	283.26 FL	*- FL
75	2		*FRONT HEADLAMPS - L/R	Cracked	5,103.20 FL	*5,103.20 FL
76	2		*FRONT HEADLAMP HID CONTROL UNITS	Not Necessary	1,731.00 FL	*- FL
77	2		*FRONT HEADLAMP HID BULB - L/R	Not Necessary	963.90 FL	*- FL
78	2		*FRONT HEADLAMP TOP GARNISHS	Not Necessary	179.90 FL	*- FL
79	2		*FRONT HEADLAMP BRACKETS - L/R	Not Necessary	371.00 FL	*- FL
80	2		*FRONT HEADLAMP SPRAY NOZZLE PEN	Not Necessary	379.00 FL	*- FL
81	1		*FRONT BRACE PANEL	Bent	215.50 FL	*215.50 FL
82	1		*FRONT SUPPORT PANEL	Buckled	435.00 FL	*435.00 FL
83	1		*FRONT SUPPORT TOP GARNISH	Cracked	180.93 FL	*180.93 FL
84	10		*FRONT SUPPORT TOP GARNISH CLIPS	Necessary	55.00 FL	*55.00 FL
85	1		*FRONT SUPPORT PANEL AIR DUCT - CTR	Not Necessary	341.55 FL	*- FL
86	2		*FRONT SIDE LOWER AIR DUCTS - L/R	Not Necessary	241.30 FL	*- FL
87	2		*FRONT SUPPORT BRACKETS	Bent	181.00 FL	*191.00 FL
88	1		*AIR CLEANER INTAKE DUCT	Not Necessary	187.45 FL	*- FL
89	1		*AIR CLEANER BOX ASSY	Not Necessary	865.00 FL	*- FL
90	1		*AIR CON CONDENSER	Dented	891.65 FL	*891.65 FL
91	1		*AIR CON CONDENSER AIR VENT	Not Necessary	241.50 FL	*- FL
92	1		*AIR CON DISCHARGE PIPE	Not Necessary	381.90 FL	*- FL
93	1		*AIR CON SUCTION PIPE	Not Necessary	361.50 FL	*- FL
94	1		*AIR CON LIQUID PIPE	Not Necessary	241.60 FL	*- FL
95	1		*RADIATOR ASSY	Dented	1,150.60 FL	*1,150.60 FL
96	1		*RADIATOR TOP COOLER HOSE	Not Necessary	141.60 FL	*- FL
97	2		*RADIATOR TOP STOPPERS	Not Necessary	36.40 FL	*- FL
98	2		*RADIATOR MODULES CARRIERS - L/R	Not Necessary	179.00 FL	*- FL
99	1		*RADIATOR BOTTOM COOLER HOSE	Not Necessary	130.65 FL	*- FL
100	1		*RADIATOR TOP HOSE CONNECTOR	Not Necessary	142.50 FL	*- FL
101	1		*RADIATOR HEAT EXCHANGE	Not Necessary	448.50 FL	*- FL
102	1		*RADIATOR TEMPERATURE SENSOR	Not Necessary	114.55 FL	*- FL
103	1		*RADIATOR EXPANSION TANK	Not Necessary	131.85 FL	*- FL
104	1		*RADIATOR EXPANSION TANK PIPE	Not Necessary	68.20 FL	*- FL
105	1		*RADIATOR AUXILIARY FAN ASSY	Not Necessary	1,485.50 FL	*- FL
106	1		*THERMOSTAT HOUSING	Not Necessary	191.60 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
107	1		*THERMOSTAT HOUSING HOSE	Not Necessary	110.30 FL	*- FL
108	1		*TRANS OIL COOLER	Not Necessary	581.60 FL	*- FL
109	1		*TRANS OIL COOLER HOSE - INLET	Not Necessary	155.90 FL	*- FL
110	1		*TRANS OIL COOLER HOSE - OUTLET	Not Necessary	181.60 FL	*- FL
111	1		*POWER STEERING COOLER PIPE	Not Necessary	331.45 FL	*- FL
112	2		*SAFETY BELT BUCKLES - L/R	Not Necessary	573.80 FL	*- FL
113	2		*FRONT SEAT HEADRESTS - L/R	Activated	1,161.20 FL	*1,161.20 FL
114	2		*ENGINE MOUNTINGS - L/R	Not Necessary	483.10 FL	*- FL
115	1		*ENGINE UNDERCOVER	Not Necessary	180.93 FL	*- FL
116	1		*REAR BOOT TOP SPOILER	Not Necessary	850.00 FS	*- FS
117	1		*BATTERY	Damaged	800.00 FS	*350.00 FS
118	1		*SET REAR FLOOR PANEL SOUND INSULATOR	Not Necessary	150.00 FS	*- FS
119	1		*SET REAR FLOOR PANEL SEALANT GUM	Necessary	120.00 FS	*60.00 FS
120	1		*SET REAR END PANEL SEALANT GUM	Necessary	120.00 FS	*60.00 FS
121	1		*SET REAR WINDSCREEN SEALANT	Not Necessary	120.00 FS	*- FS
122	1		*SET FRONT NO. PLATE WITH HOLDER	Cracked	150.00 FS	*70.00 FS
123	1		*SET FRONT GRILLE ASSY	Cracked	800.00 FS	*600.00 FS
124	1		*FRONT BUMPER SPOILER	Deformed	1,500.00 FS	*850.00 FS
125	1		*BOT AIR CON OIL	Necessary	60.00 FS	*40.00 FS
126	1		*BOT RADIATOR COOLANT	Necessary	65.00 FS	*40.00 FS
127	1		*SET FRONT BUMPER CLIP	Necessary	60.00 FS	*30.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	68,557.75	38,693.78
- List Item Discount on L Items 5.00/5.00% (\$)	3,188.14	1,829.69
Total Parts (\$)	65,369.61	36,864.09

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TOWING CHARGES.	New	200.00	150.00
2	TO REMOVE, REFIX R/INTERIOR TRIMS TO ASSIST REPAIR.	New	180.00	100.00
3	TO REINSTALL FUEL TANK TO ASSIST REPAIR.	New	200.00	0.00
4	TO RESPRAY UNDERCOATING.	New	250.00	100.00
5	TO CHECK FRONT / REAR ELECTRICAL WIRING.	New	150.00	60.00
6	TO REMOVE, REFIX REAR EXHAUST SYSTEMS.	New	180.00	100.00
7	TO REMOVE, REFIX A/C CONDENSER & REFILL A/C GAS.	New	180.00	120.00
8	TO DIAGNOSE, ERASE FAULT MEMORY AFTER REPAIR.	New	450.00	180.00
9	TO REMOVE, REFIX ENGINE PARTS.	New	300.00	0.00
10	TO RESPRAY PAINTING & ETC.	New	2,600.00	1,800.00
11	PANEL BEATING, CUT, WELD, REMOVE & REPLACING ABOVE PARTS.	New	4,500.00	2,200.00
Gross Labour Cost (S\$)			9,190.00	4,810.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >