

TC AUTOCLINIC PTE LTD
25 LENG KEE ROAD
SINGAPORE 159097

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SKZ1509B

		DAMAGED PARTS & PRICES		
S/NO PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST	S/NETT REMARKS
1 TOW HOOK COVER (SUPPLEMENTARY)	85071-4EA0A	16.80		ant ✓ OK
2 RIGHT REINFORCEMENT STAY (SUPPLEMENTARY)	H5210-4EAMA	126.00		br ✓ OK
3 LEFT REINFORCEMENT STAY (SUPPLEMENTARY)	H5211-4EAMA	126.00		bt ✓ OK
4 REINFORCEMENT (SUPPLEMENTARY)	H5030-4EAMA	619.20		ht ✓ OK
5 ENERGY ABSORBER	85090-4EA0B	126.40		OK
6 REAR BUMPER ASSEMBLY	85022-4EA0H	717.00		OK
7 SENSOR-REVERSE	SENSOR			200.00 X
8 BRACKET-BUMPER SIDE LHR	85221-4EA0A	35.90		OK
SUB TOTAL		1767.30	0.00	0.00
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)		353.46	0.00	0.00
GRAND TOTAL		1413.84	0.00	0.00
OVERALL TOTAL		1413.84		

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED