

Messrs Grab Rentals Pte Ltd

Date : 12.12.2017

Estimate To Repair : Mazda3 4-Door Sedan 1.5L SP
Vehicle No : SLM7740R
Chassis No : JM6BN22A8H0151443

TP AIG.
Vic

LKK
Adrian 26/18
@ 1/12/18

Pages : 1 of 1

S/No	Quantity	Description	Unit price	Amount
LIST ITEMS				
1	1 pc	rear bumper <i>2chd</i>	\$ 1,075.00	\$ 1,075.00
2	2 ps	rear bumper reflector <i>RH & LH</i>	\$ 55.00	\$ 110.00
3	2 ps	rear bumper tow cover <i>RH Missily</i>	\$ 18.00	\$ 36.00
4	2 ps	rear bumper side retainer <i>3pc</i>	\$ 92.00	\$ 184.00
5	2 ps	rear bumper side holder	\$ 74.00	\$ 148.00
6	4 ps	rear bumper side holder rivets	\$ 6.00	\$ 24.00
7	10 ps	rear bumper clip <i>mc</i>	\$ 5.00	\$ 50.00
8	2 ps	rear bumper end splashshield cover <i>see n</i>	\$ 80.00	\$ 160.00
9	1 pc	rear bumper reinforcement <i>Best</i>	\$ 538.00	\$ 538.00
10	1 pc	rear end panel <i>Repair</i>	\$ 556.00	\$ 556.00
11	1 pc	rear end panel inner trim <i>2chd</i>	\$ 96.00	\$ 96.00
12	1 pc	bootlid Mazda 3 badge <i>3pc</i>	\$ 54.00	\$ 54.00
13	1 pc	bootlid Skyactiv badge	\$ 64.00	\$ 64.00
14	2 ps	rear lamp <i>mc</i>	\$ 509.00	\$ 1,018.00
15	4 ps	rear lamp clip holder <i>see n</i>	\$ 8.00	\$ 32.00
Less 20 %				\$ 4,145.00
				\$ 829.00
				\$ 3,316.00
SPECIAL NETT ITEMS				
	1 set	rear bumper parking sensor <i>Damaged</i>	\$ 450.00	\$ 450.00
LABOUR & MISC. CHARGES				
1		To reinstall of rear bumper parking sensor.	\$ 120.00	\$ 120.00
2		To rust-proofing of the affected areas.	\$ 80.00	\$ 80.00
3		To check electrical lighting concerned.	\$ 60.00	\$ 60.00
4		To remove and refit interior fittings, trimmings, garnish and other, to enable repair.	\$ 150.00	\$ 150.00
5		Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same.	\$ 800.00	\$ 800.00
6		Putty and spray painting of the affected portion.	\$ 850.00	\$ 850.00
				\$ 2,060.00
Grand Total				\$ 5,826.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before after
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "no cure no pay" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Adrian King
L/S 02/01/18
03 Days

Total: 2728
L/S: 2150

Please conduct the survey at

Pegasus Engineering @ Tan Lim Motor Pte Ltd c/o 51 Defu Lane 10 Singapore 539216