

CHINA
~~NOTICE~~

DOA: 28.12.17

Date : 02.01.2018

MODEL : SONATA

Qty	Parts Description / Labour	Type	Unit Price	Amount
1	Left Side Mirror X repair			\$ 545.50
	SUB TOTAL			\$ 545.50
	LESS 20%			109.10
	DISCOUNTED TOTAL			\$ 436.40
				\$ 0.00
	Labour Charge			
	Panel Beating			\$ 100.00
	Spray Painting Charge			\$ 100.00
	Wiring Charge			\$ 50.00
	TOTAL LABOUR			\$ 250.00
	ESTIMATE TOTAL			\$ 686.40

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Page 1 of 1

Larry Ng

Calculus I/II/III

2/1/18

1 Day

45

After Repetition

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

~~Acknowledged by Repairer~~

Signature:

Date: