

**1st Autoworks Pte Ltd**  
23 Kaki Bukit Ave 4, #04-01 (South Wing) Singapore 415933

**Repair Estimate**

Date : 27/12/2017

Reference: SLS2641U  
OPEL MOKKA X  
Make: 1.6

To Whom It May Concern

Dear Sir,

RE: VEHICLE :SLS2641U  
CHASSIS NO.:W0LJD7EC5HB123991  
ENGINE NO.:A3163105GU7X0451

Name of insured :Alpine Car Rental Pte Ltd  
Date of accident.: 22/12/2017

We append hereunder the estimated cost of repairs to be carried out to the above vehicle.

**Parts**

| No. | Qty | Part Description                    | Price (SGD) |
|-----|-----|-------------------------------------|-------------|
| 1   | 1   | RHF Headlamp                        | \$ 2,600.00 |
| 2   | 1   | Front Bumper - Upper                | \$ 1,362.00 |
| 3   | 1   | Front Bumper - Lower                | \$ 448.00   |
| 4   | 1   | RHF Foglamp Cover                   | \$ 120.00   |
| 5   | 1   | RHF Foglamp                         | \$ 424.00   |
| 6   | 1   | Bar, Limiter Impact Absorber, Upper | \$ 784.00   |
| 7   | 1   | Crash Limiter, Frt End Lower        | \$ 486.00   |
| 8   | 1   | Front Bumper Absorber - Upper       | \$ 92.00    |
| 9   | 1   | Front Bumper Absorber - Lower       | \$ 72.00    |
| 10  | 1   | Front Support Panel Assy            | \$ 968.00   |
| 11  | 1   | LHF Bumper Bracket - Guide          | \$ 65.00    |
| 12  | 1   | RHF Bumper Bracket - Guide          | \$ 65.00    |
| 13  | 1   | RHF Fender                          | \$ 584.00   |
| 14  | 1   | RHF Fender Protector (Wheel Arch)   | \$ 125.00   |
| 15  | 1   | RHF Absorber                        | \$ 370.00   |
| 16  | 1   | RHF Wheel Hub                       | \$ 123.00   |
| 17  | 1   | RHF Wheel Bearing                   | \$ 208.00   |
| 18  | 1   | RHF Control Arm                     | \$ 266.00   |
| 19  | 1   | RHF Drive Shaft                     | \$ 1,800.00 |
| 20  | 1   | RHF Stabilizer Link                 | \$ 102.00   |
| 21  | 1   | RHF Knuckle Arm Assy                | \$ 299.00   |
| 22  | 1   | Stabilizer Bar                      | \$ 929.00   |
| 23  | 1   | RHF ABS Sensor                      | \$ 132.00   |
| 24  | 1   | RH Wind Mirror Assy                 | \$ 952.00   |

Parts Total: \$ 13,376.00  
Less 10%: \$ 1,337.60  
Total : \$ 12,038.40

**Labour**

Labour DescriptionNo.Price (SGD)Front portion

|   |                                                                                                                                                                               |             |            |
|---|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------|------------|
| 1 | To dismantle / renew the accident damaged portion, to panel beating, reshape, straighten, orientate and align repair / replacement parts. (\$650 PER DAY) , RHF Fender Repair | \$ 3,900.00 | 650<br>975 |
| 2 | Carry out spray painting on accident affected area (\$500 PER PANEL)                                                                                                          | \$ 2,500.00 | 1000       |
| 3 | To disconnect wire harness of electrical component to facilitate repairs, reconnect and check electrical function after repair                                                | \$ 30.00    | 20         |
| 4 | To conduct 4 wheel alignment                                                                                                                                                  | \$ 120.00   | ✓          |
| 5 | To remove and replace RHF under carriage parts                                                                                                                                | \$ 325.00   | ✓          |
| 6 | To refocus headlamp                                                                                                                                                           | \$ 80.00    | 30         |
| 7 | To remove and refit front sensor                                                                                                                                              | \$ 80.00    | 30         |

Labour Total : \$ 7,035.00

OthersOther DescriptionNo. QtyPrice (SGD)Front portion

|   |    |                                     |           |
|---|----|-------------------------------------|-----------|
| 1 | 20 | Front bumper upper/lower clip ✓ NEC | \$ 130.00 |
| 2 | 5  | RHF Fender Protector Clip ✓ NEC     | \$ 32.50  |
| 3 | 8  | Front Radiator Grille Clip X NN     | \$ 52.00  |
| 4 | 1  | RHF Rim ✓ XR                        | \$ 350.00 |
| 5 | 1  | RHF Tyre X                          | \$ 280.00 |

Other Total: \$ 844.50

GRAND TOTAL: \$ 19,917.90

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN. PARTS PRICES ARE SUBJECT TO CHANGES.

Yours faithfully

Suhaimi Ong

Service Executive  
Suhaimi Ong  
HP : 8298 8933 Fax: 6844 5185

**LKK Auto Consultants hence notify the Repairer of the following:**

- ✓ To resurvey before/after spray painting
- ✓ To display damaged part(s) during resurvey
- ✓ Parts prices are subject to confirmation
- ✓ Third party survey is on a "Without Prejudice" basis
- ✓ No illegal modification(s) is allowed
- ✓ Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Subout  
No Prejudice  
Wilson, LKK  
3 Days Repair  
Parts Price Subject Confirmation,  
D.A.D.

27/12/2017

**1st Autoworks Pte Ltd**  
23 Kaki Bukit Ave 4, #04-01 (South Wing) Singapore 415933

**Repair Estimate**

Date : 27/12/2017

Reference: SLS2641U  
OPEL MOKKA X  
Make: 1.6

To Whom It May Concern

Dear Sir,

RE: VEHICLE :SLS2641U  
CHASSIS NO.:W0LJD7EC5HB123991  
ENGINE NO.:A3163105GU7X0451

Name of insured :Alpine Car Rental Pte Ltd  
Date of accident.: 22/12/2017

We append hereunder the estimated cost of repairs to be carried out to the above vehicle.

**Parts**

| No. | Qty | Part Description                        | Price (SGD) |
|-----|-----|-----------------------------------------|-------------|
| 1   | 1   | RHF Headlamp ?                          | \$ 2,600.00 |
| 2   | 1   | Front Bumper - Upper ✓ SCR              | \$ 1,362.00 |
| 3   | 1   | Front Bumper - Lower ✓ SCR              | \$ 448.00   |
| 4   | 1   | RHF Foglamp Cover x                     | \$ 120.00   |
| 5   | 1   | RHF Foglamp x                           | \$ 424.00   |
| 6   | 1   | Bar, Limiter Impact Absorber, Upper x   | \$ 784.00   |
| 7   | 1   | Crash Limiter, Frt End Lower x          | \$ 486.00   |
| 8   | 1   | Front Bumper Absorber - Upper x         | \$ 92.00    |
| 9   | 1   | Front Bumper Absorber - Lower x         | \$ 72.00    |
| 10  | 1   | Front Support Panel Assy x              | \$ 968.00   |
| 11  | 1   | LHF Bumper Bracket - Guide x            | \$ 65.00    |
| 12  | 1   | RHF Bumper Bracket - Guide ✓ PEC        | \$ 65.00    |
| 13  | 1   | RHF Fender x                            | \$ 584.00   |
| 14  | 1   | RHF Fender Protector (Wheel Arch) ✓ SCR | \$ 125.00   |
| 15  | 1   | RHF Absorber ?                          | \$ 370.00   |
| 16  | 1   | RHF Wheel Hub ?                         | \$ 123.00   |
| 17  | 1   | RHF Wheel Bearing ?                     | \$ 208.00   |
| 18  | 1   | RHF Control Arm x ?                     | \$ 266.00   |
| 19  | 1   | RHF Drive Shaft x                       | \$ 1,800.00 |
| 20  | 1   | RHF Stabilizer Link x                   | \$ 102.00   |
| 21  | 1   | RHF Knuckle Arm Assy ?                  | \$ 299.00   |
| 22  | 1   | Stabilizer Bar x                        | \$ 929.00   |
| 23  | 1   | RHF ABS Sensor x                        | \$ 132.00   |
| 24  | 1   | RH Wind Mirror Assy x                   | \$ 952.00   |

Parts Total: \$ 13,376.00  
Less 10%: \$ 1,337.60  
Total : \$ 12,038.40

**Labour**

Labour DescriptionNo.Price (SGD)Front portion

|   |                                                                                                                                                                               |             |            |
|---|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------|------------|
| 1 | To dismantle / renew the accident damaged portion, to panel beating, reshape, straighten, orientate and align repair / replacement parts. (\$650 PER DAY) , RHF Fender Repair | \$ 3,900.00 | 650<br>975 |
| 2 | Carry out spray painting on accident affected area (\$500 PER PANEL)                                                                                                          | \$ 2,500.00 | 1000       |
| 3 | To disconnect wire harness of electrical component to facilitate repairs, reconnect and check electrical function after repair                                                | \$ 30.00    | 20         |
| 4 | To conduct 4 wheel alignment                                                                                                                                                  | \$ 120.00   | ✓          |
| 5 | To remove and replace RHF under carriage parts                                                                                                                                | \$ 325.00   | ✓          |
| 6 | To refocus headlamp                                                                                                                                                           | \$ 80.00    | 30         |
| 7 | To remove and refit front sensor                                                                                                                                              | \$ 80.00    | 30         |

Labour Total : \$ 7,035.00

OthersOther DescriptionNo. QtyPrice (SGD)Front portion

|   |    |                                     |           |
|---|----|-------------------------------------|-----------|
| 1 | 20 | Front bumper upper/lower clip ✓ NEC | \$ 130.00 |
| 2 | 5  | RHF Fender Protector Clip ✓ NEC     | \$ 32.50  |
| 3 | 8  | Front Radiator Grille Clip X NN     | \$ 52.00  |
| 4 | 1  | RHF Rim ✓ XR                        | \$ 350.00 |
| 5 | 1  | RHF Tyre X                          | \$ 280.00 |

Other Total: \$ 844.50

GRAND TOTAL: \$ 19,917.90

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN. PARTS PRICES ARE SUBJECT TO CHANGES.

Yours faithfully

Suhaimi Ong

Service Executive  
Suhaimi Ong  
HP : 8298 8933 Fax: 6844 5185

**LKK Auto Consultants** hence notify  
the Repairer of the following:

- ✓ To resurvey before/after spray painting
- ✓ To display damaged part(s) during resurvey
- ✓ Parts prices are subject to confirmation
- ✓ Third party survey is on a "Without Prejudice" basis
- ✓ No illegal modification(s) is allowed
- ✓ Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Subout  
No Prejudice  
Wilson, LKK  
3 Days Repair  
Parts Price Subject Confirmation  
Resurvey Before Paint

27/12/2017