

CITY CAB PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHB 4972M

MAKE :

MODEL : HYUNDAI i40

DATE 2/1/2018 10:32

LKK/kalvin

PbyP

Lice

AIG

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Front Bumper Cover /			\$ 1,052.20
	Front Bumper Bracket (LH) /			\$ 24.60
	Headlamp Support Panel Assy ?			\$ 1,067.50
	Headlamp (LH) /			\$ 1,388.00
	Front Fender (LH) /			\$ 619.00
	Front Fender Shield (LH) ✓			\$ 169.80
	Front Wheel Rim (LH) ✕			\$ 351.90
	Front Wheel Hub Cap (LH) /			\$ 150.70
	SUB TOTAL			\$ 4,823.70
	LESS 20%			\$ 964.74
	DISCOUNTED TOTAL			\$ 3,858.96
	Front Tyre (LH) ✕			\$ 216.00
				\$ 216.00
	Labour Charge			
	Panel Beating			\$ 1,000.00
	Spray Painting Charge			\$ 400.00
	Wiring Charge			\$ 50.00
	Tuff Kote			\$ 50.00
	Remove/Refix Aircon & Refill Gas			\$ 150.00
	Frt Wheel Alignment			\$ 80.00
	TOTAL LABOUR			\$ 1,730.00
	ESTIMATE TOTAL			\$ 5,804.96
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				

Front Tyre (LH) ✕

\$ 216.00

Nett

\$ 216.00

Labour Charge

Panel Beating

\$ 1,000.00

Spray Painting Charge

\$ 400.00

Wiring Charge

\$ 50.00

Tuff Kote

\$ 50.00

Remove/Refix Aircon & Refill Gas

\$ 150.00

Frt Wheel Alignment

\$ 80.00

TOTAL LABOUR

\$ 1,730.00

ESTIMATE TOTAL

\$ 5,804.96

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before after spray painting
- To display damaged parts during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- All modifications is allowed
- Supplementary items must be surveyed and is subject to final approval from insurance Company

Acknowledged by Repairer

Signature

Date:

Kalin LKK

2/1/18 11:36

2 Days

P/P

Before Point photo

400

360

20

20

✕

✕