

ASS. REC. BY:

AND:

CS/F118000132/T1Y6 02

Special Instruction:

Surveyor

ASSIGNMENT (Office)

From (Person): Eileen Lee

of

FCI

Date/Time: 2/1/2018

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SKP6068B

Insured: SHC8618E

at Workshop m/s

Tel: 68336282

of No. 8 Fourth Lok Yang Rd

Policy No: D-15072701MFSH

Claim No: D18000069MFSH

Sum Insured:

Excess:

Make of Veh:

D.O.A. 28/12/17

(Client's Record)

CA / REV / REP. / REV 24 HRS DS

H.O.D. Endorsement:

Date/Time: 3/1

Person Contacted:

Vehicle IN/OUT

Date/Time	Action/Instruction () Estimate
	SKP6068B - X
	SHC8618E - X
4/1/18	Email preli. revised to FCI
5/1/18	Final fig \$1170.48 confirmed by email (Reel 1858.60, 709) (No LS)

Signature *Tanjim*

REF:

'FCI'

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lump Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

WP

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

5KEG068B

Yr Regn:

2014 Sep

Type: M/Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toyota Alphard

C.C

2362

Colour:

White

A/C:

Insured / Std / NI / NA

Sp. Reading

237431

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

STEG021H808348 239

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

215 / 60 R17

R:

PS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

0

mm

R/Bal.

0

mm

L/Bal.

0

mm

L/Bal.

0

mm

D.O.A.

D.O.I.

08/01/18

Survey held at

Hutan Capital

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear o/s

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

RECEIVED 06 FEB 2018

Date/Time: File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time: File Return to?

2) sp - typist

Report Format:

CWS

Lump Sum / I.B.I. (\$

1170.48

Days Of Repair:

2

Resurvey No. of Trip:

1

Add Fee:

☐

: Site Insp. (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation

\$ + RS \$

Photos

Others

TOTAL

135

50

50

27

262



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18000132/T1vb	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 03-01-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 8618E	Veh. Inspected	SKP 6068B	
Policy No.	D-15072710MFSH	Coverage (\$)	0.00	
Claim No.	D18000069MFSH	Excess (\$)	0.00	
Assign From	EILEEN LEE	Assign Date	03/01/2018	
2. Vehicle Particulars & Condition				
Make & Model	c.c			
Engine No.	Year of Reg.			
Chassis No.	Colour			
Odometer	Steering			
Brakes	Modification			
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	28/12/2017	Inspection Date		
Survey held at				
5a. Remarks				



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: D18000069MFSH
Our ref: CS/FCI18000132/T1vb

Date: 4/1/2018

The Motor Claims Department
M/s FIRST CAPITAL INSURANCE LTD

Without Prejudice

Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. SKP 6068B


We thank you for your instruction on 2/1/2018

Please be informed that we had conducted the inspection of the above mentioned vehicle on 3/1/2018 at the premises of M/s HITACHI CAPITAL ASIA PACIFIC PTE LTD and have the following to report:-

Workshop Estimate Amount	: S\$4,029.08
Revised Estimate Amount	: S\$1,110.10
"Check" Items Amount	: S\$120.75
Market Value	: S\$
LTA Reimbursement Value	: S\$
Nett Value	: S\$

Description of Damage:

The vehicle sustained damages at the rear o/s portion.



Comments/Present Status:

Damages Consistent

Yours faithfully,

MOHAMAD TAUFIKH
M.MATAI, AMSAE-A
Automobile Assessor

Survey Department Check List (Case Handler)

Reference No.: CS/FC118000132/Tivb
Policy Type: OD / TP / TP RES / TL / EVA

Case Handler

Typist

Admin (): Case handler to make sure all Information created by the assignment team are ACCURATE.

(1) Office Assign Form

		Y-Date	N-Date	Y-Date	N-Date
C	Reference No.	✓			
C	Customer Code				
N	Assign From				
C	Assign Date	✓			
C	Veh No (Inspected)	✓			
C	Veh No (Insured)	✓			
C	D.O.A	✓			
C	Policy No	✓			
C	Claim No	✓			
C	Insurance Authorisation (CA /REV/REP)				
C	Report Type	✓			
C	Weekend Charges				
N	Survey held at/Repairer	✓			
C	Excess				

Surveyor (): Case handler to make sure the surveyor completed all required information.

(1) Assignment Form

C	Vehicle No	✓			
C	Regn Month/Year	✓			
N	Vehicle Type	✓			
N	Make & Model	✓			
C	Engine Capacity. (C.C)	✓			
N	Colour	✓			
C	Odometer. (Sp.Reading)	✓			
C	Chassis No	✓			
N	General Condition	✓			
N	Steering	✓			
N	Brake	✓			
N	Modification (Modi)	✓			
C	Tyre Size	✓			
N	Tyre Make	✓			
C	Tyre Balance	✓			
C	Date of Inspection	✓			
N	Survey held	✓			
N	Des.of Damages	✓			

(2) System - (Views/Merimen)

C	Damaged Vehicle Photographs Uploaded	✓			
---	--------------------------------------	---	--	--	--

(3) Workshop Estimate/Assignment Form

N	ALL Parts condition	✓			
C	Market Value for OD cases				
C	Estimate Repair Cost for PRI (RSI, TMI, MSIG)				
C	Days of repair	✓			
C	Finalised Amount	✓			
C	Re-inspection Cases to Finalize within 5 Days				

(4) System - (Views/Merimen)

C	Resurvey photo Uploaded	✓			
---	-------------------------	---	--	--	--

Check By: VERON 5/2/18
Case Handler Date

*C: Critical *N: Non-Critical

21/05/2014

First Capital Insurance Limited

A FAIRFAX Company

Company Reg. No. 195000106C
GST Reg. No. M2-0001676-9

MOTOR SURVEY ASSIGNMENT

Date	29-12-2017	Our Ref No. D18000069MFSH
Accident Date	28-12-2017	Claim Type. Third Party
Insured Vehicle	SHC8618E	Third Party Vehicle. SKP6068B
Survey Location	JUN TAIYO SERVICE CENTRE NO 8 FOURTH LOK YANG ROAD	
Contact Person.	GRANT CHONG	
Contact No.	68336282/ 0	Fax No. 68966591
Survey Type	DIRECT SETTLEMENT:	Tauhidh.
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	HITACHI CAPITAL ASIA PACIFIC PTE. LTD.	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	EILEEN LEE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/232472)



PRI Documents



Close



PRI Header Details

Claim No	D18000069MFSH	Policy No	D-15072701MFSH	Claimant S.No & Name	1 & HIT PTE. LT
Workshop Name	HITACHI CAPITAL ASIA PACIFIC PTE. LTD. (Contact Person : GRANT CHONG)	Survey Location & Contact Details	JUN TAIYO SERVICE CENTRE NO 8 FOURTH LO Mobile: 0 , Phone: 68336282 , Fax: 6896659 EmailId: KEANYAP.CHONG@HCSPL.COM.SG		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	DIRECT SETTLEMENT:		
Insured Name	COMFORT TRANSPORTATION PTE LTD	Insured Vehicle No	SHC8618E	TP Vehicle No	SKP600
PRI Recieved Date	29-12-2017 06:56:54 PM	Surveyor Appointed Date	02-01-2018 04:30:04 PM	Surveyor Accept Date	03-01-

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	03-01-2018	Upload Survey Report *:	
-----------------------------	--	----------------------	------------	-------------------------	--

Vehicle Particulars

Make	Please Select Make	Model	Please Select Model	Year	Select
Chasis No		Engine No		Mileage	
Color		Cubic Capacity			

Multiple Documents Upload

Upload Multiple Documents	
File Name	Action

Surveyor Job Remarks

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Monday, 5 February 2018 9:06 AM
To: 'KeanYap, Chong'; SUR; Taufikh (LKKAUTO)
Subject: RE: SKP6068B TP/1st Capital Finalization

Dear Kean,

Confirm P/P \$1,170.48 before GST.

No of days: 2 days

Final invoice and all supporting documents sent to First Capital Ins Ltd.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: KeanYap, Chong [mailto:keanyap.chong@hcspl.com.sg]
Sent: Friday, 2 February 2018 6:49 PM
To: SUR <sur@lkkauto.com>; Taufikh (LKKAUTO) <Taufikh@lkkauto.com>
Subject: SKP6068B TP/1st Capital Finalization

Dear Taufikh,

Attached with preliminary report and photo.

Please confirm P/P \$1,170.47 before GST.
2 day

Best regards,

*Grant Chong
Motor Claims Advisor
Auto Servicing Section*

Hitachi Capital Asia Pacific Pte. Ltd.
Jun Taiyo Service Centre (Automobile Leasing & Workshop)
8 Fourth Lok Yang Road, Singapore 629705
t: 6833 6282 f: 6896 6591
e: KeanYap.Chong@hcspl.com.sg
w: www.hitachi-capital.com.sg

HITACHI
Inspire the Next

***From 12th March 2018, we will be relocated to a different floor.
(NEW) 111 Somerset Road #14-05 Singapore 238164***

DISCLAIMER:

This email and/or any files and/or attachments transmitted are PRIVATE & CONFIDENTIAL and may be LEGALLY PRIVILEGED. This email is intended solely for the attention and use of the name addressee(s). If you are not a named addressee, you must not use, disseminate, forward, print or copy this email and all its contents/attachments. If you have received this email in error, please notify the sender immediately by email and delete it from your system.

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Thursday, 4 January, 2018 10:20 AM
To: 'Claim Workflow System'
Cc: EILEENLEE@FIRST-INSURANCE.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D18000069MFSH/1, SKP 6068B
Attachments: SKP 6068B PRELI ADVISED.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle SKP 6068B
Date of survey: 3/1/2018
Number of days: 2 days

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Wednesday, 3 January, 2018 10:46 AM
To: 'Claim Workflow System' <cwsmotorclaims@first-insurance.com.sg>; assignments <assignments@lkkauto.com>
Cc: EILEENLEE@FIRST-INSURANCE.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18000069MFSH/1

Dear Sir / Madam,

Thank you for the assignment.

"WISHES YOU A HAPPY NEW YEAR 2018"

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@first-insurance.com.sg>]
Sent: Tuesday, 2 January, 2018 4:29 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@FIRST-INSURANCE.COM.SG; EILEENLEE@FIRST-INSURANCE.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D18000069MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,

Admin Team

Claim Workflow System

Motor Claims Department

First Capital Insurance Limited

Tel : 6507 3848

Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.

Hitachi Capital Asia Pacific Pte. Ltd.
Jun Taiyo Service Centre

No. 8 Fourth Lok Yang Road Singapore 629705
 Tel : 64663022 Fax : 68966591
 Co. Reg.No. 199400399N GST Reg.No. M2-011899-3

VEHICLE ESTIMATE

First capital insurance Ltd

ATTN: MOTOR CLAIMS DEPT

QUOTE NO :
 ACCIDENT DATE : 28/12/2017, 13:30pm
 VRN : SKP6068B
 MODEL : TOYOTA ALPHARD 2.4A
 TP VRN : SHC8618E

	<u>Qty</u>	<u>S\$ Unit</u>	<u>S\$ Amt</u>	<u>S\$ Labor</u>
--	------------	-----------------	----------------	------------------

1. Body Repair

1 Rear bumper	1	\$	615.90	\$	615.90 <i>de ✓</i>
2 Rear bumper clips	10	\$	5.50	\$	55.00 <i>nr ✓</i>
3 Rear bumper retainer outer LH/RH	<i>1/2</i>	\$	75.90	\$	151.80 <i>nr ✓ 75.90</i>
4 Rear bumper retainer inner LH/RH	<i>1/2</i>	\$	80.50	\$	161.00 <i>? 80.50 nr ✓</i>
5 Rear bumper reflector light RH	1	\$	60.80	\$	60.80 <i>x ✓</i>
6 Taillamp RH	1	\$	495.90	\$	495.90 <i>x ✓</i>
7 Taillamp lower garnish RH	1	\$	200.80	\$	200.80 <i>x ✓</i>
8 Rear fender RH	Repair	Repair		Repair	
9 Rear fender shield RH	1	\$	175.90	\$	175.90 <i>x nr</i>
10 Rear fender shield clips RH	10	\$	5.50	\$	55.00 <i>x nr</i>
11 Tailgate	Repair	Repair		Repair	
12 Discount 25%	1		(\$493.02)	\$	(493.02)
TOTAL				\$	1,479.08

2. Labor Charges

1 Panel beat, cut, weld, re-align & replace damaged parts of affected area	250	\$	1,000.00
2 Putty, blend and paint affected area	250	\$	1,000.00
3 Check Wiring and ensure proper function	20	\$	80.00
4 Remove & reinstall bumper sensors	30	\$	120.00
5 Cavity treatment on new parts	<i>x</i>	\$	<i>x</i> 80.00
6 Remove & reinstall Rear reverse camera	<i>nr</i>	\$	<i>x</i> 120.00
7 Remove and refix tailgate lock & mechanism to facilitate repair	<i>x</i>	\$	<i>x</i> 150.00
Sub Total			\$ 2,550.00

Grand Total : \$ 4,029.08
 Add 7% GST : \$ 282.04
 Net Total : \$ 4,311.12

No. of repair days: 6

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

CUSTOMER SIGNATURE

Date:

Tan Jun 97495749
-WP-
2 days
Repair before paint
sur@lkkauto.com

HITACHI CAPITAL ASIA PACIFIC PTE LTD
 (MANAGER)

Hitachi Capital Asia Pacific Pte. Ltd.
Jun Taiyo Service Centre

No. 8 Fourth Lok Yang Road Singapore 629705
 Tel : 64663022 Fax : 68966591
 Co. Reg.No. 199400399N GST Reg.No. M2-011899-3

VEHICLE ESTIMATE

First capital insurance Ltd

QUOTE NO :
 ACCIDENT DATE : 28/12/2017, 13:30pm
 VRN : SKP6068B
 MODEL : TOYOTA ALPHARD 2.4A
 TP VRN : SHC8618E

ATTN: MOTOR CLAIMS DEPT

PARTS REPLACEMENT

1. Body Repair

	<u>Qty</u>	<u>S\$ Unit</u>	<u>S\$ Amt</u>	<u>S\$ Labor</u>
1 Rear bumper	1	\$ 615.90	\$ 615.90	
2 Rear bumper clips	10	\$ 5.50	\$ 55.00	
3 Rear bumper retainer outer LH/RH	2	\$ 75.90	\$ 151.80	
4 Rear bumper retainer inner LH/RH	2	\$ 80.50	\$ 161.00	
5 Rear bumper reflector light RH	1	\$ 60.80	\$ 60.80	
6 Taillamp RH	1	\$ 495.90	\$ 495.90	
7 Taillamp lower garnish RH	1	\$ 200.80	\$ 200.80	
8 Rear fender RH	1	Repair	Repair	
9 Rear fender shield RH	1	\$ 175.90	\$ 175.90	
10 Rear fender shield clips RH	10	\$ 5.50	\$ 55.00	
11 Tailgate	1	Repair	Repair	
12 Discount 25%	1	(\$493.02)	\$ (493.02)	
TOTAL			\$ 1,479.08	

Labor Charges

1 Panel beat, cut, weld, re-align & replace damaged parts of affected area	250	\$ 1,000.00
2 Putty, blend and paint affected area	250	\$ 1,000.00
3 Check Wiring and ensure proper function	20	\$ 80.00
4 Remove & reinstall bumper sensors	30	\$ 120.00
5 Cavity treatment on new parts		\$ 80.00
6 Remove & reinstall Rear reverse camera		\$ 120.00
7 Remove and refix tailgate lock & mechanism to facilitate repair		\$ 150.00
Sub Total		\$ 2,550.00

Parts \$ 827.30 - 25% = \$ 620.47

Labor \$ 550

Grand Total : \$ 4,029.08
 Add 7% GST : \$ 282.04
 Nett Total : \$ 4,311.12

No. of repair days: 6

CUSTOMER SIGNATURE

HITACHI CAPITAL ASIA PACIFIC PTE LTD
 (MANAGER)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI18000132/T1vbn2		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 07-02-2018		
		Code : FCI2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 8618E	Veh. Inspected	SKP 6068B	
Policy No.	D-15072710MFSH	Coverage (\$)	0.00	
Claim No.	D18000069MFSH	Excess (\$)	0.00	
Assign From	EILEEN	Assign Date	02/01/2018	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA ALPHARD	c.c	2362	
Engine No.	HIDDEN	Year of Reg.	2014	
Chassis No.	JTEGD21H808348239	Colour	WHITE	
Odometer	237431	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/60 R17	BRIDGESTONE	6 mm	
L/H Front Tyre	215/60 R17	BRIDGESTONE	6 mm	
R/H Rear Tyre	215/60 R17	BRIDGESTONE	6 mm	
L/H Rear Tyre	215/60 R17	BRIDGESTONE	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	28/12/2017	Inspection Date	03/01/2018	
Survey held at	HITACHI CAPITAL (S) PTE LTD JUN TAIYO SERVICE CENTRE NO. 8 FOURTH LOK YANG ROAD SINGAPORE 629705			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKP 6068B

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER	DEFORMED	615.90	615.90
10	REAR BUMPER CLIPS @\$5.50	NECESSARY	55.00	55.00
2	REAR BUMPER RETAINER OUTER LH/RH @\$75.90	O/S NECESSARY	151.80	75.90
2	REAR BUMPER RETAINER INNER LH/RH @\$80.50	O/S NECESSARY	161.00	80.50
1	REAR BUMPER REFLECTOR LIGHT RH	NOT NECESSARY	60.80	-
1	TAILLAMP RH	NOT NECESSARY	495.90	-
1	TAILLAMP LOWER GARNISH RH	NOT NECESSARY	200.80	-
1	REAR FENDER RH (NPA)	TO REPAIR SEE LABOUR	-	-
1	REAR FENDER SHIELD RH	NOT NECESSARY	175.90	-
10	REAR FENDER SHIELD CLIPS RH @\$5.50	NOT NECESSARY	55.00	-
1	TAILGATE (NPA)	TO REPAIR SEE LABOUR	-	-
	LESS 25% DISCOUNT		-493.02	-206.82
			1,479.08	620.48
LABOUR				
	PANEL BEAT,CUT,WELD,RE-ALIGN & REPLACE DAMAGED PARTS OF AFFECTED AREA.INCLUSIVE OF THE REPAIR OF REAR FENDER RH AND TAILGATE.		1,000.00	250.00
	PUTTY,BLEND AND PAINT AFFECTED AREA.		1,000.00	250.00
	CHECK WIRING AND ENSURE PROPER FUNCTION.		80.00	20.00
	REMOVE & REINSTALL BUMPER SENSORS.		120.00	30.00
	CAVITY TREATMENT ON NEW PARTS.	NOT NECESSARY	80.00	-
	REMOVE & REINSTALL REAR REVERSE CAMERA.	NOT NECESSARY	120.00	-
	REMOVE AND REFIX TAILGATE LOCK & MECHANISM TO FACILITATE REPAIR.	NOT NECESSARY	150.00	-
	-		-	-
	-		-	-
	-		-	-
			2,550.00	550.00
GRAND TOTAL			4,029.08	1,170.48

Report Ref No. CS/FCI18000132/T1vbn2



RECOMMENDED COST OF REPAIRS			1,170.48
-----------------------------	--	--	----------

Report Ref No. CS/FCI18000132/T1vbn2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.