



Ethicarz Pte. Ltd. 56 Loyang Way, Singapore (508775) #04-04
Loyang Enterprise Building, Email: johnong@ethicarz.sg
Tel: 63844404, FAX: 63840444

VEHICLE NUM:	SKZ1830Y
MAKE & MODEL:	HONDA VEZEL
MILEAGE:	35355
TYRE:	
CHASSIS NUM:	RU1-1108227

Kalvin 10000
3/1/8 14100000
1+3 Days.
Part by Part
Before Paint photo

ATTN:	KALVIN			
QTY	DESCRIPTION - PARTS	LEFT	RIGHT	PRICE
1	FRONT BONNET <i>500</i>			892.3
2	FRONT BONNET INNER RUBBER <i>500</i>	2	2	37.50X4PC
8	FRONT BONNET INNER TRIM CLIP <i>500</i>	4	4	8XS12
2	HEAD LAMP <i>3569-80</i>	1	1	1784.9X2PC ✓
2	HEAD LAMP CLIP <i>50</i>	1	1	5X10PC
1	FRONT BUMPER <i>500</i>			861.7 ✓
10	FRONT BUMPER CLIP <i>50</i>	5	5	5X10PCS ✓
2	FRONT BUMPER RETAINER <i>120</i>	1	1	60X2 ✓
2	FRONT BUMPER BRACKET <i>130</i>	1	1	65X2 ✓
1	FRONT BUMPER REINFORCEMENT BAR <i>500</i>			451 ✓
1	FRONT BUMPER GRILLE ASSY <i>500</i>			380 ✓
1	FRONT BUMPER GRILLE LOGO (HONDA) <i>500</i>			35 ✓
1	FRONT BUMPER LOWER GRILLE <i>500</i>			260
2	FRONT BUMPER FOG LAMP GRILLE ASSY <i>500</i>	1	1	50X2PCS
2	FRONT BUMPER FOG LAMP <i>500</i>	1	1	330X2PCS
1	FRONT BUMPER LOWER <i>500</i>			
1	FRONT BUMPER LOWER SILVER PROTECTOR <i>500</i>			
10	FRONT BUMPER LOWER SILVER PROTECTOR CLIP <i>500</i>			
1	FRONT BUMPER UNDERCOVER RUBBER <i>500</i>			88.9
2	FRONT FENDER <i>500</i>	1	1	558.70X2
2	FRONT FENDER COWLING <i>500</i>	1	1	150X2
10	FRONT FENDER COWLING CLIP <i>500</i>	5	5	5X10PCX2
2	FRONT FENDER COWLING PROTECTOR <i>500</i>	1	1	193X2
10	FRONT FENDER COWLING PROTECTOR CLIP <i>500</i>	5	5	5X10PCX2
1	FRONT SUPPORT PANEL <i>500</i>			636.2
PARTS SUBTOTAL				-20% \$ 5087.5
QTY	DESCRIPTION - SPECIAL NETT	LEFT	RIGHT	PRICE
1	FRONT CAR PLATE <i>500</i>			80
SPECIAL NETT TOTAL				\$ 40
QTY	DESCRIPTION - LABOUR	LEFT	RIGHT	PRICE
1	TO RNR ACCIDENT AFFECTED FRONT			600 1300 ✓
1	TO PUTTY AND RESPRAY ACCIDENT AFFECTED FRONT			200 1200 ✓
2	TO CHECK WIRING LAYOUT AND HEADLAMP FOCUS	1	1	30 240 ✓

[illegible]