



Ethicarz Pte. Ltd. 56 Loyang Way, Singapore (508775) #04-04
Loyang Enterprise Building, Email: johnong@ethicarz.sg
Tel: 63844404, FAX: 63840444

VEHICLE NUM: SKZ1830Y
MAKE & MODEL: HONDA VEZEL
MILEAGE: 35355
TYRE:
CHASSIS NUM: RU1-1108227

1/Calus' 1/10/11
3/1/11 14/10/11
3 Dpts.
Part by Part
Before Paint photo

ATTN:					
QTY	DESCRIPTION - PARTS	LEFT	RIGHT	PRICE	
1	FRONT BONNET			892.3	
2	FRONT BONNET INNER RUBBER	2	2	37.50X4PC	
8	FRONT BONNET INNER TRIM CLIP	4	4	8X\$12	
2	HEAD LAMP	1	1	1784.9X2PC	
2	HEAD LAMP CLIP	1	1	5X10PC	
1	FRONT BUMPER			861.7	
10	FRONT BUMPER CLIP	5	5	5X10PCS	
2	FRONT BUMPER RETAINER	1	1	60X2	
2	FRONT BUMPER BRACKET	1	1	65X2	
1	FRONT BUMPER REINFORCEMENT BAR			451	
1	FRONT BUMPER GRILLE ASSY			380	
1	FRONT BUMPER GRILLE LOGO (HONDA)			35	
1	FRONT BUMPER LOWER GRILLE			260	
2	FRONT BUMPER FOG LAMP GRILLE ASSY	1	1	50X2PCS	
2	FRONT BUMPER FOG LAMP	1	1	330X2PCS	
1	FRONT BUMPER LOWER				
1	FRONT BUMPER LOWER SILVER PROTECTOR				
10	FRONT BUMPER LOWER SILVER PROTECTOR CLIP				
1	FRONT BUMPER UNDERCOVER RUBBER			88.9	
2	FRONT FENDER	1	1	558.70X2	
2	FRONT FENDER COWLING	1	1	150X2	
10	FRONT FENDER COWLING CLIP	5	5	5X10PCX2	
2	FRONT FENDER COWLING PROTECTOR	1	1	193X2	
10	FRONT FENDER COWLING PROTECTOR CLIP	5	5	5X10PCX2	
1	FRONT SUPPORT PANEL			636.2	
1	FRONT CAR PLATE			80	
1	TO RNR ACCIDENT AFFECTED FRONT			650 1300	
1	TO PUTTY AND RESPRAY ACCIDENT AFFECTED FRONT			200 1200	
2	TO CHECK WIRING LAYOUT AND HEADLAMP FOCUS	1	1	240	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: