

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

Vehicle Insured : SKE3163L
 Accident Date : 29-Dec-2017

No. : 05696

Date : 02-Jan-2018

Our Ref : 217201 (AXA) / CHAN

PAGE : 1

LAURUS LIFESTYLE PTE LTD
 BLK 113A MCNAIR ROAD
 #15-282
 Singapore 322113

*Not Authorized
 6/1/17 @ 7
 Recovery After Paint 4 days*

ESTIMATED COST OF REPAIR FOR NISSAN TEANA SLP2858C
 =====

1 pc	Rear bumper fascia		<i>Bu</i> 840.00	n	✓
2 pcs	Rear bumper side chrome	@ S\$145.50	<i>nu</i> 291.00	n	✓
1 pc	Rear bumper reinforcement		330.90	n	✓
2 pcs	Bumper reinforcement bracket	@ S\$ 95.20	190.40	n	✓
1 pc	Rear bumper inner sponge		139.00	n	✓
2 pcs	Taillamp	<i>cm</i> @ S\$581.00	1,162.00	n	✓
1 pc	Rear end panel		<i>R</i> 550.20	n	X
1 pc	End panel top garnish		<i>su</i> 95.30	n	X
1 pc	Boot lid		<i>R</i> 1,000.70	n	X
1 pc	Boot lid lower chrome		229.80	n	✓
1 pc	Boot lid "TEANA" emblem		<i>nu</i> 95.70	n	✓
1 pc	Boot lid logo		<i>nu</i> 50.70	n	✓
1 pc	Boot lid "250XV" emblem		<i>nu</i> 80.70	n	✓

5,056.40

Less 10% : 505.64

1 pc	Rear bumper reverse sensor				4,550.76
					300.00 sn ✓
	To remove roof lining, front and rear seats, trim board and carpet			<i>nu</i>	60.00 X
	To apply undersealing			<i>nu</i>	80.00 X
	To putty and spray replaced parts				900.00 <i>6000</i>

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Con't Page 2 ...

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

Vehicle Insured : SKE3163L

Page : 2

To remove, cut-out damaged parts,
panel beating, welding, align,
refix and to renew above parts

950.00 *500*

Total : S\$ 6,840.76

Singapore Dollars Six Thousand Eight Hundred
and Forty and Cents Seventy Six Only