

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

Vehicle Insured : SLL7939R
Accident Date : 07-Dec-2017

Our Ref : 217200 (AIG) / CHAN

CHOO CHEE SING
BLK 149 RIVERVALE CRESCENT
#14-50
Singapore 540149

No. : 05695

Date : 29-Dec-2017

PAGE : 1

Not Authorized
11/12/17
Resurvey After Repair
4 days

ESTIMATED COST OF REPAIR FOR TOYOTA ALTIS SKV4896J

1 pc	Rear o/s door	1,169.20 ✓
1 pc	Rear o/s door inner lock	478.70 X
1 pc	Rear o/s door rubber	192.50 ?
1 pc	Rear o/s door frame tape(set)	84.30 ✓
1 pc	Rear o/s door outer moulding	131.20 X
1 pc	Rear o/s door glass regulator gear	167.90 ?
1 pc	Rear o/s door glass regulator motor	552.20 ?
1 pc	Rear bumper fascia	482.00 X
1 pc	Rear o/s bumper side retainer	104.40 X
1 pc	Rear o/s fender mudflap	56.90 X

		3,419.30
Less 25% :		854.83

2,564.47

To putty and spray replaced parts

900.00 *800*

To remove, cut-out damaged parts,
panel beating, welding, align,
refix and to renew above parts

700.00 *500*

To check and adjust wheel alignment

65.00 *60*

To remove sport rim for repair

120.00 *80*

Total : S\$ 4,349.47

Singapore Dollars Four Thousand Three Hundred
and Forty Nine and Cents Forty Seven Only

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: