



CO. REG. NO: 199402370D
GST NO: M2-0123250-3

AUTO PTE LTD

金興(龔)汽車私人有限公司

160 Sin Ming Drive, #02-18/19/20/21,
Sin Ming AutoCity, Singapore 575722
Tel: 6452 7018 Fax: 6458 3895

Email: service@kkinh.com.sg

No. : 29403

Vehicle Insured : SGM 2083 X
Accident Date : 29-Dec-2017

Date : 02-Jan-2018

Our Ref : 170931 (AXA) / SHUMAN

PAGE : 1

GOH SEE TIANG (MDM)-MRS CHOW
Singapore

*Not Authorized
1/1/17 @ 7
Running After Police*

ESTIMATED COST OF REPAIR FOR TOYOTA CAMRY 2.4G A (2009) SJR8537C
=====

1 pc	front bumper		<i>B</i>	560.00	✓
2 pcs	front bumper side retainer (LH/RH)	@ S\$ 75.80	<i>N/D</i>	151.60	✓
10 pcs	front bumper clips	@ S\$ 3.90	<i>M</i>	39.00	✓
1 pc	n/s front bumper foglamp		<i>S</i>	300.00	X
1 pc	n/s front bumper foglamp cover and chrome rim		<i>S</i>	78.20	X
1 pc	front bumper lower centre grille		<i>S</i>	150.00	X
1 pc	front bumper logo		<i>M</i>	115.40	✓
1 pc	front bumper top seal		<i>S</i>	80.00	X
1 pc	front grille and outer chrome		<i>S</i>	371.90	X
1 pc	n/s headlamp assy		<i>M/S</i>	1,580.00	✓
1 pc	n/s headlamp lower bracket			123.40	?
1 pc	n/s front fender		<i>B</i>	801.00	✓
1 pc	n/s front fender inner shield		<i>D</i>	198.00	✓
8 pcs	n/s front fender inner shield clips	@ S\$ 3.90	<i>M</i>	31.20	✓
1 pc	n/s front fender inner shield retainer		<i>M</i>	55.00	✓
1 pc	n/s front fender inner shield retainer pin		<i>M</i>	30.00	✓
1 pc	n/s front shock absorber		<i>B</i>	435.00	✓
1 pc	n/s front shock absorber mounting			190.00	?
1 pc	n/s front shock absorber mounting bearing			92.10	?
1 pc	n/s front shock absorber stopper			35.50	?
1 pc	n/s front shock absorber cover		<i>S</i>	59.50	X

LKK Auto Consultants hereby notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) allowed
- Supplementary item(s) must be surveyed and is subject to final approval from insurance Company

Con't Page 2 ...

Acknowledged by Repairer

Signature:

Date:



金興(龔)汽車私人有限公司

160 Sin Ming Drive, #02-18/19/20/21,
Sin Ming AutoCity, Singapore 575722

Tel: 6452 7018 Fax: 6458 3895

Email: service@kkinhin.com.sg

Vehicle Insured : SGM 2083 X
Our Ref : 170931

Page : 2
No. : 29403

1 pc	n/s front knuckle arm	B ₁	549.00	—
1 pc	n/s front knuckle arm bearing	Re	170.00	—
1 pc	n/s front bearing hub	B ₁	250.00	—
1 pc	n/s front lower arm		600.00	7
1 pc	n/s front lower arm ball joint		165.70	7
1 pc	n/s front stabilizer bar linkage	in	135.00	X
1 pc	engine mounting-LH		252.00	7
1 pc	engine mounting-RH		455.00	7
1 pc	engine mounting-front		455.00	7
1 pc	engine mounting-rear		165.00	7
1 pc	n/s front tie rod		125.00	7
1 pc	n/s front tie rod end		150.30	7
1 pc	n/s front drive shaft		1,839.30	7
1 pc	steering rack and pinion		3,175.80	7

			13,963.90	
		Less 25% :	-3,490.97	

			10,472.93	

1 pc	n/s front tyre		220.00	sn 7
1 pc	n/s front rim	Ad	540.00	sn ✓
To tow accident vehicle to workshop by normal towing			80.00	501
To remove, cut out damaged parts, panel beating, welding, align, refix and to renew affected parts.			680.00	4001
To dismantle and check front under-carriages. To replace affected portions.			240.00	2001
To conduct front wheel alignment test.			80.00	601



CO. REG. NO: 199402370D
GST NO: M2-0123250-3

AUTO PTE LTD

金興(龔)汽車私人有限公司

160 Sin Ming Drive, #02-18/19/20/21,
Sin Ming AutoCity, Singapore 575722

Tel: 6452 7018 Fax: 6458 3895

Email: service@kkimhin.com.sg

Vehicle Insured : SGM 2083 X

Our Ref : 170931

Page : 3

No. : 29403

To putty and respray on affected
portions.

880.00

To focus headlamps. To check front
wiring and lighting operation.

30.00

Total : S\$13,222.93

Singapore Dollars Thirteen Thousand Two Hundred
and Twenty Two and Cents Ninety Three Only

Note: Amount quoted above is subject to prevailing GST at time of tax invoice.