



CO. REG. NO: 199402370D
GST NO: M2-0123250-3

AUTO PTE LTD

金興(龔)汽車私人有限公司

160 Sin Ming Drive, #02-18/19/20/21,
Sin Ming AutoCity, Singapore 575722
Tel: 6452 7018 Fax: 6458 3895
Email: service@kkinhin.com.sg

Vehicle Insured : SGM 2083 X
Accident Date : 29-Dec-2017

No. : 29403

Date : 02-Jan-2018

Our Ref : 170931 (AXA) / SHUMAN

PAGE : 1

GOH SEE TIANG (MDM)-MRS CHOW
Singapore

ESTIMATED COST OF REPAIR FOR TOYOTA CAMRY 2.4G A (2009) SJR8537C

1 pc	front bumper				
2 pcs	front bumper side retainer (LH/RH)	@ S\$ 75.80	560.00 ✓		
10 pcs	front bumper clips	@ S\$ 3.90	115.40 ✓		
1 pc	n/s front bumper foglamp		39.00 ✓		
1 pc	n/s front bumper foglamp cover and chrome rim		300.00 X		
1 pc	front bumper lower centre grille		78.20 X		
1 pc	front bumper logo		150.00 X		
1 pc	front bumper top seal		115.40 ✓		
1 pc	front grille and outer chrome		80.00 X		
1 pc	n/s headlamp assy		371.90 X		
1 pc	n/s headlamp lower bracket		1,580.00 ✓		
1 pc	n/s front fender		123.40 ✓		
1 pc	n/s front fender inner shield		801.00 ✓		
8 pcs	n/s front fender inner shield clips	@ S\$ 3.90	198.00 ✓		
1 pc	n/s front fender inner shield retainer		31.20 ✓		
1 pc	n/s front fender inner shield retainer pin		55.00 ✓		
1 pc	n/s front shock absorber		30.00 ✓		
1 pc	n/s front shock absorber mounting		435.00 ✓		
1 pc	n/s front shock absorber mounting bearing		190.00 ✓		
1 pc	n/s front shock absorber stopper		92.10 ✓		
1 pc	n/s front shock absorber cover		35.50 ✓		
			59.50 X		

Con't Page 2 ...



CO. REG. NO: 199402370D
GST NO: M2-0123250-3

金興(龔)汽車私人有限公司

160 Sin Ming Drive, #02-18/19/20/21,
Sin Ming AutoCity, Singapore 575722
Tel: 6452 7018 Fax: 6458 3895
Email: service@kkimhin.com.sg

Vehicle Insured : SGM 2083 X
Our Ref : 170931

Page : 2
No. : 29403

- 1 pc n/s front knuckle arm
- 1 pc n/s front knuckle arm bearing
- 1 pc n/s front bearing hub
- 1 pc n/s front lower arm
- 1 pc n/s front lower arm ball joint
- 1 pc n/s front stabilizer bar linkage
- 1 pc engine mounting-LH
- 1 pc engine mounting-RH
- 1 pc engine mounting-front
- 1 pc engine mounting-rear
- 1 pc n/s front tie rod
- 1 pc n/s front tie rod end
- 1 pc n/s front drive shaft
- 1 pc steering rack and pinion

B₁ 549.00 —
M 170.00 —
B₁ 250.00 —
B₁ 600.00 7 ✓
B₁ 165.70 7 ✓
B₁ 135.00 X

D₁ 252.00 7 ✓
CM 455.00 7 ✓
D₁ 455.00 7 ✓
D₁ 165.00 7 ✓
B₁ 125.00 7 ✓
B₁ 150.30 7 ✓
B₁ 1,839.30 7 ✓
B₁ 3,175.80 7 ✓

Less 25% : 13,963.90
-3,490.97

10,472.93

665N G₁ 220.00 sn 309N
Del 540.00 sn ✓

80.00 501

680.00 4001

240.00 2001

80.00 601

- 1 pc n/s front tyre
- 1 pc n/s front rim

To tow accident vehicle to workshop
by normal towing

To remove, cut out damaged parts,
panel beating, welding, align,
refix and to renew affected parts.

To dismantle and check front under-
carriages. To replace affected
portions.

To conduct front wheel alignment
test.

Con't Page 3 ...



CO. REG. NO: 199402370D
GST NO: M2-0123250-3

AUTO PTE LTD

金興(龔)汽車私人有限公司

160 Sin Ming Drive, #02-18/19/20/21,
Sin Ming AutoCity, Singapore 575722
Tel: 6452 7018 Fax: 6458 3895
Email: service@kkimhin.com.sg

Vehicle Insured : SGM 2083 X
Our Ref : 170931

Page : 3
No. : 29403

To putty and respray on affected portions.

To focus headlamps. To check front wiring and lighting operation.

880.00

30.00

Total : S\$13,222.93

Singapore Dollars Thirteen Thousand Two Hundred and Twenty Two and Cents Ninety Three Only

Note: Amount quoted above is subject to prevailing GST at time of tax invoice.

\$ 12,590.00 - Part

-25%

\$ 9,442.58

\$ 760.00 - 3/1

\$ 1,330.00 - Labour

\$ 11,532.58

-20%

\$ 9,226.06

4/5 = \$ 9,250.00