

CASE OWNER:

ELANE

CC4 / EQ18000152 1543

## ASSIGNMENT

Surveyor:

Whistm

DOI:

2/1/18

Date / Time:

03/01/18

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

GBF 1805H

Claim No.:

Name of Insured:

CO-AL ENGINEERING INTEGRATED SERVICES PTE LTD

Policy No.:

DMCPHQ17-004033

Insured Tel No.:

HP: 9375 7029

Make / Model:

MITSUBISHI CANTER FEAO18R250EB

Excess Sec II :SS

D.O.A: 29/12/17

Place of Accident:

WOODLANDS AVE 12

Is driver the owner?

( YES (NO) )

Nature of Accident:

If NO, Driver Name / Age: ISLAM NAZMUL

OI GIA REPORT YES / NO ; TP GIA REPORT YES / NO

Driver Tel No.: 9078 0040

(V/L YES / NO)

Insured Liability:

% Final ? Yes / No

SIG 6536P



INSRS:

WSP: Hua Hong

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date / Time

03/01/18 (THU THN)

SIG 6536P - X ; GBF 1805H - X

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI: 12/1/18 315 PM

After call ltr to OI: 12/01/18 - DIC DE

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

11/1/18 @ 1938 - call OI, no respond.  
- to follow up call OI.12/1/18 @ 1156 am - spoke to OI, 93757029 agreed to settle on TP claims.  
Amount of NOL NOL - \$0

RECEIVED 24 SEP 2018

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

S\$

(

days) Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

20/9/18

Confirm with:

Ashely

Email

Call

Final Liability:

%

100

(Agreed / Assessed) BOLA S/N No.:

27

If NO or B 28, Ass. Lia:

Repair Cost:

S\$ 4761.50

Loss of Rental (LOR):

S\$ 1027.20

(

8

days)

x 120 to 65

Loss of Use (LOU):

S\$

(\$

x

days)

Loss of Income (LOI):

S\$

(\$

x

days)

LOR only ☐ LOU only ☐LOR + LOU ☐LOR + LOI ☐

[Tick only one]

GIA/LTA Search

S\$ 2.00

Medical:

S\$

1) Claim status: Normal/Reject/Private Settle

Disbursement:

S\$

(e.g. Tow/ Independent)

2) Report Format:

Legal Cost

S\$

3) Survey fee:

Total:

S\$ 5790.70

Global Sum S\$:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

S\$ 5790.70

Name 1:

HUA HONG PRIVATE LIMITED

Payee 2: (Strike if N.A.)

S\$

Name 2:

Payee 3: (Strike if N.A.)

S\$

Name 3:



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

EQ INSURANCE COMPANY LTD

Ref : CC4/EQI18000152/Sus3

5 MAXWELL ROAD  
#17-00 TOWER B LOCK  
MND COMPLEX SINGAPORE 069110

Date : 03-01-2018



Code : EQI

## 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBF 1805H	Veh. Inspected	SGQ 6586P
Policy No.	DMCPHQ17-004033	Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	03/01/2018

## 2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer		Steering
Brakes		Modification
General		

## 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

## 4. Description of Damages

--

## 5. General Information

Accident Date	29/12/2017	Inspection Date	03/01/2018
Survey held at	HUA HONG PTE LTD 25D SUNGEI KADUT STREET 1 SINGAPORE 729332		

## 5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
---



# HUA HONG PRIVATE LIMITED

250 Sungai Kadut Street 1 Singapore 729332  
Tel: (65) 4461 9488 Fax: (65) 4461 9699 Email: info@huahong.com.sg

## Estimate Repair List

29 December 2017

HHTPClaims17-114

EQ Insurance Company Ltd  
5 Maxwell Road  
#17-00 Tower Block MND Complex  
Singapore 069110

### ACCIDENT INVOLVING SGQ 6586 P & GBF 1805 H ON 29/12/2017 ALONG GAMBAS AVE TOWARDS PIE AT ABOUT 0755 HOURS

Insured : MAUNG MYA AYE @MUHAMMAD ABBAS  
Vehicle Registration No : SGQ 6586 P  
Vehicle Make : HONDA  
Vehicle Model : ACCORD  
Vehicle Chassis No : MRHCP2630AP060012  
Policy No : MT/00264927/02  
Date of Accident : 29/12/2017

Type of Claim: Third Party

S/N	Quantity	Description	Unit Price S\$	Amount S\$
1	1	Rear Bumper ✓ 11mm		\$ 709.40
2	10	Rear Bumper Clip ✓ 1/16"	\$ 3.70	\$ 37.00 30
3	2	Rear Bumper Retainer (LH/RH) ✓ 1/16"	\$ 20.00	\$ 40.00
4	1	Rear Reinforcement ✓ 1/8"		\$ 185.60
5	1	Rear End Panel ✓ 1/8"		\$ 327.80
6	1	Rear End Panel Top Garnish ✓ 1/8"		\$ 97.70
7	2	Rear Tail Lamp Panel (LH/RH) LH & RH ✓ 1/8"	\$ 89.80	\$ 179.60 89.80
8	2	Rear Tail Lamp (LH/RH) ✓ 1/8"	\$ 295.80	\$ 591.60
9	2	Rear Reverse Lamp (LH/RH) ✓ 1/8"	\$ 172.20	\$ 344.40
10	1	Rear Boot ✓ 1/8"		\$ 878.40
11	2	Rear Boot Hinge (LH/RH) ✓ 1/8"	\$ 48.60	\$ 97.20
12	1	Rear Boot Logo (Accord) ✓ 1/8"		\$ 19.20
13	1	Rear Boot Logo (2.4vtec) ✓ 1/8"		\$ 33.50
14	1	Rear Emblem ✓ 1/8"		\$ 34.70
15	1	Rear Boot Lock ✓ 1/8"		\$ 110.90
16	1	Rear Boot Weather Strip ✓ 1/8"		\$ 95.00
17	1	Rear Number Plate Lamp (Complete) ✓ 1/8"		\$ 48.20
18	2	Rear Boot Stopper (LH/RH) ✓ 1/8"	\$ 10.70	\$ 21.40
19	1	Rear Bumper Foam ✓ 1/8"		\$ 95.50
				\$ 3,947.10
				Less 20% \$ (789.42)
				\$ 3,157.68
20	1	Rear Number Plate X INV	NETT	\$ 35.00
21	4	Rear Reverse Sensor ✓ 1/8"	NETT \$ 112.50	\$ 450.00 350
				\$ 3,642.68



# HUA HONG PRIVATE LIMITED

250 Sungei Kadut Street 1 Singapore 729332  
Tel: (65) 6661 9688 Fax: (65) 6661 9699 Email: info@huahong.com.sg

## ACCIDENT INVOLVING SGQ 6586 P & GBF 1805 H ON 29/12/2017 ALONG GAMBAS AVE TOWARDS PIE AT ABOUT 0755 HOURS

Estimate Repair List - Vehicle SGQ 6586 P - Honda Accord

	Balance B/F	\$	3,642.68
To dismantle, cut & weld rear end panel, rear LH/RH tail lamp panel, dismantle & change rear bumper, rear LH/RH tail lamp, rear boot, knocking & pull straight rear tyre floor panel, rear LH/RH fender and all area affected by accident.		\$	1,200.00 1000
To perform wire checking.		\$	20.00 ✓
To dismantle & refit rear reverse sensor.		\$	60.00 30
To dismantle & re-align rear exhaust pipe.		\$	150.00 100
To spray rear bumper, rear boot, rear end panel, rear LH/RH tail lamp panel, rear tyre floor panel and rear LH/RH fender.		\$	1,200.00 1000
		\$	6,272.68
	7% GST	\$	439.09
	Total	\$	6,711.77

5) 2150

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Authorised by Claims Dept.  
Mrs Tan @ 9639 9195



Parts: \$ 3080.44  
S/Note: \$ 350.00  
Labour: \$ 2150.00

5580.44

Lump Sum - 20%

4464.19

4/5 \$ 4450 @ 6 days

## Catherine Chong (LKK Auto)

---

**From:** Elaine Cheong <elaine.cheong@eqinsurance.com.sg>  
**Sent:** Wednesday, 3 January, 2018 11:14 AM  
**To:** 'assignments'  
**Subject:** FW: Accident involving SGQ6586P & GBF1805H on 29/12/2017 along Gambas Ave towards PIE  
**Attachments:** OI - GBF1805H.PDF; TP - SGQ6586P.pdf

Our ref : GBF1805H  
TP ref : SGQ6586P  
Policy No. : DMCPHQ17-004033

Dear All,

Please refer to the email below.

Kindly proceed to survey the third party vehicle.

We enclosed the following documents for your perusal:

- Insured, GBF1805H- GIA report
- PRS request, SGQ6586P - GIA report

Please acknowledge receipt. Thank you.

Regards,

Elaine Cheong  
Senior Executive | Claims



**EQ Insurance Company Limited**

5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110  
did 65 6500 6772 | tel 65 6223 9433 ext 772 | fax 65 6223 4190  
[www.eqinsurance.com.sg](http://www.eqinsurance.com.sg)

 A Member of Citystate



*Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify the sender immediately and delete all copies of*

---

**From:** Yvonne Toh [mailto:yvonne@huahong.com.sg]  
**Sent:** Wednesday, January 03, 2018 11:02 AM  
**To:** Elaine Cheong  
**Cc:** jerleen@huahong.com.sg  
**Subject:** RE: Accident involving SGQ 6586 P & GBF 1805 H on 29/12/2017 along Gambas Ave towards PIE

Dear Elaine

We choose, LKK Auto Consultants Pte Ltd.

Kindly arrange for survey & advise on liability.  
Vehicle at our premise.

Thank you.

Regards

Yvonne Toh

Claims Department



**HUA HONG PRIVATE LIMITED**

25D SUNGEI KADUT STREET 1 SINGAPORE 729332

T. 6661 9688 | F. 6661 9699

E. [yvonne@huahong.com.sg](mailto:yvonne@huahong.com.sg) | W. [www.huahong.com.sg](http://www.huahong.com.sg)

**From:** Elaine Cheong [<mailto:elaine.cheong@eqinsurance.com.sg>]

**Sent:** Wednesday, 3 January 2018 9:32 AM

**To:** Yvonne Toh <[yvonne@huahong.com.sg](mailto:yvonne@huahong.com.sg)>

**Subject:** RE: Accident involving SGQ 6586 P & GBF 1805 H on 29/12/2017 along Gambas Ave towards PIE

**WITHOUT PREJUDICE**

Dear Yvonne,

We refer to your email of 29.12.2017.

We shall be appointing our surveyor to attend to the pre-repair survey of your client's vehicle.

Below is a list of motor surveyors in our panel. Please revert within 2 working days if you agree or have any objections to the appointment of any of the motor surveyors. If we do not hear from you, you are deemed to have agreed to the appointment of any of the motor surveyors listed by us. Alternatively, please specify one or more of our proposed motor surveyors to the said assignment.

<b>1) AJAX Inspection Services Pte Ltd</b> Tel: 6255 0808 Fax: 6849 9155	<b>2) Automobile Inspection Services Pte Ltd</b> Tel: 6286 0155 Fax: 6284 1539 Contact Person: Sophia
<b>3) LBS Automotive Appraisal Pte Ltd</b> <b>L.B.S. Auto Consultants Pte Ltd</b> Tel: 6281 6690 / 62832866 Fax: 6281 8748 Contact Person: Amy/ Grace	<b>4) Priority Services</b> Tel: 62934822 Fax: 62963283 Contact Person: Hui Lian
<b>5) RT Appraisal Pte Ltd</b> Tel: 67486076 Fax: 67480361 Contact Person: Ricky Teng	<b>6) LKK Auto Consultants Pte Ltd</b> Tel: 6256-3561 Fax: 6741-4108

<b>7) Kelvin Automotive Appraising Services</b> Tel: 81825263 Fax: 67461148 Contact Person: Kelvin	<b>8) Automotive Appraiser &amp; Surveying Services</b> Tel: 96623655 Fax: 67655662 Contact Person: Mr Chee
<b>9) JP Knights Pte Ltd</b> Tel: 63450068 Fax: 63445328 Contact Person: Edna Lee	

If you object to all the motor surveyors as proposed by us, please provide a list of at least 10 motor surveyors whom you consider as suitable to appoint for our consideration. We shall revert to you within 2 working days.

Meanwhile, we reserve our rights on Post-Repair Inspection, kindly contact us or our appointed surveyor before you return your client's vehicle to him/her.

Regards,

Elaine Cheong

Senior Executive | Claims



**EQ Insurance Company Limited**

5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110

did 65 6500 6772 | tel 65 6223 9433 ext 772 | fax 65 62234190

[www.eqinsurance.com.sg](http://www.eqinsurance.com.sg)



*Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify the sender immediately and delete all copies of this message.*

**From:** Yvonne Toh [<mailto:yvonne@huahong.com.sg>]

**Sent:** Friday, December 29, 2017 10:45 AM

**To:** Elaine Cheong; Janet Tan; Tan Wei Yin

**Subject:** Accident involving SGQ 6586 P & GBF 1805 H on 29/12/2017 along Gambas Ave towards PIE

Dear Sir/Mdm

Kindly advise liability for this accident case.

Our insured claiming third party. GIA report as per attached.

Should you have any clarification, please contact Mrs Tan at 6661 9695.

Thank you.

Regards

Yvonne Toh

Claims Department



**HUA HONG PRIVATE LIMITED**

25D SUNGEI KADUT STREET 1 SINGAPORE 729332

**T. 6661 9688 | F. 6661 9699**

**E. [yvonne@huahong.com.sg](mailto:yvonne@huahong.com.sg) | W. [www.huahong.com.sg](http://www.huahong.com.sg)**





# HUA HONG PRIVATE LIMITED

25D Sungei Kadut Street | Singapore 729332  
Tel: (65) 6661 9688 Fax: (65) 6661 9699 Email: info@huhong.com.sg

28 June 2018

HHTPClaims17-114F

EQ Insurance Company Ltd  
5 Maxwell Road  
#17-00 Tower Block MND Complex  
Singapore 069110

Attn: Motor Claims Department

## ACCIDENT INVOLVING SGQ 6586 P & GBF 1805 H ON 29/12/2017 ALONG GAMBAS AVE TOWARDS PIE AT ABOUT 0755 HOURS

Insured	:	MAUNG MYA AYE @MUHAMMAD ABBAS
Vehicle Registration No	:	SGQ 6586 P
Vehicle Make	:	HONDA
Vehicle Model	:	ACCORD
Vehicle Chassis No	:	MRHCP2630AP060012
Policy No	:	MT/00264927/02
Date of Accident	:	29/12/2017

Type of Claim: Third Party

Lump sum repair for the damaged portion.

	\$ 4,450.00
7% GST	\$ 311.50
	<u>\$ 4,761.50</u>

Third Party Insurer Enquiry Fee (receipt attached)

\$ 2.00

Loss of rental @ 8 days (receipt attached)

\$ 1,027.20

**Total** \$ 5,790.70



Authorised by Claims Dept

Mrs Tan @ 9639 9195



Auto  
Consultants  
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 67414108

Our Ref: CC4/EQI18000152/Sus3

08 JANUARY 2018

**CO-AL ENGINEERING INTEGRATED SERVICES PTE LTD**  
10 ADMIRALTY ST  
SINGAPORE 757695

Dear Sir/Madam,

**ACCIDENT INVOLVING GBF 1805H AND SGQ 6586P ON 29/12/2017**

We refer to the above accident where we are acting for EQ INSURANCE COMPANY LIMITED to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

Based on the accident report and accident scenario, liability is down against us. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 10 days from the date of this letter.

Please note that your No-Claim Discount (NCD)(if any) will be affected and reduced by 30% (20% for commercial vehicles) upon next renewal due to this Third Party claim. However, if your policy has a NCD protector feature, it will be deemed utilized for this claim and your NCD will be protected.

Please call us if you have further queries.

Yours faithfully,

Siti  
Case Handler  
DID: 6256 3561  
FAX: 6741 4108  
Email: [vicalpeh@lkkauto.com](mailto:vicalpeh@lkkauto.com)

c.c. **EQ INSURANCE COMPANY LIMITED**  
(Motor Claims Dept)

### AUTHORIZATION TO ACT

I, MAUNG MYA AYE @MUHAMMAD ABBAS ("the third party claimant")  
of 93 JALAN SENDUDOK #01-17 S-769471 (address),  
owner of SGR 6586 P (vehicle no.) hereby authorize  
HUA HONG PTE LTD


("the workshop") to act for me with respect to my claim for  
repair costs and/or rental and/or loss of use ("claim") for my  
vehicle no. SGR 6586 P that was damaged pursuant to the  
accident which occurred on 29/12/2017 (date) along Gambas  
Ave towards PIE (location)  
involving vehicle no/s GBF 1805 H  
("the accident").

I further authorize the workshop to settle my above mentioned  
claim in a manner that they deem fit and the workshop is further  
authorized to receive payment further to settlement of my claim  
with payment cheque/s being made in favour of the workshop.

I further acknowledge that any settlement the workshop may reach  
on my behalf is on a without prejudice and without admission of  
liability basis insofar as the driver/owner/insurers of the other  
vehicle/s is concerned.

Dated this 29 day of Dec (month) 20 17 (year)

[Signature]  
Signed by "the third party claimant"

 [Signature]  
Signed by "the workshop"  
(with chop)



## HUA HONG PRIVATE LIMITED

250 Sungei Kadut Street | Singapore 729332  
Tel: (65) 6661 9688 Fax: (65) 6661 9699 Email: info@huahong.com.sg

### TAX INVOICE

28 June 2018

HHTPClaims17-114F

EQ Insurance Company Ltd  
5 Maxwell Road  
#17-00 Tower Block MND Complex  
Singapore 069110

Attn: Motor Claims Department

**ACCIDENT INVOLVING SGQ 6586 P & GBF 1805 H ON 29/12/2017 ALONG GAMBAS AVE  
TOWARDS PIE AT ABOUT 0755 HOURS**

Insured	:	MAUNG MYA AYE @MUHAMMAD ABBAS
Vehicle Registration No	:	SGQ 6586 P
Vehicle Make	:	HONDA
Vehicle Model	:	ACCORD
Vehicle Chassis No	:	MRHCP2630AP060012
Policy No	:	MT/00264927/02
Date of Accident	:	29/12/2017

Type of Claim: Third Party

Lump sum repair for the damaged portion.

	\$	4,450.00
7% GST	\$	311.50
	\$	4,761.50



Authorised by Claims Dept  
Mrs Tan @ 9639 9195



# HUA HONG PRIVATE LIMITED








25D SUNGAI KADUT STREET 1, SINGAPORE 729332  
Tel: (65) 6661 9688 Fax: (65) 6661 9699 Email: info@huahong.com.sg

## VEHICLE RENTAL AGREEMENT

Date: 03.01.2018

V.R.A No.: 2018010003

Vehicle Rental Agreement made between HUA HONG PRIVATE LIMITED (THE OWNER) and THE HIRER/DRIVER, under the terms and conditions as set forth.

HIRER'S DETAILS					
NAME OF HIRER	MAUNG MYA AYE	NRIC No.	S 2572244 B	Gender	MALE
ADDRESS (AS STATED IN NRIC)	93 JALAN SENDUDOK #01-17, 5769472				
EMAIL ADDRESS			CONTACT NUMBER		
DRIVING LICENCE No.	S 2572244 B	DATE OF BIRTH	04.06.1953		
DRIVING EXPERIENCE	34 YEARS	NATIONALITY	SINGAPOREAN	PLACE OF ISSUE	SINGAPORE
VEHICLE DETAILS					
MAKE / MODEL	HYUNDAI AVANTE		VEHICLE REG No.	SLF 6709 B	
LEFT SIDE 			LEGEND: O - DENT X - SCRATCH C - CHIP R - RUST	PETROL 	
RIGHT SIDE 					
DATE OUT	31/12/18	TIME OUT	1630 HRS	HIRER'S SIGNATURE	
DATE IN	11/1/18	TIME IN	1630 HRS	HIRER'S SIGNATURE	
RENTAL DETAILS					
SECURITY DEPOSIT	S\$ NA		INSURANCE EXCESS	Please View Terms & Conditions Clause 27.	
RENTAL CHARGES	S\$ 120 @ PER DAY		NUMBER OF DAY(S) / WEEK(S)	8	
TOTAL	S\$ 960	GST	S\$ 67.20	GRAND TOTAL	S\$ 1027.20
REMARK(S)					



AUTHORISED SIGNATURE

HIRER'S NAME, NRIC & SIGN



RECORDS MANAGEMENT CENTRE

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE  
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580

Phone: +65 6224 0010 Fax: +65 6224 0030

Operating Hours: Monday to Friday 9am to 5pm

GST Registration No: M400017735

**Third Party Insurer Enquiry**

Our Ref No: GR-17-196153

Date of Request: 29/12/2017

Your Ref No: Online Purchase

Hua Hong Pte Ltd  
25D Sungei Kadut Street 1  
Singapore 729332

Dear Sir/Madam,

Enquiry Date 29/12/2017  
Enquiry By Toh Siew Ng  
TP Vehicle No. GBF1805H  
Accident Date 29/12/2017

**Enquiry Result**

TP Vehicle No.	Insurer	Period of Insurance	Insurer Tel. No.
GBF1805H	EQ Insurance Company Ltd	25/07/2017-24/07/2018	6223 9433

Thank You.

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

This is a computer generated document and requires no signature.



RECORDS MANAGEMENT CENTRE

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE  
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580  
 Phone: +65 6224 0010 Fax: +65 6224 0030  
 Operating Hours: Monday to Friday 9am to 5pm  
 GST Registration No: M400017735

**TAX INVOICE**

Our Ref No: GR-17-196153

Date of Request: 29/12/2017

Your Ref No: Online Purchase

Hua Hong Pte Ltd  
 25D Sungei Kadut Street 1  
 Singapore 729332

Dear Sir/Madam,

Enquiry Date 29/12/2017  
 Enquiry By Toh Siew Ng  
 TP Vehicle No. GBF1805H  
 Accident Date 29/12/2017

DESCRIPTION	AMOUNT (S\$)
TP Insurer Enquiry	1.87
GST Amount	0.13
Total Amount Due (GST Inclusive)	2.00

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

[X] GIRO [ ] Cash [ ] Cheque



Auto  
Consultants  
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

To : M/s EQ INSURANCE COMPANY LTD

Date: 15/10/2018

**THIRD PARTY DIRECT SETTLEMENT**

Vehicle No.	GBF 1805H (Insd Veh)	Your Ref. No. : DMCPHQ17-004033
	SGQ 6586P (TP Veh)	Our Ref. No. : CC4/EQI18000152/Sub3q2
Date of Accident	29/12/2017	

Liability	100%	
Final Repair Cost	: \$ 4,761.50	
Loss of Use	: \$	days
Rental (If any)	: \$ 1,027.20	8 days
Others:	: \$ 2.00	
	: \$	
	5,790.70	
Final Settlement Sum	: \$ 5,790.70	
Remarks	:	

<u>Payment Instruction: Payee's Breakdown</u>		
1)	HUA HONG PRIVATE LIMITED	: \$ 5,790.70
		: \$

JOANNE LEE

LKK Auto Consultants Pte Ltd





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
EQ INSURANCE COMPANY LTD			Ref : CC4/EQ18000152/Sub3q2	
5 MAXWELL ROAD #17-00 TOWER BLOCK MND COMPLEXSINGAPORE 069110			Date : 15-10-2018	
			Code : EQI	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	GBF 1805H	Veh. Inspected	SGQ 6586P	
Policy No.	DMCPHQ17-004033	Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From	ELAINE	Assign Date	03/01/2018	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	HONDA ACCORD	c.c	2354	
Engine No.	HIDDEN	Year of Reg.	2010	
Chassis No.	MRHCP2630AP060012	Colour	BLACK	
Odometer	115471	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	FAIR			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	225/45 R18	FALKEN	6 mm	
L/H Front Tyre	225/45 R18	FALKEN	6 mm	
R/H Rear Tyre	225/45 R18	FALKEN	6 mm	
L/H Rear Tyre	225/45 R18	FALKEN	6 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	29/12/2017	Inspection Date	03/01/2018	
Survey held at	HUA HONG PTE LTD 25D SUNGEI KADUT STREET 1 SINGAPORE 729332			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:		<b>6 Working Days</b>		



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGQ 6586P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
1	REAR BUMPER	PUNCTURE	709.40	709.40
10	REAR BUMPER CLIP @\$3.70	NECESSARY	37.00	30.00
2	REAR BUMPER RETAINER (LH/RH) @\$20.00	NECESSARY	40.00	40.00
1	REAR REINFORCEMENT	BENT	185.60	185.60
1	REAR END PANEL	DENTED	327.80	327.80
1	REAR END PANEL TOP GARNISH	DEFORMED	97.70	97.70
2	REAR TAIL LAMP PANEL (LH/RH) @\$89.80	N/S TO REPAIR SEE LABOUR / O/S DEFORMED	179.60	89.80
2	REAR TAIL LAMP (LH/RH) @\$295.80	CRACKED	591.60	591.60
2	REAR REVERSE LAMP (LH/RH) @\$172.20	SCRATCHED	344.40	344.40
1	REAR BOOT	DENTED	878.40	878.40
2	REAR BOOT HINGE (LH/RH)@\$48.60	BENT	97.20	97.20
1	REAR BOOT LOGO (ACCORD)	NECESSARY	19.20	19.20
1	REAR BOOT LOGO (2.4 VTEC)	NECESSARY	33.50	33.50
1	REAR EMBLEM	NECESSARY	34.70	34.70
1	REAR BOOT LOCK	JAMMED	110.90	110.90
1	REAR BOOT WEATHER STRIP	DEFORMED	95.00	95.00
1	REAR NUMBER PLATE LAMP (COMPLETE)	NECESSARY	48.20	48.20
2	REAR BOOT STOPPER (LH/RH) @\$10.70	NECESSARY	21.40	21.40
1	REAR BUMPER FOAM	CRACKED	95.50	95.50
	LESS 20% DISCOUNT		-789.42	-770.06
			3,157.68	3,080.24
<b>SPECIAL NETT ITEMS</b>				
1	REAR NUMBER PLATE (SN)	NOT NECESSARY	35.00	-
4	REAR REVERSE SENSOR @\$112.50 (SN)	DAMAGED	450.00	350.00
			485.00	350.00

Report Ref No. CC4/EQI18000152/Sub3q2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b>LABOUR</b>			
	TO DISMANTLE ,CUT & WELD REAR END PANEL ,REAR LH/RH TAIL LAMP PANEL,DISMANTLE & CHARGE REAR BUMPER ,REAR LH /RH TAIL LAMP ,REAR BOOT ,KNOCKING & PULL STRAIGHT REAR TYRE FLOOR PANEL ,REAR LH/RH FENDER AND ALL AREA AFFECTED BY ACCIDENT INCLUSIVE OF THE REPAIR OF REAR TAIL LAMP PANEL N/S.		1,200.00	1,000.00
	TO PERFORM WIRE CHECKING.		20.00	20.00
	TO DISMANTLE & REFIT REAR REVERSE SENSOR .		60.00	30.00
	TO DISMANTLE & RE-ALIGN REAR EXHAUST PIPE.		150.00	100.00
	TO SPRAY REAR BUMPER,REAR BOOT ,REAR END PANEL,REAR LH/RH TAIL LAMP PANEL,REAR TYRE FLOOR PANEL AND REAR LH/RH FENDER.		1,200.00	1,000.00
			2,630.00	2,150.00
	<b>GRAND TOTAL</b>		<b>6,272.68</b>	<b>5,580.24</b>
	<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>			<b>4,450.00</b>

Report Ref No. CC4/EQ18000152/Sub3q2

YEANG WAI KEEN

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.