

SPECIALISTS MOTOR PTE LTD

Block 3018A, Ubi Road 1, #01-24-26, Singapore 408711

Tel: 67472112 (5 lines) Fax: 67438032

Email: cardoc@singnet.com.sg

Bus. Reg No: 199502604 E GST No: 19-9502604-E

SM/SGH2855L/1801002

02nd January 2018

The Manager
Motor Claim Department
AXA Insurance Pte Ltd
8 Shenton Way,
#27-01 AXA Tower
Singapore 068811

Date of Accident : 31th December 2017
Location : PIE Towards Changi(close Aljunied Flyover)

Third Party Claim Vehicle No : SGJ 9766 D Toyota Wish
Repair Cost For Vehicle No : SGH 2855 L Toyota Corolla

Estimated Supply of Parts & Labours

No.	Particulars	Qty	Price	Amounts
1	Rear boot cover <i>DD/3uc</i>	1	733.50	\$ 733.50 ✓
2	Rear boot cover emblem (1.6) <i>mc</i>	1	32.20	\$ 32.20 ✓
3	Rear boot cover emblem (E) <i>mc</i>	1	38.40	\$ 38.40 ✓
4	Rear boot cover emblem (vvt) <i>mc</i>	1	38.40	\$ 38.40 ✓
5	Rear boot cover emblem (corolla) <i>mc</i>	1	31.50	\$ 31.50 ✓
6	Rear boot cover emblem (altis) <i>mc</i>	1	31.50	\$ 31.50 ✓
7	Rear boot cover lock <i>7w1</i>	1	77.50	\$ 77.50 ✓
8	Rear boot cover catch <i>11</i>	1	31.50	\$ 31.50 X
9	Rear boot cover weather strip <i>70.1</i>	1	157.10	\$ 157.10 ✓
10	Rear end panel <i>13,2500</i>	1	820.40	\$ 820.40 ✓
11	Rear end panel inner garnish <i>7w1</i>	1	66.80	\$ 66.80 ✓
12	Rear end panel inner garnish clips <i>11</i>	1set	38.00	\$ 38.00 X
13	Rear lamp assy L&R	2	272.20	\$ 544.40 ?
14	Rear lamp lower panel L&R <i>11/5000</i>	2	86.50	\$ 173.00 ipc
15	Rear bumper fascia <i>mc</i>	1	384.90	\$ 384.90 ✓
16	Rear bumper clips <i>mc</i>	1set	38.00	\$ 38.00 ✓
17	Rear bumper side retainer L&R <i>2w1</i>	2	16.20	\$ 32.40 ✓
18	Rear bumper bracket L&R	2	48.50	\$ 97.00 ?
19	Rear spare tyre board <i>70.1</i>	1	92.10	\$ 92.10 ✓
				\$ 3,458.60
Less			25%	\$ 864.65
				\$ 2,593.95
20	Rear bumper sensor (s/nett) <i>shut</i>	1set	380.00	\$ 380.00 200
21	Rear number plate (s/nett) <i>11</i>	1set	50.00	\$ 50.00 X
22	Rear end panel (s/nett) <i>mc</i>	1	80.00	\$ 80.00 50
				\$ 3,103.95

*not authorized
date
1/5/18
3/1/18
whenever the sign
is done.*

SPECIALISTS MOTOR PTE LTD

Block 3018A, Ubi Road 1, #01-24-26, Singapore 408711

Tel: 67472112 (5 lines) Fax: 67438032

Email: cardoc@singnet.com.sg

Bus. Reg No: 199502604 E GST No: 19-9502604-E

SM/SGH2855L/1801002

02nd January 2018

Balance b/f	\$ 3,103.95
<u>Labour Charges :-</u>	<u>Amounts</u>
Cut out, renew, knocking & welding rear boot cover, rear end panel, rear boot floor panel, remove & install all damage parts, straighten & re-align body.	\$ 1,080.00 800
Remove & install rear bumper sensor	\$ 80.00 50
Tuff-kote on damage parts	\$ 40.00 ✓
Spray painting on damage parts	\$ 1,280.00 1000
Check lighting after repairs	\$ 35.00 20
Labour Charge	\$ 2,515.00
Total Amount	\$ 5,618.95

GST will be reflected in the final bills.

Notes : -Please inform us within 14 days, from the date of this letter, in the event that the owner/driver is in breach of its policy with your company, failing which we shall hold your company liable for all costs of repairs, loss of use and storage.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: