

## COMFORTDELGRO ENGINEERING PTE LTD

## REPAIR ESTIMATE\*

VEHICLE NO : SHB2362L

MAKE : HYUNDAI

MODEL : SONATA

Date : 02.01.2018

| Qty                  | Parts Description / Labour        | Type | Unit Price | Amount                 |
|----------------------|-----------------------------------|------|------------|------------------------|
| 1                    | Front Windscreen ✓                |      |            | \$ 1,015.00            |
| 1                    | Front Windscreen Molding ✓        |      |            | \$ 60.00               |
| 1                    | Roof Upholstery X                 |      |            | \$ 2,875.00            |
| 1                    | Roof Panel Assy X repair          |      |            | \$ 1,194.90            |
| 1                    | Roof Molding X                    |      |            | \$ 132.30              |
| SUB TOTAL            |                                   |      |            | \$ 5,277.20            |
| LESS 20%             |                                   |      |            | 1,055.44               |
| DISCOUNTED TOTAL     |                                   |      |            | \$ 4,221.76            |
| 1                    | Roof LED SIGN ✓ <i>new</i>        |      |            | \$ 1,200.00 Nett       |
| 1                    | Roof Antennae ✓ <i>one</i>        |      |            | \$ 180.00 Nett         |
|                      |                                   |      |            | \$ 180.00              |
| <b>Labour Charge</b> |                                   |      |            |                        |
| 1                    | Panel Beating                     |      |            | \$ 1,000.00 <i>200</i> |
| 1                    | Spray Painting Charge             |      |            | \$ 400.00 <i>200</i>   |
| 1                    | Wiring Charge                     |      |            | \$ 50.00 <i>20</i>     |
| 1                    | Tuff Kote                         |      |            | \$ 80.00 <i>x</i>      |
| 1                    | Remove/refix Front Windscreen     |      |            | \$ 120.00 <i>100</i>   |
| 1                    | Remove/Refix Cushion & Upholstery |      |            | \$ 120.00 <i>50</i>    |
| 1                    | Remove/refix Roof Top LED SIGN    |      |            | \$ 120.00 <i>100</i>   |
| TOTAL LABOUR         |                                   |      |            | \$ 1,890.00            |
| ESTIMATE TOTAL       |                                   |      |            | \$ 6,291.76            |

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

TOTAL LABOUR

K a / 1000

3/1/18 15:35 hr

3 Aug 20

45

After Repair p/h

Larry Ng

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.