

## CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED PANDAN GARDENS CUSTOMER SERVICE CENTRE



209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

## TAX INVOICE

Co Reg No : 197701469G

GST Reg No : MR-8500111-X

Invoice Name & Address		Owner Name & Vehicle Info
India International Insurance Pte Ltd	Cust No/Name	/Lion City Rentals Pte Ltd
Motor Claims Department	Reg No/Reg Date	SLD9908J / 04/07/2016
64 Cecil Street	Date In/Mileage	18/01/2018/ 127051
#04/05 IOB Building	Chassis/Package	MMBSTA13AHH002003
Singapore 049711	Engine No	3A92UDH5725
Contact No	Make/Model	MIT/17MY ATTRAGE 1.2 CVT
	Colour/Trim	WO5 WHITE PEARL / BK BLACK

E PNT88000 REPLACE DAMAGED PARTS, REPLACE FRONT BUMPER, HOOD, FRONT SUPPORT PANEL REPAIR ALL OTHER AFFECTED AREAS, ADJUST AND ALIGN BODY GAPS ALIGNMENT TO THE SAME E PNT98000 RESPRAY ON BUMPER, HOOD, FRONT SUPPORT PANEL, AND ALL OTHER AFFECTED AREAS TO THE SAME E PNT88000 REMOVE AND REINSTALL RADIATOR AND CONDENSOR TO FACILITATE REPAIR A 97000001 VACUUM & TOP UP A/COND GAS AND CHECK SYSTEM A 54900099 CHECK WIRING AND CHASSIS ELECTRICAL SYSTEM A 10028901 CONDUCT DIAGNOSTIC CHECK USING MUT TESTER AND CLEAR TROUBLE CODE M SUNDRY APPLY ANTI COROSSION ON AFFECTED PORTIONS SUPPLY & REPLACE FRONT LICENSE PLATE WITH PLASTIC FRAME X PANEL ASSY, FR END SUPPLY & REPLACE FRONT LICENSE PLATE WITH PLASTIC FRAME X BRACKET, FR BUMPER, LH 1.00 13.00 00.00 13. BRACKET, FR BUMPER, RH 1.00 13.00 00.00 13. COVER, HEADLAMP SUPT PANEL 1.00 62.00 00.00 62. X MARK, THREE-DIA 1.00 548.00 00.00 548. K GRILLE, RADIATOR X HEADLAMP ASSY, LH 1.00 654.00 00.00 654. X HEADLAMP ASSY, LH 1.00 665.00 00.00 6654. X HEADLAMP ASSY, LH 1.00 668.00 00.00 668. X RATCH, HOOD 1.00 1.00 1.00 1.00 1.00 1.00 1.00 1.0	Account No	Terms	Date/Time Printed	CSE	Operator		WIP No	Invoid	e/Credit Note N
E PNT88000     REPLACE DAMAGED PARTS, REPLACE FRONT BUMPER, HOOD, FRONT SUPPORT PANEL REPAIR ALL OTHER AFFECTED AREAS, ADJUST AND ALIGN BODY GAPS ALIGNMENT TO THE SAME  E PNT98000     RESPRAY ON BUMPER, HOOD, FRONT SUPPORT PANEL, AND ALL OTHER AFFECTED AREAS TO THE SAME  E PNT88000     REMOVE AND REINSTALL RADIATOR AND CONDENSOR TO FACILITATE REPAIR  A 9700001     VACUUM & TOP UP A/COND GAS AND CHECK SYSTEM A 54900099     CHECK WIRING AND CHASSIS ELECTRICAL SYSTEM A 10028901     CONDUCT DIAGNOSTIC CHECK USING MUT TESTER AND CLEAR TROUBLE CODE  M SUNDRY     APPLY ANTI COROSSION ON AFFECTED PORTIONS  SUNDRY SUNDRIES  S SPECIALISTJOB     SUPPLY & REPLACE FRONT LICENSE PLATE WITH PLASTIC FRAME  X PANEL ASSY, FR END     1.00 1045.00 00.00 1045.  X BRACKET, FR BUMPER, LH     1.00 13.00 00.00 13.  X GRILLE, FR UNDER     1.00 163.00 00.00 163.  X GRILLE, FR BUMPER, RH     1.00 163.00 00.00 62.  X FACE, FR BUMPER     1.00 696.00 00.00 696.  X MARK, THREE-DIA     1.00 548.00 00.00 548.  X HEADLAMP ASSY, LH     1.00 654.00 00.00 654.  X HEADLAMP ASSY, LH     1.00 722.00 00.00 722.  X LATCH, HOOD     1.00 684.00 00.00 662.	CTP00040	Cash					19084	41425	796
REPLACE DAMAGED PARTS, REPLACE FRONT BUMPER, HOOD, FRONT SUPPORT PANEL REPAIR ALL OTHER AFFECTED AREAS, ADJUST AND ALIGN BODY GAPS ALIGNMENT TO THE SAME  E PNT98000  RESPRAY ON BUMPER, HOOD, FRONT SUPPORT PANEL, AND ALL OTHER AFFECTED AREAS TO THE SAME  E PNT88000  REMOVE AND REINSTALL RADIATOR AND CONDENSOR TO FACILITATE REPAIR  A 97000001  VACUUM & TOP UP A/COND GAS AND CHECK SYSTEM  A 54900099  CHECK WIRING AND CHASSIS ELECTRICAL SYSTEM  A 10028901  CONDUCT DIAGNOSTIC CHECK USING MUT TESTER AND CLEAR TROUBLE CODE  M SUNDRY APPLY ANTI COROSSION ON AFFECTED PORTIONS  M SUNDRY SUNDRIES  S SPECIALISTJOB  SUPPLY & REPLACE FRONT LICENSE PLATE WITH PLASTIC FRAME  X PANEL ASSY,FR END X BRACKET,FR BUMPER,H  1.00 13.00 00.00 13. X GRILLE,FR UNDER 1.00 163.00 00.00 163. X GRILLE,FR UNDER 1.00 660.00 00.00 62. X FACE,FR BUMPER 1.00 670.00 00.00 1045. COVER,HEADLAMP SUPT PANEL 1.00 1045.00 1045.00 00.00 1045. COVER,HEADLAMP SUPT PANEL 1.00 1045. COVER,HEADLA	A STANSON		Description of Goo	ds / Servic	es	Qty	Unit Price	Disc%	Amount
RESPRAY ON BUMPER, HOOD, FRONT SUPPORT PANEL, AND ALL OTHER	REPLACE D	LL OTHER							1375.00
REMOVE AND REINSTALL RADIATOR AND CONDENSOR TO FACILITATE REPAIR A 97000001 VACUUM & TOP UP A/COND GAS AND CHECK SYSTEM A 54900099 CHECK WIRING AND CHASSIS ELECTRICAL SYSTEM A 10028901 CONDUCT DIAGNOSTIC CHECK USING MUT TESTER AND CLEAR TROUBLE CODE M SUNDRY APPLY ANTI COROSSION ON AFFECTED PORTIONS M SUNDRY SUNDRIES SPECIALISTJOB SUPPLY & REPLACE FRONT LICENSE PLATE WITH PLASTIC FRAME X PANEL ASSY,FR END 1.00 1045.00 10.00 1045. X BRACKET,FR BUMPER,LH 1.00 13.00 00.00 13. X GRILLE,FR UNDER X GRILLE,FR UNDER 1.00 163.00 00.00 163. X COVER,HEADLAMP SUPT PANEL 1.00 62.00 00.00 62. X FACE,FR BUMPER 1.00 650.00 00.00 511. X RARK,THREE-DIA 1.00 51.00 00.00 548. X HEADLAMP ASSY,LH 1.00 654.00 00.00 654. X HOOD 1.00 722.00 00.00 668. CONTRADIATION 1.00 668.00 00.00 668. CONTRADIATION 1.00 668.00 00.00 668. CONTRADIATION 1.00 668.00 00.00 668.	RESPRAY O			PORT PANEL	, AND ALL OTHER				1260.00
VACUUM & TOP UP A/COND GAS AND CHECK SYSTEM A 54900099 CHECK WIRING AND CHASSIS ELECTRICAL SYSTEM A 10028901 CONDUCT DIAGNOSTIC CHECK USING MUT TESTER AND CLEAR TROUBLE CODE M SUNDRY APPLY ANTI COROSSION ON AFFECTED PORTIONS M SUNDRIES S SPECIALISTJOB SUPPLY & REPLACE FRONT LICENSE PLATE WITH PLASTIC FRAME X PANEL ASSY, FR END X BRACKET, FR BUMPER, LH X BRACKET, FR BUMPER, RH 1.00 13.00 00.00 13. X GRILLE, FR UNDER X GRILLE, FR UNDER X COVER, HEADLAMP SUPT PANEL 1.00 163.00 00.00 163. X COVER, HEADLAMP SUPT PANEL 1.00 160.00 160.00 160.00 161.00 160	REMOVE AN		TALL RADIATOR AND C	CONDENSOR	TO FACILITATE REPAIR				120.00
CHECK WIRING AND CHASSIS ELECTRICAL SYSTEM A 10028901 CONDUCT DIAGNOSTIC CHECK USING MUT TESTER AND CLEAR TROUBLE CODE M SUNDRY APPLY ANTI COROSSION ON AFFECTED PORTIONS M SUNDRY SUNDRIES S SPECIALISTJOB SUPPLY & REPLACE FRONT LICENSE PLATE WITH PLASTIC FRAME X PANEL ASSY,FR END X BRACKET,FR BUMPER,LH X BRACKET,FR BUMPER,RH 1.00 13.00 00.00 13. X BRACKET,FR BUMPER,RH 1.00 13.00 00.00 13. X GRILLE,FR UNDER 1.00 62.00 00.00 62. X COVER,HEADLAMP SUPT PANEL 1.00 696.00 00.	VACUUM &	TOP UP A	A/COND GAS AND CHEC	CK SYSTEM					80.00
CONDUCT DIAGNOSTIC CHECK USING MUT TESTER AND CLEAR TROUBLE CODE  M SUNDRY     APPLY ANTI COROSSION ON AFFECTED PORTIONS  M SUNDRY     SUNDRIES  S SPECIALISTJOB     SUPPLY & REPLACE FRONT LICENSE PLATE WITH PLASTIC FRAME  X PANEL ASSY, FR END     1.00 1045.00 00.00 13.  BRACKET, FR BUMPER, LH     1.00 13.00 00.00 13.  X BRACKET, FR BUMPER, RH     1.00 163.00 00.00 163.  X GRILLE, FR UNDER     1.00 62.00 00.00 62.  X COVER, HEADLAMP SUPT PANEL     1.00 696.00 00.00 696.  X MARK, THREE-DIA     1.00 51.00 00.00 51.  X GRILLE, RADIATOR     1.00 548.00 00.00 548.  X HEADLAMP ASSY, LH     1.00 654.00 00.00 654.  X HOOD     1.00 722.00 00.00 722.  X LATCH, HOOD     1.00 68.00 00.00 68.	CHECK WIR	RING AND	CHASSIS ELECTRICAL	SYSTEM					30.00
APPLY ANTI COROSSION ON AFFECTED PORTIONS  M SUNDRY SUNDRIES  S SPECIALISTJOB SUPPLY & REPLACE FRONT LICENSE PLATE WITH PLASTIC FRAME  X PANEL ASSY,FR END X BRACKET,FR BUMPER,LH X BRACKET,FR BUMPER,RH X GRILLE,FR UNDER X GRILLE,FR UNDER X COVER,HEADLAMP SUPT PANEL X COVER,HEADLAMP SUPT PANEL X GRILLE,RADIATOR X GRILLE,RADIATOR X GRILLE,RADIATOR X GRILLE,RADIATOR X GRILLE,RADIATOR X HEADLAMP ASSY,LH X HOOD X LATCH,HOOD X LATCH,HOOD X LATCH,HOOD X LATCH,HOOD X CONTROL OF THE MITH PLASTIC FRAME  1.00 1045.00	CONDUCT D	IAGNOSTI	C CHECK USING MUT	TESTER AND	CLEAR TROUBLE CODE				200.00
SUNDRIES  S SPECIALISTJOB SUPPLY & REPLACE FRONT LICENSE PLATE WITH PLASTIC FRAME  X PANEL ASSY,FR END X BRACKET,FR BUMPER,LH X BRACKET,FR BUMPER,RH X GRILLE,FR UNDER X COVER,HEADLAMP SUPT PANEL X FACE,FR BUMPER X GRILLE,RADIATOR X GRILLE,RADIATOR X GRILLE,RADIATOR X HEADLAMP ASSY,LH X HOOD X LATCH,HOOD X LATCH,HOOD X CONVENTED ASSYLE ASSYLE ASSYLE ASSOCIATION OF SERVICE ASSOCIATION OF SERV		I COROSS	SION ON AFFECTED PO	RTIONS					60.00
SUPPLY & REPLACE FRONT LICENSE PLATE WITH PLASTIC FRAME         X PANEL ASSY,FR END       1.00       1045.00       00.00       1045.         X BRACKET,FR BUMPER,LH       1.00       13.00       00.00       13.         X BRACKET,FR BUMPER,RH       1.00       13.00       00.00       163.         X COVER,HEADLAMP SUPT PANEL       1.00       62.00       00.00       62.         X FACE,FR BUMPER       1.00       696.00       00.00       696.         X MARK,THREE-DIA       1.00       51.00       00.00       548.         X GRILLE,RADIATOR       1.00       548.00       00.00       548.         X HEADLAMP ASSY,LH       1.00       654.00       00.00       654.         X HOOD       1.00       722.00       00.00       68.		;							20.00
X PANEL ASSY,FR END       1.00       1045.00       00.00       1045.         X BRACKET,FR BUMPER,LH       1.00       13.00       00.00       13.         X BRACKET,FR BUMPER,RH       1.00       13.00       00.00       13.         X GRILLE,FR UNDER       1.00       163.00       00.00       62.         X COVER,HEADLAMP SUPT PANEL       1.00       62.00       00.00       62.         X FACE,FR BUMPER       1.00       696.00       00.00       696.         X MARK,THREE-DIA       1.00       51.00       00.00       51.         X GRILLE,RADIATOR       1.00       548.00       00.00       548.         X HEADLAMP ASSY,LH       1.00       654.00       00.00       654.         X HOOD       1.00       722.00       00.00       68.			FRONT LICENSE PLAT	E WITH PLA	STIC FRAME				50.00
X       BRACKET,FR BUMPER,LH       1.00       13.00       00.00       13.         X       BRACKET,FR BUMPER,RH       1.00       13.00       00.00       13.         X       GRILLE,FR UNDER       1.00       163.00       00.00       163.         X       COVER,HEADLAMP SUPT PANEL       1.00       62.00       00.00       62.         X       FACE,FR BUMPER       1.00       696.00       00.00       696.         X       MARK,THREE-DIA       1.00       51.00       00.00       51.         X       GRILLE,RADIATOR       1.00       548.00       00.00       548.         X       HEADLAMP ASSY,LH       1.00       654.00       00.00       654.         X       HOOD       1.00       722.00       00.00       68.         X       LATCH,HOOD       1.00       68.00       00.00       68.						1.00	1045.00	00.00	1045.00
X       BRACKET,FR BUMPER,RH       1.00       13.00       00.00       13.         X       GRILLE,FR UNDER       1.00       163.00       00.00       163.         X       COVER,HEADLAMP SUPT PANEL       1.00       62.00       00.00       62.         X       FACE,FR BUMPER       1.00       696.00       00.00       696.         X       MARK,THREE-DIA       1.00       51.00       00.00       51.         X       GRILLE,RADIATOR       1.00       548.00       00.00       548.         X       HEADLAMP ASSY,LH       1.00       654.00       00.00       654.         X       HOOD       1.00       722.00       00.00       68.         X       LATCH,HOOD       1.00       68.00       00.00       68.						1.00	13.00	00.00	13.00
X COVER, HEADLAMP SUPT PANEL  X FACE, FR BUMPER  X MARK, THREE-DIA  X GRILLE, RADIATOR  X HEADLAMP ASSY, LH  X HEADLAMP ASSY, LH  X HOOD  X LATCH, HOOD  X LATCH, HOOD  X COVER, HEADLAMP SUPT PANEL  1.00 62.00 00.00 62. 62. 62. 62. 62. 62. 63. 62. 62. 62. 63. 62. 63. 62. 63. 62. 63. 63. 63. 64. 65. 66. 67. 68. 69. 69. 69. 69. 69. 69. 69. 69. 69. 69			,RH			1.00	13.00	00.00	13.00
X FACE,FR BUMPER  1.00 696.00 00.00 696.  X MARK,THREE-DIA  1.00 51.00 00.00 51.  X GRILLE,RADIATOR  1.00 548.00 00.00 548.  X HEADLAMP ASSY,LH  1.00 654.00 00.00 654.  X HOOD  X LATCH,HOOD  X LATCH,HOOD  1.00 68.00 00.00 68.						1.00	163.00	00.00	163.00
X MARK, THREE-DIA 1.00 51.00 00.00 51. X GRILLE, RADIATOR 1.00 548.00 00.00 548. X HEADLAMP ASSY, LH 1.00 654.00 00.00 654. X HOOD 1.00 722.00 00.00 722. X LATCH, HOOD 1.00 68.00 00.00 68.	경기 : : : : : : : : : : : : : : : : : : :		PT PANEL				62.00	00.00	62.00
X GRILLE,RADIATOR 1.00 548.00 00.00 548. X HEADLAMP ASSY,LH 1.00 654.00 00.00 654. X HOOD 1.00 722.00 00.00 722. X LATCH,HOOD 1.00 68.00 00.00 68.						1.00	696.00	00.00	696.00
X HEADLAMP ASSY,LH 1.00 654.00 00.00 654. X HOOD 1.00 722.00 00.00 722. X LATCH,HOOD 1.00 68.00 00.00 68.	(1987)					1.00	51.00	00.00	51.00
X HOOD 1.00 722.00 00.00 722. X LATCH, HOOD 1.00 68.00 00.00 68.						1.00	548.00	00.00	548.00
X LATCH, HOOD 1.00 68.00 00.00 68.		ASSY,LH					654.00	00.00	654.00
V CONDENSED ACCV A /O DEEDTOE		_							722.00
X CONDENSER ASSY, A/C REFRIGE 1.00 715.00 00.00 715.									68.00
	x condenser	ASSY,A/	C REFRIGE			1.00	715.00	00.00	715.00



## CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED PANDAN GARDENS CUSTOMER SERVICE CENTRE



209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

## **TAX INVOICE**

Co Reg No : 197701469G

GST Reg No : MR-8500111-X

Invoice Name & Address		Owner Name & Vehicle Info		
India International Insurance Pte Ltd	Cust No/Name	/Lion City Rentals Pte Ltd		
Motor Claims Department	Reg No/Reg Date SLD9908J / 04/07/2016			
64 Cecil Street	Date In/Mileage	18/01/2018/ 127051		
#04/05 IOB Building MSG	Chassis/Package	MMBSTA13AHH002003		
Singapore 049711	Engine No	3A92UDH5725		
Contact No	Make/Model	MIT/17MY ATTRAGE 1.2 CVT		
	Colour/Trim	WO5 WHITE PEARL / BK BLACK		

Account No	Terms	Date/Time Print	ted	CSE	Operator		WIP No	Invoice	/Credit Note No
CTP00040	Cash	14/12/2018/ 09	9:24	TLT	260 / AiTing		19084	414257	96
		Description of	Goods /	Services		Qty	Unit Price		Amount
X PANEL, HEAZ Z TEXT TP CLAIM DOA: 29 SURVEYOR	INDIA SH 9.12.17					1.00	65.00	00.00	65.00
	æl.								
	"G	uarantee your i	warranty	, maintai	n with Cycle & (	Carriage."			
Parts Labour Standard M Specialist Diagnostic Sundry/Oth	Job s Job ers		4,815.00 3,065.00 0.00 50.00 0.00 80.00			7% GST on	Net 8010.0 tal Payabl Pai Total Du	0 e d	8,010.00 560.70 8,570.70 0.00 8,570.70