



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED

PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

MITSUBISHI
MOTORS

ESTIMATE

Co Reg No : 197701469G

GST Reg No : MR-8500111-X

| Invoice Name & Address | Owner Name & Vehicle Info |
|-----------------------------|---|
| Lion City Rentals Pte Ltd | Cust No/Name KL000023/Lion City Rentals Pte Ltd |
| 60 Anson Road | Reg No/Reg Date SLD9908J / 04/07/201 |
| #11-01 Mapletree Anson | Date In/Mileage / 0 |
| Singapore 079914 | Chassis No MMBSTA13AHH002003 |
| Contact No Mobile: 67420984 | Engine No 3A92UDH5725 |
| | Make/Model MIT/17MY ATTRAGE 1.2 CVT |
| | Colour/Trim W05 WHITE PEARL / BK BLACK |

| Account No | Terms | Date/Time Printed | CSE | Operator | WIP No | | |
|---|---------------------------|-------------------|-------|-------------------|------------|-------|--------------|
| CSM00041 | Cash | 02/01/2018/ 19:23 | | 465 / Tay Jian Ye | 19084 | | |
| Description of Goods / Services | | | | Qty | Unit Price | Disc% | Amount |
| E PNT88000 | | | | | | | 1375 2200.00 |
| TO RENEW FRT BUMPER,HOOD,WELD AND CUT FRT SUPPORT PANEL | | | | | | | 1260 1680.00 |
| E PNT98000 | | | | | | | 120? 200.00 |
| PAINT WORK SPRAY FRT BUMPER, HOOD, FRT SUPPORT PANEL | | | | | | | 80? 200.00 |
| E PNT88000 | | | | | | | 30 50.00 |
| TO REMOVE AND REFIT RADIATOR AND CONDENSOR | | | | | | | ✓ 200.00 |
| A 97000001 | | | | | | | 60. 80.00 |
| TO TOP UP AIR CON GAS AND CHECK SYSTEM | | | | | | | m.s/ 50.00 |
| A 54900099 | | | | | | | 20. 50.00 |
| CHECK WIRING AND CHASSIS ELECTRICAL SYSTEM | | | | | | | ? 1045.00 |
| A 10028901 | | | | | | | na 13.00 |
| TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST | | | | | | | na 13.00 |
| USING HI-SCAN PRO TEST | | | | | | | de 163.00 |
| M SUNDRY | | | | | | | con 62.00 |
| TO APPLY ANTI COROSSION ON AFFECTED PORTION | | | | | | | de 696.00 |
| M SUNDRY | | | | | | | de 30.00 |
| TO SUPPLY FRT NUMBER PLATE AND FRAME | | | | | | | de 49.00 |
| M SUNDRY | | | | | | | con 548.00 |
| SUNDRIES | | | | | | | de 654.00 |
| M | PANEL ASSY,FR END | | 1.00 | 1045.00 | 00.00 | | ? 654.00 |
| M | BRACKET,FR BUMPER,LH | | 1.00 | 13.00 | 00.00 | | b6 722.00 |
| M | BRACKET,FR BUMPER,RH | | 1.00 | 13.00 | 00.00 | | b6 68.00 |
| M | GRILLE,FR UNDER | | 1.00 | 163.00 | 00.00 | | ? 52.00 |
| M | COVER,HEADLAMP SUPT PANEL | | 1.00 | 62.00 | 00.00 | | |
| M | FACE,FR BUMPER | | 1.00 | 696.00 | 00.00 | | |
| P | CLIP,FR BUMPER | | 10.00 | 3.00 | 00.00 | | |
| M | MARK,THREE-DIA | | 1.00 | 49.00 | 00.00 | | |
| M | GRILLE,RADIATOR | | 1.00 | 548.00 | 00.00 | | |
| M | HEADLAMP ASSY,LH | | 1.00 | 654.00 | 00.00 | | |
| M | HEADLAMP ASSY,RH | | 1.00 | 654.00 | 00.00 | | |
| M | HOOD | | 1.00 | 722.00 | 00.00 | | |
| M | LATCH,HOOD | | 1.00 | 68.00 | 00.00 | | |
| M | HINGE,HOOD,LH | | 1.00 | 52.00 | 00.00 | | |

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

MITSUBISHI
MOTORS**ESTIMATE**

Co Reg No : 197701469G

GST Reg No : MR-8500111-X

| Invoice Name & Address | Owner Name & Vehicle Info |
|---|--|
| Lion City Rentals Pte Ltd 60 Anson Road #11-01 Mapletree Anson Singapore 079914 Contact No Mobile: 67420984 | Cust No/Name KL000023/Lion City Rentals Pte Ltd Reg No/Reg Date SLD9908J / 04/07/201 Date In/Mileage / 0 Chassis No MMBSTA13AHH002003 Engine No 3A92UDH5725 Make/Model MIT/17MY ATTRAGE 1.2 CVT Colour/Trim W05 WHITE PEARL / BK BLACK |

| Account No | Terms | Date/Time Printed | CSE | Operator | WIP No |
|------------|-------|-------------------|-----|-------------------|--------|
| CSM00041 | Cash | 02/01/2018/ 19:23 | | 465 / Tay Jian Ye | 19084 |

| Description of Goods / Services | Qty | Unit Price | Disc% | Amount |
|---------------------------------|------|------------|-------|--------|
| M HINGE, HOOD, RH | 1.00 | 52.00 | 00.00 | 52.00 |
| M CONDENSER ASSY, A/C REFRIGE | 1.00 | 715.00 | 00.00 | 715.00 |

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SURVEYOR NAME:

Tay Jian Ye 97445749

SURVEYOR SIGNATURE:

DATE:

3/1/17 E Spr - WP

REMARKS:

Resurvey before paint
6 days.
sur@lkkauto.com

Confirm & accepted by

| | | |
|----------------------|----------|------------------|
| | Nett | 10,246.00 |
| 7% GST on | 10246.00 | 717.22 |
| Total Payable | | 10,963.22 |

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.