

MG SOLUTION PTE LTD

23 Kaki Bukit Avenue 4 (South Wing) #02-03 Singapore 415933

Tel: (+65) 6243 1373 | Fax: (+65) 6243 1376

Reg. No: 201427944N

India
Insurance

TO	: INDIA INTERNATIONAL INSURANCE	DATE	: 26-Dec-17
ATTENTION	: MOTOR CLAIMS DEPT	JOB TYPE	: T/P CLAIM
ESTIMATE REPORT	:		
<u>VEHICLE DETAILS</u>			
VEHICLE NO	: SKT8779Z		
MODEL	: HONDA VEZEL 1.5X CVT		
CHASSIS NO	:		
<u>ACCIDENT DETAILS</u>		DATE	: 23-Dec-17
		TIME	: 16:50PM
THIRD PARTY REQUESTOR / CONTACT : MS HONG / SHARON			

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT COST PRICE	UNIT COST PRICE
1	FRONT BUMPER ✓ SCR / DD	1	\$ 1,085.00	\$ 1,085.00
2	FRONT BUMPER SIDE RETAINER RH ✓ NEC	1	\$ 58.00	\$ 58.00
3	FRONT BUMPER REINFORCEMENT ?	1	\$ 390.00	\$ 390.00
4	FRONT BUMPER TOWING COVER ✓ DIS	1	\$ 89.00	\$ 89.00
5	FRONT BUMPER FOG LAMP RH ✓ CRA	1	\$ 355.80	\$ 355.80
6	FRONT BUMPER FOG LAMP GARNISH RH ?	1	\$ 135.00	\$ 135.00
7	FRONT BUMPER LOWER GRILLE ✓ WP / DIS	1	\$ 222.50	\$ 222.50
8	FRONT BUMPER LOWER LID ✓ SCR / DD	1	\$ 433.80	\$ 433.80
9	FRONT GRILLE ✓ CRA	1	\$ 588.20	\$ 588.20
10	FRONT LOGO GARNISH ?	1	\$ 378.20	\$ 378.20
11	HID HEADLAMP RH ?	1	\$ 1,802.00	\$ 1,802.00
12	HEADLAMP LOWER BRACKET RH ?	1	\$ 74.00	\$ 74.00
13	WHEEL ARCH RH ?	1	\$ 255.80	\$ 255.80
14	FRONT SUPPORT PANEL X	1	\$ 655.20	\$ 655.20
15	FRONT REVERSE SENSOR ✓ SCR	1/2	\$ 212.80	\$ 425.60

TOTAL PRICE \$6,948.10

ADD 20% \$ 1,389.62

SUB TOTAL PRICE \$8,337.72

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	FRONT NUMBER PLATE ✓ DD	1	\$ 50.00	\$ 50.00

2	FRONT BUMPER CLIPS(SET) ✓ N.E.C	1	\$ 20.00	\$ 20.00
3	FRONT BUMPER GRILLE CLIPS(SET) ✓ N.E.C	1	\$ 20.00	\$ 20.00
4	FRONT LOGO GARNISH CLIPS(SET) 2	1	\$ 20.00	\$ 20.00
5	HEADLAMP CLIPS(SET) 2	1	\$ 20.00	\$ 20.00
6	WHEEL ARCH CLIP(SET) 2	1	\$ 22.00	\$ 22.00

TOTAL \$152.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (FRONT)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST	APPROVED
1	TO PANEL BEAT, REMOVE AND REPLACE PARTS	\$ 1,200.00	200	
2	TO SPRAY PAINT AFFECTED AREA	\$ 1,200.00	250	
3	MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 180.00	X	
4	WIRING CHECK	\$ 150.00	X	
5	TO REFOCUS HEADLAMP BEAM	\$ 100.00	X	
6	TO REMOVE AND REFIX FRONT REVERSE SENSOR	\$ 200.00	30	

TOTAL \$3,030.00

ESTIMATE REPORT

TOTAL PARTS COST : \$8,489.72
TOTAL LABOUR COST : \$3,030.00
TOTAL REPAIR COST : \$11,519.72

APPROVED DETAILS

EXCESS :
NO. OF WORKING DAYS :
RE-SURVEY :
PART BY PART OR LUMP SUM :
DATE & TIME OF SURVEY :
SURVEYED BY :
CONTACT NUMBER :
FAX NUMBER :

LKK Auto Consultants hence notify the Repairer of the following:

- ✓ To resurvey before/after spray painting
- ✓ To display damaged part(s) during resurvey
- ✓ Parts prices are subject to confirmation
- ✓ Third party survey is on a "Without Prejudice" basis
- ✓ No illegal modification(s) is allowed
- ✓ Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Without Prejudice
Part Price Subject to Confirmation
Resurvey After Paint
2 Days Repair
Wilson, LKK
27/12/2017
Lump Sum