

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHC5697X - AIG**AAD1712-303**

Not Authorised
11/12/17
Resony Ate Rina

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHC5697X - JHOW

VF1ABL15AUC280292

RENAULT

LATITUDE

28.12.2017

AIG**PART****LIST**

1	1	BUMPER COVER REAR	\$	R 1,108.46
2	1	BUMPER LOWER REAR	\$	S 768.84
3	1	BUMPER BRACKET CTR REAR	\$	S 113.47
4	1	BUMEPR BRACKET SIDE RH REAR	\$	S 135.97
5	1	BUMEPR RETAINER RH REAR	\$	S 44.99
6	1	BUMPER REFLECTOR RH	\$	S 43.61
7	1	BUMEPR BRACKET SIDE LH REAR	\$	S 135.97
8	1	BUMEPR RETAINER LH REAR	\$	S 44.99
9	1	BUMPER REFLECTOR LH	\$	S 43.61
10	1	BUMPER BEAM REAR	\$	R 777.52
11	1	BUMPER BEAM BRACKET LH REAR	\$	R 225.95
12	1	BUMPER BEAM BRACKET RH REAR	\$	R 225.95
13	1	BOOT REAR	\$	R 2,872.68
14	1	BOOT FINISHER	\$	S 470.06
15	1	BOOT WHEATERSTRIP	\$	S 323.05
16	1	BOOT REFLECTOR LAMP LH	\$	S 493.35
17	1	BOOT REFLECTOR LAMP RH	\$	S 493.35
18	1	BOOT BADGE 'RENAULT'	\$	nn 225.36
19	1	BOOT BADGE	\$	nn 225.36
20	1	BOOT STRUT LH	\$	S 276.08
21	1	BOOT STRUT RH	\$	S 276.08
22	1	BOOT HINGE LH	\$	R 367.84
23	1	BOOT HINGE RH	\$	R 367.84
24	1	BOOT INNER TRIM	\$	S 586.45
25	1	BOOT SWITCH	\$	S 168.13
26	1	BOOT LOCK	\$	R 202.67
27	1	BOOT LOCK CATCH	\$	R 74.40
28	2	LICENCE PLATE LAMP	\$	S 50.52
29	2	BOOT RUBBER PLUG	\$	S 221.81
30	1	FENDER PANEL REAR LH	\$	R 3,299.13
31	1	WHEELARCH REAR LH	\$	S 543.47
32	1	FENDER PANEL REAR RH	\$	R 3,299.13
33	1	WHEELARCH REAR RH	\$	S 543.47
34	1	TAILLAMP RH	\$	S 552.55

X

TRANS-CAB AUTO SERVICES PTE LTD
 NO.2 ANG MO KIO ST63 SINGAPORE 569111
 TEL NO. 6287 6666 FAX NO. 6257 1330
 CO/GST REG NO. 201019626G
SHC5697X - AIG

AAD1712-303

35	1	TAILLAMP PANEL RH	\$	R	986.70
36	1	TAILLAMP LH	\$	Sn	552.55
37	1	TAILLAMP PANEL LH	\$	R	986.70
38	1	OUTER PANEL REAR (End Panel)	\$	R	1,471.77
39	1	OUTER PANEL REAR (End Panel)TRIM	\$	Sn	404.56
40	1	EXHAUST REAR	\$	R	7,489.05
41	1	EXHAUST CAP REAR	\$	R	230.49

TOTAL	\$	31,723.96
10%	\$	3,172.40
	\$	28,551.56

Specical Nett

1	1SET	PARKING AID	\$	Sn	700.00
2	1SET	REAR BUMPER CLIP	\$	nn	66.00
3	1SET	BUMPER BRACKET CTR CLIP	\$	nn	33.00
4	1SET	BUMEPR BRACKET SIDE CLIP RH RR	\$	nn	10.00
5	1SET	BUMEPR RETAINER RH CLIP RR	\$	nn	20.00
6	1SET	BUMEPR BRACKET SIDE CLIP LH RR	\$	nn	10.00
7	1SET	BUMEPR RETAINER CLIP LH RR	\$	nn	20.00
8	1SET	BUMPER LOWER REAR RIVET	\$	Sn	22.00
9	1SET	BUMPER LOWER REAR CLIP	\$	nn	66.00
10	1	EXHAUST MOUNTING REAR	\$	Sn	17.82
11	1SET	BOOT FINISHER CLIP	\$	nn	24.20
12	1	BOOT STICKER "Trans-cab"	\$	nn	30.00
13	1	BOOT STICKER "6555-3333"	\$	nn	30.00
14	1	BOOT INNER TRIM CLIP	\$	nn	45.00
15	1SET	FENDER WHEELARCH REAR RH CLIP	\$	nn	35.00
16	1SET	FENDER WHEELARCH REAR LH CLIP	\$	nn	35.00
17	1	TAILLAMP CLIP RH	\$	nn	5.00
18	1	TAILLAMP CLIP LH	\$	nn	5.00
19	2	REAR WINDSCREEN SELANT	\$	nn	80.00
20	1	WINDSCREEN MOULDING	\$	Sn	100.00
21	1	REAR WINDSCREEN INNER SPONGE SEAL	\$	nn	100.00
22	1	SPARE TYRE RIM (ROUE 7J 16H 2547)	\$	Sn	385.00
23	1	SPARE TYRE	\$	Sn	330.00

TOTAL	\$	2,169.02
TOTAL PARTS	\$	30,720.58

Putty And Spray Painting Of The Affected
 Portion.

\$

3,000.00

22d

TRANS-CAB AUTO SERVICES PTE LTD

AAD1712-303

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHC5697X - AIG

Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	nn 2,800.00	X
To Rust-Proofing Of The Affected Areas.	\$	nn 170.00	X
To reinstall rear bumper parking sensor.	\$	nn 170.00	X
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	nn 170.00	X
To repair and realign rear exhaust pipe.	\$	nn 170.00	X
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	nn 170.00	X
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	nn 170.00	X
To transfer of rear fender fittings, attachment and perform water seepage test.	\$	nn 380.00	X
Towing Fees	\$	nn 120.00	X
To transfer of rear windscreen fittings and conduct water seepage test.	\$	nn 170.00	X
To check steering geometry and computer wheel alignment	\$	nn 220.00	X

TOTAL \$ 7,710.00**Over All Total \$ 38,430.58****(PARTS BY PARTS)****Repair Days****10 Days***1 day*

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: