

ASS. REC. BY:

REF: CS/FCL18000167/Kvbn2 Special Instruction:

Surveyor: Kenneth ASSIGNMENT (Office)

From (Person): Airik of FCL Date/Time: 03012018 4:47pm

Estimated Cost: Bill to:

OD/TP/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: 9B 9778A Insured: SHA 90955

at Workshop m/s Truns Cab Tel: 6287 6666

of No. 2 AMK 04 63

Policy No: Claim No: SHA 90955 (Don: 11/1/2018)

Sum Insured: Excess: 11/1/18 @ 430pm Swee Keong

Make of Veh: (Client's Record) D.O.A. 01-01-2018

CA / REV / REP. / REV 24 HRS 'wp' 04-01-2018 H.O.D. Endorsement:

Date/Time: 03012018 4:57pm Person Contacted: Candy Vehicle: IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SHB 9778A - CS/UOT16010450/Kvbn2 DOA: 31072016
	SHA 90955 - CS/FCL180016356/Kvbnk3 DOA: 230814
4/1/18	LS \$ 11,150 (Red 34, 397.07, 7610)
5/1/18	Email preli revised to FCI

REF: FCL

ASSIGNMENT

From: \_\_\_\_\_ Date: 04/01/2018

Estimated Cost: \_\_\_\_\_

OD  / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SHB 9778A

at Workshop m/s Trums Cob

of no. 2 AMK St 63

Insured \_\_\_\_\_

Policy No: \_\_\_\_\_

Claims No: \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

Veh No: SHB 9778A Yr Reg: 07 13

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi /  Prime Mover / Truck / Trailer or \_\_\_\_\_

Make Pearce <sup>A)</sup> Latitude cc 1995

Colour M. White 1Rd A/C: Insured / Std / NI / NA

Sp. Reading 552644 T-Radio: Insured / Std / NI / NA

Eng No: \_\_\_\_\_

C/No: V11ABL15AUC 273116

Gen. Cond:  Good / Fair / Poor / Burnt

Steering: In  order / Jammed / Leaked / Burnt or \_\_\_\_\_

Brake: In  order / Jammed / Leaked / Burnt or \_\_\_\_\_

Mod:  Nil / S/Rim / STD A/Rim or \_\_\_\_\_

Tyre Size F: 215/60R16

R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or 6. by 6. by

Front	Rear
R/Bal. <u>6</u> mm	R/Bal. <u>8</u> mm
L/Bal. <u>6</u> mm	L/Bal. <u>8</u> mm
D.O.A. <u>1/1/18</u>	D.O.I. <u>4/1/18</u>

Survey held at: \_\_\_\_\_

Des. of Damages: Frt /  Rear / O/S / N/S / U/C / Rooftop or \_\_\_\_\_

The U/C / Chassis frame / Body Structure affected due to collision



(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent?: Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent?: Yes or No

Est. Repairs: 17 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Date / Time Action / Instruction

5/1 File pass to Corbina

RECEIVED 12 JAN 2018

Date/Time File Pass to?  : Preli. Report

: Final Report

Date/Time File Return to? 12/1- typist

Report Format: TP

Lump Sum / I.B.I: 11, 150/2

Days Of Repair: 12

Resurvey No. of Trip: -

Add Fee:  Site Insp \$  Interview \$  Tech Insp \$  Nearend \$

Survey Fee: \_\_\_\_\_

Transportation: \_\_\_\_\_

Photo: 580

Other: OSP

15/1/18

36x15: 540
190+540
50
26
786

## Survey Department Check List (Case Handler)

Reference No. : CS | FCI 18000167 | Kvb  
 Policy Type: OD / TP / TP RES / TL / EVA

Case Handler

Typist

**Admin (** \_\_\_\_\_ **)**: Case handler to make sure all Information created by the assignment team are **ACCURATE**.

**(1) Office Assign Form**

		Y-Date	N-Date	Y-Date	N-Date
C	Reference No.	✓			
C	Customer Code				
N	Assign From				
C	Assign Date	✓			
C	Veh No (Inspected)	✓			
C	Veh No (Insured)	✓			
C	D.O.A	✓			
C	Policy No				
C	Claim No				
C	Insurance Authorisation (CA /REV/REP)				
C	Report Type	✓			
C	Weekend Charges				
N	Survey held at/Repairer	✓			
C	Excess				

**Surveyor (** \_\_\_\_\_ **)**: Case handler to make sure the surveyor completed all required information.

**(1) Assignment Form**

C	Vehicle No	✓			
C	Regn Month/Year	✓			
N	Vehicle Type	✓			
N	Make & Model	✓			
C	Engine Capacity. (C.C)	✓			
N	Colour	✓			
C	Odometer. (Sp.Reading)	✓			
C	Chassis No	✓			
N	General Condition	✓			
N	Steering	✓			
N	Brake	✓			
N	Modification (Modi)	✓			
C	Tyre Size	✓			
N	Tyre Make	✓			
C	Tyre Balance	✓			
C	Date of Inspection	✓			
N	Survey held	✓			
N	Des.of Damages	✓			

**(2) System - (Views/Merimen)**

C	Damaged Vehicle Photographs Uploaded	✓			
---	--------------------------------------	---	--	--	--

**(3) Workshop Estimate/Assignment Form**

N	ALL Parts condition	✓			
C	Market Value for OD cases				
C	Estimate Repair Cost for PRI (RSI, TMI, MSIG)				
C	Days of repair	✓			
C	Finalised Amount				
C	Re-inspection Cases to Finalize within 5 Days				

**(4) System - (Views/Merimen)**

C	Resurvey photo Uploaded				
---	-------------------------	--	--	--	--

Check By: Veron 5/1/18  
Case Handler Date



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI18000167/Kvb

36 ROBINSON ROAD  
#16-01 CITY HOUSESINGAPORE 068877

Date : 03-01-2018



Code : FCI2

## 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHA 9095S	Veh. Inspected	SHB 9778A
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From	AINI	Assign Date	03/01/2018

## 2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

## 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

## 4. Description of Damages

--

## 5. General Information

Accident Date	01/01/2018	Inspection Date	04/01/2018
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111		

## 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

MOTOR SURVEY ASSIGNMENT

Date 3.1.18

Our Ref No. SHA 90955

Accident Date 1.1.18

Claim Type THIRD PARTY

Insured Vehicle SHA90955

Third Party Vehicle SHB9778A

Survey Location TRANS CAB AUTO  
No. 2 ANA MO KIO ST 63  
S(569111)

Contact Person CANDY KONG

Contact No. 62876666

Fax No. 62571330

Survey Type Without Prejudice.

Appointed Surveyor LKK AUTO CONSULTANTS PTE LTD

Contact Person

Fax No. 68416315

Contact Number 62563561

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

Encl. Accident Reports & est

Cc : Workshop TRANS-CAB AUTO

Attention CANDY KONG

Officer In charge YIN MIN AUNG

IMPORTANT NOTE

Kindly submit the survey report by email only to [surveyor@first-insurance.com.sg](mailto:surveyor@first-insurance.com.sg) within 14 days for survey assignment and 7 days for re-inspection.

This is a computer generated letter, no signature required.

## Catherine Chong (LKK Auto)

---

**From:** Aini Binte Md Min <aini@first-insurance.com.sg>  
**Sent:** Wednesday, 3 January, 2018 4:47 PM  
**To:** 'assignments@lkkauto.com'  
**Cc:** 'candy.kong@transcab.com.sg'  
**Subject:** NEW ASSIGNMENT (O/REF: SHA9095S)  
**Attachments:** 03012018164427-0001.pdf; FW: ARRANGE FOR SURVEY SHB9778A (2.01 MB)

Dear Sirs

New survey assignment for your handling.

Thanks & Regards

Aini  
Motor Claims Department  
First Capital Insurance Ltd  
Tel: 6507 3848 (Ext 138)  
Fax: 65073849

Personal Data Protection Act 2012 ("PDPA"):

Under the PDPA, there are various requirements that regulate the processing of your personal data. Please refer to [www.first-insurance.com.sg](http://www.first-insurance.com.sg) for details of PDPA Personal Data Collection Statement.

Confidentiality Notice: This e-mail is confidential. It may also be legally privileged.

If you are not the addressee or to whom it is intended, you may not copy, forward, disclose or use any part of it.

If you have received this message in error, please delete the message and all copies from your system and notify the sender immediately by return e-mail.

Veron Chen (LKKAuto)

---

**From:** Veron Chen (LKKAuto)  
**Sent:** Friday, 5 January, 2018 11:50 AM  
**To:** Admin-D (LKKAuto); 'Aini Binte Md Min'  
**Cc:** SUR  
**Subject:** RE: NEW ASSIGNMENT (O/REF: SHA9095S)  
**Attachments:** SHB 9778A PRELI ADVISED.pdf

Dear Aini,

Enclosed preliminary revised of vehicle SHB 9778A  
Date of survey: 4/1/2018  
Number of days: 12 days

**Kindly provides us the claim number.**

Best Regards,  
Veron Chen | Case Handler  
LKK Auto Consultants Pte Ltd  
Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315  
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

-----Original Message-----

**From:** Admin-D (LKKAuto)  
**Sent:** Wednesday, 3 January, 2018 4:56 PM  
**To:** 'Aini Binte Md Min' <aini@first-insurance.com.sg>; assignments <assignments@lkkauto.com>  
**Cc:** SUR <sur@lkkauto.com>  
**Subject:** RE: NEW ASSIGNMENT (O/REF: SHA9095S)

Dear Aini,

Thank you for the assignment.

"Wishes you a Happy New Year 2018"

Best Regards,  
Catherine Chong | Admin  
LKK Auto Consultants Pte Ltd  
Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue  
1, #02-25 | S(408933)

-----Original Message-----

**From:** Aini Binte Md Min [mailto:aini@first-insurance.com.sg]

Sent: Wednesday, 3 January, 2018 4:47 PM  
To: 'assignments@lkkauto.com' <assignments@lkkauto.com>  
Cc: 'candy.kong@transcab.com.sg' <candy.kong@transcab.com.sg>  
Subject: NEW ASSIGNMENT (O/REF: SHA9095S)

Dear Sirs

New survey assignment for your handling.

Thanks & Regards

Aini  
Motor Claims Department  
First Capital Insurance Ltd  
Tel: 6507 3848 (Ext 138)  
Fax: 65073849

Personal Data Protection Act 2012 ("PDPA"):  
Under the PDPA, there are various requirements that regulate the processing of your personal data.  
Please refer to [www.first-insurance.com.sg](http://www.first-insurance.com.sg) for details of PDPA Personal Data Collection Statement.

Confidentiality Notice: This e-mail is confidential. It may also be legally privileged.  
If you are not the addressee or to whom it is intended, you may not copy, forward, disclose or use any part of it.  
If you have received this message in error, please delete the message and all copies from your system and notify the sender immediately by return e-mail.

“ ”





Auto  
Consultants  
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAVA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: PLEASE ADVISED  
Our ref: CS/FCI18000167/Kvb

Date : 5/1/2018

The Motor Claims Department  
M/s First Capital Insurance Ltd

Dear Sir/Madam,

**INITIAL INSPECTION REPORT OF VEHICLE NO. SHB 9778A**


We thank for your instruction on 3/1/2018

Please be informed that we had conducted the inspection of the above mentioned vehicle on 4/1/2018 at the premises of M/s TRANS-CAB AUTO SERVICES PTE LTD and have the following to report:-

Workshop Estimate Amount	: S\$45,547.07
Revised Estimate Amount	: S\$13,958.58
"Check" Items Amount	: S\$
Market Value	: S\$
LTA Reimbursement Value	: S\$
Nett Value	: S\$

Description of Damage:

The vehicle sustained damages at the rear portion



Comments/Present Status:

Damages Consistent

Yours faithfully,

Kenneth Kong  
Licensed Appraiser

## Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	3878K
Vehicle Details	
Vehicle No.:	SHB9778A
Vehicle to be Exported:	Yes
Intended De-registration Date:	04 Jan 2018
Vehicle Make:	RENAULT
Vehicle Model:	LATITUDE 2.0L DCI AUTO D/AB 4DR
Primary Colour:	Red
Manufacturing Year:	2013
Engine No.:	M9R8839C000239
Chassis No.:	VF1ABL15AUC273116
Maximum Power Output:	127.0 kW (170 bhp)
Open Market Value:	\$19,998.00
Original Registration Date:	31 Jul 2013
First Registration Date:	31 Jul 2013
Transfer Count:	0
Actual ARF Paid:	\$12,498.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	30 Jul 2021
PARF Rebate Amount:	\$9,373.00
Intended COE Rebate Details	

COE Expiry Date:	30 Jul 2021
COE Category:	A - Car (1600cc & below)
COE Period(Years):	8
PQP Paid:	\$51,810.00
COE Rebate Amount:	\$23,119.00
<b>Total Rebate Amount:</b>	<b>\$32,492.00</b>
<b>Message</b>	
Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 04 Jan 2018

OK

**Trans-cab Auto Services Pte Ltd**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHB 9778A****AAD1801-022***Not Authored  
21 Sep @ 11, 1506*

Vehicle No.:  
Chassis No.:  
Vehicle Make:  
Vehicle Model:  
Date of Accident :  
Third Party Insurer :

**SHB 9778A**  
VF1ABL15AUC273116  
RENAULT  
LATITUDE  
1.1.2018  
**FIRST CAPITAL**

	<b>PART</b>		<b>LIST</b>	
1	1 BUMPER COVER REAR	\$	<i>Bu</i> 1,108.46	—
2	1 BUMPER LOWER REAR	\$	<i>Di</i> 768.84	—
3	1 BUMPER BRACKET CTR REAR	\$	<i>CM</i> 113.47	—
4	1 BUMEP R BRACKET SIDE RH REAR	\$	<i>Sn</i> 135.97	X
5	1 BUMEP R RETAINER RH REAR	\$	<i>Sn</i> 44.99	X
6	1 BUMPER REFLECTOR RH	\$	<i>Sn</i> 43.61	X
7	1 BUMEP R BRACKET SIDE LH REAR	\$	<i>Sn</i> 135.97	X
8	1 BUMEP R RETAINER LH REAR	\$	<i>Sn</i> 44.99	X
9	1 BUMPER REFLECTOR LH	\$	<i>Sn</i> 43.61	X
10	1 BUMPER BEAM REAR	\$	<i>Bu</i> 777.52	—
11	1 BUMPER BEAM BRACKET LH REAR	\$	<i>Bu</i> 225.95	—
12	1 BUMPER BEAM BRACKET RH REAR	\$	<i>Bu</i> 225.95	—
13	1 BOOT REAR	\$	<i>Bu</i> 2,872.68	—
14	1 BOOT FINISHER	\$	<i>Sn</i> 470.06	X
15	1 BOOT WHEATERSTRIP	\$	<i>Di</i> 323.05	—
16	1 BOOT REFLECTOR LAMP LH	\$	<i>CM</i> 493.35	—
17	1 BOOT REFLECTOR LAMP RH	\$	<i>Sn</i> 493.35	X
18	1 BOOT BADGE 'RENAULT'	\$	<i>Re</i> 225.36	—
19	1 BOOT BADGE	\$	<i>Re</i> 225.36	—
20	1 BOOT STRUT LH	\$	<i>Sn</i> 276.08	X
21	1 BOOT STRUT RH	\$	<i>Sn</i> 276.08	X
22	1 BOOT HINGE LH	\$	<i>R</i> 367.84	X
23	1 BOOT HINGE RH	\$	<i>R</i> 367.84	X
24	1 BOOT INNER TRIM	\$	<i>Sn</i> 586.45	X
25	1 BOOT SWITCH	\$	<i>Sn</i> 168.13	X
26	1 BOOT LOCK	\$	<i>R</i> 202.67	X
27	1 BOOT LOCK CATCH	\$	<i>R</i> 74.40	X
28	2 LICENCE PLATE LAMP	\$	<i>Sn</i> 50.52	X
29	2 BOOT RUBBER PLUG	\$	<i>Sn</i> 221.81	X
30	1 FENDER PANEL INNER TRIM REAR LH	\$	<i>Sn</i> 671.45	X

12035.81

**Trans-cab Auto Services Pte Ltd**

**AAD1801-022**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHB 9778A**

31	1 FENDER PANEL REAR LH	\$	R	3,299.13	✓
32	1 WHEELARCH REAR LH	\$	Sm	543.47	X
33	1 FENDER PANEL INNER TRIM REAR RH	\$	Sm	671.45	X
34	1 FENDER PANEL REAR RH	\$	R	3,299.13	X
35	1 WHEELARCH REAR RH	\$	Sm	543.47	X
36	1 TAILLAMP RH	\$	Sm	552.55	X
37	1 TAILLAMP PANEL RH	\$	R	986.70	X
38	1 TAILLAMP LH	\$	Sm	552.55	X
39	1 TAILLAMP PANEL LH	\$	R	986.70	X
40	1 OUTER PANEL REAR (End Panel)	\$	Bt	1,471.77	✓
41	1 OUTER PANEL REAR (End Panel)TRIM	\$	nd	404.56	✓
42	1 SPARE WHEEL PANEL (Luggage Floor Panel)	\$	Bt/Sm	2,189.88	✓
43	1 SPARE WHEEL PANEL TRIM	\$	Sm	612.21	X
44	1 EXHAUST REAR	\$	R	7,489.05	X
45	1 EXHAUST CAP REAR	\$	Sm	230.49	X
45	1 BUMPER COVER FRT	\$	R	1,259.42	X

<b>TOTAL</b>	<b>\$</b>	<b>37,128.37</b>	4
<b>10%</b>	<b>\$</b>	<b>3,586.89</b>	
	<b>\$</b>	<b>-32,282.05</b>	

25092.53  
33415.51

**Special Nett**

1	1SET PARKING AID	\$	Short	700.00	✓
2	1SET REAR BUMPER CLIP	\$	nr	66.00	✓
3	1SET BUMPER BRACKET CTR CLIP	\$	nr	33.00	✓
4	1SET BUMEP R BRACKET SIDE CLIP RH RR	\$	nr	10.00	X
5	1SET BUMEP R RETAINER RH CLIP RR	\$	nr	20.00	X
6	1SET BUMEP R BRACKET SIDE CLIP LH RR	\$	nr	10.00	X
7	1SET BUMEP R RETAINER CLIP LH RR	\$	nr	20.00	X
8	1SET BUMPER LOWER REAR RIVET	\$	nr	22.00	X
9	1SET BUMPER LOWER REAR CLIP	\$	nr	66.00	✓
10	1 EXHAUST MOUNTING REAR	\$	Sm	17.82	X
11	1SET BOOT FINISHER CLIP	\$	nr	24.20	X
12	1 BOOT STICKER "Trans-cab"	\$	nr	30.00	✓
13	1 BOOT STICKER "6555-3333"	\$	nr	30.00	✓
14	1 BOOT INNER TRIM CLIP	\$	nr	45.00	X
15	1SET FENDER WHEELARCH REAR RH CLIP	\$	nr	35.00	X
16	1SET FENDER WHEELARCH REAR LH CLIP	\$	nr	35.00	X
17	1 FENDER INNER TRIM CLIP LH	\$	nr	28.00	X

**Trans-cab Auto Services Pte Ltd**

AAD1801-022

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHB 9778A**

18	1 FENDER INNER TRIM CLIP LH	\$	<i>nn</i> 28.00	}
19	1 TAILLAMP CLIP RH	\$	<i>nn</i> 5.00	
20	1 TAILLAMP CLIP LH	\$	<i>nn</i> 5.00	
21	2 REAR WINDSCREEN SELANT	\$	<i>nn</i> 80.00	
22	1 WINDSCREEN MOULDING	\$	<i>nn</i> 100.00	
23	1 REAR WINDSCREEN INNER SPONGE SEAL	\$	<i>nn</i> 100.00	
24	1 SPARE TYRE RIM (ROUE 7J 16H 2547)	\$	<i>sn</i> 385.00	
25	1 SPARE TYRE	\$	<i>sn</i> 330.00	X

**TOTAL \$ 2,225.02**

**TOTAL PARTS \$ 34,507.07**

**LABOUR**

Putty And Spray Painting Of The Affected Portion.	\$	4,500.00	<i>1100l</i>
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	4,200.00	<i>1200l</i>
To Rust-Proofing Of The Affected Areas.	\$	170.00	<i>90l</i>
To reinstall rear bumper parking sensor.	\$	170.00	<i>60l</i>
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	170.00	<i>60l</i>
To repair and realign rear exhaust pipe.	\$	170.00	}
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	170.00	
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	170.00	}
To transfer of rear luggage floor panel fittings, attachment and perform water seepage test.	\$	170.00	

**Trans-cab Auto Services Pte Ltd**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHB 9778A**

To supply and re-do rear luggage floor panel insulation padding.	\$	380.00	<i>Sci</i>
To transfer of rear fender fittings, attachment and perform water seepage test.	\$	<i>NA</i> 380.00	<i>X</i>
To transfer of rear windscreen fittings and conduct water seepage test.	\$	<i>~</i> 170.00	<i>X</i>
To check steering geometry and computer wheel alignment	\$	<i>~</i> 220.00	<i>X</i>
<b>TOTAL</b>	<b>\$</b>	<b>11,040.00</b>	

**Over All Total** \$ 45,547.07 *46680.53*

**(LUMP SUM)**

**Repair Days**

*15 Days*  
*12 days*

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
  - To display damaged part(s) during resurvey
  - Parts prices are subject to confirmation
  - Third party survey is on a "Without Prejudice" basis
  - No illegal modification(s) is allowed
  - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:




## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI18000167/Kvbn2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 17-01-2018	
		Code : FCI2	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>			
Insured Veh.	SHA 9095S	Veh. Inspected	SHB 9778A
Policy No.		Coverage (\$)	0.00
Claim No.	SHA 9095S (DOA:1/1/2018)	Excess (\$)	0.00
Assign From	AINI	Assign Date	03/01/2018
<b>2. Vehicle Particulars &amp; Condition</b>			
Make & Model	RENAULT LATITUDE (A)	c.c	1995
Engine No.	HIDDEN	Year of Reg.	2013
Chassis No.	VF1ABL15AUC273116	Colour	METALLIC WHITE / RED
Odometer	552644	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		
<b>3. Conditions of Tyres</b>			
	Size	Make	Balance
R/H Front Tyre	215/60 R16	LING LONG	6 mm
L/H Front Tyre	215/60 R16	LING LONG	6 mm
R/H Rear Tyre	215/60 R16	LING LONG	8 mm
L/H Rear Tyre	215/60 R16	LING LONG	8 mm
<b>4. Description of Damages</b>			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
<b>5. General Information</b>			
Accident Date	01/01/2018	Inspection Date	04/01/2018
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111		
<b>5a. Remarks</b>			
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>			
ESTIMATED NORMAL PERIOD FOR REPAIR:		<b>12 Working Days</b>	





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 4

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHB 9778A

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
1	BUMPER COVER REAR	BUCKLED	1,108.46	1,108.46
1	BUMPER LOWER REAR	DISTORTED	768.84	768.84
1	BUMPER BRACKET CTR REAR	CRACKED	113.47	113.47
1	BUMPER BRACKET SIDE RH REAR	SERVICEABLE	135.97	-
1	BUMPER RETAINER RH REAR	SERVICEABLE	44.99	-
1	BUMPER REFLECTOR RH	SERVICEABLE	43.61	-
1	BUMPER BRACKET SIDE LH REAR	SERVICEABLE	135.97	-
1	BUMPER RETAINER LH REAR	SERVICEABLE	44.99	-
1	BUMPER REFLECTOR LH	SERVICEABLE	43.61	-
1	BUMPER BEAM REAR	BENT	777.52	777.52
1	BUMPER BEAM BRACKET LH REAR	BENT	225.95	225.95
1	BUMPER BEAM BRACKET RH REAR	BENT	225.95	225.95
1	BOOT REAR	BUCKLED	2,872.68	2,872.68
1	BOOT FINISHER	SERVICEABLE	470.06	-
1	BOOT WEATHERSTRIP	DISTORTED	323.05	323.05
1	BOOT REFLECTOR LAMP LH	CRACKED	493.35	493.35
1	BOOT REFLECTOR LAMP RH	SERVICEABLE	493.35	-
1	BOOT BADGE "RENAULT"	NECESSARY	225.36	225.36
1	BOOT BADGE	NECESSARY	225.36	225.36
1	BOOT STRUT LH	SERVICEABLE	276.08	-
1	BOOT STRUT RH	SERVICEABLE	276.08	-
1	BOOT HINGE LH	TO REPAIR SEE LABOUR	367.84	-
1	BOOT HINGE RH	TO REPAIR SEE LABOUR	367.84	-
1	BOOT INNER TRIM	SERVICEABLE	586.45	-
1	BOOT SWITCH	SERVICEABLE	168.13	-
1	BOOT LOCK	TO REPAIR SEE LABOUR	202.67	-
1	BOOT LOCK CATCH	TO REPAIR SEE LABOUR	74.40	-
2	LICENCE PLATE LAMP	SERVICEABLE	50.52	-



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
2	BOOT RUBBER PLUG	SERVICEABLE	221.81	-
1	FENDER PANEL INNER TRIM REAR LH	SERVICEABLE	671.45	-
1	FENDER PANEL REAR LH	TO REPAIR SEE LABOUR	3,299.13	-
1	WHEELARCH REAR LH	SERVICEABLE	543.47	-
1	FENDER PANEL INNER TRIM REAR RH	SERVICEABLE	671.45	-
1	FENDER PANEL REAR RH	TO REPAIR SEE LABOUR	3,299.13	-
1	WHEELARCH REAR RH	SERVICEABLE	543.47	-
1	TAILLAMP RH	SERVICEABLE	552.55	-
1	TAILLAMP PANEL RH	TO REPAIR SEE LABOUR	986.70	-
1	TAILLAMP LH	SERVICEABLE	552.55	-
1	TAILLAMP PANEL LH	TO REPAIR SEE LABOUR	986.70	-
1	OUTER PANEL REAR (END PANEL)	BENT	1,471.77	1,471.77
1	OUTER PANEL REAR (END PANEL) TRIM	DENTED	404.56	404.56
1	SPARE WHEEL PANEL (LUGGAGE FLOOR PANEL)	BENT / BUCKLED	2,189.88	2,189.88
1	SPARE WHEEL PANEL TRIM	SERVICEABLE	612.21	-
1	EXHAUST REAR	TO REPAIR SEE LABOUR	7,489.05	-
1	EXHAUST CAP REAR	SERVICEABLE	230.49	-
1	BUMPER COVER FRT	TO REPAIR SEE LABOUR	1,259.42	-
	LESS 10% DISCOUNT		-3,712.83	-1,142.62
			<b>33,415.51</b>	<b>10,283.58</b>
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	SET PARKING AID (SN)	SHORTED	700.00	700.00
1	SET REAR BUMPER CLIP (SN)	NECESSARY	66.00	66.00
1	SET BUMPER BRACKET CTR CLIP (SN)	NECESSARY	33.00	33.00
1	SET BUMPER BRACKET SIDE CLIP RH RR (SN)	NOT NECESSARY	10.00	-
1	SET BUMPER RETAINER RH CLIP RR (SN)	NOT NECESSARY	20.00	-
1	SET BUMPER BRACKET SIDE CLIP LH RR (SN)	NOT NECESSARY	10.00	-
1	SET BUMPER RETAINER CLIP LH RR (SN)	NOT NECESSARY	20.00	-
1	SET BUMPER LOWER REAR RIVET (SN)	NOT NECESSARY	22.00	-

Report Ref No. CS/FCI18000167/Kvbn2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	SET BUMPER LOWER REAR CLIP (SN)	NECESSARY	66.00	66.00
1	EXHAUST MOUNTING REAR (SN)	SERVICEABLE	17.82	-
1	SET BOOT FINISHER CLIP (SN)	NOT NECESSARY	24.20	-
1	BOOT STICKER "TRANS-CAB" (SN)	NECESSARY	30.00	30.00
1	BOOT STICKER "6555-3333" (SN)	NECESSARY	30.00	30.00
1	BOOT INNER TRIM CLIP (SN)	NOT NECESSARY	45.00	-
1	SET FENDER WHEELARCH REAR RH CLIP (SN)	NOT NECESSARY	35.00	-
1	SET FENDER WHEELARCH REAR LH CLIP (SN)	NOT NECESSARY	35.00	-
1	FENDER INNER TRIM CLIP LH (SN)	NOT NECESSARY	28.00	-
1	FENDER INNER TRIM CLIP LH (SN)	NOT NECESSARY	28.00	-
1	TAILLAMP CLIP RH (SN)	NOT NECESSARY	5.00	-
1	TAILLAMP CLIP LH (SN)	NOT NECESSARY	5.00	-
2	REAR WINDSCREEN SEALANT (SN)	NOT NECESSARY	80.00	-
1	WINDSCREEN MOULDING (SN)	NOT NECESSARY	100.00	-
1	REAR WINDSCREEN INNER SPONGE SEAL (SN)	NOT NECESSARY	100.00	-
1	SPARE TRYE RIM (ROUE 7J 16H 2547)(SN)	SERVICEABLE	385.00	-
1	SPARE TYRE (SN)	SERVICEABLE	330.00	-
			2,225.02	925.00
	<b>LABOUR</b>			
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		4,500.00	1,100.00
	PANEL BEATING, KNOCKING AND STRAIGHTENING THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME. INCLUSIVE OF THE REPAIR OF BOOT HINGE LH, BOOT HINGE RH, BOOT LOCK, BOOT LOCK CATCH, FENDER PANEL REAR LH, FENDER PANEL REAR RH, TAILLAMP PANEL RH, TAILLAMP PANEL LH, EXHAUST REAR AND BUMPER COVER FRT.		4,200.00	1,200.00
	TO RUST-PROOFING OF THE AFFECTED AREAS.		170.00	90.00
	TO REINSTALL REAR BUMPER PARKING SENSOR.		170.00	60.00
	TO TRANSFER OF BOOTLID FITTINGS, ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.		170.00	60.00
	TO REPAIR AND REALIGN REAR EXHAUST PIPE }.		170.00	80.00
	TO DROP REAR EXHAUST BOX, RENEW THE SAME, TO REPAIR AND REALIGN CENTRE EXHAUST PIPE }.		170.00	-

Report Ref No. CS/FCI18000167/Kvbn2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:4 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO TRANSFER OF REAR END PANEL FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST }		170.00	80.00
	TO TRANSFER OF REAR LUGGAGE FLOOR PANEL FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST }		170.00	-
	TO SUPPLY AND RE-DO REAR LUGGAGE FLOOR PANEL INSULATION PADDING.		380.00	80.00
	TO TRANSFER OF REAR FENDER FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	380.00	-
	TO TRANSFER OF REAR WINDSCREEN FITTINGS AND CONDUCT WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.	NOT NECESSARY	220.00	-
			11,040.00	2,750.00
	<b>GRAND TOTAL</b>		<b>46,680.53</b>	<b>13,958.58</b>
	<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>			<b>11,150.00</b>

Report Ref No. CS/FCI18000167/Kvbn2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.