

ASS. REC. BY:

REF:

CS/FCI18000178/Unbn2

Special Instruction:

SURVIVOR:

Marius,

ASSIGNMENT (Office)

CWS

From (Person):

Tanna, Yung

of

Fci

Date/Time:

3/1/2018

Estimated Cost:

Bill to:

OD-TP/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLR 6559D

Insured:

SHA 5407C

at Workshop m/s

Kah Motor

Tel:

68413838

of

15 Ubi Rd 4

Policy No:

D-15072701MESH

Claim No:

D18000113MESH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

28/12/2017

CA / REV / REP. / REV 24 HRS DS

04.01.2018 @ 3pm

H.O.D. Endorsement:

Date/Time:

03/01/2018 1.45pm

Person Contacted:

Steven

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SLR 6559D-X
	SHA 5407C-X
5/1/18	Email preli revised to FCI
9/1/18	Final fig \$ 2527.92 confirmed by email (Red 6798.58, 737)

REP: FEL

ASSIGNMENT

From: Date: 04012018

Estimated Cost:

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SLR 6559D

at Workshop m/s Kah Motor

of 15 Ubi Rd 4

Insured

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh: Steven

3pm

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Report: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 4 days Res: Yes or No

Lum Sum: 131 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS '08 27456011

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SLR 6559D Yr Regn: 8 17

Type: ☒ M/Cam / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or CAI

Make: Honda HRV cc 1496

Colour: Brown A/C: Insured / Std / NI / NA

So. Reading: 9106 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: JHMRU18106X202894

Gen. Cond: Good / Fair / Poor / Burnt

Steering: ☒ In order / Jammed / Leaked / Burnt orBrake: ☒ In order / Jammed / Leaked / Burnt orModi: Nil ☒ S/Rim / STD A/Rim or

Tyre Size: F: 215/60R16

R:

BS: ☒ DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front:

Rear:

R/Bal: S mm R/Bal: S mm

L/Bal: S mm L/Bal: S mm

D.O.A. D.O.I. 4/1/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

2527.92

RECEIVED 09 FEB 2018

Date/Time: File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time: File Return to?

2) 9/2-typist

Days Of Repair: 4

Resurvey No. of Trip: 1

Survey Fee

Transportation

1) S-RS (S)

2) Photos

3) Others

Add Fee:

☐

Site Insp: \$

☐

Interview: \$

☐

Tech Insp: \$

☐

Workshop: \$

Report Format: CWS

Lump Sum / I.B.I. \$ 2527.92

170

50

50

62

332



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI18000178/Uvb

36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Date : 03-01-2018



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHA 5407C	Veh. Inspected	SLR 6559D
Policy No.	D-15072701MFSH	Coverage (\$)	0.00
Claim No.	D18000113MFSH	Excess (\$)	0.00
Assign From	JOANNEY	Assign Date	03/01/2018

2. Vehicle Particulars & Condition

Make & Model	c.c
Engine No.	Year of Reg.
Chassis No.	Colour
Odometer	Steering
Brakes	Modification
General	

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	28/12/2017	Inspection Date
Survey held at		

5a. Remarks

--



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: D18000113MFSH
Our ref: CS/FCI18000178Uvb

DATE: 5/1/2018

The Motor Claims Department
M/s FIRST CAPITAL INSURANCE LTD

WITHOUT PREJUDICE

Dear Sir/Madam

INITIAL INSPECTION REPORT OF VEHICLE NO. SLR 6559D


We thank for your instruction on 3/1/2018

Please be informed that we had conducted the inspection of the above mentioned vehicle on vehicle on 4/1/2018 at the premises of M/s KAH MOTOR CO SDN BHD and have the following to report:-

Workshop Estimate Amount	: S\$9,326.50
Revised Estimate Amount	: S\$794.00
"Check" Items Amount	: S\$7,534.40
Market Value	: S\$
LTA Reimbursement Value	: S\$
Nett Value	: S\$

Description of Damage:

The vehicle sustained damages at the front portion.



Comments/Present Status:
Damages Consistent

Yours faithfully,

MARCUS CHUA
Licensed Appraiser

Survey Department Check List (Case Handler)

Reference No. : es/FCI/18000178/Uvb
Policy Type: OD / TP / TP RES / TL / EVA

Case Handler

Typist

Admin (): Case handler to make sure all Information created by the assignment team are **ACCURATE**.

(1) Office Assign Form

		Y-Date	N-Date	Y-Date	N-Date
C	Reference No.	✓			
C	Customer Code				
N	Assign From				
C	Assign Date	✓			
C	Veh No (Inspected)	✓			
C	Veh No (Insured)	✓			
C	D.O.A	✓			
C	Policy No	✓			
C	Claim No	✓			
C	Insurance Authorisation (CA /REV/REP)				
C	Report Type	✓			
C	Weekend Charges				
N	Survey held at/Repairer	✓			
C	Excess				

Surveyor (): Case handler to make sure the surveyor completed all required information.

(1) Assignment Form

C	Vehicle No	✓			
C	Regn Month/Year	✓			
N	Vehicle Type	✓			
N	Make & Model	✓			
C	Engine Capacity. (C.C)	✓			
N	Colour	✓			
C	Odometer. (Sp.Reading)	✓			
C	Chassis No	✓			
N	General Condition	✓			
N	Steering	✓			
N	Brake	✓			
N	Modification (Modi)	✓			
C	Tyre Size	✓			
N	Tyre Make	✓			
C	Tyre Balance	✓			
C	Date of Inspection	✓			
N	Survey held	✓			
N	Des.of Damages	✓			

(2) System - (Views/Merimen)

C	Damaged Vehicle Photographs Uploaded	✓			
---	--------------------------------------	---	--	--	--

(3) Workshop Estimate/Assignment Form

N	ALL Parts condition	✓			
C	Market Value for OD cases				
C	Estimate Repair Cost for PRI (RSI, TMI, MSIG)				
C	Days of repair	✓			
C	Finalised Amount	✓			
C	Re-inspection Cases to Finalize within 5 Days				

(4) System - (Views/Merimen)

C	Resurvey photo Uploaded	✓			
---	-------------------------	---	--	--	--

Check By: Vetion 9/2/18
Case Handler Date

*C: Critical *N: Non-Critical

21/05/2014

First Capital Insurance Limited

A FAIRFAX Company

Company Reg. No. 195000106C
GST Reg. No. M2-0001676-9

MOTOR SURVEY ASSIGNMENT

Date	02-01-2018	Our Ref No. D18000113MFSH
Accident Date	28-12-2017	Claim Type. Third Party
Insured Vehicle	SHA5407C	Third Party Vehicle. SLR6559D
Survey Location	15 UBI ROAD 4	
Contact Person.	STEVEN CHUI	
Contact No.	68413838/ 68413838	Fax No. 0
Survey Type	DIRECT SETTLEMENT:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	
Contact Number.	NA	Fax No. 68416315

04 01 2018 @ 3pm
overseeing
Steven
03 01 2018 @ 1:45pm

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	KAH MOTOR CO SDN BHD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	JOANNEY	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/232536)



PRI Documents



Close



PRI Header Details

Claim No	D18000113MFSH	Policy No	D-15072701MFSH	Claimant S.No & Name	1 & KA
Workshop Name	KAH MOTOR CO SDN BHD (Contact Person : STEVEN CHUI)	Survey Location & Contact Details	15 UBI ROAD 4 Mobile: 68413838 , Phone: 68413838 , Fax: EmailId: STEVENCHUI@HONDA.COM.SG		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	DIRECT SETTLEMENT:		
Insured Name	COMFORT TRANSPORTATION PTE LTD	Insured Vehicle No	SHA5407C	TP Vehicle No	SLR655
PRI Recieved Date	02-01-2018 10:14:03 PM	Surveyor Appointed Date	03-01-2018 12:34:54 PM	Surveyor Accept Date	03-01-

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	03-01-2018	Upload Survey Report *:	
-----------------------------	----------------------	----------------------	------------	-------------------------	----------------------

Vehicle Particulars

Make	Please Select Make	Model	Please Select Model	Year	Select
Chasis No		Engine No		Mileage	
Color		Cubic Capacity			

Multiple Documents Upload

Upload Multiple Documents	
File Name	Action

Surveyor Job Remarks

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Friday, 9 February 2018 11:31 AM
To: SUR; Steven Chui
Subject: RE: SLR6559D FB

Dear Steven,

Confirmed finalize amount \$2527.92 before GST

Total 4 working days

Final invoice and all supporting documents sent to First Capital Ins Ltd.

OIC Joanna Yong ,Ref: D18000113MFSH

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Steven Chui [<mailto:stevenchui@honda.com.sg>]
Sent: Thursday, February 08, 2018 10:41 AM
To: SUR <sur@lkkauto.com>
Subject: SLR6559D FB

Dear Si/mdm,

Attached final repair bill for SLR6559D, kindly let me know if finalise.

Total 4 working days

Thank you!

Wish everybody "Happy Chinese New Year"

Steven Chui
Bodyshop Service Advisor
Kah Motor Co. Sdn Bhd
15 Ubi Road 4
Singapore 408610
E-mail: stevenchui@honda.com.sg

Contact : 68465672
H/phone:90721766



Confidential Note: The information contained in this email is intended only for the use of the individual or entity named above and may contain information that is privileged, confidential and exempt from disclosure under applicable law. If the reader of this message is not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this communication is strictly prohibited. If you have received this message in error, please immediately notify the sender and delete the mail. Thank you.

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Friday, 5 January, 2018 2:15 PM
To: 'Claim Workflow System'
Cc: SUR; Joanne Yong Lai fong
Subject: RE: SURVEY ASSESSMENT - D18000113MFSH/1, SLR 6559D
Attachments: SLR 6559D PRELI ADVISED.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle SLR 6559D
Date of survey: 4/1/2018
Number of days: 4 days

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@first-insurance.com.sg>]
Sent: Wednesday, 3 January, 2018 12:34 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@FIRST-INSURANCE.COM.SG; JOANNEYONG@FIRST-INSURANCE.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D18000113MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,
Admin Team
Claim Workflow System
Motor Claims Department
First Capital Insurance Limited
Tel : 6507 3848
Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	2870A
Vehicle Details	
Vehicle No.:	SLR6559D
Vehicle to be Exported:	No
Intended De-registration Date:	04 Jan 2018
Vehicle Make:	HONDA
Vehicle Model:	HRV 1.5 DX CVT
Primary Colour:	Beige
Manufacturing Year:	2017
Engine No.:	L15B4532893
Chassis No.:	JHMRU1810GX202894
Maximum Power Output:	96.0 kW (128 bhp)
Open Market Value:	\$19,608.00
Original Registration Date:	23 Aug 2017
First Registration Date:	23 Aug 2017
Transfer Count:	0
Actual ARF Paid:	\$14,608.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	22 Aug 2027
PARF Rebate Amount:	\$10,956.00
Intended COE Rebate Details	
COE Expiry Date:	22 Aug 2027
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$46,778.00
COE Rebate Amount:	\$45,055.00
Total Rebate Amount:	\$56,011.00

The information contained herein is correct as at 04 Jan 2018

OK

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S1252870A

Name
WEE YEW KHIAM

黃幼謙

Race
CHINESE

Date of Birth
16-01-1957

Sex
M

Country of Birth
SINGAPORE

REPUBLIC OF SINGAPORE DRIVING LICENCE

Licence Number S1252870A

Name
WEE YEW KHIAM

Birth Date
16 Jan 1957

Issue Date
05 Mar 2003

000258728D

093436

S1252870A

Address
APT BLK 224C COMPAASSVALE WALK #10-850
SINGAPORE 543224

NRIC No: S1252870A

Group
B+

Date of issue
04-05-1993

Date
30-07-1998

No: 2523126

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS:

Class	Description	PASS DATE
Class 3	Motor Cars and Motor Tractors the weight of which unladen does not exceed 2500 kilograms	17 Apr 1978

NP 428A

Licence No: S1252870A

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : FIRST CAPITAL INSURANCE LTD
36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877

Registration No : SLR6559D

Chassis No : JHMRU1810GX202894

Model : HRV DX-SIN CVT YM 2016

Owner's Name : WEE YEW KHAM

Ins Policy No. :

Date of Accident : 28/12/2017

Document No. : SQT17005254 Page 1

Date : 29. Dec 2017

Customer No. : WF002

Svc Advisor :

Engine No : L15B4532893

Date | Time : 29. Dec 2017 9:49:02 AM

Surveyor Name :

Survey Date :

Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	GST Amt	Amount incld GST
71126-T7B-Z01	SET,FR.GRILLE ASSY <i>one</i>	1	265.50	✓ 199.12	265.50 ✓	18.59	284.09
71122-T7A-901	MOLDINGFR.GRILLE UPPER <i>one</i>	1	186.10	✓ 139.57	186.10 ✓	13.03	199.13
71123-T7A-901	MOLDINGFR.GRILLE <i>11</i>	1	42.80	✗	42.80 ✗	3.00	45.80
75700-TA0-A00	EMBLEMFR. <i>DEC</i>	1	25.90	✓ 19.42	25.90 ✓	1.81	27.71
90301-ST0-003	NUTPUSH 3MM <i>nu</i>	2	1.90	✓ 2.85	3.80 ✓	0.27	4.07
71150-T7A-000	BEAMR.FR.GRILLE SIDE UPPER <i>11</i>	1	38.70	✗	38.70 ✗	2.71	41.41
71151-T7A-000	BEAMR.FR.GRILLE SIDE UPPER <i>11</i>	1	17.20	✗	17.20 ✗	1.20	18.40
71152-T7A-000	BEAML.FR.GRILLE SIDE UPPER <i>11</i>	1	4.50	✗	4.50 ✗	0.32	4.82
91505-TM8-003	CLIPBUMPER <i>nu</i>	20	2.00	✓ 30	40.00 ✓	2.80	42.80
04711-T7A-N00ZZ	FACEFR.BUMPER <i>DD/DE</i>	1	466.20	✓ 349.65	466.20 ✓	32.63	498.83
71103-T7A-000	GRILLEFR.BUMPER <i>one</i>	1	77.50	✓ 58.12	77.50 ✓	5.43	82.93
71140-T7A-000	BEAMR.FR.BUMPER UPPER <i>11</i>	1	23.90	✗	23.90 ✗	1.67	25.57
71190-T7A-000	BEAML.FR.BUMPER UPPER <i>one</i>	1	23.90	✓ 17.92	23.90 ✓	1.67	25.57
71130-T7A-000ZZ	BEAM COMPFR.BUMPER <i>DD</i>	1	236.60	✓ 177.45	236.60 ✓	16.56	253.16
71161-T7A-000	GARNISHR.FR.BUMPER BEAM <i>11</i>	1	7.50	✗	7.50 ✗	0.53	8.03
71166-T7A-000	GARNISHL.FR.BUMPER BEAM <i>11</i>	1	7.50	✗	7.50 ✗	0.53	8.03
71193-T7A-000	SPACERR.FR.BUMPER SIDE <i>3rd</i>	1	10.40	✓ 7.80	10.40 ✓	0.73	11.13
71198-T7A-000	SPACERL.FR.BUMPER SIDE <i>3rd</i>	1	10.40	✓ 7.80	10.40 ✓	0.73	11.13
80110-T7A-003	CONDENSER COMP <i>11</i>	1	568.10	✗	568.10	39.77	607.87
33100-T7S-E11	HEADLIGHT ASSYR. <i>11</i>	1	1661.00	✗	1661.00 ✗	116.27	1777.27
33150-T7S-E11	HEAD LIGHT ASSY,L. <i>11</i>	1	1479.70	✗	1479.70 ✗	103.58	1583.28
91555-T7A-J01	CLIPAMBIENT SENSOR <i>nu</i>	1	4.30	✓ 3.22	4.30 ✓	0.27	4.60
BO-NUM-COMP-S	NUMBER PLATE WITH CASING-S(N) <i>3rd</i>	1	45.00	✓ 45	45.00 ✓	3.15	48.15
Sum Item					5246.50	367.28	5,613.78

TP DIRECT SETTLEMENT (J/NO:)

OWNER:SLR6559D

OWNER INSURER:WEE YEW KHAM

ACC DATE:28/12/2017

SURVEYED BY:

DATE:

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : FIRST CAPITAL INSURANCE LTD
36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877

Registration No : SLR6559D

Chassis No : JHMRU1810GX202894

Model : HRV DX-SIN CVT YM 2016

Owner's Name : WEE YEW KHIAM

Ins Policy No. :

Date of Accident : 28/12/2017

Document No. : SQT17005254

Date : 29. Dec 2017

Customer No. : WF002

Svc Advisor :

Engine No : L15B4532893

Date | Time : 29. Dec 2017 9:49:02 AM

Surveyor Name :

Survey Date :

Authorisation Date :

Page 2

Item	Description	Qty	Unit Price	Disc %	Amount	GST Amt	Amount incld GST
	REF NO:						
	TP INSURER: FIRST CAPITAL						
	TP VEH: SHA5407C						
BOSUN	SUNDRIES	1	80.00	10%	80.00	5.60	85.60
BMA01D	REMOVE & INSTALL A/C CONDENSER WITH FITTINGS.	1	180.00		180.00	12.60	192.60
BMA02D	REMOVE & INSTALL A/C COOLING COIL WITH FITTINGS.	1.8	100.00		180.00	12.60	192.60
BKBH12S	STRAIGHTEN ALIGN FR R BULKHEAD WHEELHOUSE & 1 parts.	1	2240.00		2240.00	156.80	2396.80
BP03R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (3P)	1	1400.00		1400.00	98.00	1498.00
Sum Labor					4080.00	285.60	4365.60

Survey By

Date & Time

Excess

Status

Signature

Marcus Kheh

4/1/18 @ 3pm

Not followed

to be photo before party.

4 day.

Total Amount 9,326.50 652.88 9,979.38

Total (Inclusive of GST) 9,979.38

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Printed on 2/1/2018 9:09:11 AM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s)

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

SERVICE PRE-INVOICE

GST Reg No.: M200050223

Company Ref. No.: S80FC1380G

Customer: WF002 / FIRST CAPITAL
 Chassis No: JHMRU1810GX202894
 License No: SLR6559D
 Mileage: 8345
 Engine No: L15B4532893

Document No: SVO18002825
 Printed By: FSCHUI
 Order Date: 15. January 2018
 Order Time: 8:19:04 AM
 Service Advisor: STEVEN CHUI FOOK SENG

ITEM	DESCRIPTION	QTY	UNIT	DISC %	AMOUNT	7% GST Amount incld Amount	GST
	TP DIRECT SETTLEMENT (J/NO: 69791 OWNER:SLR6559D OWNER INSURER:WEE YEW KHAM ACC DATE:28/12/2017 SURVEYED BY:MARCUS DATE: REF NO: TP INSURER:FIRST CAPITAL TP VEH:SHA5407C						
71122-T7A-901	MOLDINGFR.GRILLE UPPER	1	186.10	25	139.57	9.77	149.34
75700-TA0-A00	EMBLEMFR.	1	25.90	25	19.42	1.36	20.78
90301-ST0-003	NUTPUSH 3MM	2	1.90	25	2.85	0.20	3.05
91505-TM8-003	CLIPBUMPER	20	2.00	25	30.00	2.10	32.10
04711-T7A-N00ZZ	FACEFR.BUMPER	1	466.20	25	349.65	24.48	374.13
71193-T7A-000	SPACERR.FR.BUMPER SIDE	1	10.40	25	7.80	0.55	8.35
71198-T7A-000	SPACERL.FR.BUMPER SIDE	1	10.40	25	7.80	0.55	8.35
BO-NUM-COMP-S	NUMBER PLATE WITH CASING-S(N)	1	45.00		45.00	3.15	48.15
71126-T7B-Z01	SET.FR.GRILLE ASSY	1	265.50	25	199.12	13.94	213.06 ✓
71190-T7A-000	BEAML.FR.BUMPER UPPER	1	23.90	25	17.92	1.25	19.17
71130-T7A-000ZZ	BEAM COMPFR.BUMPER	1	236.60	25	177.45	12.42	189.87
71103-T7A-000	GRILLEFR.BUMPER	1	77.50	25	58.12	4.07	62.19
91555-T7A-J01	CLIPAMBIENT SENSOR	1	4.30	25	3.22	0.23	3.45
	SUM PARTS:				1,057.92	74.07	1,131.99
		1	10.00		10.00	0.70	10.70
BOSUN	0672 SUNDRIES						
	0626	1	560.00		560.00	39.20	599.20
BKBH12S	EXT-YJ STRAIGHTEN ALIGN FR R BULKHEAD WHEELHOUSE & RENEW DAMAGE PARTS.	1	900.00		900.00	63.00	963.00
BP03R	EXT-YBH SPRAY PAINTING ON REPAIRED OR REPLACED AREAS.(3P)						
	SUM LABOUR:				1,470.00	102.90	1,572.90
	TOTAL SGD				2,527.92	176.97	2,704.89
	Total Payable (SGD)						2,704.89

GST Amount is calculated from individual line(s)

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI18000178/Uvbn2		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 12-02-2018		
		Code : FCI2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHA 5407C	Veh. Inspected	SLR 6559D	
Policy No.	D-15072701MFSH	Coverage (\$)	0.00	
Claim No.	D18000113MFSH	Excess (\$)	0.00	
Assign From	JOANNE YONG	Assign Date	03/01/2018	
2. Vehicle Particulars & Condition				
Make & Model	HONDA HRV (A)	c.c	1496	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	JHMRU1810GX202894	Colour	BROWN	
Odometer	9106	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/60 R16	DUNLOP	8 mm	
L/H Front Tyre	215/60 R16	DUNLOP	8 mm	
R/H Rear Tyre	215/60 R16	DUNLOP	8 mm	
L/H Rear Tyre	215/60 R16	DUNLOP	8 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	28/12/2017	Inspection Date	04/01/2018	
Survey held at	KAH MOTOR CO SDN BERHAD 15 UBI ROAD 4 SINGAPORE 408610			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLR 6559D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	SET FR GRILLE ASSY (SN)	CRACKED	265.50	199.12
1	MOLDINGFR GRILLE UPPER (SN)	CRACKED	186.10	139.57
1	MOLDINGFR GRILLE (SN)	NOT NECESSARY	42.80	-
1	EMBLEMFR (SN)	NECESSARY	25.90	19.42
2	NUTPUSH 3MM (SN)	NECESSARY	3.80	2.85
1	BEAMR FR GRILLE SIDE UPPER (SN)	NOT NECESSARY	38.70	-
1	BEAMR FR GRILLE SIDE UPPER (SN)	NOT NECESSARY	17.20	-
1	BEAML FR GRILLE SIDE UPPER (SN)	NOT NECESSARY	4.50	-
20	CLIPBUMPER (SN)	NECESSARY	40.00	30.00
1	FACEFR BUMPER (SN)	DENTED / DEFORMED	466.20	349.65
1	GRILLEFR BUMPER (SN)	CRACKED	77.50	58.12
1	BEAMR FR BUMPER UPPER (SN)	NOT NECESSARY	23.90	-
1	BEAML FR BUMPER UPPER (SN)	CRACKED	23.90	17.92
1	BEAM COMPFR BUMPER (SN)	DENTED	236.60	177.45
1	GARNISHR FR BUMPER BEAM (SN)	NOT NECESSARY	7.50	-
1	GARNISHL FR BUMPER BEAM (SN)	NOT NECESSARY	7.50	-
1	SPACERR FR BUMPER SIDE (SN)	BENT	10.40	7.80
1	SPACERL FR BUMPER SIDE (SN)	BENT	10.40	7.80
1	CONDENDER COMP (SN)	NOT NECESSARY	568.10	-
1	HEADLIGHT ASSYR (SN)	NOT NECESSARY	1,661.00	-
1	HEADLIGHT ASSY L (SN)	NOT NECESSARY	1,479.70	-
1	CLIPAMBIENT SENSOR (SN)	NECESSARY	4.30	3.22
1	NUMBER PLATE WITH CASING (SN)	BENT	45.00	45.00
1	SUNDRIES (SN)	NECESSARY	80.00	10.00
			5,326.50	1,067.92
LABOUR				
	REMOVE & INSTALL A/C CONDENSER WITH FITTINGS.	NOT NECESSARY	180.00	-
	REMOVE & INSTALL A/C COOLING COIL WITH FITTINGS.	NOT NECESSARY	180.00	-
	STRAIGHTEN ALIGN FR R BULKHEAD WHEELHOUSE & RENEW DAMAGE PARTS.		2,240.00	560.00

Report Ref No. CS/FCI18000178/Uvbn2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS (3P).		1,400.00	900.00
			4,000.00	1,460.00
GRAND TOTAL			9,326.50	2,527.92
RECOMMENDED COST OF REPAIRS				2,527.92

Report Ref No. CS/FC118000178/Uvbn2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.