

ASS. REC. BY:

REF:

CS/AIG18000182/STB 9

Special Instruction:

SUPERVISOR:

MAMUN

ASSIGNMENT (Office)

From (Person):

Chan Yoke Shi

of

AIG

Date/Time:

2/1/2018

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJA 7731D

Insured:

SLT5283U

at Workshop m/s

Wong Kee

Tel:

81821895 Victor Wong

of

BLK1019 Yishun Ind PKA #01-366

Policy No:

Claim No:

199494323686003

Sum Insured:

Excess:

Make of Veh:

D.O.A.

2/1/2017

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

3/1

Person Contacted:

Victor

Vehicle ☒ IN ☐ OUT

Date/Time

Action/Instruction (✓): Estimate

SJA 7731D - X

SLT5283U - X

lump sum \$4000/- 7 days (red: 3241.50, 4491.0)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AIG ASIA PACIFIC INSURANCE PTE LTD		Ref : CS/AIG18000182/Stb	
78 SHENTON WAY #08-16 CHARTIS BUILDING SINGAPORE 079120		Date : 03-01-2018	
		Code : AIG	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SLT 5283U	Veh. Inspected	SJA 7731D
Policy No.		Coverage (\$)	0.00
Claim No.	1994943236SG003	Excess (\$)	0.00
Assign From	CHAN YOKE SHI	Assign Date	03/01/2018
2. Vehicle Particulars & Condition			
Make & Model	c.c		
Engine No.	Year of Reg.		
Chassis No.	Colour		
Odometer	Steering		
Brakes	Modification		
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	21/12/2017	Inspection Date	
Survey held at			
5a. Remarks			

Contact Number

OTHERS-98342306

Email Address

IZZUDDIN.AMIN.SAF@GMAIL.COM



WENG KEE MOTOR

DATE: 03-01-2018

REPAIR ESTIMATE

VEHICLE: SJA 7731 D

MODEL: Honda Civic

S/n	Description of part	Qty	Estimate
1	Rear boot lid outer garnish R	1	95.40 R
2	Rear boot lid outer garnish clip - set ✓ NEC.	1	40.00 ✓ NEC
3	Rear boot lid round stopper ✓ NEC.	2	30.00 ✓ NEC
4	Rear boot weather strip ✓ Deform.	1	126.60 ✓ Deform
5	Rear boot lock mechanism ✓ TM	1	116.80 ✓ TM
6	Rear boot lid lock sensor ?	1	175.30 X NN Δ
7	Rear boot buzzer ?	1	99.60 X NN Δ
8	Rear boot lid lamp LH ?	1	116.00 X NN Δ
9	Rear boot logo ✓ NEC.	1	47.30 ✓
10	Rear boot emblem 'Civic' ✓ NEC	1	48.60 ✓ } NEC
11	Rear boot emblem 'i-vtec' ✓ NEC.	1	43.50 ✓ }
12	Rear fender inner trim LH X	1	324.80 X NN
13	Rear fender inner trim LH clip - set ✓ MS	7	20.00 ✓ MS
14	Rear bumper ✓ Deform.	1	647.00 ✓ Deform
15	Rear bumper clip - set ✓ NEC.	1	40.00 ✓ NEC
16	Rear bumper lower centre garnish ✓ TN.	1	99.30 ✓ TN
17	Rear bumper side garnish LH ✓ SCR	1	20.67 ✓ SCR
18	Rear bumper side retainer RH/LH ✓ NEC	2	48.30 ✓ NEC
19	Rear bumper reflector LH ?	1	46.70 X NAD
20	Rear bumper reflector cover LH ?	1	78.30 ✓ CRK
21	Rear bumper reinforcement ✓ BT	1	356.40 ✓ BT
22	Rear tow cover ✓ MS	1	22.20 ✓ MS
23	Rear tail lamp panel LH ?	1	89.20 R
24	Rear tail lamp LH ?	1	267.80 ✓ CRK
25	Rear tail lamp clip - set ?	1	10.00 ✓ NEC
26	Rear tail lamp lower bracket LH ?	1	43.70 X NN
27	Rear end panel ✓ ✓ BT	1	440.00 ✓ BT
28	Rear end panel top garnish ?	1	95.60 ✓ Deform
29	Rear end panel top garnish clip - set ?	1	40.00 ✓ NEC
30	Spare tyre top board X	1	197.80 X NN
Sub-total 1			3,826.87
Discount 20%			3,061.50
31	Rear end panel sealant ✓ NEC.	1	80.00 40. ✓ } NEC
32	Tail lamp sealant ?	1	160.00 30 ✓ }
33	Tail lamp pad ?	2	80.00 40 X NN
34	Car number plate rear holder ✓ SCR.	1	50.00 35 X NN

WENG KEE MOTOR

35 Reverse sensor ✓ ms

3	750.00	600 ✓ ms
Sub-total 2	1,120.00	
Parts total	4,181.50	

Labour

36 To straighten and panel beating rear frame members. To cut/weld rear LH tail lamp and rear end panel. To remove and refit above parts.	1,700.00	900
37 To putty, re-spray painting and polish affected areas.	1,300.00	1000
38 To remove and transfer rear boot lid components.	150.00	50
39 To check and rectify wiring system.	120.00	50
40 To remove and replace reverse sensor and check	120.00	40
41 Remove and replace interior upholstery	750.00	60
42 To rust proof affected areas.	120.00	60

Labour total	3,060.00
Parts & Labour total	7,241.50



Sebastian 3/1/18

- Lump Sum Repair.
- Question Mark Item Photo
- Photo After Paint

90036121

sebastianyang@lkkauto.com

7 days.

LKK Auto Consultants hereby notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

2638.37
- 20%
<u>2110.70</u>
+ 670
+ 2190
<u>4970.70</u>
- 20%
<u>3976.56</u>

L/S : \$ 4000 @ 7 days

confirmed.

...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	22 Dec 2017 Edit Reg		02 Jan 2018 00:00 Edit Adj Rpt	S\$4,000.00 Edit Estimates	S\$4,000.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	Leow Yoon Khean , ID: S16015671								
Main Claimant:	MUHAMMAD IZZUDDIN BIN AMIRRUDDIN , ID: S8719290C								
Vehicle Reg. No.:	SJA7731D	Date of Loss:	21/12/2017 09:00 - :59 [7 Months and 19 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 1994943236SG	Policy/Cover Note No.:	1700072699 (Comprehensive)						
Vehicle Reg. No. (Insured):	SLT5283U	Policy No. (Claimant):							
		Excess:							
Repairer:	Weng Kee Motor (HQ) Block 1019 #01-366 Yishun Ind. Park A, 768761 Yishun - Tel: 6854 1273								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Lee, Ming-Yao] MingYao.Lee@aig.com								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Sathya Sai Kathirrasen] ... [Final Rpt due 15/01/2018]								
Claimant's Solicitor:	CHEONGHOH LAW CORPORATION - Tel: 63378700								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
AIG_SG (05/01/2018): Request To Upload TP GIA Report									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SJA7731D (1994943236SG)**
[SLT5283U]
TP
MUHAMMAD IZZUDDIN BIN AMIRRUDDIN
Dec 21 2017 9:00AM
[Leow Yoon Khean]
Weng Kee Motor

Upload Documents			Upload Photos		Compose New Letter		Upload Video		Upload Audio		View		View in Browser	
Assessment Reports											1 per page		☐	☒
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)										Thumbnail	Print	
1	05/01/18 10:36	Accident Statement From: OD - Reg. No: SLT5283U, Claimant: LEOW YOUN KHEAN									1	Load HTM		
											3 per page		☐	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)										Thumbnail	Print	
1	28/05/18 17:24	General View									1	Load JPG	☒	
2	28/05/18 17:24	General View									1	Load JPG	☒	
3	28/05/18 17:24	General View									1	Load JPG	☒	
4	28/05/18 17:24	General View									1	Load JPG	☒	
5	28/05/18 17:24	General View									1	Load JPG	☒	
6	28/05/18 17:24	General View									1	Load JPG	☒	
7	28/05/18 17:24	General View									1	Load JPG	☒	
8	28/05/18 17:24	General View									1	Load JPG	☒	
9	28/05/18 17:24	General View									1	Load JPG	☒	
10	28/05/18 17:24	General View									1	Load JPG	☒	
11	28/05/18 17:24	General View									1	Load JPG	☒	
12	28/05/18 17:24	General View									1	Load JPG	☒	
13	28/05/18 17:24	General View									1	Load JPG	☒	
14	28/05/18 17:24	General View									1	Load JPG	☒	
15	28/05/18 17:24	General View									1	Load JPG	☒	
16	28/05/18 17:24	General View									1	Load JPG	☒	
17	28/05/18 17:24	General View									1	Load JPG	☒	
18	28/05/18 17:24	General View									1	Load JPG	☒	
19	28/05/18 17:24	General View									1	Load JPG	☒	
20	28/05/18 17:24	General View									1	Load JPG	☒	
21	28/05/18 17:24	General View									1	Load JPG	☒	
22	28/05/18 17:24	General View									1	Load JPG	☒	
23	28/05/18 17:24	General View									1	Load JPG	☒	
24	28/05/18 17:24	General View									1	Load JPG	☒	
25	28/05/18 17:24	General View									1	Load JPG	☒	
26	28/05/18 17:24	General View									1	Load JPG	☒	
27	28/05/18 17:24	General View									1	Load JPG	☒	
28	28/05/18 17:24	General View									1	Load JPG	☒	
29	28/05/18 17:24	General View									1	Load JPG	☒	
30	28/05/18 17:24	General View									1	Load JPG	☒	
31	28/05/18 17:24	General View									1	Load JPG	☒	
32	28/05/18 17:24	General View									1	Load JPG	☒	
33	28/05/18 17:24	General View									1	Load JPG	☒	

Assessment Reports			1 per page	☒
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
34	28/05/18 17:24	General View	 Load JPG	☒
35	28/05/18 17:24	General View	 Load JPG	☒
36	28/05/18 17:24	General View	 Load JPG	☒
37	28/05/18 17:24	General View	 Load JPG	☒
38	28/05/18 17:24	General View	 Load JPG	☒
39	28/05/18 17:24	General View	 Load JPG	☒
40	28/05/18 17:24	General View	 Load JPG	☒
41	28/05/18 17:24	General View	 Load JPG	☒
42	28/05/18 17:24	General View	 Load JPG	☒
43	28/05/18 17:24	General View	 Load JPG	☒
44	28/05/18 17:24	General View	 Load JPG	☒
45	28/05/18 17:24	General View	 Load JPG	☒
46	28/05/18 17:24	General View	 Load JPG	☒
47	28/05/18 17:24	General View	 Load JPG	☒
48	29/06/18 11:27	Dismantled Parts	 Load JPG	☒
49	29/06/18 11:27	Dismantled Parts	 Load JPG	☒
50	29/06/18 11:27	Dismantled Parts	 Load JPG	☒
51	29/06/18 11:27	Dismantled Parts	 Load JPG	☒
52	29/06/18 11:27	Dismantled Parts	 Load JPG	☒
53	29/06/18 11:27	Dismantled Parts	 Load JPG	☒
54	29/06/18 11:27	Dismantled Parts	 Load JPG	☒
55	29/06/18 11:27	Dismantled Parts	 Load JPG	☒
56	29/06/18 11:27	Dismantled Parts	 Load JPG	☒
57	29/06/18 11:27	Dismantled Parts	 Load JPG	☒
58	29/06/18 11:27	Dismantled Parts	 Load JPG	☒
59	29/06/18 11:27	Dismantled Parts	 Load JPG	☒
60	29/06/18 11:27	Dismantled Parts	 Load JPG	☒
61	29/06/18 11:27	Dismantled Parts	 Load JPG	☒
62	29/06/18 11:27	Dismantled Parts	 Load JPG	☒
63	29/06/18 11:27	Dismantled Parts	 Load JPG	☒
64	29/06/18 11:27	Dismantled Parts	 Load JPG	☒
65	29/06/18 11:27	Dismantled Parts	 Load JPG	☒
66	29/06/18 11:27	Dismantled Parts	 Load JPG	☒
67	29/06/18 11:27	Dismantled Parts	 Load JPG	☒
68	29/06/18 11:27	Dismantled Parts	 Load JPG	☒
69	29/06/18 11:27	Dismantled Parts	 Load JPG	☒
70	29/06/18 11:27	Dismantled Parts	 Load JPG	☒
71	29/06/18 11:27	Dismantled Parts	 Load JPG	☒
72	29/06/18 11:27	Dismantled Parts	 Load JPG	☒
73	29/06/18 11:27	Dismantled Parts	 Load JPG	☒
74	29/06/18 11:27	Dismantled Parts	 Load JPG	☒
75	29/06/18 11:27	Dismantled Parts	 Load JPG	☒
76	29/06/18 11:27	Dismantled Parts	 Load JPG	☒
77	29/06/18 11:27	Photo After Spray	 Load JPG	☒
78	29/06/18 11:27	Photo After Spray	 Load JPG	☒
79	29/06/18 11:27	Photo After Spray	 Load JPG	☒

Documents Checklist

DOCUMENTS CHECKLIST

Reset

Save

Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**Show Remarks To:** ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co. Reg. No. 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/AIG18000182/VTBQ2

Date: 14/08/2018

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1700072699
Claimant Vehicle No : SJA7731D **Insured Vehicle No :** SLT5283U
 Date of Loss: 21/12/2017 Nature of Claim: TP Claim No: 1994943236SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJA7731D**
 Make & Model: HONDA CIVIC, 1.6 VTI (A) Engine No: R16B21601640
 Reg. Date: 02/05/2017 (Man. Year: 2017) Chassis No: MRHFC5650GT001335
 Colour: Black Odometer: 19723 km
 Engine Capacity: 1597 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 215/55 R16 Rear Tyre Size: 215/55 R16
 Front Left Side: Hankook 6 mm Rear Left Side: Hankook 6 mm
 Front Right Side: Hankook 6 mm Rear Right Side: Hankook 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,181.50	2,780.70	1,400.80	33.50
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,060.00	2,190.00	870.00	28.43
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,241.50	4,970.70	2,270.80	31.36
Approved Total (Overridden) (S\$)		4,000.00		
Nett Amount (S\$)	7,241.50	4,000.00	3,241.50	44.76

INSPECTION

Date of Assignment: 02/01/2018
 Date Inspected: 03/01/2018 Inspected At: Weng Kee Motor (HQ)
 Block 1019 #01-366 Yishun Ind. Park A
 Singapore 768761
 Estimated Period of Repair: 7.0 days

Adjuster: Sathya Sai Kathirrasen

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT LID OUTER GARNISH	Repair	95.40 FL	*- FL
2	1		*SET REAR BOOT LID OUTER GARNISH CLIP	Necessary	40.00 FL	*40.00 FL
3	2		*REAR BOOT LID ROUND STOPPER	Necessary	30.00 FL	*30.00 FL
4	1		*REAR BOOT WEATHER STRIP	Deformed	126.60 FL	*126.60 FL
5	1		*REAR BOOT LOCK MECHANISM	Jammed	116.80 FL	*116.80 FL
6	1		*REAR BOOT LID LOCK SENSOR	Not Necessary	175.30 FL	*- FL
7	1		*REAR BOOT BUZZER	Not Necessary	99.60 FL	*- FL
8	1		*REAR BOOT LID LAMP LH	Not Necessary	116.00 FL	*- FL
9	1		*REAR BOOT LOGO	Necessary	47.30 FL	*47.30 FL
10	1		*REAR BOOT EMBLEM CIVIC	Necessary	48.60 FL	*48.60 FL
11	1		*REAR BOOT EMBLEM I-VTEC	Necessary	43.50 FL	*43.50 FL
12	1		*REAR FENDER INNER TRIM LH	Not Necessary	324.80 FL	*- FL
13	1		*SET REAR FENDER INNER TRIM LH CLIP (7 SET)	Missing	20.00 FL	*20.00 FL
14	1		*REAR BUMPER	Deformed	647.00 FL	*647.00 FL
15	1		*SET REAR BUMPER CLIP	Necessary	40.00 FL	*40.00 FL
16	1		*REAR BUMPER LOWER CENTRE GARNISH	Torn	99.30 FL	*99.30 FL
17	1		*REAR BUMPER SIDE GARNISH LH	Scratched	20.67 FL	*20.67 FL
18	2		*REAR BUMPER SIDE RETAINER RH/LH	Necessary	48.30 FL	*48.30 FL
19	1		*REAR BUMPER REFLECTOR LH	Not Necessary	46.70 FL	*- FL
20	1		*REAR BUMPER REFLECTOR COVER LH	Cracked	78.30 FL	*78.30 FL
21	1		*REAR BUMPER REINFORCEMENT	Bent	356.40 FL	*356.40 FL
22	1		*REAR TOW COVER	Missing	22.20 FL	*22.20 FL
23	1		*REAR TAIL LAMP PANEL LH	Repair	89.20 FL	*- FL
24	1		*REAR TAIL LAMP LH	Cracked	267.80 FL	*267.80 FL
25	1		*SET REAR TAIL LAMP CLIP	Necessary	10.00 FL	*10.00 FL
26	1		*REAR TAIL LAMP LOWER BRACKET LH	Not Necessary	43.70 FL	*- FL
27	1		*REAR END PANEL	Dented	440.00 FL	*440.00 FL
28	1		*REAR END PANEL TOP GARNISH	Deformed	95.60 FL	*95.60 FL
29	1		*SET REAR END PANEL TOP GARNISH CLIP	Necessary	40.00 FL	*40.00 FL
30	1		*SPARE TYRE TOP BOARD	Not Necessary	197.80 FL	*- FL
31	1		*REAR END PANEL SEALANT	Necessary	80.00 FS	*40.00 FS
32	1		*TAIL LAMP SEALANT	Necessary	160.00 FS	*30.00 FS
33	2		*TAIL LAMP PAD	Not Necessary	80.00 FS	*- FS
34	1		*CAR NUMBER PLATE REAR HOLDER	Not Necessary	50.00 FS	*- FS
35	3		*REVERSE SENSOR	Missing	750.00 FS	*600.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	4,946.87	3,308.37
- List Item Discount on L Items 20.00/20.00% (\$\$)	765.37	527.67
Total Parts (\$\$)	4,181.50	2,780.70

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO STRAIGHTEN AND PANEL BEATING REAR FRAME MEMBERS .TO CUT/WELD REAR LH TAIL LAMP AND REAR END PANEL .TO REMOVE AND REFIT ABOVE PARTS	New	1,100.00	900.00
2	TO PUTTY ,RE-SPRAY PAINTING AND POLISH AFFECTED AREAS	New	1,300.00	1,000.00
3	TO REMOVE AND TRANSFER REAR BOOT LID COMPONENTS	New	150.00	80.00
4	TO CHECK AND RECTIFY WIRING SYSTEM	New	120.00	50.00
5	TO REMOVE AND REPLACE REVERSE SENSOR AND CHECK	New	120.00	40.00
6	REMOVE AND REPLACE INTERIOR UPHOLSTERY	New	150.00	60.00
7	TO RUST PROOF AFFECTED AREAS	New	120.00	60.00
Gross Labour Cost (S\$)			3,060.00	2,190.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >