

ASS. REC. BY:

REF:

CS/AIG18000186/Krb22

Special Instruction:

Surveyor

Mugman

ASSIGNMENT (Office)

From (Person):

Chan Yoke Shi

of

AIG

Date/Time:

2/1/2018

Estimated Cost:

Bill to:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No:

GBM14T

Insured:

SLU 9640R

at Workshop m/s

LH Express

Tel:

90089959 Mr Yeo

of

BIC 5038 AMC #01-405

Policy No:

Claim No:

995369286956003

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

27/12/2017

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

2/1

Person Contacted:

Mr Yeo

Vehicle

IN/OUT

| Date/Time | Action/Instruction () Estimate |
|-----------|---|
| | GBM14T - CS MSG18005570 Gabya Det: 31/3/2015. |
| | SLU 9640R - X |
| 20/12 | 1/Ly @ 52501 Cashm ordk |
| | Ref: \$ 8075.83.61/1. |

* ASS. REC. BY:

REF:

1761

Kenna

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MY

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

05 days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

4/1 1500 hrs to Corium

RECEIVED 7 FEB 2010

Date/Time, File Pass to?

☐

Preil. Report

☒

Final Report

Date/Time, File Return to?

Days Of Repair:

5

Resurvey No. of Trip:

1

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Survey Fee:

Transportation:

S - RS \$

Photos

Others

TOTAL

Report Format:

TP

Lump Sum / LB-I: (\$

5250

Veh No:

SKV 488J

Yr Regn:

06, 14

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toy

Vellone

c.c.

2362

Colour

Silver

A/C:

Insured / Std / NI / NA

Sp. Reading

83929

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

AN1420

8293706

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inoper? / Jammed / Leaked / Burnt or

Brake: Inoper? / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

235/50R18

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

6

mm

Rear

R/Bal.

5

mm

L/Bal.

6

mm

L/Bal.

5

mm

D.O.A.

27/12/17

D.O.I.

3/1/18

Survey held at

Des. of Damages: Fnt / Rear / O/S / N/S / UIC / Rooftop or

O/S M

The UIC / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

Preil. Report

☒

Final Report

Date/Time, File Return to?

Days Of Repair:

5

Resurvey No. of Trip:

1

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Survey Fee:

Transportation:

S - RS \$

Photos

Others

TOTAL

Report Format:

TP

Lump Sum / LB-I: (\$

5250

250

20

270




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile | | | |
|---|-----------------|--------------------------|---|
| AIG ASIA PACIFIC INSURANCE PTE LTD | | Ref : CS/AIG18000186/Krb | |
| 78 SHENTON WAY #08-16 CHARTIS BUILDING SINGAPORE 079120 | | Date : 03-01-2018 |  |
| Code : AIG | | | |
| 1. Policy Particulars :- THIRD PARTY CLAIM | | | |
| Insured Veh. | SLU 9640R | Veh. Inspected | SBM 14T |
| Policy No. | | Coverage (\$) | 0.00 |
| Claim No. | 1994943236SG003 | Excess (\$) | 0.00 |
| Assign From | CHAN YOKE SHI | Assign Date | 02/01/2018 |
| 2. Vehicle Particulars & Condition | | | |
| Make & Model | c.c | | |
| Engine No. | Year of Reg. | | |
| Chassis No. | Colour | | |
| Odometer | Steering | | |
| Brakes | Modification | | |
| General | | | |
| 3. Conditions of Tyres | | | |
| | Size | Make | Balance |
| R/H Front Tyre | | | mm |
| L/H Front Tyre | | | mm |
| R/H Rear Tyre | | | mm |
| L/H Rear Tyre | | | mm |
| 4. Description of Damages | | | |
| | | | |
| 5. General Information | | | |
| Accident Date | 27/12/2017 | Inspection Date | |
| Survey held at | | | |
| 5a. General Remarks | | | |
| | | | |

- Pre repair inspection request - SBM14T VS SLU9640R (OI) DOA 27/12/2017

From: Chan, Yoke Shi
To: assignments, Admin A
Cc: Tan, Lily (AIG), Fong, Andy-SY, Kaur, Baljit, Chin, Lee-Ying, Abu Kassim, Noor Mariesa, Md Ishak, Mohd Imran, Lim, Sheng Yang
Sent: Tuesday, 2 January, 2018 11:21:01 AM
Attachments:  80001 (Notice of Accident).pdf

Hi,

Please refer to the enclosed request from **Cheong Hoh Lee**.

Claim no : 9953692569SG003
Case Owner : KAI JYE WUI

If you have any queries/concerns, please let us know.
Kindly assist to assign Kenneth Kong as Single Joint Expert as requested.

Thank you.

Regards,

Yoke Shi @ Ashley
AIG
Claim Adjuster II, Singapore FNOL, Claims Operations – Auto
Shared Services – Malaysia | Global Business Services

AIG Shared Services (M) Sdn Bhd (887191-D)
Menara Worldwide, Level 12, 198 Jalan Bukit Bintang, 55100 Kuala Lumpur, Malaysia
Tel +6 03 2719 6000 | Ext 1012102

yokeshi.chan@aig.com | www.aig.com

From: Cheong Hoh Lee [mailto:mail@cheonghoh.sg]
Sent: Tuesday, January 02, 2018 11:16 AM
To: Chan, Yoke Shi
Cc: Tan, Lily (AIG); Fong, Andy-SY; Kaur, Baljit; Chin, Lee-Ying; Abu Kassim, Noor Mariesa; Md Ishak, Mohd Imran; Lim, Sheng Yang
Subject: Re: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SLU9640R AND SBM14T ON 27/12/2017

Dear Sir/ Madam,

We refer to the above matter and to your email of even date.

Our client hereby nominate Kenneth Kong of your said email to conduct the pre-repair survey of the damages to our client's vehicle arising out of the above mentioned accident.

Please be informed that our client's vehicle, SBM 14 T is currently laying at our client's workshop, L.H. Express Motor Trading at Blk 5038 Ang Mo Kio Ave 3 #01-405 Ang Mo Kio Industrial Park 2 Singapore 569541. Kindly contact the person in charge Mr Yeo at 9008 9959 before your surveyor attending at the said workshop.

Kindly proceed to do the needful.

Regards,
Melody
Cheonghoh Law Corporation
Blk 53 Chin Swee Road #03-05
Singapore 160053
Tel: 6337 8700
Fax: 6337 3700

Kenneth

Veh Out

On Jan 2, 2018, at 11:04 AM, Chan, Yoke Shi <yokeshi.chan@aig.com> wrote:

Without Prejudice

Your Reference : LCH.my/AMK08-80001.18
Our Reference : 9953692569SG003

Dear Sir/Madam,

We refer to your Notice of Accident of even date.

Measurement printout

Car standard measurement

Beissbarth © * SL

M * R * * OK * TOYOTA AP / 3.00 / 4033 / C

Date: 03.01.2018 14:45:46

Version (program)
v5.0b3100/v5.0b3100Version (FWA)
v5.0b1507Version (target data)
Toyota AP v03.00Serial number
QZ0000178Last service
02.11.2016**Customer**

Company: L H

Vehicle

Registration: SBM 14 T

Order

Vehicle: Toyota AP v03.00
TOYOTA JAPAN * Alphard/Vellfire * ANH20W/GGH20W * 2WD * 18"

| Rear Axle | | Initial Measurement | Target Data | Final Measurement |
|--------------------------|-------|------------------------|-------------------------|----------------------|
| Camber | left | -1°30' | -0°30' [-1°30'] +0°30' | -1°30' |
| | right | -1°48' | | -1°48' |
| Cross Camber | | +0°17' | [0°30'] | +0°18' |
| Individual Toe | left | +0°12' | -0°15' [+0°15'] +0°15' | +0°22' |
| | right | +0°21' | | +0°12' |
| Total Toe | | +0°33' | -0°30' [+0°30'] +0°30' | +0°34' |
| Setback | | -0°01' | | -0°01' |
| Geometrical driving axis | | +0°05' | | |
| Front Axle | | Initial Measurement | Target Data | Final Measurement |
| Castor 20° | left | +6°47' | -0°45' [+5°55'] +0°45' | +6°47' |
| | right | +5°59' | | +5°59' |
| K.P.I. 20° | left | +9°16' | [11°35'] | |
| | right | +9°25' | [11°35'] | |
| Toe out on turns | left | -1°59' | | |
| | right | -1°26' | | |
| Camber | left | +3°11' | -0°45' [-0°15'] +0°45' | +3°14' |
| | right | -1°34' | | -1°34' |
| Cross Camber | | +4°45' | [0°30'] | +4°47' |
| Individual Toe | left | -0°14' | -0°08' [+0°04'] +0°08' | -0°15' |
| | right | -0°17' | | -0°17' |
| Cross Toe | | +0°03' | [0°30'] | +0°01' |
| Total Toe | | -0°32' | -0°15' [+0°08'] +0°15' | -0°32' |
| Setback | | +0°00' | | +0°00' |
| Included Angle 20° | left | +8°03' | | |
| | right | +7°51' | | |

MBUB17170494 / Su Brothers' Motor Workshop - AMK
ENTRY DATE & TIME: 28/12/2017 16:20
SUBMITTED BY: Koh Siew Ling

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 28/12/2017 16:20
Date Of Accident 27/12/2017 17:45
Exact Location Of Accident UPP ALJUNIED RD & MACPHERSON RD JUNCTION
Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number SBM14T
~~Insurance Policyholder~~
Name Of Registered Owner TAN KIM BOON
NRIC No S1414943J
Email Address NOEMAIL
Mobile Phone No (LOCAL) +65-98181414
Alternative Phone No OTHERS-98181414

~~Vehicle Particulars~~
Manufacturer TOYOTA
Model VELLFIRE

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

~~Insurance Company~~
Name of Insurance Company NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage COMPREHENSIVE
Fleet Policy NO
Policy Number 5081067026-01

Cover Note Number

~~Driver~~
Name of Driver TAN KIM BOON
NRIC No S1414943J
Date Of Birth 09/06/1960
Occupation INDOOR
Date Of Driving Pass 23/06/1978
Driving Experience 39 YEARS AND 4 MONTHS
Gender MALE
Mobile Number (LOCAL) +65-98181414
Fax Number
Contact Number OTHERS-98181414
Email Address NOEMAIL

Address 37 CHUAN VIEW
 Postcode 554765
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured OWNER
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 Insurance Company of Driver's Own Vehicle -
 -

General Information of the Accident

Type Of Accident COLLISION - CHANGE/CROSS LANE
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles involved in the accident
 Was any body injured in the Accident? NO
 Was any injured conveyed to hospital by ambulance? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? NO
 If Yes, Please state which Police Station
 Was notice of Intended Prosecution given? NO
 If Yes, against whom?

Driver's Statement of Accident

I WAS TRAVELLING ALONG UPPER ALJUNIED ROAD TOWARDS ALJUNIED ROAD ON THE 3RD LANE OF 4 LANES ROAD. APPROACHING THE JUNCTION WITH MACPHERSON ROAD, THE TRAFFIC LIGHT WAS GREEN SO I PROCEED. SUDDENLY A VEHICLE SLU 9640 R ON MY RIGHT TRYING TO CUT INTO MY LANE. DUE TO HIS FRONT VEHICLE WANTED TO TURN INTO THE RIGHT AND HIS VEHICLE COLLIDED ONTO MY FRONT RIGHT SIDE OF MY VEHICLE.

Attachments

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? NO
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SLU9640R
 Vehicle Make/Model/Colour KIA
 Details Of Properties
 Vehicle Category PRIVATE CAR
 Name of Driver KOH SIONG WEE BENJAMIN
 NRIC/Passport Number S8726869A
 Contact Number 97810998
 Address
 Postcode
 Insurance Company Name
 Nature Of Damage
 No. Of Passenger (Including Driver)

Sketch Plan Pg. 1

SKETCH PLANIMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My Insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my Insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all Insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all Insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



Sketch Plan #2 Pg. 1

SKETCH PLAN

Macpherson
RoadUpper Aljunied
Road
Towards Aljunied
Road Junction
Macpherson
Road

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was travelling along Upper Aljunied Road towards Aljunied Road ~~and~~ on the 2nd lane of 4 lanes road. Approaching the Junction with Macpherson Road the traffic ~~was~~ light was green so I proceeded, suddenly a vehicle SLU 9840R on my right ^{my lane} cut into ^{my lane} due to his front a vehicle wanted to turn into the light and his vehicle collided onto my front right side of my vehicle.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:Driver's Signature
(If driver is not the policyholder)
Date & Time:Reporting Centre Personnel's Signature
Name:
NRIC/PIN No.:

CHANGING BROCHURE/BOOK NO. V3



LH. Express Motor Trading

Blk 5038,, Ang Mo Kio Ind. Park 2 #01-405 Singapore 569541.

Tel: 64817221 Fax: 64816131 Email: dyeolhmotortradind@gmail.com

*Not Authorized
6/1 Sep @ \$250k
Running After Repair*

Tan Kim Boon

37 Chuan View

Singapore 554765

Vehicle No : SBM 14 T

Chassis No : ANH20-8293707

Make : Toyota Vellfire

Year : 2010

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

| QTY | Description | Acknowledged by Repairer Signature: <u>Unit Price</u> | Amount |
|-----|-------------|--|--------|
| | | Date: | |

Estimate Cost Of Repair

| | |
|---|-------------------------------------|
| 1 | Front Bumper |
| 1 | Front Bumper Side Retainers RH |
| 1 | Front Bumper Lower Garnish RH |
| 1 | Headlamp Assy RH |
| 1 | Front Fog Lamp Assy RH |
| 1 | Front Fog Lamp Garnish RH |
| 1 | Front Grille(Chrome) |
| 1 | Front Fender RH |
| 1 | Front Fender Inner Shield RH |
| 1 | Front Door Assy RH |
| 1 | Front Shock Absorber RH |
| 1 | Front Lower Arm RH |
| 1 | Front Knuckle Arm RH |
| 1 | Front Knuckle Bearing <i>350.50</i> |

| | | |
|---------------|--------------------|---|
| <i>Bullem</i> | \$1,280.90 | ✓ |
| <i>n/i</i> | \$85.95 | ✓ |
| <i>Sm</i> | \$167.90 | X |
| <i>CM</i> | \$3,108.85 | ✓ |
| <i>Sm</i> | \$381.50 | X |
| <i>Sm</i> | \$251.80 | X |
| <i>Sm</i> | \$795.80 | X |
| <i>Bu</i> | \$997.60 | ✓ |
| <i>n/i</i> | \$175.90 | ✓ |
| <i>R</i> | \$1,455.70 | X |
| <i>Sm</i> | \$495.00 | X |
| <i>Sm</i> | \$719.80 | X |
| <i>By</i> | \$628.90 | ✓ |
| <i>m</i> | \$566.70 | ✓ |
| | <u>\$11,112.30</u> | |
| less 25% | <u>\$2,778.08</u> | |
| | <u>\$8,334.23</u> | |

Labour Charges

To remove and replaced damaged parts including straightening repositioning replacement parts.

480
\$1,300.00

To putty and spray paint on front accident affected portion.

\$1,500.00 *700*

| | | |
|--|-------------|-----|
| To Spray Anti Rust On Accident Affected Portion | \$280.00 | 301 |
| To remove/refit wire harness, all related connectors. Check proper funtion. Focus headlamps. | \$100.00 | 201 |
| To install front sensor, control unit. Re-connect wires harness. Check function. | nn \$120.00 | X |
| To transfer front door assy mechannisms with motor assembly and all attachments. | nn \$120.00 | X |
| To carry out all wheel alignment and reset settings where necessary to specifications. | \$180.00 | 601 |

Special Nett Item

| | | | |
|----------------------|-----|--------------------|--------|
| Front sensor RH | 5m | \$391.60 | X |
| 1 Front sport rim RH | 11m | \$650.00 | 3508m- |
| 1 Front Tyre RH | 1m | \$350.00 | X |
| Grand Total : | | <u>\$13,325.83</u> | |

...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

| CLAIM SUBFOLDER TRACKING | | | | | | | |
|--------------------------|---|---------------|---|--|--|-------------|---|
| Case | Notified | Est Submitted | Adj Assigned | Adj Rpt | Adj Submitted | Ins Auth'ed | Status |
| Main | 29 Dec 2017 Edit Reg | | 02 Jan 2018 00:00 Edit Adj Rpt | S\$5,250.00 Edit Estimates | S\$5,250.00 View Rpt | | Pending for Survey Report Cancel Case |

| | | | | |
|----------------------|---------------------------|-------------------------------|---------------------------|--------------------------|
| Main | Reference | Claim Details | Documents | Show All |
|----------------------|---------------------------|-------------------------------|---------------------------|--------------------------|

| CLAIM SUBFOLDER DETAILS | | | [Created by adjuster] |
|-----------------------------|---|------------------------|----------------------------|
| Insured: | BENJAMIN KOH SIONG WEE, ID: S8726869A | | |
| Main Claimant: | TAN KIM BOON, ID: S1414943J | | |
| Vehicle Reg. No.: | SBM14T | Date of Loss: | 27/12/2017 17:00 - :59 |
| Claim Type: | TP / 9953692569SG | Policy/Cover Note No.: | 1700086947 (Comprehensive) |
| Vehicle Reg. No. (Insured): | SLU9640R | Policy No. (Claimant): | |
| | | Excess: | |
| Repairer: | LH Express Motor Trading (HQ) BLK 5038 ANG MO KIO AVE 3 #01-405 ANG MO KIO IND. PARK 2, 569541 Ang Mo Kio - Tel: | | |
| Handling Insurer: | AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Wui, Shawn-KJ] Shawnkaijye.Wui@aig.com | | |
| Adjuster: | LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 15/01/2018] | | |
| Claimant's Solicitor: | CHEONGHOH LAW CORPORATION - Tel: 63378700 | | |

| ASSOCIATED MAIL RECEIVED | View All | Compose Case Mail |
|--|--------------------------|-----------------------------------|
| • AIG_SG (05/01/2018): Request To Upload TP GIA Report | | |

| ALL ASSOCIATED TASKS | | | | | | | | | | View All | Search Tasks | Create New Task | Complete |
|----------------------|----------|------|------------|---------|---------|-------------|--------------|------------|-------|--------------------------|------------------------------|---------------------------------|--------------------------|
| Due Date | Priority | Type | Task Group | Subject | Handler | Assigned By | Completed On | Created On | Done? | | | | |
| No results. | | | | | | | | | | | | | |

Claim Documents

*SBM14T (9953692569SG)
[SLU9640R]
TP
TAN KIM BOON
Dec 27 2017 5:00PM
[BENJAMIN KOH SIONG WEE]
LH Express Motor Trading

| | | | | |
|---|----------------|---|---|-------------------------------|
| Upload Documents Upload Photos Compose New Letter Upload Video Upload Audio | | | View View in Browser ▼ | |
| Assessment Reports | | | 1 per page ▼ | |
| No | Finalized On | AIG Asia Pacific Insurance Pte. Ltd. (SG) | | Thumbnail Print |
| 1 | 05/01/18 10:30 | Accident Statement From:OD - Reg. No: SLU9640R, Claimant: KOH SIONG WEE, BENJAMIN | | Load HTM |

Documents Checklist

| | |
|--|--|
| DOCUMENTS CHECKLIST | Reset Save Print |
| There are no document checklists configured. | |

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

//

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/AIG18000186/KRBE2**Date:** 26/02/2018**REFERENCE**

| | | | |
|-----------------------|--------------------------------------|----------------------|--------------|
| Handling Insurer: | AIG Asia Pacific Insurance Pte. Ltd. | Policy No: | 1700086947 |
| Claimant Vehicle No : | SBM14T | Insured Vehicle No : | SLU9640R |
| Date of Loss: | 27/12/2017 | Nature of Claim: | TP |
| | | Claim No: | 9953692569SG |

DESCRIPTION & IDENTIFICATION OF VEHICLE

| | | | |
|-----------------------------|-----------------------------------|-------------|--------------|
| Reg No: | SBM14T | Engine No: | 2AZG229687 |
| Make & Model: | TOYOTA VELLFIRE, 2.4 V (A) | Chassis No: | ANH208293706 |
| Reg. Date: | 19/06/2014 (Man. Year: 2013) | Odometer: | 83929 km |
| Colour: | Metallic Silver | | |
| Engine Capacity: | 2362 cc | | |
| Market Value/New Car Price: | N/A | | |
| Sum Insured (\$\$): | Market Value/New Car Price | | |

CONDITION OF VEHICLE AT THE TIME OF SURVEY

| | | | | |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition: | Steering (Serviceable): | Yes | Footbrake (Serviceable): | Yes |
| Handbrake (Serviceable): | Yes | Engine Modification: | No | Pre-accident Condition: |

CONDITION OF TYRES

| | | | |
|-------------------|---------------|------------------|---------------|
| Front Tyre Size: | 235/50 R18 | Rear Tyre Size: | 235/50 R18 |
| Front Left Side: | Yokohama 6 mm | Rear Left Side: | Yokohama 5 mm |
| Front Right Side: | Yokohama 6 mm | Rear Right Side: | Yokohama 5 mm |

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|---|-------------------|-------------------|-------------------|---------------|
| Parts | 9,725.82 | 5,321.45 | 4,404.37 | 45.29 |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 3,600.00 | 1,290.00 | 2,310.00 | 64.17 |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Calculated Gross Total (\$\$) | 13,325.82 | 6,611.45 | 6,714.37 | 50.39 |
| Approved Total (Overridden) (\$\$) | | 5,250.00 | | |
| Nett Amount (\$\$) | 13,325.82 | 5,250.00 | 8,075.82 | 60.60 |

INSPECTION

| | | |
|-----------------------------|--------------------------|--|
| Date of Assignment: | 02/01/2018 | LH Express Motor Trading (HQ) |
| Date Inspected: | 03/01/2018 Inspected At: | BLK 5038 ANG MO KIO AVE 3 #01-405 ANG MO KIO |
| | | IND. PARK 2 |
| | | Singapore 569541 |
| Estimated Period of Repair: | 5.0 days | |

Adjuster: KENNETH KONG**Manager:** Janice Lee Si Hua

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|-----|-----|----------|---------------------------------|-------------------|-------------|--------------|
| 1 | 1 | | *FRONT BUMPER | Buckled / Cracked | 1,280.90 FL | *1,280.90 FL |
| 2 | 1 | | *FRONT BUMPER SIDE RETAINERS RH | Distorted | 85.95 FL | *85.95 FL |
| 3 | 1 | | *FRONT BUMPER LOWER GARNISH RH | Serviceable | 167.90 FL | *- FL |
| 4 | 1 | | *HEADLAMP ASSY RH | Cracked | 3,108.85 FL | *3,108.85 FL |
| 5 | 1 | | *FRONT FOG LAMP ASSY RH | Serviceable | 381.50 FL | *- FL |
| 6 | 1 | | *FRONT FOG LAMP GARNISH RH | Serviceable | 251.80 FL | *- FL |
| 7 | 1 | | *FRONT GRILLE (CHROME) | Serviceable | 795.80 FL | *- FL |
| 8 | 1 | | *FRONT FENDER RH | Buckled | 997.60 FL | *997.60 FL |
| 9 | 1 | | *FRONT FENDER INNER SHIELD RH | Distorted | 175.90 FL | *175.90 FL |
| 10 | 1 | | *FRONT DOOR ASSY RH | Repair | 1,455.70 FL | *- FL |
| 11 | 1 | | *FRONT SHOCK ABSORBER RH | Serviceable | 495.00 FL | *- FL |
| 12 | 1 | | *FRONT LOWER ARM RH | Serviceable | 719.80 FL | *- FL |
| 13 | 1 | | *FRONT KNUCKLE ARM RH | Bent | 628.90 FL | *628.90 FL |
| 14 | 1 | | *FRONT KNUCKLE BEARING | Necessary | 566.70 FL | *350.50 FL |
| 15 | 1 | | *FRONT SENSOR RH | Serviceable | 391.60 FS | *- FS |
| 16 | 1 | | *FRONT SPORT RIM RH | Dented | 650.00 FS | *350.00 FS |
| 17 | 1 | | *FRONT TYRE RH | Serviceable | 350.00 FS | *- FS |

F=Franchise part. S=SpcNett. L=ListItemDisc.

| | | |
|---|-----------|----------|
| Sub Total (\$\$) | 12,503.90 | 6,978.60 |
| - List Item Discount on L Items 25.00/25.00% (\$\$) | 2,778.08 | 1,657.15 |
| Total Parts (\$\$) | 9,725.82 | 5,321.45 |

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|------------------------|--|----------|------------|----------|
| Labour Items | | | | |
| 1 | TO REMOVE AND REPLACED DAMAGED PARTS INCLUDING STRAIGHTENING REPOSITIONING REPLACEMENT PARTS | New | 1,300.00 | 480.00 |
| 2 | TO PUTTY AND SPRAY PAINT ON FRONT ACCIDENT AFFECTED PORTION | New | 1,500.00 | 700.00 |
| 3 | TO SPRAY ANTI RUST ON ACCIDENT AFFECTED PORTION | New | 280.00 | 30.00 |
| 4 | TO INSTALL FRONT SENSOR, CONTROL UNIT. RE-CONNECT WIRES HARNESS. CHECK FUNCTION | New | 120.00 | 0.00 |
| 5 | TO TRANSFER FRONT DOOR ASSY MECHANISMS WITH MOTOR ASSEMBLY AND ALL ATTACHMENTS | New | 120.00 | 0.00 |
| 6 | TO CARRY OUT ALL WHEEL ALIGNMENT AND RESET SETTINGS WHERE NECESSARY O SPECIFICATIONS | New | 180.00 | 60.00 |
| 7 | TO REMOVE/REFIT WIRE HARNESS, ALL RELATED CONNECTORS. CHECK PROPER FUNCTION. FOCUS HEADLAMPS | New | 100.00 | 20.00 |
| Gross Labour Cost (\$) | | | 3,600.00 | 1,290.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >