

REF:

173/ALH18000188/Arb

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To inspect Vehicle No: _____
 at Workshop n/s _____
 of _____
 Insured _____
 Policy No: 1700050662
 Claims No: 136728087156
 Sum Insured: _____ Excess: 80.00
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.

Bal. or Market Value: 128K
 IDAC Accident Report: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: 05 885 days Res: Yes or No
 Lum Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SL51817L Yr Regn: 2017 Sept
 Type: M Car M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: Audi A3 Sedan cc: 999
 Colour: Blue A/C: Insured / Std / NI / NA
 Sp. Reading: 4872 T.Radio: Insured / Std / NI / NA
 Eng No: _____
 C.No: WAUZZZ8V3J1010810
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brakes: In order / Jammed / Leaked / Burnt or
 Mod: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 205/55R16
 R: 205/55R16
BS DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or

Front: _____ Rear: _____
 R/Bal: 06 mm R/Bal: 06 mm
 L/Bal: 06 mm L/Bal: 06 mm
 D.O.A. _____ D.O.I. 03/01/18
 Survey held at: Premium
 Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or
Front o/s, u/c
 The UIC / Chassis frame / Body Structure affected due to collision:

Date / Time Action / Instruction

00 AIG

SL5 1817L - x

Revert through menimen; seek mandate
 5/1/17 Mandate approve; Inform repenver proceed to repair

Confirm \$10,603.60, 5 days
 Red: \$13,737.00, 567.

RECEIVED 20 MAR 2018

Date/Time: File Pass to?

☐

Prel. Report

1) Input

☒

Final Report

Date/Time: File Return to?

2)

Days Of Repair: 5Resurvey No. of Trip: 1

Survey Fee:

Transportation:

_____ B + RS _____ B

Photo:

Other:

Add Fee:

☐

Site Insp: \$

☐

Interview: \$

☐

Tech. Insp: \$

☐

Weekend: \$

Report Format: 0DLump Sum / I.B.I: \$ 13,737.00

TOTAL:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AIG ASIA PACIFIC INSURANCE PTE LTD

Ref : CC3/AIG18000188/Arb

78 SHENTON WAY #08-16
CHARTIS BUILDING
SINGAPORE 079120

Date : 03-01-2018



Code : AIG

1. Policy Particulars :- OWN DAMAGE

Insured Veh.	Veh. Inspected	SLS 1817L
Policy No. 1700050662	Coverage (\$)	0.00
Claim No.	Excess (\$)	0.00
Assign From	Assign Date	03/01/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No. HIDDEN	Year of Reg.	
Chassis No.	Colour	
Odometer -	Steering	
Brakes	Modification	
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date 31/12/2017	Inspection Date 03/01/2018
Survey held at PREMIUM AUTOMOBILES PTE LTD 55 UBI ROAD 1 SINGAPORE 408699	

5a. Remarks

A) THE MARKET VALUE IS S\$----- (EST. AVERAGE)
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.

Note: This document has not been finalised.
LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
AIG Building
78 Shenton Way #07-16
Singapore 079120

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Loo, Tong Shing

Date: 04 Jan 2018

Preliminary Advice

Vehicle No	: SLS1817L	Accident Date	: 31/12/2017
Make	: AUDI A3	Policy No.	: 1700050662
Assignment Date	: 03/01/2018	Excess	: S\$0.00
Date of Inspection	: 03/01/2018	Est. Duration of Repair	: 5.00
Inspection At	: PREMIUM AUTOMOBILES PTE LTD (UBI) 55 UBI ROAD 1 SINGAPORE 408699		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front o/s portion and undercarriage and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	24,178.00
Revised Amount	:S\$	12,245.00
Check Items (Estimated)	:S\$	8,968.00
Total	:S\$	21,213.00
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	128,000.00
COE / PARF Rebate	:S\$	56,376.00
Salvage Value	:S\$	
Margin for Repair	:S\$	71,624.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	7238A
Vehicle Details	
Vehicle No.:	SL51817L
Vehicle to be Exported:	No
Intended De-registration Date:	04 Jan 2018
Vehicle Make:	AUDI
Vehicle Model:	A3 SEDAN 1.0 TFSI S TRONIC (LED & NAV)
Primary Colour:	Blue
Manufacturing Year:	2017
Engine No.:	CHZ525661
Chassis No.:	WAUZZZ8V3J1010810
Maximum Power Output:	85.0 kW (113 bhp)
Open Market Value:	\$26,975.00
Original Registration Date:	12 Sep 2017
First Registration Date:	12 Sep 2017
Transfer Count:	0
Actual ARF Paid:	\$19,765.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	11 Sep 2027
PARF Rebate Amount:	\$14,823.00
Intended COE Rebate Details	
COE Expiry Date:	11 Sep 2027
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$42,900.00
COE Rebate Amount:	\$41,553.00
Total Rebate Amount:	\$56,376.00

The information contained herein is correct as at 04 Jan 2018

OK

Print Received Message

This mail is associated with :

***SLS1817L (1367280871SG)**

OD

Dec 31 2017 2:15PM

[TAN WEI CHENG ALVIN]

Premium Automobiles Pte Ltd

From AIG Asia Pacific Insurance Pte. Ltd. (AIG_SG), sent on 04/01/2018 14:46 PM.
To LKK_HQ
Subject SLS1817L / OD / 31/12/2017 / Coverage & Excess update

Dear LKK Auto Consultants Pte Ltd

Please note that policy is in force and excess amount is \$0.00

Thank you
Loo, Tong Shing

Print Received Message

This mail is associated with :

***SLS1817L (1367280871SG)**

OD

Dec 31 2017 2:15PM

[TAN WEI CHENG ALVIN]

Premium Automobiles Pte Ltd

From AIG Asia Pacific Insurance Pte. Ltd. (AIG_SG), sent on 04/01/2018 17:15 PM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$12245.00) - SLS1817L - Claim Handler: Loo, Tong Shing

Approved:12245.00:Re-inspect and upload damage photos of FRONT BUMPER GRILLE - CENTRE. Re-inspection to be done for damage check and supplementary items / labour.

Janice Lee (LKKAuto)

From: Janice Lee (LKKAuto)
Sent: Friday, January 05, 2018 8:57 AM
To: 'Claims Dept'
Cc: SUR
Subject: RE: SLS 1817 L Own Damage Claims **Vehicle IN**

Dear Sir,

As instructed by our client, please proceed to repair the insured vehicle **SLS 1817L (excess \$0.00/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Thank you.

Best Regards,

Janice Lee (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: janicelee@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claims Dept [mailto:claims@premiumauto.com.sg]
Sent: Friday, January 05, 2018 8:20 AM
To: SUR <sur@lkkauto.com>
Cc: claims@premiumauto.com.sg
Subject: RE: SLS 1817 L Own Damage Claims **Vehicle IN**

Dear all,

Any update on the approval for this case?

Kindly chase AIG for the approval urgently.

Many thanks!

Best regards,
Jeffery Tan

Premium Automobiles Pte Ltd (Reg No 199902211W)
55 Ubi Road 1 Road Singapore 408699
p. +65 6388 2323 d. +65 6768 9911 f. +65 6841 1183
e. claims@premiumauto.com.sg w. www.audi.com.sg



Email Disclaimer

This email, including any attachment, is confidential and may also be privileged.
If you have received it in error, please notify us immediately by reply email and then delete this message from your system.
Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you

From: Claims Dept [<mailto:claims@premiumauto.com.sg>]

Sent: Wednesday, 3 January, 2018 11:20 AM

To: 'SUR' <sur@lkkauto.com>

Cc: claims@premiumauto.com.sg

Subject: SLS 1817 L Own Damage Claims **Vehicle IN**

Dear all,

Survey was carried out earlier this morning.

Kindly assist in the approval from AIG for this case urgently as the vehicle is in the workshop pending approval before we can proceed to repair the vehicle.

Many thanks!

Best regards,
Jeffery Tan

Premium Automobiles Pte Ltd (Reg No 199902271W)

55 Ubi Road 1 Road Singapore 408699

p. +65 6388 2323 d. +65 6768 9911 f. +65 6841 1183

e. claims@premiumauto.com.sg w. www.audi.com.sg

Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65 6836 2223



Email Disclaimer

This email, including any attachment, is confidential and may also be privileged.
If you have received it in error, please notify us immediately by reply email and then delete this message from your system.
Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	02/01/2018 11:51
Date Of Accident	31/12/2017 14:15
Exact Location Of Accident	SIMS AVENUE (BUS STOP 81031)
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLS1817L
Insured/Policyholder	
Name Of Registered Owner	TAN WEI CHENG ALVIN
NRIC No	S8917238A
Email Address	ALVINTANWC1989@GMAIL.COM
Mobile Phone No	(LOCAL) +65-97663687
Alternative Phone No	OTHERS-97663687

Vehicle Particulars

Manufacturer	AUDI
Model	A3 SEDAN 1.0 TFSI
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	1700050662
Cover Note Number	

Driver


Name of Driver	TAN WEI CHENG ALVIN
NRIC No	S8917238A
Date Of Birth	23/05/1989
Occupation	INDOOR
Date Of Driving Pass	01/08/2011
Driving Experience	6 YEARS AND 4 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97663687
Fax Number	
Contact Number	OTHERS-97663687
EEmail Address	ALVINTANWC1989@GMAIL.COM

Nature Of Damage

No. Of Passenger (Including Driver)

Sketch Plan #2

SKETCH PLAN



A: 5LS 1817L

B: 54C 726D

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was driving on Sms Avenue on bus lane on 31st December 2017 at about 2pm. I was driving at a low speed and there was a car in the next lane that suddenly swerved into my lane without signals signalling. I had already jammed brake but it was too late impact from car drove my car up the kerb Video ~~to~~ from in-car camera to provide more evidence

DECLARATION

I/We declare the foregoing particulars are true in every respect.


Policyholder's Signature
Date & Time: 2/1/17, 9.03am

Driver's Signature
(If driver is not the policyholder)
Date & Time


Reporting Centre Personnel's Signature
Name: Tony Fong
NRIC/IN No: 670451471

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S8917238A



Name
TAN WEI CHENG, ALVIN

陳偉程

Race
CHINESE

Date of birth
23-05-1989

Sex
M

Country of birth
SINGAPORE

REPUBLIC OF SINGAPORE DRIVING LICENCE

Licence Number: S8917238A

Name:
TAN WEI CHENG, ALVIN

Birth Date: 23 May 1989

Issue Date: 01 Aug 2011




001957112A



58917238A



Date of issue
03-05-2004

Address
APT BLK 244 TAMPINES STREET 21
#12-379
SINGAPORE 521244

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

EFFECTIVE DATE

Class 3 Motor Cars $\leq$ 3000kg with $\leq$ 7 passengers, exclusive of the driver, and other motor vehicles $\leq$ 2500kg 01 Aug 2011

NP 428A



Licence No: S8917238A

AIG**COVER NOTE****AUDI AUTO PROTECTOR PRIVATE VEHICLE**The following is described on this Cover Note, hereby **DECLARED** to the terms and conditions of the policy issued to the Policyholder.

Name of Policyholder : **TAN WEI CHENG, ALVIN**
 Period of Insurance : **13 Sep 2017 to 11 Sep 2018**
 Engine No. : **CH2525661**
 Chassis No. : **WAUZZZ8V3J1010810**

Vehicle No. : **SLS1817L**
 Cover Note No. : **1700050662**
 Endorsement No. :
 Issued Date : **11 Sep 2017**

ABOUT THE COVER

Make/Model : **AUDI A3 Sedan 1.0 TFSI S tronic**
 Engine Capacity/Tonnage : **999.00 CC** Sum Insured : **Market Value** First Year of Registration : **2017**
 Driver Restriction : **NA** Off Peak Car : **No** Insuring with COE/PAF : **Yes**

Person or Classes of Persons Entitled to Drive* :

a) The Policyholder

b) Any other person who is driving on the Policyholder's order or with his/her permission

This Policy will indemnify the Policyholder or any authorized driver only if he/she meets the specified age condition.

You have to pay an additional sum of \$3,000 as "Young and/or Inexperienced Driver Excess" ("YIDR") if You are or Your Authorized Driver (named or unnamed) is under the age of 22 and/or has less than 2 years' driving experience.

Age Condition : **All Age Condition**

Limitation as to use*

Use only for social, domestic and pleasure purposes and for the Policyholder's business.

This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

Loss of Use

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third Party Risks and Compensation) Act (Cap. 186) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS**Section 1**

Fire - \$0. Own Damage - \$600. Theft - \$0. Flood Cover - \$0.

Section 2

Property Damage - \$0.

Windscreen : \$100.

Named Driver and Excess (where applicable)

TAN WEI CHENG, ALVIN - \$600 (Own Damage)

APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

1. Audi Customer Service Center Add: 55 Ubi Road 1 Singapore +65 699 63662222

For other Approved Reporting Centres/AIG Authorized Repairers, please contact our 24-hour accident emergency hotline at +65 6338 6200. Alternatively, you may refer to AIG website www.aig.com.sg or AIG SG Mobile App. Simply search and download "AIG SG" from iTunes or Google Play.**IMPORTANT NOTES**Hire Purchase Company/Employer's Loan : **United Overseas Bank Limited**

If you do not receive your Certificate of Insurance and policy documents within 30 days from the inception date stated on this cover note, please contact us immediately.
 (We hereby certify that this Cover Note is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Cap. 186), Part IV of the Road Transport Act, 1987 (Malaysia) and Motor Vehicles (Third Party Risks) Rules, 1959 (Malaysia). For Corporate Policies, this Cover Note is valid for 60 days from the commencement date of the period of insurance.)

0504125276

PREMIUM LEASING - SCS

281 ALEXANDRA ROAD AUDI CUSTOMER SERVICE CENTRE

SINGAPORE 159938

Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

AIG Asia Pacific Insurance Pte. Ltd.AUTHORISED REPRESENTATIVE *Cheng Guan Yee*78 Shenton Way #07-18 AIG Building S078120 | T +65 6419 3000 | F +65 6415 5723 | www.aig.com.sg

AIG Asia Pacific Insurance Pte. Ltd.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate	:	Accident Repairs
Workshop	:	Ubi Road 1
Contact No	:	6366 2323
Fax No	:	6841 1183
Reference	:	PA/OD/0005/2018/JT
Date	:	2-Jan-18

Vehicle IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name	:	Mr. Alvin Tan Wei Cheng Alvin
Address	:	3 Elias Green #12-06 Singapore 519960
Telephone	:	HP +65 9766 3687
Type of Claim	:	Own Damage Claims
Policy No.	:	1700050662
Vehicle No	:	SLS 1817 L
Model Code	:	Audi A3 Sedan 1.0 TFSI (A)
Model / Year	:	Sep-17
Engine No	:	CHZ 525661
Chassis No	:	WAUZZZ8V3J1010810
Mileage	:	
Date In	:	2-Jan-18
Liability	:	-
Excess Cost	:	-
Estimated By	:	Johnny Boo / Allan Wu
Accident Date	:	31-Dec-17
Place of Accident	:	Sims Avenue (Bus Stop 81031)

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLS 1817 L.

S/n	Nature of Jobs		Estimated Charges	Surveyor's Recommendation
1	To remove and transfer front wire harness for headlights, horns, fog lamps, outside temperature sensor and headlight washer assy.	S/N \$	360.00	✓ 360
2	To dismantle and renew front bumper, RHS front fender and RHS headlight. Re-organize front crash management components. Reinstall all parts removed.	\$	2,100.00	1250 1250
3	To respray front bumper, RHS front fender and bonnet. x	\$	2,100.00	1100 1100
4	To dismantle front suspension assy. Inspect for damages and renew accordingly.	S/N \$	2,400.00	? X
5	To renew RHS front rim and tire. Carry out wheel alignment.	S/N \$	280.00	✓ 280
6	To carry out diagnostic checks.	S/N \$	192.00	✓ 192
TOTAL LABOUR CHARGES		:	<u>\$ 7,432.00</u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLS 1817 L.

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
1	FRONT BUMPER <i>Reformed</i>	\$ 1,667.00 ✓	1333.60
2	FRONT BUMPER GUIDE - RHS <i>258 MV</i>	\$ 31.00 +	X
3	FRONT BUMPER GRILLE - CENTRE <i>Not in</i>	\$ 133.00 ✓	106.00
4	FRONT BUMPER LOWER CLOSING ELEMENT <i>Not in</i>	\$ 445.00 +	} X
5	FRONT BUMPER END PLATE - RHS <i>Not in</i>	\$ 246.00 +	
6	FRONT BUMPER TRIM - LHS/RHS	\$ 270.00 +	
7	FRONT WHEEL HOUSE LINER SPOILER - RHS <i>Not in</i>	\$ 31.00 ?	
8	FRONT BUMPER AIR GRILLE - RHS <i>came</i>	\$ 156.00 ✓	124.40
9	FRONT FENDER - RHS <i>Distorted</i>	\$ 708.00 ✓	566.00
10	FRONT FENDER INNER BRACKET - RHS <i>?</i>	\$ 33.00 ✓	25.76
11	FRONT FENDER OUTER BRACKET - RHS <i>Bent</i>	\$ 23.00 ✓	18.16
12	FRONT FENDER BRACE - RHS	\$ 81.00 ✓	64.80
13	FRONT WHEEL HOUSE LINER - RHS <i>2nd</i>	\$ 146.00 ✓	116.80
14	WHEEL HOUSE LINER ATTACHEMENT - RHS <i>Not in</i>	\$ 75.00 ?	X
15	LED HEADLIGHT - RHS <i>cut</i>	\$ 5,458.00 ✓	4366.40
16	HEADLIGHT WASHER - RHS <i>not in</i>	\$ 123.00 +	
17	FRONT ALUMINIUM RIM - RHS <i>cut</i>	\$ 658.00 ✓	527.20
18	FRONT TRACK ARM - RHS <i>Not in</i>	\$ 318.00 ?	} X
19	FRONT WHEEL BEARING HOUSING - RHS <i>Not in</i>	\$ 502.00 ?	
20	FRONT WHEEL BEARING - RHS <i>Not in</i>	\$ 375.00 ?	
SUB TOTAL SPARE PARTS CHARGES		\$ 11,479.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLS 1817 L.

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
21	FRONT GUIDE ARM - RHS <i>Not Nec</i>	\$ 110.00 ?	} X
22	STEERING RACK <i>Not Nec</i>	\$ 4,225.00 ?	
23	STEERING RACK REPAIR KIT <i>Not Nec</i>	\$ 40.00 ?	
24	STEERING RACK TRACK ROD - RHS <i>Not Nec</i>	\$ 82.00 ?	
25	TIE ROD - RHS <i>Not Nec</i>	\$ 110.00 ?	
26	FRONT TIRE - RHS <i>per car</i>	TBC	1
27	SUSPENSION BOLTS AND NUTS <i>Not Nec</i>	\$ 300.00 ?	125.00 X
28	SUNDRIES <i>Nec.</i>	\$ 400.00 ?	46.88
TOTAL SPARE PARTS CHARGES :		\$ 16,746.00	
TOTAL LABOUR CHARGES		\$ 7,432.00	
GRAND TOTAL		\$ 24,178.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adrian King.
Surveyed Date : 03/01/18
Authorised Date :
Excess Cost :
Liability :
Remarks : Not Authorised, 05 Days.

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183
Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Supplementary Estimate

GST Reg No. 16-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 / Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/0005/2016/JT 8-Feb-18 CHANG 1 of 1 SLS 1817 L Audi A3 SEDAN 1.0 TFSI
Quantity	Description	Unit Price	Amount
<u>Parts</u>			
1	FRONT BUMPER FOAM <i>Reband</i>	\$ 162.00	✓ 125.60
	TOTAL PARTS :	\$ 162.00	
	GRAND TOTAL :	\$ 162.00	

Adrian Ling
S.S.

For Premium Automobiles Pte Ltd



[Signature]

Authorised Signature

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate	:	Accident Repairs
Workshop	:	Ubi Road 1
Contact No	:	6366 2323
Fax No	:	6841 1183
Reference	:	PA/OD/0005/2018/JT
Date	:	02-Jan-18

Vehicle IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Hi Adrian

5 days - ok - jb 17 Mar 18

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name	:	Mr. Alvin Tan Wei Cheng Alvin
Address	:	3 Elias Green #12-06 Singapore 519960
Telephone	:	HP +65 9766 3687
Type of Claim	:	Own Damage Claims
Policy No.	:	1700050662
Vehicle No	:	SLS 1817 L
Model Code	:	Audi A3 Sedan 1.0 TFSI (A)
Model / Year	:	Sep-17
Engine No	:	CHZ 525661
Chassis No	:	WAUZZZ8V3J1010810
Mileage	:	
Date In	:	02-Jan-18
Liability	:	-
Excess Cost	:	-
Estimated By	:	Johnny Boo / Allan Wu
Accident Date	:	31-Dec-17
Place of Accident	:	Sims Avenue (Bus Stop 81031)

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLS 1817 L.

S/n	Nature of Jobs		Estimated Charges	Surveyor's Recommendation
1	To remove and transfer front wire harness for headlights, horns, fog lamps, outside temperature sensor and headlight washer assy.	S/N	\$ 360.00	\$ 360.00
2	To dismantle and renew front bumper, RHS front fender and RHS headlight. Re-organize front crash management components. Reinstall all parts removed.		\$ 2,100.00	\$ 1,250.00
3	To respray front bumper, RHS front fender and bonnet.		\$ 2,100.00	\$ 1,100.00
4	To dismantle front suspension assy. Inspect for damages and renew accordingly.	S/N	\$ 2,400.00	NN
5	To renew RHS front rim and tire. Carry out wheel alignment.	S/N	\$ 280.00	\$ 280.00
6	To carry out diagnostic checks.	S/N	\$ 192.00	\$ 192.00
TOTAL LABOUR CHARGES		:	<u>\$ 7,432.00</u>	<u>\$ 3,182.00</u>

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLS 1817 L.

S/N	Parts Description	<u>Damaged Parts & Prices</u>	
		S/Nett	Remark
1	FRONT BUMPER	\$ 1,667.00	\$ 1,333.60
2	FRONT BUMPER GUIDE - RHS	\$ 31.00	
3	FRONT BUMPER GRILLE - CENTRE	\$ 133.00	\$ 106.00
4	FRONT BUMPER LOWER CLOSING ELEMENT	\$ 445.00	
5	FRONT BUMPER END PLATE - RHS	\$ 246.00	
6	FRONT BUMPER TRIM - LHS/RHS	\$ 270.00	
7	FRONT WHEEL HOUSE LINER SPOILER - RHS	\$ 31.00	
8	FRONT BUMPER AIR GRILLE - RHS	\$ 156.00	\$ 124.40
9	FRONT FENDER - RHS	\$ 708.00	\$ 566.00
10	FRONT FENDER INNER BRACKET - RHS	\$ 33.00	\$ 25.76
11	FRONT FENDER OUTER BRACKET - RHS	\$ 23.00	\$ 18.16
12	FRONT FENDER BRACE - RHS	\$ 81.00	\$ 64.80
13	FRONT WHEEL HOUSE LINER - RHS	\$ 146.00	\$ 116.80
14	WHEEL HOUSE LINER ATTACHEMENT - RHS	\$ 75.00	
15	LED HEADLIGHT - RHS	\$ 5,458.00	\$ 4,366.40
16	HEADLIGHT WASHER - RHS	\$ 123.00	
17	FRONT ALUMINIUM RIM - RHS	\$ 658.00	\$ 527.20
18	FRONT TRACK ARM - RHS	\$ 318.00	
19	FRONT WHEEL BEARING HOUSING - RHS	\$ 502.00	
20	FRONT WHEEL BEARING - RHS	\$ 375.00	
SUB TOTAL SPARE PARTS CHARGES		\$ 11,479.00	\$ 7,249.12

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLS 1817 L.

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
	c/f	\$	7,249.12
21	FRONT GUIDE ARM - RHS	\$ 110.00	
22	STEERING RACK	\$ 4,225.00	
23	STEERING RACK REPAIR KIT	\$ 40.00	
24	STEERING RACK TRACK ROD - RHS	\$ 82.00	
25	TIE ROD - RHS	\$ 110.00	
26	FRONT TIRE - RHS	TBC	
27	SUSPENSION BOLTS AND NUTS	\$ 300.00	
28	SUPPLEMENTARY	\$ 162.00	\$ 125.60
29	SUNDRIES	\$ 400.00	\$ 46.88
TOTAL SPARE PARTS CHARGES :		\$ 16,908.00	\$ 7,421.60
TOTAL LABOUR CHARGES		\$ 7,432.00	\$ 3,182.00
GRAND TOTAL		\$ 24,340.00	\$ 10,603.60

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Net.

Premium Automobiles

55-Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Supplementary Estimate

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 / Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/0005/2018/JT 08-Feb-18 CHANG 1 of 1 SLS 1817 L Audi A3 SEDAN 1.0 TFSI
Quantity	Description	Unit Price	Amount
<u>Parts</u>			
1	FRONT BUMPER FOAM	\$ 162.00	\$ 125.60
	TOTAL PARTS :	\$ 162.00	\$ 125.60
	GRAND TOTAL :	\$ 162.00	

For Premium Automobiles Pte Ltd

Authorised Signature

Janice Lee (LKKAUTO)

From: Boo seng yak <boojohnny@gmail.com>
Sent: Saturday, March 17, 2018 4:42 PM
To: Adrian Ling (LKKAUTO); Janice Lee (LKKAUTO); SUR; Carrine Leong; Nora Khai
Subject: FINAL REVISION SLS1817L - OD AIG - SURVEYED 3 JAN 18
Attachments: PA00052018 - SLS 1817 L - Audi A3 Sedan 1.0 TFSI (A) - RHS (AIG) + SUPP.xls; IMG_5857 (640x360).jpg; IMG_5858 (640x360).jpg

Hi Adrian and all,

Revised estimate is attached.

Please confirm repair cost of \$10,603.60 @ 5 days of repairs.

Photos of supplementary attached.

Your early closure is well appreciated.

best regards - jlb

Premium Automobiles

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Motor Claims Dept
Yr Ref: SLS 1817 L

Norah Khai
6768 9911
6841 1183
Nora.khai@premiumauto.com.sg
Body & Paint Dept
PA/OD/0005/2018/MAS

27 March 2018

Dear Sir,

RE: INSURANCE CLAIM FOR SLS 1817 L, Audi A3 Sedan 1.0 TFSI

With reference to the above-mentioned vehicle, no **SLS 1817 L**, claimant, **Mr. Tan Wei Cheng, Alvin**, please find the related document per attached.

1. A copy of the Original invoice no. 85012270 – S\$11,345.85
2. A copy of the Discharge Voucher duly signed by client.

Based on the above document, we would appreciate you could expedite the payment soonest possible.

If you require any further clarification, please do not hesitate to contact me at 6768 9911.

Regards

This is a computer-generated document. No signature is required.

Norah Khai
Claims Dept

Encls

AIG – SLS 1817 L

from
Telephone +65-
Telefax +65-
EMail
Our department
Our Ref
Your Ref
Date

total pages

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Service & Parts Centres
55 Ubi Rd 1
Singapore 408699
Telephone (65) 6336 2323
Telefax (65) 684 11183

REPUBLIC OF SINGAPORE
IDENTITY CARD NO S8917238A



Name
TAN WEI CHENG, ALVIN

陳偉程

Race
CHINESE

Date of birth
23-05-1989

Country of birth
SINGAPORE



REPUBLIC OF SINGAPORE DRIVING LICENCE



Licence Number: S8917238A

Name
TAN WEI CHENG, ALVIN

Birth Date: 23 May 1989

Issue Date: 01 Aug 2011




NRIC No: S8917238A



Date of issue
03-08-2004

Address
APT BLK 244 TAMPINES STREET 21
#12-379
SINGAPORE 521244

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

	EFFECTIVE DATE
Class 3 Motor Cars $\leq$ 3000kg with $\leq$ 7 passengers, exclusive of the driver, and other motor vehicles $\leq$ 2500kg	01 Aug 2011

NP 428A



Licence No: S8917238A

AIG**COVER NOTE****AUDI AUTO PROTECTOR PRIVATE VEHICLE**The following is described on this Cover Note, hereby **RECEIVED COVERED** in the terms and conditions of the policy issued to the Policyholder.

Name of Policyholder : TAN WEI CHENG, ALVIN
 Period of Insurance : 12 Sep 2017 to 11 Sep 2018
 Engine No. : CHZ525661
 Chassis No. : WAUZZZ8V3J1010810

Vehicle No. : SLS1817L
 Cover Note No. : 1700050662
 Endorsement No. :
 Issued Date : 11 Sep 2017

ABOUT THE COVER

Make/Model : AUDI A3 Sedan 2.0 TFSI S tronic
 Engine Capacity/Tonnage : 999 00 CC
 Driver Restriction : NA
 Person or Classes of Persons Entitled to Drive* :
 Sum Insured : Market Value
 Off Peak Car : No
 First Year of Registration : 2017
 Insuring with COE/PARF : Yes

a) The Policyholder
 b) Any other person who is driving on the Policyholder's order or with his/her permission
 This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition

You have to pay an additional sum of \$3,000 as "Young and/or inexperienced Driver Excess" ("YIDP") if you are or Your Authorised Driver (named or unnamed) is under the age of 23 and/or has less than 2 years' driving experience

Age Condition : All Age Condition

Limitation as to use*

Use only for social, domestic and pleasure purposes and for the Policyholder's business
 This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade

Loss of Use

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third Party Risks and Compensation) Act (Cap. 185) and Section 95 of the Road Transport Act, 1987 (Malaysia) are not to be included under these headings

EXCESS

Section 1
 Fire - \$0 Own Damage - \$600 Theft - \$0 Flood Cover - \$0

Section 2
 Property Damage - \$0

Windscreen : \$100

Named Driver and Excess (where applicable)
 TAN WEI CHENG, ALVIN - \$600 (Own Damage)

APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

1 Audi Customer Service Center Add: 55 Ubi Road 1 Singapore 406699 63662323

For other Approved Reporting Centres/AIG Authorised Repairers, please contact our 24-hour accident emergency hotline at +65 6338 6200. Alternatively, you may refer to AIG website www.aig.com.sg or AIG SG Mobile App. Simply search and download "AIG SG" from iTunes or Google Play

IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: United Overseas Bank Limited



If you do not receive your Certificate of Insurance and policy documents within 30 days from the inception date stated on this cover note, please contact us immediately.
 We hereby certify that this Cover Note is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Cap. 185), Part IV of the Road Transport Act, 1987 (Malaysia) and Motor Vehicles (Third Party Risks) Rules, 1959 (Malaysia). For Corporate Policies, this Cover Note is valid for 60 days from the commencement date of the period of insurance

0504125276

PREMIUM LEASING - SCS

281 ALEXANDRA ROAD AUDI CUSTOMER SERVICE CENTRE

SINGAPORE 159938

Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

AIG Asia Pacific Insurance Pte. Ltd.

AUTHORISED REPRESENTATIVE *Cheng Guan Tan*



Premium Automobiles Pte Ltd

Audi Centre Singapore
281 Alexandra Road
Singapore 159938
Main Telephone: 6836 2223
Main Telefax: 6471 3233
Page 1 15:54

Alexandra Service Centre
281 Alexandra Road
Singapore 159938
Telephone: 6388 2223
Telefax: 6475 1623

Ubi Service Centre
55 Ubi Road 1
Singapore 408722
Telephone: 6300 3344
Telefax: 6841 7122

Customer Service
Service Appointment: 6366 2223
Hour Breakdown Service: 6628 1231
Email: customer.care@premiumauto.com.sg

INS TAX INVOICE
Company Reg. No. 199902271W
GST Reg. No. 199902271W

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice: 85012270 Date : 23/03/2018 Order : SLS1817L Term : 30	Account: A0006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	---	--

Regn No.: SLS1817L (V 35166) Regn Date: 12/09/2017 Mileage: 4880 WIP No.: 50549

Model: A3 SEDAN 1.0 TFSI 8VMANG (NAV, Chassis: WAUZZZ8V331010810 Engine: CHZ 525661 Dept: U

VSB No.:

You have been assisted by :- UB-Carrine ()

		Details	Qty	Unit Price	Amount
S	BODYWORK	M: TO REMOVE AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, FOG LAMPS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY.	360.00	1.00	360.00
S	BODYWORK	M: TO DISMANTLE AND RENEW FRONT BUMPER, RHS FRONT FENDER AND RHS HEADLIGHT. RE-ORGANIZE FRONT CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	1250.00	1.00	1,250.00
S	BODYWORK	M: TO RESPRAY FRONT BUMPER AND RHS FRONT FENDER.	1100.00	1.00	1,100.00
S	BODYWORK	M: TO RENEW RHS FRONT RIM AND CARRY OUT WHEEL ALIGNME	280.00	1.00	280.00
S	BODYWORK	M: TO CARRY OUT DIAGNOSTIC CHECKS.	192.00	1.00	192.00
X	ABV0601025DC	WHEEL Less 020%	1.00	659.00	527.20
X	ABV0941774D	HEADLIGHT Less 020%	1.00	5458.00	4,366.40
X	ABV5821172G	WHEEL HOUS Less 020%	1.00	146.00	116.80
X	ABV5821106A	FENDER Less 020%	1.00	707.50	566.00

Sub-Total

7% GST

Grand Total



Premium Automobiles Pte Ltd

Audi Centre Singapore
281 Alexandra Road
Singapore 158838
Main Telephone: 6384 2223
Main Telefax: 6471 3731

Alexandra Service Centre
281 Alexandra Road
Singapore 158838
Telephone: 6384 2223
Telefax: 6471 3731

Ubi Service Centre
55 Ubi Road 1
Singapore 408053
Telephone: 6384 2223

Customer Service
Service Appointment
Hour Breakdown Service
Email: customer.care@premiumauto.com.sg

6366 2328
9628 1233

INS TAX INVOICE

Company Reg. No. 199902271W
GST Reg. No. 199902271W

Page 2 15:54

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice: 85012270 Date : 23/03/2018 Order : SLS1817L Term : 30	Account: A0006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	---	--

Regn No.: SLS1817L (V 35166) Regn Date: 12/09/2017 Mileage: 4888 WIP No.: 50549

Model: A3 SEDAN 1.0 TFSI 8VMANG (NAV, Chassis: WAUZZZ8V3J1010010 Engine: CHZ 525661 Dept: U

VSF No.:

You have been assisted by :- UB-Carrine ()

		Details	Qty	Unit Price	Amount
X	A8V0807550A	FOAM INSERT	1.00	157.00	125.60
X	A8V5807065R GRU	COVER	1.00	1667.00	1,333.60
X	A8V5807184	GUIDE	1.00	30.60	24.48
X	A8V5821468B	BRACKET	1.00	32.20	25.76
X	A8V0821136C	SUPPORT	1.00	81.00	64.80
X	A8V5821472A	BRACKET	1.00	22.70	18.16
X	A8V5807647B 9B9	GRILLE	1.00	132.50	106.00
X	A8V5807682M 9B9	GRILL	1.00	155.50	124.40
X	AN 0161857	POP-RIVET	5.00	2.00	11.20
X	AN 91022001	NUT	10.00	1.40	11.20

Parts 7,421.60
Labour 0.00
Sublet 3,182.00
Menus 0.00
Lubricant 0.00

Sub-Total 10,603.60

7% GST 742.25

Grand Total 11,345.85



Received by

For & on behalf of
Premium Automobiles Pte Ltd

Customer

Premium Automobiles

Telefax

to **AIG Asia Pacific Insurance Pte Ltd**
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Motor Claims Dept
Yr Ref: SLS 1817 L

Norah Khai
6768 9828
6841 1183

Body Repair

PA/OD/0005/2018/GW
12 January 2018

from
Telephone +65-
Telefax +65-
Mobile +65-
Our department
Your Claim Ref
Our Ref
Date

total pages

RE : CLAIM – OWNER'S SATISFACTION/DISCHARGE VOUCHER

Make & Model : Audi A3 Sedan 1.0 TFSI (A)
Vehicle Chassis No. : WAUZZZ8V3J1010810
Vehicle Regn No. : SLS 1817 L
Vehicle Mileage : 4872 KM
Vehicle Owner : Mr. Tan Wei Cheng, Alvin
Certificate No : 1700050662
Policy Excess : NIL
Accident Date : 31-Dec-17
Place : Sims Avenue (Bus Stop 81031)
Repair Cost : \$ 11,345.85
WIP No. : 50549
Repairer's Name : Premium Automobiles Pte Ltd

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Service & Parts Centres
55 Ubi Road 1
Singapore 408699
Telephone (65) 6366 2323
Telefax (65) 6841 1183

I/We certify that the vehicle has been fully repaired to my entire satisfaction and that payment of the repairer's charges that are claimable under the policy will be deemed in full and final settlement of my claim.

Owner / Insured Signature : 
Time :
Date : 13/1/18

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	04 Jan 2018 11:26		03 Jan 2018 18:27 Edit Adj Rpt	S\$10,603.60 Edit Estimates	S\$10,603.60 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	TAN WEI CHENG ALVIN, ID: S8917238A, Tel: +6597663687, Email: ALVINTANWC1989@GMAIL.COM								
Vehicle Reg. No.:	SLS1817L	Date of Loss:	31/12/2017 14:00 - :59						
Claim Type:	OD / 1367280871SG	Policy/Cover Note No.:	1700050662 (Comprehensive)						
		Excess:	S\$0.00						
Repairer:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1, 408699 Ubi - Tel: 67689828/9827/9911								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000 ... [Handled by Loo, Tong Shing] TongShing.Loo@aig.com								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 12/01/2018]								
Driver/Custodian:	TAN WEI CHENG ALVIN (28 / Male), NRIC: S8917238A, Tel: +6597663687								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
- AIG_SG (04/01/2018): Alert - Adj Mandate Approved (S\$12245.00) - SLS1817L - Claim Handler: Loo, Tong ... - AIG_SG (04/01/2018): SLS1817L / OD / 31/12/2017 / Coverage & Excess update - AIG_SG (04/01/2018): SLS1817L / OD / 31/12/2017 / Coverage & Excess update									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLS1817L (1367280871SG)

OD

Dec 31 2017 2:15PM

[TAN WEI CHENG ALVIN]

Premium Automobiles Pte Ltd

Upload Documents		Upload Photos	Compose New Letter	Upload Video	Upload Audio	View View in Browser	
Video						1 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)		Thumbnail	Print		
1	02/01/18 13:00	Video - Accident [Linked Accident Report Documents]		Load MP4			
Assessment Reports						1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print		
1	04/01/18 13:33	Adjuster Immediate Advice		Load HTM			
Photos/Images						3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print		
1	04/01/18 14:02	General View		Load JPG	☒		
2	04/01/18 14:02	General View		Load JPG	☒		
3	04/01/18 14:02	General View		Load JPG	☒		
4	04/01/18 14:02	General View		Load JPG	☒		
5	04/01/18 14:02	General View		Load JPG	☒		
6	04/01/18 14:02	General View		Load JPG	☒		
7	04/01/18 14:02	General View		Load JPG	☒		
8	04/01/18 14:02	General View		Load JPG	☒		
9	04/01/18 14:02	General View		Load JPG	☒		
10	04/01/18 14:02	General View		Load JPG	☒		
11	04/01/18 14:02	General View		Load JPG	☒		
12	04/01/18 14:02	General View		Load JPG	☒		
13	04/01/18 14:02	General View		Load JPG	☒		
14	04/01/18 14:02	General View		Load JPG	☒		
15	04/01/18 14:02	General View		Load JPG	☒		
16	04/01/18 14:02	General View		Load JPG	☒		
17	04/01/18 14:02	General View		Load JPG	☒		
18	04/01/18 14:02	General View		Load JPG	☒		
19	04/01/18 14:02	General View		Load JPG	☒		
20	04/01/18 14:02	General View		Load JPG	☒		
21	04/01/18 14:02	General View		Load JPG	☒		
22	19/03/18 15:27	Reinspection Photo		Load JPG	☒		
23	19/03/18 15:27	Reinspection Photo		Load JPG	☒		
24	19/03/18 15:27	Reinspection Photo		Load JPG	☒		
25	19/03/18 15:27	Reinspection Photo		Load JPG	☒		
26	19/03/18 15:27	Reinspection Photo		Load JPG	☒		
27	19/03/18 15:27	Reinspection Photo		Load JPG	☒		
28	19/03/18 15:27	Reinspection Photo		Load JPG	☒		
29	19/03/18 15:27	Reinspection Photo		Load JPG	☒		

30	19/03/18 15:27	Reinspection Photo	1	Load JPG	☒
31	19/03/18 15:27	Reinspection Photo	1	Load JPG	☒
32	19/03/18 15:27	Reinspection Photo	1	Load JPG	☒
33	19/03/18 15:27	Reinspection Photo	1	Load JPG	☒
34	19/03/18 15:27	Reinspection Photo	1	Load JPG	☒
35	19/03/18 15:27	Reinspection Photo	1	Load JPG	☒
Documentation					
			1 per page	☒	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	04/01/18 14:01	Certificate of Insurance	1	Load PDF	
2	04/01/18 14:01	Singapore Accident Statement	1	Load PDF	
3	04/01/18 14:01	Insured Persons NRIC & DL	1	Load PDF	
4	04/01/18 14:01	WORKSHOP ESTIMATE	1	Load PDF	
5	02/04/18 10:33	WORKSHOP INVOICE	1	Load PDF	
6	02/04/18 10:33	DISCHARGE VOUCHER	1	Load PDF	
7	02/04/18 10:33	SUPPLEMENTARY PART	1	Load PDF	

Linked Accident Report Documents

View [View in Browser](#)

Video			1 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	02/01/18 13:00	Video - Accident	 Load MP4	

Assessment Reports			1 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	02/01/18 13:15	Accident Statement	 Load HTM	

Photos/Images			3 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	02/01/18 12:56	Accident Photo	 Load JPG	☒
2	02/01/18 12:56	Accident Photo	 Load JPG	☒
3	02/01/18 12:56	Accident Photo	 Load JPG	☒
4	02/01/18 12:56	Accident Photo	 Load JPG	☒
5	02/01/18 12:56	Accident Photo	 Load JPG	☒
6	02/01/18 12:56	Accident Photo	 Load JPG	☒
7	02/01/18 12:56	Accident Photo	 Load JPG	☒
8	02/01/18 12:56	Accident Photo	 Load JPG	☒
9	02/01/18 12:56	Accident Photo	 Load JPG	☒
10	02/01/18 12:56	Accident Photo	 Load JPG	☒
11	02/01/18 12:56	Accident Photo	 Load JPG	☒
12	02/01/18 12:56	Accident Photo	 Load JPG	☒
13	02/01/18 12:56	Accident Photo	 Load JPG	☒
14	02/01/18 12:56	Accident Photo	 Load JPG	☒
15	02/01/18 12:56	Accident Photo	 Load JPG	☒

Documentation			1 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	02/01/18 12:52	Sketch Plan	 Load JPG	☒
2	02/01/18 12:52	Sketch Plan #2	 Load JPG	☒

Documents Checklist

DOCUMENTS CHECKLIST[Reset](#)[Save](#)[Print](#)

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

^

v

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co. Reg. No: 199807198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #07-16
Singapore 079120

Our File No: CC3/AIG18000188/ARBQ2

Date: 02/04/2018

REFERENCE

Insured/Claimant: TAN WEI CHENG ALVIN Policy No: 1700050662
Date of Loss: 31/12/2017 Nature of Claim: OD Claim No: 1367280871SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLS1817L
Make & Model: AUDI A3, 999cc TFSI (A) Engine No: CHZ525661
Reg. Date: 12/09/2017 (Man. Year: 2017) Chassis No: WAUZZZ8V3J1010810
Colour: Blue Odometer: 4872 km
Engine Capacity: 999 cc
Market Value/New Car Price: S\$128,000.00
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55 R16 Rear Tyre Size: 205/55 R16
Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm
Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	16,871.60	7,421.60	9,450.00	56.01
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,432.00	3,182.00	4,250.00	57.19
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	24,303.60	10,603.60	13,700.00	56.37
+ GST 7.00/7.00% (S\$)	1,701.25	742.25	959.00	56.37
Nett Amount (S\$)	26,004.85	11,345.85	14,659.00	56.37

INSPECTION

Date of Assignment: 03/01/2018
Date Inspected: 03/01/2018 Inspected At: Premium Automobiles Pte Ltd (UBI)
55 Ubi Road 1
Singapore 408699

Estimated Period of Repair: 5.0 days

Adjuster: ADRIAN LING

Manager: Janice Lee Si Hua

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	1,667.00 FS	*1,333.60 FS
2	1		*FRONT BUMPER GUIDE-RHS	Not Necessary	31.00 FS	*- FS
3	1		*FRONT BUMPER GRILLE -CENTRE	Necessary	133.00 FS	*108.00 FS
4	1		*FRONT BUMPER LOWER CLOSING ELEMENT	Not Necessary	445.00 FS	*- FS
5	1		*FRONT BUMPER END PLATE -RHS	Not Necessary	246.00 FS	*- FS
6	2		*FRONT BUMPER TRIM -LHS/RHS	Not Necessary	270.00 FS	*- FS
7	1		*FRONT WHEEL HOUSE LINER SPOILER -RHS	Not Necessary	31.00 FS	*- FS
8	1		*FRONT BUMPER AIR GRILLE -RHS	Cracked	156.00 FS	*124.40 FS
9	1		*FRONT FENDER -RHS	Distorted	708.00 FS	*566.00 FS
10	1		*FRONT FENDER INNER BRACKET -RHS	Bent	33.00 FS	*25.76 FS
11	1		*FRONT FENDER OUTER BRACKET -RHS	Bent	23.00 FS	*18.16 FS
12	1		*FRONT FENDER BRACE-RHS	Bent	81.00 FS	*64.80 FS
13	1		*FRONT WHEEL HOUSE LINER -RHS	Deformed	146.00 FS	*116.80 FS
14	1		*WHEEL HOUSE LINER ATTACHMENT -RHS	Not Necessary	75.00 FS	*- FS
15	1		*LED HEALIGHT -RHS	Cut	5,458.00 FS	*4,366.40 FS
16	1		*HEADLIGHT WASHER -RHS	Not Necessary	123.00 FS	*- FS
17	1		*FRONT ALUMINIUM RIM -RHS	Cut	658.00 FS	*527.20 FS
18	1		*FRONT TRACK ARM -RHS	Not Necessary	318.00 FS	*- FS
19	1		*FRONT WHEEL BEARING HOUSING -RHS	Not Necessary	502.00 FS	*- FS
20	1		*FRONT WHEEL BEARING -RHS	Not Necessary	375.00 FS	*- FS
21	1		*FRONT GUIDE ARM-RHS	Not Necessary	110.00 FS	*- FS
22	1		*STEERING RACK	Not Necessary	4,225.00 FS	*- FS
23	1		*STEERING RACK REPAIR KIT	Not Necessary	40.00 FS	*- FS
24	1		*STEERING RACK TRACK ROD-RHS	Not Necessary	82.00 FS	*- FS
25	1		*TIE ROD-RHS	Not Necessary	110.00 FS	*- FS
26	1		*FRONT TIRE -RHS (NPA)	Not Necessary	0.00 FS	*- FS
27	1		*SUSPENSION BOLTS AND NUTS	Not Necessary	300.00 FS	*- FS
28	1		*SUNDRIES	Necessary	400.00 FS	*46.88 FS
29	1		*FRONT BUMPER FOAM	Deformed	125.60 FS	*125.60 FS
Total Parts (S\$)					16,871.60	7,421.60

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS ,HORNS ,FOG LAMPS ,OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY	New	360.00	360.00
2	TO DISMANTLE AND RENEW FRONT BUMPER ,RHS FRONT FENDER AND RHS HEADLIGHT.RE-ORGANIZE FRONT CRASH MANAGEMENT COMPONENTS .REINSTALL ALL PARTS REMOVED	New	2,100.00	1,250.00
3	TO RESPRAY FRONT BUMPER ,RHS FRONT FENDER AND BONNET	New	2,100.00	1,100.00
4	TO DISMANTLE FRONT SUSPENSION ASSY .INSPECT FOR DAMAGES AND RENEW ACCORDINGLY	New	2,400.00	0.00
5	TO RENEW RHS FRONT RIM AND TIRE .CARRY OUT WHEEL ALIGNMENT	New	280.00	280.00
6	TO CARRY OUT DIAGNOSTIC CHECKS	New	192.00	192.00
Gross Labour Cost (S\$)			7,432.00	3,182.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >