

Please arrange to survey vehicle at
8 KAKI BUKIT AVENUE 4 - GATE 2
#07-48 PREMIER @ KAKI BUKIT
SINGAPORE 415875

not actual
see
take photo before repair.
3 L.
5/1/18

ABWIN 論輝

Date : 03/01/2018
TP Vehicle No. : GBF-5529-D
To : AIG ASIA PACIFIC INSURANCE PTE LTD
Attn : Motor Claim Department

LINDA LIAO
ABWIN SERVICE PTE LTD
DID: 67139417
Fax: 67139415
HP: 97519596

Owner : HUPFARRI ENTERPRISE PTE. LTD
EQ INSURANCE COMPANY LTD
Certificate No. : DMCPhQ17-001648
Vehicle No. : GBD-4035-D
Make & Model : TOYOTA DYNA 3.0 M

2488.50

Accident Date: 16/12/2017

ESTIMATED REPAIR COST DETAILS

QTY	DESCRIPTION	REPAIR AMOUNT	SURVEYOR APP.
-----	-------------	---------------	---------------

List Item

1	FRONT BUMPER	\$750.60	X
1	FRONT BUMPER BRACKET LH	\$250.00	X
1	FRONT BUMPER INNER GARNISH LH	\$85.00	X
1	LH CORNER PANEL	\$300.00	X
1	LH HEADLAMP BEAM	\$85.00	X
1	LH HEADLAMP	\$850.20	X
1	LH FRONT DOOR	\$1,549.10	✓
1	LH FRONT DOOR SIGNALAMP	\$68.90	✓
1	LH FRONT DOOR STEP PANEL	\$98.00	X
1	LH FRONT DOOR STEP GARNISH	\$385.50	X
1	LH FRONT WING MIRROR COVER	\$150.65	X
1	LH FRONT WING MIRROR ASSY	\$685.00	X
	Sub Total	\$5,257.95	
	Discount 25% on Parts	(\$1,314.49)	
		\$3,943.46	

1618
289.
1213.50

Special Nett

1	LH FRONT DOOR STICKER	\$35.00	✓
1	LH FRONT DOOR ADVERTISEMENT STICKER	\$500.00	180
2	LH REAR SLIDING DOOR ARTWORK	\$3,200.00	X
1	LH FRONT TYRE	\$250.00	X
1	LH FRONT RIM	\$250.00	X
	Sub Total	\$4,235.00	

Labour & Misc

TO PANEL BEAT LH FRONT DOOR , FRONT BUMPER , LH REAR DOOR 2 PCS	\$1,500.00	400
TO SPRAY PAINT ON AFFECTED AREAS	\$1,500.00	600
TO REMOVE AND PASTE LH REAR DOOR , LH FRONT DOOR STICKER , ADVERTISEMENT	\$150.00	60

Date : 03/01/2018
 TP Vehicle No. : GBF-5529-D
 To : AIG ASIA PACIFIC INSURANCE PTE LTD
 Attn : Motor Claim Department

LINDA LIAO
 ABWIN SERVICE PTE LTD
 DID: 67139417
 Fax: 67139415
 HP: 97519596

Owner : HUPFARRI ENTERPRISE PTE. LTD
 EQ INSURANCE COMPANY LTD
 Certificate No. : DMCPHQ17-001648
 Vehicle No. : GBD-4035-D
 Make & Model : TOYOTA DYNA 3.0 M

Accident Date: 16/12/2017

ESTIMATED REPAIR COST DETAILS

QTY	DESCRIPTION	REPAIR AMOUNT	SURVEYOR APP.
	Sub Total	\$3,150.00	

Sub Total \$11,328.46
 GST 7% \$792.99
 Total \$12,121.45

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: