

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/TP/0021/2018/GW
Date : 5-Jan-18

Vehicle NOT IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way
#07-16 AIG Building
Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Ms.Tan Peck Hoon Elsie
Address : 34 JALAN CHELAGI
SINGAPORE 509595
Telephone : HP +65 98276201
Type of Claim : Third Party Claims
Policy No. : 2100482791-01
Vehicle No : **SLF 9689 E**
Model Code : AUDI Q3 1.4 TFSI S-TRONIC
Model / Year : Sep-16
Engine No : CZD 246837
Chassis No : WAUZZZ8V9HR014802
Mileage : -
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 3-Jan-18
Place of Accident : UBI AVE 4

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLF 9689 E.

S/N	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove and transfer rear parking aid. Check function	S/N \$ 280.00	✓
2	To dismantle and renew rear bumper assy. Re - organise rear crash management components. Reinstall all parts removed.	\$ 1,050.00	500
3	To respray rear bumper and RHR fender.	\$ 1,400.00	1100
4	To carry out diagnostic checks.	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES		: \$ 2,922.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLF 9689 E.

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	REAR BUMPER <i>Repair</i>	\$ 1,238.00	X
2	TAIL LIGHT - RH <i>not on</i>	\$ 387.00	X
3	REAR BUMPER SPOILER <i>cut</i>	\$ 388.00	✓
4	REAR BUMPER GUIDE SECTION - RH <i>see on</i>	\$ 81.00	X
5	REAR WHEEL COVER - LH /RH <i>on</i>	\$ 444.00	✓
6	REAR NO. PLATE <i>not on</i>	\$ 25.00	X
7	SUNDRIES <i>?</i>	\$ 200.00	?
TOTAL SPARE PARTS		:	\$ 2,763.00
TOTAL LABOUR CHARGES		:	\$ 2,922.00
GRAND TOTAL		:	\$ 5,685.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adrian Lj
Surveyed Date : 24/01/18
Authorised Date :
Excess Cost :
Liability :
Remarks : Not Authorised, 02 days.

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant