

Please arrange to survey vehicle at
8 KAKI BUKIT AVENUE 4 - GATE 2
#07-48 PREMIER @ KAKI BUKIT
SINGAPORE 415875

ABWIN 諭輝

Date : 03/01/2018
TP Vehicle No. : SHA-2064-C
To : INDIA INTERNATIONAL INSURANCE PTE LTD
Attn : Motor Claim Department

LINDA LIAO
ABWIN SERVICE PTE LTD
DID: 67139417
Fax: 67139415
HP: 97519596

Owner : SAPHAD SERVICES
NTUC INCOME INSURANCE CO-OPERATIVE LTD
Certificate No. : 5090555637
Vehicle No. : GBF-9557-X
Make & Model : TOYOTA HIACE 3.0 DX M

Accident Date: 18/12/2017

ESTIMATED REPAIR COST DETAILS

QTY	DESCRIPTION	REPAIR AMOUNT	SURVEYOR APP.
List Item			
1	REAR BUMPER <i>Deep cut</i>	\$411.60	✓
1	RH TAILLAMP <i>0/5 11</i>	\$277.62	X
1	RH REAR FENDER <i>0/5 R</i>	\$1,381.70	✓
1	RH REAR FENDER LOWER FENDER <i>0/5 R</i>	\$533.60	X
1	RH SLIDING DOOR <i>11</i>	\$1,711.60	✓
1	RH CORNER INNER PANEL <i>11</i>	\$421.60	X
1	RH CORNER PANEL <i>R</i>	\$525.90	X
1	RH REAR AIR VENT <i>11</i>	\$91.20	X
Sub Total		\$5,354.82	
Discount 25% on Parts		(\$1,338.71)	
		\$4,016.12	

Labour & Misc

TO STRAIGHTEN AND PANEL BEAT ACCIDENT AREAS	\$1,500.00	600
TO SPRAY PAINT ON AFFECTED AREAS	\$1,500.00	400
TO TRANSFER & REFIX REAR FENDER FIXTURE & FITTING <i>11</i>	\$1,200.00	X
Sub Total	\$4,200.00	

not added
later
take photo after repair
p/p s
3 day.
10/1/18

Sub Total	\$8,216.12
GST 7%	\$575.13
Total	\$8,791.24

P- 411-6
25%
30870
1000
\$130870

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Sig:

Page 1 of 1