

LINDA LIAO  
ABWIN SERVICE PTE LTD  
DID: 67139417  
Fax: 67139415  
HP: 97519596

Date : 03/01/2018  
TP Vehicle No. : SHA-2064-C  
To : INDIA INTERNATIONAL INSURANCE PTE LTD  
Attn : Motor Claim Department

Owner : SAPHAD SERVICES  
NTUC INCOME INSURANCE CO-OPERATIVE LTD  
Certificate No. : 5090555637  
Vehicle No. : GBF-9557-X  
Make & Model : TOYOTA HIACE 3.0 DX M

Accident Date: 18/12/2017

## ESTIMATED REPAIR COST DETAILS

QTY	DESCRIPTION	REPAIR AMOUNT	SURVEYOR APP.
-----	-------------	---------------	---------------

### List Item

1	REAR BUMPER	\$411.60
1	LH TAILLAMP	\$277.62
1	LH REAR FENDER	\$1,381.70
1	LH REAR FENDER LOWER FENDER	\$533.60
1	LH SLIDING DOOR	\$1,711.60
1	LH CORNER INNER PANEL	\$421.60
1	LH CORNER PANEL	\$525.90
1	LH REAR AIR VENT	\$91.20
	<b>Sub Total</b>	<b>\$5,354.82</b>
	<b>Discount 25% on Parts</b>	<b>(\$1,338.71)</b>
		<b>\$4,016.12</b>

### Labour & Misc

TO STAIGHTEN AND PANEL BEAT ACCIDENT AREAS	\$1,500.00
TO SPRAY PAINT ON AFFECTED AREAS	\$1,500.00
TO TRANSFER & REFIX REAR FENDER FIXTURE & FITTING	\$1,200.00
<b>Sub Total</b>	<b>\$4,200.00</b>

<b>Sub Total</b>	<b>\$8,216.12</b>
<b>GST 7%</b>	<b>\$575.13</b>
<b>Total</b>	<b>\$8,791.24</b>